



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/07/2018

### Survey Details:

Date of loss	26-May-18
Date of appointment	31-May-18
Date of survey	30-Jul-18
Location of survey	MBM WHEELPOWER PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLC 7007C
Make and Model	TOYOTA HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
Date of registration	15/7/2016
Excess	
Market Value	\$110,000
Parf Rebate	\$67,668
Nett Loss	\$42,332

### Repair details:

Initial Estimate	\$ 11,200.00
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 2,576.25
Check items (estimate)	\$ 528.75
Labour	\$ 920.00
<b>Total</b>	<b>\$ 4,025.00</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>

Number of days for repair	4
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

OI CHANGE LANE. BOLA 15

**Mandate:**

Liability(TP)		100%
Proposed repair cost	\$	2,524.50
Loss of use	\$	400.00 no. of days 4 DAYS X \$100.00
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	2.00
Others	\$	
<b>Proposed Total</b>	<b>\$</b>	<b>2,926.50</b>

