

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

31-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8616 R

1 pc	n/s headlamp <i>✓</i>	\$ 1,028.00
1 pc	Front bumper <i>X repair</i>	\$ 531.00
1 pc	Front bumper emblem <i>✓</i>	\$ 44.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X</i>	\$ 32.00
1 pc	Front bumper n/s protector <i>✓</i>	\$ 51.00
1 pc	Front bumper n/s fog lamp cover <i>X</i>	\$ 61.00
1 pc	Front n/s fender <i>X repair</i>	\$ 384.00
1 pc	Front n/s fender inner shield <i>X</i>	\$ 120.00
		\$ 2,251.00
Less 10%		\$ 225.10
		\$ 2,025.90

S/NETT

1 set	Front bumper clips <i>X</i>	\$ 48.00
1 set	Front n/s fender inner shield clips <i>X</i>	\$ 28.00
1 pc	Front n/s fender sticker <i>X</i>	\$ 30.00
1 set	Front n/s head lamp lower clips <i>✓</i>	\$ 6.00
1 set	Front n/s head lamp side clips <i>✓</i>	\$ 3.00

Sundry	\$ 50.00 <i>20</i>
To check for wiring and to focus headlamp	\$ 80.00 <i>20</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same, etc.	\$ 650.00 <i>400</i>
To putty and spray painting on front bumper, front n/s fender	\$ 400.00 <i>360</i>
To apply rustproofing on the repaired and replaced panels.	\$ 120.00 <i>X</i>
	\$ 3,440.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kaharickery
M 31/5/18 1635hrs
3 by
U.S. n 11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: