

ASS. REC. BY

REF: CS/LPC18009864/Krd302

Special Instruction:

Surveyor  
Mehmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

31/5/18 @ 7.46 pm

Estimated Cost:

Bill to:

☒ OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SB2 77T

Insured:

at Workshop m/s

K. Kim Hin Auto

Tel:

64527018

of

160 Gin Ming Drive # 02-20

Policy No:

Z17VPOS 015959

Claim No:

17/18/18/VPOS/020637

Sum Insured:

Excess:

0.00

Make of Veh:

(Client's Record)

D.O.A.

25/5/2018

CA / ☒ REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:36am @ 31/5/18

Person Contacted:

Shu men

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SB2 77T - CGG/AIG16010589 / Kwb3g2 DOA: 6/6/16
31/5/18	Report from Mehmen
1/6/18	Authorise repair; Inform Shu men email
15/6	@ 8616.80 Confirmed by email @ 4 days Red: \$3669.28, 30%.

ASS. REC. BY:

REF: LPC /

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 837k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SBZ 777Yr Regn: 05, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or \_\_\_\_\_

Make: Mc E200 Komp.cColour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 196831

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDB 2110412B 39885Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 245/402R19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 25/5/18D.O.I. 31/5/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/6 File pgs to Catherine

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) \_\_\_\_\_



: Prell. Report



: Final Report

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee: 2x15=30Transportation: 170+30+40

S - RS. \$

Photos 50Others 50+50TOTAL 63TOTAL 453.10

463

Report Format: ODLump Sum / I.B.I: (\$ 8616.90)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2018 Sendback Est	30 May 2018 17:50 S\$12,286.18	31 May 2018 07:46 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

### CLAIM SUBFOLDER DETAILS

Insured:	SEE KIAN CHONG, ID: S2011306E, Tel: +6596742282, Email: NOEMAIL		
Vehicle Reg. No.:	SBZ77T	Date of Loss:	25/05/2018 16:00 - :59 [107 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/18/18/VP05/020637	Policy/Cover Note No.:	Z17VP05015959 (Comprehensive) Coverage: 26/11/2017 - 25/11/2018
		Excess:	S\$0.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/06/2018]		
Driver/Custodian:	SEE KIAN CHONG (64 / Male), NRIC: S2011306E, Tel: +6596742282		
Adj Asg. Remarks:	SURVEY & REVERT		

### ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

### ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Gerald Poh

Date: 31 May 2018

## **Preliminary Advice**

Vehicle No	: SBZ77T	Accident Date	: 25/05/2018
Make	: MERCEDES-BENZ E200K	Policy No.	: Z17VP05015959
Assignment Date	: 31/05/2018	Excess	: S\$0.00
Date of Inspection	: 31/05/2018	Est. Duration of Repair	: 4.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident. The undercarriage is affected due to collision.

Repairer's Estimate (Gross)	:S\$	12,286.18
Revised Amount	:S\$	6,860.85
Check Items (Estimated)	:S\$	2,088.05
Total	:S\$	8,948.90

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	26,718.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,282.00

### **Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Print Received Message

This mail is associated with :

**SBZ77T (17/18/18/VP05/020637)**

OD

May 25 2018 4:00PM

[SEE KIAN CHONG]

K Kim Hin Auto Pte Ltd

**From** Lonpac Insurance Bhd (HQ) (LONPAC\_HQ), sent on 01/06/2018 09:19 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8948.90) - SBZ77T - Claim Handler: Gerald Poh

Approved:8948.90.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/05/2018 17:29
Date Of Accident	25/05/2018 16:45
Exact Location Of Accident	UBI ROAD 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBZ77T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEE KIAN CHONG
NRIC No	S2011306E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96742282
Alternative Phone No	OFFICE-96742282

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200K-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05015959
Cover Note Number	

### Driver

Name of Driver	SEE KIAN CHONG
NRIC No	S2011306E
Date Of Birth	11/07/1953
Occupation	INDOOR
Date Of Driving Pass	15/01/1972
Driving Experience	46 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96742282
Fax Number	
Contact Number	OFFICE-96742282
EMail Address	NOEMAIL

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



26/12/2018 @  
10:25 Am

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1306E

### Vehicle Details

Vehicle No.:	SBZ77T
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	27195631145229
Chassis No.:	WDB2110412B398885
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,943.00
Original Registration Date:	26 May 2009
First Registration Date:	26 May 2009
Transfer Count:	1
Actual ARF Paid:	\$51,943.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2019
PARF Rebate Amount:	\$25,971.00

### Intended COE Rebate Details

COE Expiry Date:	25 May 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$7,552.00
COE Rebate Amount:	\$747.00
<b>Total Rebate Amount:</b>	<b>\$26,718.00</b>

The information contained herein is correct as at 28 May 2018

OK





CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM HIN AUTO PTE LTD

**金興(龔)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05015959	Date of Loss:	25/05/2018
Vehicle Reg. No.:	SBZ77T	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SEE KIAN CHONG	Contact No:	+6596742282
Driver:	SEE KIAN CHONG		

Make/Model:	MERCEDES-BENZ E200K, 1.8 (A)	Vehicle Reg. Date:	26/05/2009
Vehicle Colour:	BLUE		
Engine No:	27195631145229	Chassis No:	WDB2110412B398885
Odometer:	0 KM		

Paint Type:  
Total Loss?  
Est. Duration of Repair  
(day)

NO

4 ✓

discuss NOT Authorised  
11 May 8?  
Penny After Point  
EX NIC

Description of  
Accident/Loss

PLEASE REFER TO SKETCH PLAN.

Remarks:

VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU.

Present Location:

K KIM HIN AUTO PTE LTD (HQ)

**COST OF CLAIMS**

	Amount
Parts	10,986.18
Miscellaneous Items	0.00
Labour	1,300.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>12,286.18</b>
<b>+ GST 7.00% (S\$)</b>	<b>860.03</b>
<b>Nett Amount (S\$)</b>	<b>13,146.21</b>

This claim is handled by: **WONG SHU MAN**

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 30 May 2018)

**Parts:** 143      MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SBZ77T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	R	0.00	0.00	*880.00 F	X
2	1		*O/S FRONT BUMPER SIDE BRACKET	R	0.00	0.00	*42.00 F	X
3	2		*FRONT BUMPER CHROME MOULDING (LH/RH)	RM	0.00	0.00	*114.00 F	✓
4	1		*O/S HEADLAMP	Sm	0.00	0.00	*1,260.00 F	X
5	1		*O/S FRONT FENDER	R	0.00	0.00	*405.00 F	X
6	1		*O/S FRONT FENDER PROTECTOR AND CHROME MOULDING	SVL	0.00	0.00	*44.00 F	?
7	1		*O/S FRONT FENDER PROTECTOR EMBLEM	RM	0.00	0.00	*35.00 F	?
8	1		*O/S FRONT FENDER INNER SHIELD-FRONT	CM	0.00	0.00	*50.00 F	✓
9	1		*O/S FRONT SPORT RIM	RM	0.00	0.00	*530.00 F	✓
10	1		*O/S FRONT LOWER ARM	D.T	0.00	0.00	*314.00 F	✓
11	1		*O/S FRONT LOWER ARM BALL JOINT	B.T	0.00	0.00	*80.00 F	?
12	1		*O/S FRONT LOWER CONTROL ARM	B.T	0.00	0.00	*225.00 F	?
13	1		*O/S FRONT LOWER KNUCKLE ARM	M	0.00	0.00	*525.00 F	?
14	1		*O/S FRONT LOWER KNUCKLE ARM BEARING AND BEARING HUB	RM	0.00	0.00	*320.00 F	?
15	1		*O/S FRONT UPPER ARM	D.T	0.00	0.00	*290.00 F	?
16	4		*O/S FRONT ALIGNMENT SCREW	RM	0.00	0.00	*88.00 F	?
17	1		*O/S FRONT STABILIZER BAR LINKAGE	Sm	0.00	0.00	*71.50 F	X
18	1		*O/S FRONT TIE ROD	B.T	0.00	0.00	*31.00 F	✓
19	1		*O/S FRONT TIE ROD END	M	0.00	0.00	*80.00 F	✓
20	1		*STEERING RACK AND PINION	B.T/Ty	0.00	0.00	*3,960.00 F	✓
21	1		*O/S FRONT TYRE	SVL	0	0.00	*240.00 FS	?

F=Franchise part. S=SpcNett.

Sub Total (S\$)	9,584.50
+ Margin on L,N Items 15.00% (S\$)	1,401.68
<b>Total Parts (S\$)</b>	<b>10,986.18</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED OR KINGS DOLLY.	New	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	30d 450.00
3	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	24d 320.00
4	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	6d 80.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	40d 420.00
6	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	2d 30.00
Gross Labour Cost (\$\$)			1,300.00

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

**金興(興)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER:

Lonpac Insurance Bhd (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05015959	Date of Loss:	25/05/2018
Vehicle Reg. No.:	SBZ77T	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SEE KIAN CHONG	Contact No:	+6596742282
Driver:	SEE KIAN CHONG		

Make/Model:	MERCEDES-BENZ E200K, 1.8 (A)	Vehicle Reg. Date:	26/05/2009
Vehicle Colour:	BLUE		
Engine No:	27195631145229	Chassis No:	WDB2110412B398885
Odometer:	0 KM		

Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4 ✓		

*disk & etc* *NOT AUTHORIZED*  
*21 May 87*  
*Anthony Adu Paim*  
*EX NIL*  
*Fax: 62564315*

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU.
Present Location:	K KIM HIN AUTO PTE LTD (HQ)

**COST OF CLAIMS**

	Amount
Parts	10,986.18
Miscellaneous Items	0.00
Labour	1,300.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>12,286.18</b>
<b>+ GST 7.00% (S\$)</b>	<b>860.03</b>
<b>Nett Amount (S\$)</b>	<b>13,146.21</b>

This claim is handled by: WONG SHU MAN

# REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2018)
Parts:	143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBZ77T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	R	0.00	0.00 *880.00 F X
2	1		*O/S FRONT BUMPER SIDE BRACKET	R	0.00	0.00 *42.00 F X
3	2		*FRONT BUMPER CHROME MOULDING (LH/RH) ✓	R	0.00	0.00 *114.00 F ✓
4	1		*O/S HEADLAMP	R	0.00	0.00 *1,260.00 F X
5	1		*O/S FRONT FENDER	R	0.00	0.00 *405.00 F X
6	1		*O/S FRONT FENDER PROTECTOR AND CHROME MOULDING	R	0.00	0.00 *44.00 F X
7	1		*O/S FRONT FENDER PROTECTOR EMBLEM	R	0.00	0.00 *35.00 F X
8	1		*O/S FRONT FENDER INNER SHIELD-FRONT ✓	R	0.00	0.00 *50.00 F ✓
9	1		*O/S FRONT SPORT RIM ✓ 525	R	0.00	0.00 *530.00 F ✓
10	1		*O/S FRONT LOWER ARM ✓	R	0.00	0.00 *314.00 F ✓
11	1		*O/S FRONT LOWER ARM BALL JOINT ✓		0.00	0.00 *80.00 F ✓
12	1		*O/S FRONT LOWER CONTROL ARM ✓		0.00	0.00 *225.00 F ✓
13	1		*O/S FRONT LOWER KNUCKLE ARM ✓		0.00	0.00 *525.00 F ✓
14	1		*O/S FRONT LOWER KNUCKLE ARM BEARING AND BEARING HUB ✓		0.00	0.00 *320.00 F ✓
15	1		*O/S FRONT UPPER ARM ✓		0.00	0.00 *290.00 F ✓
16	4		*O/S FRONT ALIGNMENT SCREW ✓		0.00	0.00 *88.00 F ✓
17	1		*O/S FRONT STABILIZER BAR LINKAGE ✓		0.00	0.00 *71.50 F X
18	1		*O/S FRONT TIE ROD ✓		0.00	0.00 *31.00 F ✓
19	1		*O/S FRONT TIE ROD END ✓		0.00	0.00 *80.00 F ✓
20	1		*STEERING RACK AND PINION ✓		0.00	0.00 *3,960.00 F ✓
21	1		*O/S FRONT TYRE		0	0.00 *240.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (\$)	9,584.50
+ Margin on L,N Items 15.00% (\$)	1,401.68
<b>Total Parts (\$)</b>	<b>10,986.18</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

6606

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED OR KINGS DOLLY.	New	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	30d 450.00
3	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	24d 320.00
4	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	6d 80.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	40d 420.00
6	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	20d 30.00
Gross Labour Cost (S\$)			1,300.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

$$\begin{array}{r}
 6606 \\
 + \quad 15\% \\
 \hline
 7596.90 \text{ s/Parts} \\
 + 1020 \text{ Labour} \\
 \hline
 \$8616.90 \quad \checkmark \text{ ok}
 \end{array}$$



# PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)  
TEL NO : 64523938 (6 LINES) FAX NO : 64527936  
A/C DEPT : 64590882  
Business Reg & GST NO : 201512120M



D176708

## TAX INVOICE

K.KIM HIN AUTO PTE LTD  
BLK160 SIN MING DRIVE  
#02-18/19/20/21 SIN MING AUTOCITY  
S'PORE 575708  
REMARK : VEH NO.SBZ77T

DELIVER TO :  
ENGINE #02-18/19  
BODY PARTS #02-20/21

INV NO : I176708  
DATE : 01/06/2018  
A/C NO : 304710  
TERM : 60  
PAGE : 1 OF 1  
ISSUE : APS

Printed on 01/06/2018 10:33:54

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	211 885 2321MB	FF BUMPER MOULDING LH ✓	SS2Q09	1	PCS	57.00 ✓	57.00
2	211 885 2421MB	FF BUMPER MOULDING RH ✓	SS2Q09	1	PCS	57.00 ✓	57.00
3	211 698 0230MB	FRT FENDER SEAL F.RH ✓	3W3G01	1	PCS	50.00 ✓	50.00
4	B6647 4510	SPORT RIM ✓	LC <del>1201 5308</del>	1	PC	525.00 ✓	525.00
5	219 460 1100MB	P/S RACK & PINION ✓	LC	1	PC	3,960.0 ✓	3,960.00

RECEIVED BY

PICKED BY:

SUB-TOTAL : S\$ 4,649.00  
ADD 7% GST : S\$ 325.43  
TOTAL : S\$ 4,974.43

Goods sold are not returnable except Repairs/Service at authorized workshop.



# PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)  
TEL NO : 64523938 (6 LINES) FAX NO : 64527936  
A/C DEPT : 64590882  
Business Reg & GST NO : 201512120M



D176702

REPRINT

K.KIM HIN AUTO PTE LTD  
BLK160 SIN MING DRIVE  
#02-18/19/20/21 SIN MING AUTOCITY  
S'PORE 575708  
REMARK : VEH NO.SBZ77T

DELIVER TO :  
ENGINE #02-18/19  
BODY PARTS #02-20/21

## TAX INVOICE

INV NO : I176702  
DATE : 01/06/2018  
A/C NO : 304710  
TERM : 60  
PAGE : 1 OF 1  
ISSUE : APS

Printed on 01/06/2018 10:44:18

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	211 330 8207MB	CONTROL ARM RH	2W1D09	1	PCS	314.00	314.00
2	211 330 0435MB	FRT LOWER BALL JOINT	SS1H32	1	PCS	80.00	80.00
3	211 330 4411MB	FRT.THRUST ARM RH	2W1C22	1	PCS	165.00	165.00
4	211 333 2914MB	THRUST ARM BUSH	2W1C11	1	PCS	60.00	60.00
5	211 330 6520MB	FRT.STEERING KNUCKL RH	SS1H33	1	PCS	525.00	525.00
6	211 330 0138MB	UPPER ARM	SS1J29	1	PCS	200.00	200.00
7	000 330 1007MB	UPPER ARM BALL JOINT	SS1H12	1	PCS	94.00	94.00
8	230 330 0325MB	FRT BEARING HUP	3W	1	PC	320.00	320.00
9	000 330 0018MB	FRT LOWER ARM SCREW	SS1H27	4	PC	22.00	88.00
10	230 338 0015MB	STEERING TIE ROD	SS1J23	1	PCS	31.00	31.00
11	211 330 2803MB	TIE ROD,OUTSIDE RH	SS1H10	1	PCS	80.00	80.00
12	230 338 0015MB	STEERING TIE ROD	SS1J23	1	PCS	31.00	31.00
13	211 330 2703MB	TIE ROD,OUTSIDE LH	SS1H10	1	PCS	80.00	80.00

RECEIVED BY

PICKED BY: 8514

SUB-TOTAL : S\$ 2,068.00  
ADD 7% GST : S\$ 144.76  
TOTAL : S\$ 2,212.76

Goods sold are not returnable except Repairs/Service at authorized workshop.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2018 <a href="#">Sendback Est</a>	30 May 2018 17:50 <b>S\$12,286.18</b>	31 May 2018 07:46 <a href="#">Edit Adj Rpt</a>	<b>S\$8,616.90</b> <a href="#">Edit Estimates</a>	<b>S\$8,616.90</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**

Insured:	SEE KIAN CHONG, ID: S2011306E, Tel: +6596742282, Email: NOEMAIL		
Vehicle Reg. No.:	SBZ77T	Date of Loss:	25/05/2018 16:00 - :59 [107 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/18/18/VP05/020637	Policy/Cover Note No.:	Z17VP05015959 (Comprehensive) Coverage: 26/11/2017 - 25/11/2018
		Excess:	S\$0.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/06/2018]		
Driver/Custodian:	SEE KIAN CHONG (64 / Male), NRIC: S2011306E, Tel: +6596742282		
Adj Asg. Remarks:	SURVEY & REVERT		

  
**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

- LONPAC\_HQ (01/06/2018): Alert - Adj Mandate Approved (S\$8948.90) - SBZ77T - Claim Handler: Gerald Poh

  
**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**SBZ77T (17/18/18/VP05/020637)**





































**OD**

**May 25 2018 4:00PM**




**[SEE KIAN CHONG]**

**K Kim Hin Auto Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)								Thumbnail	Print			
1	30/05/18 17:50	Repairer Estimates								Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	31/05/18 17:21	Adjuster Immediate Advice								Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
2	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
3	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
4	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
5	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
6	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
7	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
8	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
9	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
10	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
11	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
12	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
13	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
14	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
15	15/10/18 16:19	General View								Load JPG	<input checked="" type="checkbox"/>			
16	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
17	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
18	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
19	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
20	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
21	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
22	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
23	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
24	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
25	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
26	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
27	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
28	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
29	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
30	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
31	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
32	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
33	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			
34	02/11/18 15:18	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	02/11/18 15:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
58	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
59	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
60	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
61	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
62	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
63	02/11/18 15:18	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 17:42	Certificate of Insurance	 Load PDF	
2	30/05/18 17:42	Log card (if available)	 Load PDF	
3	30/05/18 17:42	Insured's NRIC	 Load PDF	
4	30/05/18 17:42	TRANSFER FEE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 17:41	SBZ 77T EST	 Load PDF	
2	02/11/18 10:14	Parts Invoice	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 18:30	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 18:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 18:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
3	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	28/05/18 18:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	28/05/18 17:42	Sketch Plan		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse  
Singapore 199555

Our File No: CS/LPC18009864/KRD3E2

Date: 07/11/2018

### REFERENCE

Insured/Claimant: SEE KIAN CHONG Policy No: Z17VP05015959  
Date of Loss: 25/05/2018 Nature of Claim: OD Claim No: 17/18/18/VP05/020637

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBZ77T**  
Make & Model: MERCEDES-BENZ E200K, 1.8 (A) Engine No: 27195631145229  
Reg. Date: 26/05/2009 (Man. Year: 2008) Chassis No: WDB2110412B398885  
Colour: Metallic Black Odometer: 196831 km  
Engine Capacity: 1796 cc  
Market Value/New Car Price: S\$37,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40Z R19 Rear Tyre Size: 245/40Z R19  
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,986.18	7,596.90	3,389.28	30.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,020.00	280.00	21.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,286.18</b>	<b>8,616.90</b>	<b>3,669.28</b>	<b>29.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>860.03</b>	<b>603.18</b>	<b>256.85</b>	<b>29.87</b>
<b>Nett Amount (S\$)</b>	<b>13,146.21</b>	<b>9,220.08</b>	<b>3,926.13</b>	<b>29.87</b>

### INSPECTION

Date of Assignment: 31/05/2018 Present Location: K Kim Hin Auto Pte Ltd (HQ)  
Date Inspected: 31/05/2018 Inspected At: K Kim Hin Auto Pte Ltd (HQ)  
160 Sin Ming Drive #02-20, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2018)
<b>Parts:</b> 143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SBZ77T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Repair	880.00 F	*- F
2	1		*O/S FRONT BUMPER SIDE BRACKET (WCP)	Repair	42.00 F	*- F
3	2		*FRONT BUMPER CHROME MOULDING (LH/RH) (WCP)	Necessary	114.00 F	*114.00 F
4	1		*O/S HEADLAMP (WCP)	Serviceable	1,260.00 F	*- F
5	1		*O/S FRONT FENDER (WCP)	Repair	405.00 F	*- F
6	1		*O/S FRONT FENDER PROTECTOR AND CHROME MOULDING (WCP)	Serviceable	44.00 F	*- F
7	1		*O/S FRONT FENDER PROTECTOR EMBLEM (WCP)	Not Necessary	35.00 F	*- F
8	1		*O/S FRONT FENDER INNER SHIELD-FRONT (WCP)	Cracked	50.00 F	*50.00 F
9	1		*O/S FRONT SPORT RIM (WCP)	Dented	530.00 F	*525.00 F
10	1		*O/S FRONT LOWER ARM (WCP)	Distorted	314.00 F	*314.00 F
11	1		*O/S FRONT LOWER ARM BALL JOINT (WCP)	Bent	80.00 F	*80.00 F
12	1		*O/S FRONT LOWER CONTROL ARM (WCP)	Bent	225.00 F	*225.00 F
13	1		*O/S FRONT LOWER KNUCKLE ARM (WCP)	Bent	525.00 F	*525.00 F
14	1		*O/S FRONT LOWER KNUCKLE ARM BEARING AND BEARING HUB (WCP)	Necessary	320.00 F	*320.00 F
15	1		*O/S FRONT UPPER ARM (WCP)	Distorted	290.00 F	*294.00 F
16	4		*O/S FRONT ALIGNMENT SCREW (WCP)	Necessary	88.00 F	*88.00 F
17	1		*O/S FRONT STABILIZER BAR LINKAGE (WCP)	Serviceable	71.50 F	*- F
18	1		*O/S FRONT TIE ROD (WCP)	Bent	31.00 F	*31.00 F
19	1		*O/S FRONT TIE ROD END (WCP)	Bent	80.00 F	*80.00 F
20	1		*STEERING RACK AND PINION (WCP)	Bent / Jammed	3,960.00 F	*3,960.00 F
21	1		*O/S FRONT TYRE	Serviceable	240.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>9,584.50 6,606.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				+ Margin on L,N Items 15.00/15.00% (S\$)	1,401.68	990.90
				Total Parts (S\$)	10,986.18	7,596.90

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED OR KINGS DOLLY.	New	0.00	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	450.00	300.00
3	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	320.00	240.00
4	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	80.00	60.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	420.00	400.00
6	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	30.00	20.00
Gross Labour Cost (S\$)			<b>1,300.00</b>	<b>1,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >