

SS. REC. BY:

REF:

C8/MSG18009870/71vd362

Special Instruction:

SUBJECT:

Tamblich
Merimen

ASSIGNMENT (Office)

From (Person):

Jocelyn Ng 6594 2539 MSIG

Date/Time:

31/5/18 @ 9.22am

Estimated Cost:

Bill to:

① TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCW 2808S

Insured:

at Workshop n/z

Performance

Tel:

9116 5200

of

303 Alexandra Rd

Policy No:

27855060 SMP

Claim No:

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A

28/5/2018

CA / REY / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:16am @ 31/5/18

Person Contacted:

Chua

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SCW 2808S - CV1 / VAL 18009813 / MV

DUA: 28/5/18

1/6/18

Revert by merimen

5/6/18

@513pm Jocelyn said not exceeding \$27,000

5/6/18

Informed Mr Chua c/A not exceeding \$27,000 ex \$500 by email

6/6/18

@451pm Jocelyn said max repair cost \$28K

REF:

MS167

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

4500

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

441K 92K 1/6/18
 IDAC Accident Report Consistent? : Yes or No *Taufik*

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res: Yes or No

Lum Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

China

Veh No: *SCW 28085* Yr Regn: *2015 Feb*
 Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make

*BMW 218I**cc 1477*

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

35074

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WK A2193203LVZ50793

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

205/60R16

BS / DUN / EXNOVA GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

D.O.I. _____

6/5/18

Survey held at _____

*PMU*Des. of Damage: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

1st 6/10/18

Check Unit

6/6/18 Informed Inthiran c/a not exceeding \$28K
 6/6/18 @ 537pm Jocelyn call up repair cost also can be \$29K
 3/8/18 Confirmed RS \$28,000 by email (Ref 20,555-90, 429)

RECEIVED

Date/Time: File Pass to?



Prel. Report

11



Final Report

Date/Time: File Return to?

3/8 - typist

Days Of Repair: *12*Resurvey No. of Trip: *3*

Survey Fee

400

Transportation

\$ - RT - \$

1. Photo

1. Other

*10*Report Format: *merimen*

Lump Sum / I.B.I. \$

RS \$28000

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Workshop (\$)

400



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009870/T1vd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-05-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SCW 2808S
Policy No. 27855060SMP	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From MERIMEN (JOCELYN NG)	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 28/05/2018	Inspection Date 31/05/2018
Survey held at PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018		31 May 2018 09:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	CHIN TECK CHUAN, ID: S2555798J, Tel: +6598184738		
Vehicle Reg. No.:	SCW2808S	Date of Loss:	28/05/2018 20:00 - :59 [39 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	27855060SMP (Comprehensive) Coverage: 10/02/2018 - 09/02/2019
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/06/2018]		
Driver/Custodian:	DAVIN HUANG (27 / Male), NRIC: N7177367		
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date:	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SCW2808S (559819)**

OD

May 28 2018 8:00PM

[CHIN TECK CHUAN]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 03/08/2018 13:32 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$28000.00) - SCW2808S - Claim Handler: Jocelyn Ng Shin Bun

Approved:28000.00:Repair limit \$29000.00 nett, excluding GST

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jocelyn Ng Shin Bun	Date: 02 Aug 2018

Preliminary Advice

Vehicle No	: SCW2808S	Accident Date	: 28/05/2018
Make	: BMW 218i	Policy No.	: 27855060SMP
Assignment Date	: 31/05/2018	Excess	: S\$500.00
Date of Inspection	: 31/05/2018	Est. Duration of Repair	: 12.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	48,555.90	(incl.supplementary \$4670.60)
Revised Amount	:S\$	28,000.00	(incl.supplementary \$4670.60)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	28,000.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$	92,000.00	
COE / PARF Rebate	:S\$	61,952.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	30,048.00	

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Chua Kee Sin <chua.kee.sin@simedarby.com.sg>
Sent: Thursday, 7 June 2018 9:55 AM
To: Veron Chen (LKKAUTO)
Cc: SUR; Teng Wai Khan; Keith Leo Chi Yung
Subject: RE: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Ms Veron ,

Noted, we will carry out with the necessary repairs and rearrange for the survey accordingly.

Thank you

Regards,

Chua Kee Sin

Customer Service Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 9116 5200 | Fax (+65) 6479 4601
chua.kee.sin@simedarby.com.sg



<http://www.pml.com.sg/catatestdrive/>



Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, June 06, 2018 4:54 PM
To: Inthiran Thurasamy
Cc: SUR; Chua Kee Sin; Teng Wai Khan
Subject: RE: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Inthiran,

As instructed by our client , please proceed to repair the insured vehicle **SCW 2808S ,not exceeding part by part \$28,000/- (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 6 June 2018 3:43 PM

To: 'Inthiran Thurasamy' <inthiran.thurasamy@simedarby.com.sg>

Cc: SUR <sur@lkkauto.com>; Chua Kee Sin <chua.kee.sin@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>

Subject: RE: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Inthiran,

Will revert to insurance.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]

Sent: Wednesday, 6 June 2018 3:13 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Chua Kee Sin <chua.kee.sin@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>

Subject: RE: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Veron,

We regret to informed that we are unable to undertake the repair with limit of \$27K. We would like request the limit repair at \$29K.

Please revert to us.

Thank you.

Warm regards

Inthiran

Customer Service Advisor

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Body & Paint Department



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 6 June, 2018 9:56 AM
To: Inthiran Thurasamy
Cc: SUR
Subject: FW: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Inthiran,

Forward email as requested.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 5 June 2018 5:44 PM
To: Chua Kee Sin <chua.kee.sin@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Mr Chua,

As instructed by our client , please proceed to repair the insured vehicle **SCW 2808S ,not exceeding part by part \$27,000/- (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SCW2808S (559819)**

OD

May 28 2018 8:00PM

[CHIN TECK CHUAN]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 06/06/2018 16:56 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$20557.25) - SCW2808S - Claim Handler: Jocelyn Ng Shin Bun

Approved:20557.25:Repair limit \$29000.00 nett, excluding GST

DOCUMENTS SUMMARY

There are no documents.

View Sent Message

This mail is associated with :

***SCW28085 (559819)**

OD

May 28 2018 8:00PM

[CHIN TECK CHUAN]

Performance Motors Limited

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **06/06/2018 15:31 PM.**

To jocelyn_ng@sg.msg-asia.com

Subject COUNTER PROPOSE ON REPAIR COST

Dear Jocelyn,

According to repairer they are unable to undertake the repair with limit of \$27K. They request the limit repair at \$29K.

For your approval please.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 5 June 2018 5:44 PM
To: Chua Kee Sin
Cc: SUR
Subject: SCW 2808S-DOA: 28/5/2018 (MSIG OD)

Dear Mr Chua,

As instructed by our client , please proceed to repair the insured vehicle **SCW 2808S ,not exceeding part by part \$27,000/- (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SCW28085 (559819)**

OD

May 28 2018 8:00PM

[CHIN TECK CHUAN]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 05/06/2018 17:18 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$20557.25) - SCW28085 - Claim Handler: Jocelyn Ng Shin Bun

Approved:20557.25:Repair limit \$27000.00 net, excluding GST

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SCW2808S (559819)**

OD

May 28 2018 8:00PM

[CHIN TECK CHUAN]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 05/06/2018 16:09 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$20557.25) - SCW2808S - Claim Handler: Jocelyn Ng Shin Bun

Approved:20557.25;We will revert on repair limit, depending on the surveyor's assessment on check items.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jocelyn Ng Shin Bun	Date: 01 Jun 2018

Preliminary Advice

Vehicle No	: SCW2808S	Accident Date	: 28/05/2018
Make	: BMW 218i	Policy No.	: 27855060SMP
Assignment Date	: 31/05/2018	Excess	: S\$500.00
Date of Inspection	: 31/05/2018	Est. Duration of Repair	: 12.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,885.30
Revised Amount	:S\$	20,557.25
Check Items (Estimated)	:S\$	16,574.50
Total	:S\$	37,131.75
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	61,952.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,048.00

Remarks

- () The vehicle is economical/not economical for repair.
- (X) Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$30,048.00


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5798J
Vehicle Details	
Vehicle No.:	SCW2808S
Vehicle to be Exported:	No
Intended De-registration Date:	01 Jun 2018
Vehicle Make:	B.M.W.
Vehicle Model:	218I ACTIVE TOURER D/AB LED DSC ABS NAV
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	F4020983B38A15A
Chassis No.:	WBA2A32030VZ50793
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,690.00
Original Registration Date:	10 Feb 2015
First Registration Date:	10 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$19,366.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2025
PARF Rebate Amount:	\$14,524.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$47,428.00
Total Rebate Amount:	\$61,952.00

The information contained herein is correct as at 01 Jun 2018

OK



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Good Buy! 2017 Toyota Harrier 2.0A Premium Panoramic



1.98% Interest Rates, 1 Owner,
 Low Depreciation, 100%
 Accident Free!

P PRIME MOTOR & LEASING

SHOWING CREDIT ENHANCING PRICES FROM 10% CASHLESS

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

17 vehicles

bmw 218

Sort by Date Posted 20 results/page

Advanced Search **Search**

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Milage	Yeh Type	Status
bmw 218		Any	Any	2015	Any	Any	Any	Available



BMW 2 Series 218i Active Tourer

\$99,800

\$12,300 /yr

15-May-2015

1,499 cc

30,598 km

Hatchback

Available

High Spec Model With GPS Build In, Auto Tailgate, Premium Interior Trimming. No Further Repair Needed, Buy With A Piece Of Mind. Avail Extended Warranty From Agent PML Till April 2020 Still

Autobest Traders Pte Ltd

Rated: 30-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



BMW 2 Series 218i Active Tourer

\$106,800

\$13,120 /yr

10-Sep-2015

1,499 cc

37,271 km

Hatchback

Available

Enjoy The Latest BMW Front-wheel Drive Technology, Low Fuel Consumption, Extreme Agility And Road Holding, Vacation Drive? Be Pampered With The Ample Of Leg & Head Room, Piles Of Luggages At The Boot....

Performance Premium Selection Limited

Rated: 30-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



BMW 2 Series 218i Active Tourer

\$96,000

\$12,620 /yr

30-Jan-2015

1,499 cc

33,200 km

Hatchback

Available

Full PML Service Record, Parallel Auto Parking Assist, Reverse Sensor, Auto Bi Xenon Lights, Eco Pro, Keyless Entry/Start, Auto Tailgate, Serviced And Maintained By PML.

Rated: 28-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



BMW 2 Series 218i Active Tourer

\$100,800

\$11,830 /yr

30-Oct-2015

1,499 cc

37,300 km

Hatchback

Available

1 Careful Owner. 3 Years PML Warranty. Definitely The Best Condition In Town, Guaranteed Accident Free. PML Unit. Buy With A Piece Of Mind. 100% Quality Buy! STA And VICOM Evaluation Welcome. Vehicle ...

Rated: 28-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but
 Unsure of its Condition?
 Get STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



BMW 2 Series 218i Active Tourer

\$104,800

\$12,650 /yr

22-Sep-2015

1,499 cc

36,000 km

Hatchback

Available

Best Price. Spacious Continental SUV At Affordable Price. 3 Years Warranty. Low Mileage. Good Condition. Well Maintained By 1 Careful Owner. Agent Services. Park Under Shelter. Like New Car. Call Now ...

Rated: 26-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



BMW 2 Series 218i Active Tourer

\$91,800

\$12,130 /yr

26-Feb-2015

1,499 cc

50,000 km

Hatchback

Available

One Owner, Fully Agent Maintained, 100% Accidents Free, Price Negotiable, Easy Loan/Trade In Available.

Rated: 27-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



BMW 2 Series 218i Active Tourer

\$106,800

\$12,740 /yr

28-Oct-2015

1,499 cc

55,734 km

Hatchback

Available

In-House Loan And Refinance Scheme Available. No Gimmicks! Down Payment \$10680 With Monthly \$1454, Full PML Service Record, 1 Owner, Parallel Auto Parking Assist, Reverse Camera, Auto Bi Xenon Lights W...

Rated: 26-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



BMW 2 Series 218i Active Tourer

\$99,800

\$12,310 /yr

28-Aug-2015

1,499 cc

48,000 km

Hatchback

Available

New Arrival, 1 Owner, Fully Maintained And Warranty By Agent PML, Full Serviced Record, Sporty Black On Black Leather Interior, Very Well Maintained, New SLZ Plots. High Loan Available.

Rated: 25-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$98,999

\$11,980 /yr

25-Sep-2015

1,499 cc

70,000 km

Hatchback

Available

Special 2.48% Banks Interest Rate! 1 Owner, Full Serviced Histories And Warranty By With PHL, Certified Premium 110 Points Check, Agent, Owner Upgraded To New Audi, Flexible Financing Available, Spec...

Premium Automobiles

Posted: 23-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$99,800

\$12,160 /yr

28-Aug-2015

1,499 cc

-

Hatchback

Available

\$0 Down Payment For Limited Period Only! Other Loan Packages From Bank/In House/Balloon Scheme Available With Most Attractive And 100% Fast Approval Rates! 1 Owner Only! Full Serviced History And Val...

Le Motor Enterprise

Posted: 24-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW



Best car deals without the hassle of paperwork!

We have over a thousand consignment cars available for sale at highly attractive prices. All without the need to do paperwork. Pick out your favourite car today.

Find out more!


BMW 2 Series 218i Active Tourer

\$89,800

\$11,840 /yr

27-Feb-2015

1,499 cc

45,000 km

Hatchback

Available

Cheapest In The Market! 1 Owner Car. Excellent Condition! Low Fuel Consumption! No Repairs Needed. We Welcome VICOM/STA Evaluation! Call Now To Test Drive.

Posted: 24-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$99,555

\$12,140 /yr

31-Aug-2015

1,499 cc

45,000 km

Hatchback

Available

Full Agent Maintain, Servicing Just Done, Still Under PHL Warranty, 2.28% Loan Interest, 24/7 Roadside Assistance Coverage. Free Car Spa Polishing! Highest Trade In For Your Car. Low Down Payment, Hig...

Cars Inn Credit Pte Ltd

Posted: 18-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$108,800

\$12,650 /yr

29-Oct-2015

1,499 cc

25,500 km

Hatchback

Available

1 Owner Sporty Pearl White With Low Mileage 25,500 KM Only As Owner Stationed Overseas, Full Serviced Histories And Warranty By With PHL, Accident Free, High Loan Available, Trade In Welcome, Viewing ...

Posted: 06-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$93,800

\$12,390 /yr

30-Apr-2015

1,499 cc

56,420 km

Hatchback

Available

\$2,000 Republic Auto Warranty Service Credit PHL Unit, Maintained By Agent, Well Kept, Call For Viewing Or SMS To Arrange For Test Drive.

Republic Auto

Posted: 05-May-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$97,500

\$13,080 /yr

27-Jan-2015

1,499 cc

40,000 km

Hatchback

Available

3 Years Agent Warranty, Mint Condition. Please Call For An Appointment. Extended Warranty Available. Loan And Trade In Provided.

Posted: 23-Apr-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$95,800

\$12,550 /yr

15-May-2015

1,499 cc

60,000 km

Hatchback

Available

Fully Maintained By Agent PHL Agent Unit. Extended Warranty From PHL May 2020 Or 200,000km. Price Negotiable, Consignment Unit, Appointment Only. Call Now.

Performance Carz Pte Ltd

Posted: 22-Apr-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW


BMW 2 Series 218i Active Tourer

\$106,900

\$12,910 /yr

30-Sep-2015

1,499 cc

40,000 km

Hatchback

Available

3 Digit Carplate. Just Serviced At PHL With Receipts To Show. Great Fuel Consumption. Full Tank Can Clock 7 00 Plus Km. Owner's 4th Car. Car Driven To Send Son Every Morning. Problem Free. Looking For...

Posted: 21-Apr-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For 102 advertisements, view [Expired ads](#)

20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 218, bmw 218 Singapore, used bmw 218 Singapore, used bmw 218, used vehicles Singapore or even buy used bmw 218 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2018 10:37
Date Of Accident	28/05/2018 20:30
Exact Location Of Accident	CTE (SLE/TPE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCW2808S
Insured/Policyholder	
Name Of Registered Owner	CHIN TECK CHUAN
NRIC No	S2555798J
Email Address	TCCHIN828@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98184738
Alternative Phone No	OFFICE-98184738

Vehicle Particulars

Manufacturer	BMW
Model	218I ACTIVE TOURER

Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
--	--------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	10117226

Driver

Name of Driver	DAVIN HUANG
Passport No/FIN	N7177367
Date Of Birth	17/10/1990
Occupation	INDOOR
Date Of Driving Pass	14/04/2015
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(FOREIGN) +614-24565305
Fax Number	
Contact Number	
Email Address	DAVIN.HUANG@UQCONNECT.EDU.AU

Address	12B JOAN ROAD
Postcode	298905
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KRISTY CHIN JIA SHIN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHF735L
Vehicle Make/Model/Colour	RENAULT RED
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SEAH HOCK TEAN
NRIC/Passport Number	S1207559F
Contact Number	9137157
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR LEFT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was driving on CTE (SLEET/PE) Slip Road onto CTE. CAR in front of taxi stopped suddenly and causing taxi to stop suddenly. Was not able to stop in time as I was checking side mirror at the time first car stopped.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/5/18

 30/5/2018
Reporting Centre Personnel's Signature
Name:
NRIC/PIN No: @ 9586w

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64796772

280, Kampong Arang Road
East Coast Centre
Singapore 438186
Tel. 63190888 (AfterSales)
Fax. 63449772

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47120
Date Estimated : 30/05/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 7

- ESTIMATE REPAIR FOR -

Chin Teck Chuan
12B Joan Road

Singapore 298905

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

DESCRIPTION

VALUE

Replace right front chassis, front support panel, bonnet,
both front side fender, front bumper and remove attachment e
tc include knock on accident dent

✓ 5950 11,050.00

Spray painting front bumper, both front side fender, bonnet,
right front door and right wheel house

✓ 4351 5,439.00

To tow accident vehicle to PML workshop.

✓ ✓ 195.00

To supply front emboss number plate.

✓ 65 83.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1X)

mx 451? 531.00

To remove and install exhaust pipe, heat shield and
propeller shaft to facilitate repairs.

mx photo 451? 531.00

To remove and install engine and auto transmission to
facilitate jacking of chassis to mounting of car on celette
bench including replacement of damaged parts.

mx photo 1404? 1,652.00

To replace radiator assembly, fan housing with fan including
pressure test, bleed cooling system and conduct checks for
leak. (For all models except 7 series).

✓ 702 826.00

To replace engine mountings including re-alignment of
engine block to body frame.

mx photo 577? 679.00

To replace air con condenser and air con hose including to
vacuum system, top up freon gas and check for leak.
(For all models except for 7 series).

✓ 852 1,003.00

To carry out body cavity preservation.

✓ 451 531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

✓ 150 177.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 17461559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438190
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190558 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47120
Date Estimated : 30/05/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

DESCRIPTION

VALUE

Sundries.

150.00

Total Labour 1: 22,847.00

DESCRIPTION

QTY

PRIC

VALUE

BLIND RIVET (4PCS)	10	0.90	9.00
EXPANDING RIVET	2	0.75	1.50
HOSE CYLINDER HEAD TRANSMISSION OIL	1	60.20	60.20
O RING 16X2.5	1	9.40	9.40
TOP COOLING MODULE MOUNTING	2	9.10	18.20
RADIATOR	1	720.25	720.25
COVER -coolant	1	28.90	28.90
Gasket set	1	46.85	46.85
Gasket set - cooling fan	1	46.85	46.85
LOWER BRACKET	2	28.25	56.50
LH MODULE BRACKET	1	28.25	28.25
RH MODULE BRACKET	1	28.25	28.25
FASTENING ELEMENTS	1	10.35	10.35
FASTENING ELEMENTS	1	10.35	10.35
HOSE RADIATOR ENGINE	1	104.60	104.60
HOSE RADIATOR TOP THERMOSTAT	1	77.50	77.50
PIPE RADIATOR EXPANSION TANK	1	58.15	58.15
HOSE GEARBOX OIL HEAT EXCHANGER	1	54.25	54.25
LINE COOLANT PUMP HEAT EXCHANGER	1	111.40	111.40
Hose, expans	1	52.95	52.95
PIPE EXPANSION TANK CYLINDER HEAD	1	58.15	58.15
HOSE TRANSMISSION OIL HEAT EXCHANGE	1	54.25	54.25
RADIATOR EXPANSION TANK	1	134.05	134.05
FAN HOUSING WITH FAN	1	915.95	915.95
CHARGE AIR COOLER	1	548.80	548.80
FRT AXLE SUPPORT	1	1,343.50	1,343.50
Wheel well, right	1	1,848.30	1,848.30
Screw plate	1	30.55	30.55
FRT LH FENDER	1	573.30	573.30
FRT RH FENDER	1	573.30	573.30
BONNET	1	1,144.55	1,144.55
Holder, brak	1	9.85	9.85
BONNET LH HINGE	1	107.00	107.00
BONNET RH HINGE	1	107.00	107.00
RH SUPPORTING STRUT WHEEL HOUSE EXT	1	160.85	160.85
Supporting strut wheel house	1	138.60	138.60
LH EXTENSION WHEEL HOUSING STRUT	1	135.80	135.80
RH EXTENSION WHEEL HOUSING STRUT	1	135.75	135.75
RH EXTENSION WHEEL HOUSING STRUT	1	135.75	135.75
LH CROSS SUPPORT SIDE PANEL	1	43.05	43.05
RH CROSS SUPPORT SIDE PANAL	1	43.05	43.05
RH CROSS SUPPORT SIDE PANAL	1	43.05	43.05

Performance Motors Limited

A member of the Fine Derby Group

Co. Reg. No. 197421559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Fine Derby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

309, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190889 (AfterSales)
Fax. 63449773

111, Alexandra Road
Fine Derby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motocrad)
64796601 (AfterSales)
64796624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47120
Date Estimated : 30/05/2018
Prepared By : Chua Kee Sin

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
LH TOP SIDE PANEL BRACKET	1	32.15	32.15
Bracket, sid	1	32.15	32.15
GRILLE BUMPER MIDDLE CLOSED (BASIS)	1	95.25	95.25
FRT BUMPER LH INSERT	1	9.55	9.55
FRT BUMPER RH INSERT	1	9.70	9.70
CROSSLINK FRT	1	121.35	121.35
FRT IMPACT ABSORBER	1	47.80	47.80
RH DEFORMATION ELEMENT	1	99.30	99.30
FRT LH BOTTOM DEFORMATION ELEMENT	1	84.30	84.30
FRT RH BOTTOM DEFORMATION ELEMENT	1	84.30	84.30
FRT BUMPER BOTTOM CARRIER	1	143.60	143.60
FRT LH SIDE PANEL TOP MOUNTING	1	8.80	8.80
FRT RH SIDE PANEL TOP MOUNTING	1	8.85	8.85
GRILLE SIDE OPEN LH	1	70.25	70.25
GRILLE SIDE OPEN RH	1	70.25	70.25
FRT BUMPER PANEL PRIMED BASIS	1	801.90	801.90
LH ROD	1	20.00	20.00
RH ROD	1	20.00	20.00
LH SUPPORT FOG LAMP (GESCHLOSSEN)	1	50.95	50.95
RH SUPPORT FOG LAMP (GESCHLOSSEN)	1	50.95	50.95
FRT BUMPER TOP CARRIER	1	368.90	368.90
RH VERTICAL STRUT	1	48.20	48.20
RH VERTICAL STRUT	1	48.20	48.20
FRT LH GRILLE	1	86.05	86.05
FRT RH GRILLE	1	86.05	86.05
LICENCE PLATE HOLDER	1	68.95	68.95
GROMMET	2	0.75	1.50
LOCK F HOOD LH	1	40.85	40.85
HOOD LOCK WITH MICRO SWITCH RH	1	48.40	48.40
GAS FILLED STRUT ENGINE COMPARTMENT	2	121.00	242.00
CATCH BRACKET	2	54.05	108.10
Abdeckung Sc	1	14.80	14.80
REAR BOWDEN CABLE ENGINE COMP. LID	1	34.25	34.25
LH SUPPORT HEADLIGHT ARM	1	124.85	124.85
RH SUPPORT HEADLIGHT ARM	1	124.85	124.85
LH BOTTOM ADAPTER	1	81.45	81.45
SEAL COOLER TOP	1	24.00	24.00
SUPPORT LH	1	90.25	90.25
SUPPORT RH	1	90.25	90.25
CROSSLINK FRONT	1	110.25	110.25
FRT LH WHEEL ARCH COVER	1	132.60	132.60
FRT RH WHEEL ARCH COVER	1	132.60	132.60
AIR DUCT	1	190.50	190.50
RH GASKET HEADLIGHT AND HOOD	1	18.75	18.75
PLAQUE 82MM	1	69.50	69.50
FRT ENGINE HOOD SEALING	1	23.20	23.20
FRT LH FENDER SEALING	1	23.70	23.70
FRT RH FENDER SEALING	1	21.90	21.90
LH GASKET HEADLIGHT AND HOOD	1	19.70	19.70

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/630 (Motocrad)
Fax. 64796601 (AfterSales)
64796624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47120
Date Estimated : 30/05/2018
Prepared By : Chua Kee Sin

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
STRAINER FOR WASH PUMP	1	7.80	7.80
FILLER PIPE WASH CONTAINER	1	51.05	51.05
COVER F WINDSHIELD CLEANING CONTAINER	1	13.45	13.45
WINDSHIELD CLEANING CONTAINER	1	126.45	126.45
LH HEADLIGHT LED TECHNOLOGY	1	2,137.85	2,137.85
RH HEADLIGHT LED TECHNOLOGY	1	2,137.85	2,137.85
RH FOG LIGHT	1	276.40	276.40
CONDENSER AIR CONDITIONING WITH DRI	1	1,008.85	1,008.85
ULTRASONIC SENSOR BLACK	4	248.70	994.80
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
DOUBLE WASH PUMP	1	109.45	109.45

Total Parts : 21,038.30

Claims ☒ 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 31/5/18 15:50 Excess S\$ 1500

Surveyor's Name Tanjun Sign Tanjun

Surveyor's Tel 92495249 Authorised Yes / No

Authorised Date Not Authorise Time _____

RESURVEY PARTS PHOTO BY SURVEYOR ☒ Yes / No PML Yes / No

Surveyor's E-mail tanjun@lkkauto.com

No. of Working Days Recommend 10-12 days

[Signature]
8/6/18

6203-95

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	22,847.00
Parts	:	21,038.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	3,071.97
Grand Total	:	46,957.27

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190211 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438380
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47120
Date Estimated : 30/05/2018
Prepared By : Chua Kee Sin

Page No. : 5 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448771318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 47120**
Date Estimated : **30/05/2018**
Prepared By : **Chua Kee Sin**Page No. : **6 of 7**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438186
Tel: 63190888 (AfterSales)
Fax: 63449771

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47120**
Date Estimated : **30/05/2018**
Prepared By : **Chua Kee Sin**

Page No. : **7 of 7**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCW2808S	VZ50793	10/02/2015	218iA AT	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.8(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right, the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pmi.com.sg

A member of the Stone-Island Group
Co. Rep. Tel. 1-877-411-0000, EXT. Rep. Tel. 800-200-0000



SUPPLEMENTARY

Page No. 19

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
3CW28088	VZ50793	10/02/2015	218iA AT	0

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	
Total Parts :	4,670.60
Total Labour & Parts :	4,670.60

Performance Motors Limited

A member of the Sino Caddy Group
Co. Reg. No. 197301559W, GST Reg. No. M2-002081-1



FINAL REPORT

Estimate No. : b1 47120
Date Estimated : 30/05/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chin Teck Chuan
12B Joan Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 298905

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SCW2808S	VZ50793	10/02/2015	218iA AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, intake manifold system and attachments, front LH/RH fenders and attachments, bonnet and attachments, RH extension wheel housing strut, RH interior engine support, front crosslink, RH deformation element, front LH/RH bottom deformation elements, RH foglamp support, support RH, front panel v strut, front RH wheel arch cover, air duct and attachments, horn, windscreen cleaning container and attachments, RH fog light include pulling and straightening on accident areas, to make good the front RH door and knocking out dents caused by the accident	5950.00		5,950.00	
To spray painting front bumper, front LH/RH fenders, bonnet, front RH door and front RH wheel housing	4351.00		4,351.00	
To tow accident vehicle to PML workshop.	195.00		195.00	
To supply front emboss number plate.	83.00		83.00	
To replace radiator assembly, fan housing with fan include pressure tests, bleed cooling system and conducting checks for leak	702.00		702.00	
To replace air con condenser and air con hose include vacuum system, top up freon gas and conducting checks for leak	852.00		852.00	
To carry out body cavity preservation.	451.00		451.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET	0.90	4.00		3.60
# TORX BOLT WITH WASHER *	2.40	10.00		24.00 (A)

Performance Motors Limited

A member of the Stone Dobby Group
Co. Reg. No. 197601559W. GST Reg. No. M2-0020081-X



FINAL REPORT

# EXPANDING NUT L=19.9MM *	1.40	10.00	14.00	(A)
# PIPE CLIP *	5.75	2.00	11.50	
# ACOUSTIC COVER FRT *	135.65	1.00	135.65	
# RIBBED V BELT 6 PK X 1715 *	81.90	1.00	81.90	
# INTAKE MANIFOLD SYSTEM *	560.75	1.00	560.75	
# T MAP SENSOR 1.5 BAR *	176.10	1.00	176.10	
# AIR INTAKE DUCT *	226.35	1.00	226.35	(A)
# FUEL FEED LINE *	90.90	1.00	90.90	
RADIATOR	720.25	1.00	720.25	(A)
LOWER BRACKET	28.25	2.00	56.50	
FASTENING ELEMENTS	10.35	2.00	20.70	(A)
FAN HOUSING WITH FAN	915.95	1.00	915.95	
# ASA BOLT M12X1.5 *	9.10	2.00	18.20	(A)
# FOAM SEAL *	8.30	2.00	16.60	
FRT AXLE SUPPORT	1,343.50	1.00	1,343.50	(A)
# COMBINATION NUT M14X1.5 *	5.55	2.00	11.10	
# CABLE CLIP *	0.90	10.00	9.00	(A)
# BRACKET LEVER SENSOR FRT *	17.70	1.00	17.70	
FRT LH FENDER	573.30	1.00	573.30	(A)
FRT RH FENDER	573.30	1.00	573.30	
BONNET	1,144.55	1.00	1,144.55	(A)
BONNET LH HINGE	107.00	1.00	107.00	
BONNET RH HINGE	107.00	1.00	107.00	(A)
RH EXTENSION WHEEL HOUSING STRUT	135.75	1.00	135.75	
RH CROSS SUPPORT SIDE PANEL	43.05	1.00	43.05	(A)
# RH INTERIOR ENGINE SUPPORT *	166.50	1.00	166.50	
GRILLE BUMPER MIDDLE CLOSED (BASIS)	95.25	1.00	95.25	(A)
FRT BUMPER LH INSERT	9.55	1.00	9.55	
FRT BUMPER RH INSERT	9.70	1.00	9.70	(A)
# LH ADAPTER BOTTOM *	81.45	1.00	81.45	
# RH ADAPTER BOTTOM *	81.45	1.00	81.45	(A)
CROSSLINK FRT	121.35	1.00	121.35	
# SUPPORT BUMPER *	11.60	1.00	11.60	(A)
FRT IMPACT ABSORBER	47.80	1.00	47.80	
RH DEFORMATION ELEMENT	99.30	1.00	99.30	(A)
FRT LH BOTTOM DEFORMATION ELEMENT	84.30	1.00	84.30	
FRT RH BOTTOM DEFORMATION ELEMENT	84.30	1.00	84.30	(A)
FRT RH SIDE PANEL TOP MOUNTING	8.85	1.00	8.85	
FRT BUMPER PANEL PRIMED BASIS	801.90	1.00	801.90	(A)
RH SUPPORT FOG LAMP (GESCHLOSSEN)	50.95	1.00	50.95	
# NUT PANEL M12	6.50	1.00	6.50	(A)
# NUT PANEL M12	6.50	1.00	6.50	
FRT BUMPER TOP CARRIER	368.90	1.00	368.90	(A)
FRT LH GRILLE	86.05	1.00	86.05	
FRT RH GRILLE	86.05	1.00	86.05	(A)
LICENCE PLATE HOLDER	68.95	1.00	68.95	
# BMW EMBLEM *	69.50	1.00	69.50	(A)
# RH BRACKET FOR GAS SPRING *	15.45	1.00	15.45	
LOCK F HOOD LH	90.10	1.00	90.10	(A)
HOOD LOCK WITH MICRO SWITCH RH	90.10	1.00	90.10	
CATCH BRACKET	54.05	2.00	108.10	(A)
# ENGINE HOOD SOUND INSULATING *	171.45	1.00	171.45	
# CLIP *	0.80	11.00	8.80	(A)
# CLIP *	0.80	4.00	3.20	
RH SUPPORT HEADLIGHT ARM	124.85	1.00	124.85	(A)
SEAL COOLER TOP	24.00	1.00	24.00	
SUPPORT RH	90.25	1.00	90.25	

Performance Motors Limited

A member of the Sava Group
Co. Reg. No. 197801589W, GST Reg. No. M2-0000081-X



FINAL REPORT

CROSSLINK FRONT	110.25	1.00	110.25	
# FRONT PANEL V STRUT *	110.25	1.00	110.25	(A)
FRT RH WHEEL ARCH COVER	132.60	1.00	132.60	
AIR DUCT	190.50	1.00	190.50	
# RH PARTITION WALL LOWER SECTION *	39.10	1.00	39.10	(A)
FRT ENGINE HOOD SEALING	23.20	1.00	23.20	
FRT LH FENDER SEALING	23.70	1.00	23.70	
FRT RH FENDER SEALING	21.90	1.00	21.90	
RH GASKET HEADLIGHT AND HOOD	19.45	1.00	19.45	
# HORN HIGH PITCH *	80.85	1.00	80.85	(A)
FILLER PIPE WASH CONTAINER	51.05	1.00	51.05	
COVER F WINDSHIELD CLEANING CONTAINER	13.45	1.00	13.45	
WINDSHIELD CLEANING CONTAINER	126.45	1.00	126.45	
# RH HEADLIGHT BRACKET *	34.00	1.00	34.00	
# RH LED MODULE CORNERING LIGHT *	786.65	1.00	786.65	(A)
RH HEADLIGHT LED TECHNOLOGY	2,137.85	1.00	2,137.85	
# CONTROL UNIT FRT LIGHT ELECTRONIC *	872.10	1.00	872.10	(A)
RH FOG LIGHT	276.40	1.00	276.40	
CONDENSER AIR CONDITIONING WITH DRI	1,008.85	1.00	1,008.85	
# SUCTION PIPE (R134A) *	121.05	1.00	121.05	
# SUCTION PIPE *	121.05	1.00	121.05	
# PRESSURE HOSE F EVAPORATOR CONDENSE *	296.75	1.00	296.75	
# PRESSURE HOSE COMPRESSOR-CONDENSER *	149.55	1.00	149.55	
# ANTI-FREEZE 1.5 LITRES *	19.75	2.00	39.50	(A)

SUPPLEMENTARY ITEMS

Total Labour :	12,884.00
Total Parts :	17,097.70
Total Labour & Parts :	29,981.70
Deduction for Excess :	500.00
Total Repair Costs less Excess:	29,481.70
GST @7%:	2,063.72
Grand Total :	31,545.42

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 August 2018 2:27 PM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SCW2808S (Limit repair \$28,000)

Dear Caroline,

Confirm COR at limit repair \$28,000 before excess \$500 and GST.

No of days: 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 20 July 2018 5:58 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SCW2808S (Limit repair \$28,000)

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR at limit repair \$28,000 before excess and GST.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

...CLAIM SUBFOLDER...(Pending for Survey Report)





































CLAIM SUBFOLDER TRACKING


















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018		31 May 2018 09:22 Edit Adj Rpt	S\$28,000.00 Edit Estimates	S\$28,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHIN TECK CHUAN , ID: S2555798J, Tel: +6598184738								
Vehicle Reg. No.:	SCW2808S	Date of Loss:	28/05/2018 20:00 - :59 [39 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 559819	Policy/Cover Note No.:	278550605MP (Comprehensive) Coverage: 10/02/2018 - 09/02/2019						
		Excess:	S\$500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/06/2018]								
Driver/Custodian:	DAVIN HUANG (27 / Male), NRIC: N7177367								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (03/08/2018): Alert - Adj Mandate Approved (S\$28000.00) - SCW2808S - Claim Handler: Jocelyn Ng... MSIG_SG (06/06/2018): Alert - Adj Mandate Approved (S\$20557.25) - SCW2808S - Claim Handler: Jocelyn Ng... MSIG_SG (05/06/2018): Alert - Adj Mandate Approved (S\$20557.25) - SCW2808S - Claim Handler: Jocelyn Ng... MSIG_SG (05/06/2018): Alert - Adj Mandate Approved (S\$20557.25) - SCW2808S - Claim Handler: Jocelyn Ng... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



















































*SCW2808S (559819)
OD
May 28 2018 8:00PM
[CHIN TECK CHUAN]
Performance Motors Limited


































Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/05/18 11:12	Accident Statement	 Load HTM	
			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	01/06/18 13:55	Adjuster Immediate Advice	 Load HTM	
2	02/08/18 14:54	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	01/06/18 09:56	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				<input checked="" type="checkbox"/>
34	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
35	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
36	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
37	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
38	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
39	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
40	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
41	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
42	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
43	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
44	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
45	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
46	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
47	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
48	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
49	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
50	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
51	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
52	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
53	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
54	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
55	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
56	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
57	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
58	01/06/18 09:56	General View		<input checked="" type="checkbox"/>
59	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
60	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
61	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
62	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
63	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
64	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
65	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
66	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
67	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
68	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
69	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
70	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
71	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
72	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
73	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
74	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
75	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
76	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
77	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
78	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
79	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
80	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
81	01/06/18 09:57	General View		<input checked="" type="checkbox"/>
82	01/06/18 09:57	General View		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
83	01/06/18 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
84	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>





Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
133	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	02/08/18 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	02/08/18 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>













































Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
183	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	02/08/18 14:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
227	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
228	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
229	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
230	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
231	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
232	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
233	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
234	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
236	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
237	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
238	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
242	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
243	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
244	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
245	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
246	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
247	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
248	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
249	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
250	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
251	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
252	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
253	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
254	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
255	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
256	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
257	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
258	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
259	02/08/18 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/05/18 16:35	Estimate & GIA Report	 Load PDF	
2	30/05/18 16:35	COE PARF - SCW2808S	 Load PDF	
3	30/05/18 16:35	TP SLV4584Y GIA Report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 13:58	MARK ESTIMATE	 Load PDF	
2	02/08/18 14:44	1ST MARK ESTIMATE	 Load PDF	
3	02/08/18 14:44	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/05/18 10:44	Video - Accident	 Load AVI	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/05/18 11:12	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
3	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
24	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
25	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
26	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
27	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
28	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
29	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
30	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
31	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
32	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
33	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
34	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
35	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
36	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
37	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
38	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
39	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
40	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
41	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
42	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
43	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
44	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
45	30/05/18 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/05/18 10:42	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18009870/T1VD3E2

Date: 20/08/2018

REFERENCE

Insured/Claimant: CHIN TECK CHUAN Policy No: 27855060SMP
Date of Loss: 28/05/2018 Nature of Claim: OD Claim No: 559819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCW2808S**
Make & Model: BMW 218i, 1.5 ACTIVE TOURER D/AB LED DSC AB (A) Engine No: F4020983B38A15A
Reg. Date: 10/02/2015 (Man. Year: 2014) Chassis No: WBA2A32030VZ50793
Colour: Grey Odometer: 35074 km
Engine Capacity: 1499 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,029.95	17,330.70	8,699.25	33.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,614.00	12,651.00	9,963.00	44.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,643.95	29,981.70	18,662.25	38.36
Approved Total (Overridden) (S\$)		28,000.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	48,143.95	27,500.00	20,643.95	42.88
+ GST 7.00/7.00% (S\$)	3,370.08	1,925.00	1,445.08	42.88
Nett Amount (S\$)	51,514.03	29,425.00	22,089.03	42.88

INSPECTION

Date of Assignment: 31/05/2018
Date Inspected: 31/05/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941
Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2018)
Parts:	M1-MPV	BMW 218i 1.5 ACTIVE TOURER D/AB LED DSC AB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCW2808S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*BLIND RIVET (10PCS)	Necessary-4PCS ONLY	9.00 FS	*3.60 FS
4	2		*EXPANDING RIVET	Not Necessary	1.50 FS	*- FS
5	1		*HOSE CYLINDER HEAD TRANSMISSION OIL	Not Necessary	60.20 FS	*- FS
6	1		*O RING 16X2.5	Not Necessary	9.40 FS	*- FS
7	2		*TOP COOLING MODULE MOUNTING	Not Necessary	18.20 FS	*- FS
8	1		*RADIATOR	Bent	720.25 FS	*720.25 FS
9	1		*COVER - COOLANT	Not Necessary	28.90 FS	*- FS
10	1		*SET GASKET	Not Necessary	46.85 FS	*- FS
11	1		*SET GASKET - COOLING FAN	Not Necessary	46.85 FS	*- FS
12	2		*LOWER BRACKET	Bent	56.50 FS	*56.50 FS
13	1		*LH MODULE BRACKET	Not Necessary	28.25 FS	*- FS
14	1		*RH MODULE BRACKET	Not Necessary	28.25 FS	*- FS
15	1		*FASTENING ELEMENTS	Necessary	10.35 FS	*10.35 FS
16	1		*FASTENING ELEMENTS	Necessary	10.35 FS	*10.35 FS
17	1		*HOSE RADIATOR ENGINE	Not Necessary	104.60 FS	*- FS
18	1		*HOSE RADIATOR TOP THERMOSTAT	Not Necessary	77.50 FS	*- FS
19	1		*PIPE RADIATOR EXPANSION TANK	Not Necessary	58.15 FS	*- FS
20	1		*HOSE GEARBOX OIL HEAT EXCHANGER	Not Necessary	54.25 FS	*- FS
21	1		*LINE COOLANT PUMP HEAT EXCHANGER	Not Necessary	111.40 FS	*- FS
22	1		*HOSE, EXPANS	Not Necessary	52.95 FS	*- FS
23	1		*PIPE EXPANSION TANK CYLINDER HEAD	Not Necessary	58.15 FS	*- FS
24	1		*HOSE TRANSMISSION OIL HEAT EXCHANGE	Not Necessary	54.25 FS	*- FS
25	1		*RADIATOR EXPANSION TANK	Not Necessary	134.05 FS	*- FS
26	1		*FAN HOUSING WITH FAN	Cracked	915.95 FS	*915.95 FS
27	1		*CHARGE AIR COOLER	Not Necessary	548.80 FS	*- FS
28	1		*FRT AXLE SUPPORT	Bent	1,343.50 FS	*1,343.50 FS
29	1		*WHEEL WELL, RIGHT	Not Necessary	1,848.30 FS	*- FS
30	1		*SCREW PLATE	Not Necessary	30.55 FS	*- FS
31	1		*FRT LH FENDER	Bent	573.30 FS	*573.30 FS
32	1		*FRT RH FENDER	Bent	573.30 FS	*573.30 FS
33	1		*BONNET	Bent	1,144.55 FS	*1,144.55 FS
34	1		*HOLDER, BRAK	Not Necessary	9.85 FS	*- FS
35	1		*BONNET LH HINGE	Bent	107.00 FS	*107.00 FS
36	1		*BONNET RH HINGE	Bent	107.00 FS	*107.00 FS
37	1		*RH SUPPORTING STRUT WHEEL HOUSE EXT	Not Necessary	160.85 FS	*- FS
38	1		*SUPPORTING STRUT WHEEL HOUSE	Not Necessary	138.60 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*LH EXTENSION WHEEL HOUSING STRUT	Not Necessary	135.80 FS	*- FS
40	1		*RH EXTENSION WHEEL HOUSING STRUT	Bent	135.75 FS	*135.75 FS
41	1		*RH EXTENSION WHEEL HOUSING STRUT	Not Necessary	135.75 FS	*- FS
42	1		*LH CROSS SUPPORT SIDE PANEL	Not Necessary	43.05 FS	*- FS
43	1		*RH CROSS SUPPORT SIDE PANEL	Bent	43.05 FS	*43.05 FS
44	1		*RH CROSS SUPPORT SIDE PANEL	Not Necessary	43.05 FS	*- FS
45	1		*LH TOP SIDE PANEL BRACKET	Not Necessary	32.15 FS	*- FS
46	1		*BRACKET, SID	Not Necessary	32.15 FS	*- FS
47	1		*GRILLE BUMPER MIDDLE CLOSED (BASIS)	Cracked	95.25 FS	*95.25 FS
48	1		*FRT BUMPER LH INSERT	Necessary	9.55 FS	*9.55 FS
49	1		*FRT BUMPER RH INSERT	Necessary	9.70 FS	*9.70 FS
50	1		*CROSSLINK FRT	Bent	121.35 FS	*121.35 FS
51	1		*FRT IMPACT ABSORBER	Deformed	47.80 FS	*47.80 FS
52	1		*RH DEFORMATION ELEMENT	Deformed	99.30 FS	*99.30 FS
53	1		*FRT LHBOTTOM DEFORMATION ELEMENT	Deformed	84.30 FS	*84.30 FS
54	1		*FRT RH BOTTOM DEFORMATION ELEMENT	Deformed	84.30 FS	*84.30 FS
55	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	143.60 FS	*- FS
56	1		*FRT LH SIDE PANEL TOP MOUNTING	Not Necessary	8.80 FS	*- FS
57	1		*FRT RH SIDE PANEL TOP MOUNTING	Necessary	8.85 FS	*8.85 FS
58	1		*GRILLE SIDE OPEN LH	Not Necessary	70.25 FS	*- FS
59	1		*GRILLE SIDE OPEN RH	Not Necessary	70.25 FS	*- FS
60	1		*FRT BUMPER PANEL PRIMED BASIS	Deformed	801.90 FS	*801.90 FS
61	1		*LH ROD	Not Necessary	20.00 FS	*- FS
62	1		*RH ROD	Not Necessary	20.00 FS	*- FS
63	1		*RH SUPPORT FOG LAMP (GESCHLOSSEN)	Cracked	50.95 FS	*50.95 FS
64	1		*FRT BUMPER TOP CARRIER	Bent	368.90 FS	*368.90 FS
65	1		*RH VERTICAL STRUT	Not Necessary	48.20 FS	*- FS
66	1		*RH VERTICAL STRUT	Not Necessary	48.20 FS	*- FS
67	1		*FRT LH GRILLE	Cut	86.05 FS	*86.05 FS
68	1		*FRT RH GRILLE	Cracked	86.05 FS	*86.05 FS
69	1		*LICENSE PLATE HOLDER	Deformed	68.95 FS	*68.95 FS
70	2		*GROMMET	Not Necessary	1.50 FS	*- FS
71	1		*LOCK F HOOD LH	Bent	90.10 FS	*90.10 FS
72	1		*HOOD LOCK WITH MICRO SWITCH RH	Bent	90.10 FS	*90.10 FS
73	2		*GAS FILLED STRUT ENGINE COMPARTMENT	Not Necessary	242.00 FS	*- FS
74	2		*CATCH BRACKET	Bent	108.10 FS	*108.10 FS
75	1		*ABDECKUNG SC	Not Necessary	14.80 FS	*- FS
76	1		*REAR BOWDEN CABLE ENGINE COMP. LID	Not Necessary	34.25 FS	*- FS
77	1		*LH SUPPORT HEADLIGHT ARM	Not Necessary	124.85 FS	*- FS
78	1		*RH SUPPORT HEADLIGHT ARM	Cracked	124.85 FS	*124.85 FS
79	1		*LH BOTTOM ADAPTER	Not Necessary	81.45 FS	*- FS
80	1		*SEAL COOLER TOP	Necessary	24.00 FS	*24.00 FS
81	1		*SUPPORT LH	Not Necessary	90.25 FS	*- FS
82	1		*SUPPORT RH	Deformed	90.25 FS	*90.25 FS
83	1		*CROSSLINK FRONT	Bent	110.25 FS	*110.25 FS
84	1		*FRT LH WHEEL ARCH COVER	Not Necessary	132.60 FS	*- FS
85	1		*FRT RH WHEEL ARCH COVER	Deformed	132.60 FS	*132.60 FS
86	1		*AIR DUCT	Deformed	190.50 FS	*190.50 FS
87	1		*RH GASKET HEADLIGHT AND HOOD	Necessary	19.45 FS	*19.45 FS
88	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
89	1		*FRT ENGINE HOOD SEALING	Deformed	23.20 FS	*23.20 FS
90	1		*FRT LH FENDER SEALING	Necessary	23.70 FS	*23.70 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*FRT RH FENDER SEALING	Necessary	21.90 FS	*21.90 FS
92	1		*LH GASKET HEADLIGHT AND HOOD	Not Necessary	19.70 FS	*- FS
93	1		*STRAINER FOR WASH PUMP	Not Necessary	7.80 FS	*- FS
94	1		*FILLER PIPE WASH CONTAINER	Deformed	51.05 FS	*51.05 FS
95	1		*COVER F WINDSHIELD CLEANING CONTAINER	Deformed	13.45 FS	*13.45 FS
96	1		*WINDSHIELD CLEANING CONTAINER	Deformed	126.45 FS	*126.45 FS
97	1		*LH HEADLIGHT LED TECHNOLOGY	Serviceable	2,137.85 FS	*- FS
98	1		*RH HEADLIGHT LED TECHNOLOGY	Cracked	2,137.85 FS	*2,137.85 FS
99	1		*RH FOG LIGHT	Cracked	276.40 FS	*276.40 FS
100	4		*ULTRASONIC SENSOR BLACK	Not Necessary	994.80 FS	*- FS
101	4		*DECOUPLING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
102	1		*DOUBLE WASH PUMP	Not Necessary	109.45 FS	*- FS
103	10		*TORX BLT WITH WASHER	Necessary	24.00 FS	*24.00 FS
104	10		*EXPANDING NUT L=19.9MM	Necessary	14.00 FS	*14.00 FS
105	2		*PIPE CLIP	Necessary	11.50 FS	*11.50 FS
106	1		*ACOUSTIC COVER FRT	Necessary	135.65 FS	*135.65 FS
107	1		*RIBBED V BELT 6 PK X 1715	Cut	81.90 FS	*81.90 FS
108	1		*INTAKE MANIFOLD SYSTEM	Cracked	560.75 FS	*560.75 FS
109	1		*T MAP SENSOR 1.5 BAR	Cracked	176.10 FS	*176.10 FS
110	1		*AIR INTAKE DUCT	Deformed	226.35 FS	*226.35 FS
111	1		*FUEL FEED LINE	Bent	90.90 FS	*90.90 FS
112	2		*ASA BOLT M12X1.5	Necessary	18.20 FS	*18.20 FS
113	2		*FOAM SEAL	Necessary	16.60 FS	*16.60 FS
114	2		*COMBINATION NUT M14X1.5	Necessary	11.10 FS	*11.10 FS
115	10		*CABLE CLIP	Necessary	9.00 FS	*9.00 FS
116	1		*BRACKET LEVER SENSOR FRT	Necessary	17.70 FS	*17.70 FS
117	1		*RH INTERIOR ENGINE SUPPORT	Bent	166.50 FS	*166.50 FS
118	1		*LH ADAPTER BOTTOM	Distorted	81.45 FS	*81.45 FS
119	1		*RH ADAPTER BOTTOM	Distorted	81.45 FS	*81.45 FS
120	1		*SUPPORT BUMPER	Necessary	11.60 FS	*11.60 FS
121	1		*NUT PANEL M12	Necessary	6.50 FS	*6.50 FS
122	1		*NUT PANEL M12	Necessary	6.50 FS	*6.50 FS
123	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
124	1		*RH BRACKET FOR GAS SPRING	Bent	15.45 FS	*15.45 FS
125	1		*ENGINE HOOD SHROUD INSULATING	Deformed	171.45 FS	*171.45 FS
126	11		*CLIP	Necessary	8.80 FS	*8.80 FS
127	4		*CLIP	Necessary	3.20 FS	*3.20 FS
128	1		*FRONT PANEL V STRUT	Bent	110.25 FS	*110.25 FS
129	1		*RH PARTITION WALL LOWER SECTION	Bent	39.10 FS	*39.10 FS
130	1		*HORN HIGH PITCH	Cracked	80.85 FS	*80.85 FS
131	1		*RH HEADLIGHT BRACKET	Distorted	34.00 FS	*34.00 FS
132	1		*RH LED MODULE CORNERING LIGHT	Cracked	786.65 FS	*786.65 FS
133	1		*CONTROL UNIT FRT LIGHT ELECTRONIC	Distorted	872.10 FS	*872.10 FS
134	1		*SUCTION PIPE (R134A)	Bent	121.05 FS	*121.05 FS
135	1		*SUCTION PIPE	Bent	121.05 FS	*121.05 FS
136	1		*PRESSURE HOSE F EVAPORATOR CONDENSE	Distorted	296.75 FS	*296.75 FS
137	1		*PRESSURE HOSE COMPRESSOR - CONDENSER	Distorted	149.55 FS	*149.55 FS
138	2		*ANTI-FREEZE 1.5 LITRES	Necessary	39.50 FS	*39.50 FS
139	1		*LH SUPPORT FOG LAMP (GERSCHLOSSEN)	Not Necessary	50.95 FS	*- FS
140	1		*CONDENSER AIR CONDITIONING WITH DRI	Bent	1,008.85 FS	*1,008.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 26,029.95 17,330.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE RIGHT FRONT CHASSIS, FRONT SUPPORT PANEL, BONNET, BOTH FRONT SIDE FENDER, FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	11,050.00	5,950.00
2	SPRAY PAINTING FRONT BUMPER, BOTH FRONT SIDE FENDER, BONNET, RIGHT FRONT DOOR AND RIGHT WHEEL HOUSE	New	5,439.00	4,351.00
3	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	0.00
5	TO REMOVE AND INSTALL EXHAUST PIPE, HEAT SHIELD AND PROPELLER SHAFT TO FACILITATE REPAIRS	New	531.00	0.00
6	TO REMOVE AND INSTALL ENGINE AND AUTO TRANSMISSION TO FACILITATE JACKING OF CHASSIS TO MOUNTING OF CAR ON CELETTE BENCH INCLUDING REPLACEMENT OF DAMAGED PARTS	New	1,652.00	0.00
7	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CONDUCT CHECKS FOR LEAK (FOR ALL MODELS EXCEPT 7 SERIES)	New	826.00	702.00
8	TO REPLACE ENGINE MOUNTINGS INCLUDING RE-ALIGNMENT OF ENGINE BLOCK TO BODY FRAME	New	679.00	0.00
9	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT FOR 7 SERIES)	New	1,003.00	852.00
10	TO CARRY OUT BODY CAVITY PRESERVATION	New	531.00	451.00
11	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			22,614.00	12,651.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >