

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 551A - AIG**AAD1805-264***Not Authorized
11 May @ 5950h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 551A

VF1ABL15AUC278398

RENAULT

LATITUDE

27.5.2018

AIG

PART		LIST	
1	FENDER PANEL FRT RH	\$	B 783.83 ✓
1	WHEELARCH FRT RH	\$	SL 278.84 X
1	FENDER BRACKET LOWER RH	\$	SL 15.79 X
1	FENDER INSULATOR RH	\$	SL 130.84 X
1	DOOR PANEL FRT RH	\$	B 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	N 261.28
1	DOOR HINGE LOWER RH	\$	N 300.55
1	DOOR CHECK FRT RH	\$	SL 194.77
1	DOOR LOCK FRT RH	\$	N 908.75
1	DOOR CATCH FRT RH	\$	SL 131.23
1	DOOR HANDLE OUTER FRT RH	\$	N 477.76
1	DOOR HANDLE COVER FRT RH	\$	N 13.22
1	DOOR HANDLE MODULE FRT RH	\$	SL 133.60
1	DOOR REGULATOR FRT RH	\$	D, 505.19 —
1	DOOR REGUALTOR MOTOR FRT RH	\$	T 796.46 —
1	DOOR REGULATOR GUIDE FRT RH	\$	SL 120.97
1	DOOR PANEL REAR RH	\$	N 2,844.66
1	DOOR GUIDE REAR RH	\$	SL 176.82
1	DOOR HINGE UPPER RH	\$	N 274.50
1	DOOR HINGE LOWER RH	\$	N 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	SL 203.06
1	DOOR LOCK REAR RH	\$	N 908.75
1	DOOR HANDLE OUTER REAR RH	\$	SL 126.49
1	DOOR HANDLE CAP REAR RH	\$	SL 35.52
1	DOOR HANDLE SEAL REAR RH	\$	SL 7.89
1	DOOR HANDLE COVER REAR RH	\$	SL 13.22
1	DOOR HANDLE MODULE REAR RH	\$	SL 133.60
1	DOOR REGULATOR REAR RH	\$	N 1,135.10
1	DOOR REGUALTOR MOTOR REAR RH	\$	SL 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	SL 12.43

Trans-cab Auto Services Pte Ltd**AAD1805-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 551A - AIG

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	SL 6.31	
1	DOOR FINISHER REAR RH	\$	SL 423.10	
1	DOOR MOULDING REAR RH	\$	SL 176.82	
1	DOOR MOULDING CLIP L70Y	\$	NN 5.92	
1	DOOR MOULDING SCREW L70Y	\$	NN 6.91	
1	DOOR CASING REAR RH	\$	SL 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	SL 30.39	
1	DOOR CASING CLIP	\$	NN 12.63	
1	DOOR CASING LIGHT L70Y	\$	SL 48.74	
1	DOOR FINISHER INNER REAR RH	\$	SL 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	N 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	N 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	N 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	N 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	SL 210.96	
1	DOOR BLIND REAR RH	\$	SL 741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	SL 410.66	
1	DOOR SEAL REAR RH	\$	SL 162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	SL 229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	SL 334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	SL 115.64	
1	FENDER PANEL REAR RH	\$	N 3,299.13	X
1	FENDER PANEL INNER TRIM REAR	\$	SL 671.45	X
1	WHEELARCH REAR RH	\$	SL 543.47	X
1	DOOR MIRROR ASSY RH	\$	CM 1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	SL 466.51	X
1	ROCKER PANEL INNER RH	\$	SL 1,024.79	X
1	ROCKER PANEL CENTER RH	\$	SL 990.25	X
1	VEHICLE HARNESS PASS ROOM	\$	N 10,003.86	X
1	DOOR HARNESS WIRE	\$	SL 2,670.00	X
1	CENTRE PILLAR OUTER	\$	N 880.14	X
1	CENTER PILLAR INNER	\$	N 907.76	X
1	CENTER PILLAR REINFORCEMENT LH	\$	N 1,176.15	X

\$	43,937.34
----	------------------

10% \$	4,393.73
--------	-----------------

\$	39,543.61
----	------------------

Trans-cab Auto Services Pte Ltd

AAD1805-264

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 551A - AIG

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	X
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT RH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

TOTAL \$ 462.13**TOTAL PARTS \$ 40,005.74****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	60d
Putty and spray painting of the affected portion.	\$	4,200.00	66d
To rust-proofing of the affected areas.	\$	170.00	9d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80d
To check steering geometry and computer wheel alignment	\$	nn	220.00 X

Trans-cab Auto Services Pte Ltd**AAD1805-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 551A - AIG

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 <i>601</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees.	\$	120.00 <i>501</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>

TOTAL \$ 11,830.00**Over All Total \$ 51,835.74****LUMP SUM (REPAIR DAY)*****15 DAYS******5 day*****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: