

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7751P - AIG**AAD1805-267***Not Notarised
6 Aug 2008*

Vehicle No.:	SHB 7751P
Chassis No.:	KL1LA69RJB107035
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	26.5.2018
Third Party Insurer :	AIG

		PART	LIST
1	1	Rear Bumper	\$ 1,202.00
2	1	Rear Bumper Beam	\$ 239.94
3	1	Rear Bumper Centre Absorber	\$ 260.00
4	1	Rear Bumper Side Retainer RH	\$ 68.76
5	1	Rear Bumper Side Retainer LH	\$ 68.76
6	1	Rear Bumper Reflectors RH	\$ 119.74
7	1	Rear Bumper Reflectors LH	\$ 119.74
8	1	Rear Bumper Tow Hook Cover	\$ 93.00
9	1	Rear End Panel Outer	\$ 623.76
10	1	Rear End Panel Inner Trim	\$ 263.84
11	1	Rear Luggage Floor Panel	\$ 973.00
12	1	Rear Luggage Floor Panel Insulator	\$ 63.50
13	1	Rear Luggage Floor Panel Trim Board	\$ 378.00
14	1	Bootlid	\$ 973.00
15	1	Bootlid inner trim board	\$ 400.00
16	1	Bootlid Weatherstrip	\$ 344.28
17	1	Bootlid Lock - Top	\$ 466.56
18	1	Bootlid 'CHEVROLET' Badge	\$ 120.62
19	1	Bootlid Logo	\$ 138.84
20	1	Bootlid 'EPICA LT' Badge	\$ 119.84
21	1	Bootlid Reflector Centre	\$ 217.97
22	1	Bootlid Reflector RH	\$ 128.40
23	1	Bootlid Reflector LH	\$ 128.40
24	1	Rear Tail Lamp RH	\$ 479.30
25	1	Rear Tail Lamp LH	\$ 479.30
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$ 1,110.00
27	1	Rear Fender RH	\$ 1,145.00
28	1	Rear Fender Inner Trim RH	\$ 418.44
29	1	Rear Fender LH	\$ 1,145.00

Trans-cab Auto Services Pte Ltd

AAD1805-267

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7751P - AIG

30	1	Rear Fender Inner Trim LH	\$	418.44	X
----	---	---------------------------	----	--------	---

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	40.00	}
2	1Set	Rear Bumper Parking Sensor	\$	300.00	
3	1Set	Rear Bumper Fastener Clip	\$	44.00	
4	1Set	Rear Fender Inner Trim Clip LH	\$	30.00	
5	1Set	Rear Bumper End Dust Cover Clip	\$	30.00	
6	1	Rear Exhaust Mounting	\$	300.00	
7	2	Rear Windscreen Sealant	\$	80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	100.00	
9	1	Spare Tyre	\$	180.00	
10	1	Spare Wheel Rim	\$	126.74	

TOTAL	\$	1,230.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,667.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	X
----	----------	---

To Check Electrical Lighting Concerned.

\$	170.00	X
----	--------	---

To Rust-Proofing Of The Affected Areas.

\$	170.00	X
----	--------	---

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	2001
----	----------	------

To reinstall rear bumper parking sensor.

\$	170.00	X
----	--------	---

Trans-cab Auto Services Pte Ltd**AAD1805-267**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7751P - AIG

To transfer of end panel fittings and conduct water seepage test.	\$	170.00 X
To transfer of boot fittings and conduct water seepage test.	\$	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
	\$	8,150.00
TOTAL	\$	20,817.43

Repair Days (LUMP SUM)~~10 Days~~

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: