

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4266H

DATE 30/5/2018 10:33

MAKE :

MODEL : HYUNDAI SONATA

LKK/kawani

U Sam

Like

ALG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover ✓			\$ 538.80	
	Front Bumper Sponge ✕			\$ 136.30	
	Front Bumper Reinforcement ✕			\$ 504.10	
	Front Bumper Bracket Top (LH/RH) ✕		\$ 22.40	\$ 44.80	
	Front Bumper Protector (LH/RH) ✕ <i>Hyundai</i>		\$ 29.20	\$ 58.40	
	Front Bumper Bracket (LH/RH) ✕		\$ 20.10	\$ 40.20	
	Headlamp Support Panel Assy ✕			\$ 1,023.00	
	Headlamp (LH/RH) <i>LH ✓ RH ✕</i>		\$ 797.90	\$ 1,595.80	
	Headlamp Halogen Bulb (LH/RH) ✕		\$ 13.80	\$ 27.60	
	Front Fender (LH) ✓			\$ 593.00	
	Front Fender Shield (LH) ✕			\$ 86.00	
	Front Fender Retainer ✕			\$ 9.20	
	SUB TOTAL			\$ 4,657.20	
	LESS 20%			\$ 931.44	
	DISCOUNTED TOTAL			\$ 3,725.76	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Front Number Plate ✕			\$ 25.00	Nett
	Front No Plate Trim Cover ✕			\$ 30.00	Nett
				\$ 155.00	
	Labour Charge				
	Panel Beating			\$ 850.00 <i>300</i>	
	Spray Painting Charge			\$ 400.00 <i>360</i>	
	Wiring Charge			\$ 50.00 <i>20</i>	
	Tuff Kote			\$ 50.00 <i>20</i>	
	Towing Charge			\$ 80.00 <i>60</i>	
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>✕</i>	
	TOTAL LABOUR			\$ 1,550.00	
	ESTIMATE TOTAL			\$ 5,430.76	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K9/14 (UCC)

30/5/18 12:15 PM

287

4/5

After Repair