



India International Insurance Pte Ltd
64 Cecil Street
#05 IOB Building
Singapore 049711
Attn : Mr. Gabriel Wee

Quotation for Repair Costs

Policy Number	Vehicle Registration No	Consultants	Date
	SJQ7236H	Erwin - 92210404	01/06/2018

Item	Description	Quantity	Unit Price S\$	Total Price S\$
1	Rear Bumper	1	859.21	859.21 <i>del</i>
2	Rear Bumper Retainer	1	17.18	17.18 <i>del</i>
3	Rear Exhaust	1	629.70	629.70 <i>? ✓ ht</i>
4	Rear Light Body	1	363.34	363.34 <i>? ✓ cry</i>
5	Rear Bumper reverse Sensor <i>SN</i>	1	220.00	220.00 <i>200mm</i>
6	To check rear compartment wiring system	1	60.00	60.00 <i>30</i>
7	To install and re-programme reverse sensor	1	150.00	150.00 <i>30</i>
8	To remove inner trim, garnishes for necessary checking and repair	1	250.00	250.00 <i>60</i>
9	To transfer item to new bumper and car boot	1	220.00	220.00 <i>x ny</i>
10	Panel beating to straighten, repair, realign damaged area	1	550.00	550.00 <i>400</i>
11	Spray painting on new parts and affected damaged area	1	600.00	600.00 <i>400</i>
12	To apply anti-rust coating on affected area	1	120.00	120.00 <i>30</i>
13	Labour charge	1	250.00	250.00 <i>a n</i>
Total				4,289.43

Remarks :-

Estimated Repair Period : To be agreed
We are not GST registered.

For & On behalf of
Fujimotorsports Automotive Pte Ltd



Erwin Ho

Parts. 1869.43
Parts discount 20% - 1495.54
SN 200
Labour - 950
2645.54
4/5 B. 2100
WP. 92495749
01/06/18
Resumy after repair.
sun @ 11hants.com
4 days.

Fujimotorsports Automotive Pte Ltd

48 Toh Guan Road East, #01-115 Enterprise Hub, Singapore 608586
T. 92210404/93668787 e. fujimotorsports@hotmail.com