

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1991Y

DATE 28/5/2018 14:26

MAKE :

MODEL : HYUNDAI SONATA

HXM
Jm.
Lsum

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>X repair</i>			\$ 1,349.50	
	Boot Lid Rubber <i>X su</i>			\$ 110.90	
	Boot Lid Lock Upper <i>X su</i>			\$ 132.10	
	Boot Lid Lock Lower <i>X su</i>			\$ 30.30	
	Boot Lid Sonata Plate <i>- su</i>			\$ 43.60	
	Boot Lid Hyundai Plate <i>- su</i>			\$ 24.20	
	Boot Lid 'H' Emblem <i>- su</i>			\$ 26.10	
	Boot Lid CRDI Plate <i>- su</i>			\$ 22.70	
	Boot Lid Lamp (RH) <i>- su</i>			\$ 230.20	
	Boot Lid Trimboard <i>X su</i>			\$ 165.40	
	Boot Lid Trimboard Clips (10pcs) <i>X su</i>			\$ 10.00	
	Rear Bumper <i>- Defend su</i>			\$ 578.40	
	Rear Bumper Reinforcement <i>su</i>			\$ 483.30	
	Rear Bumper Clip <i>- su</i>			\$ 22.00	
	Rear Bumper Sponge <i>su</i>			\$ 137.40	
	Rear Bumper Under Cover <i>X su</i>			\$ 185.80	
	Rear Bumper Protector (RH) <i>- su</i>			\$ 38.00	
	Tail Lamp (RH) <i>- su</i>			\$ 344.00	
	Rear Panel <i>X repair</i>			\$ 391.80	
	Rear Panel Garnish <i>X su</i>			\$ 95.80	
	Rear Fender (RH) <i>- su</i>			\$ 1,935.90	
	Rear Fender Inner Lining (RH) <i>X su</i>			\$ 74.10	
	Rear Windscreen Moulding <i>- su</i>			\$ 60.00	
	SUB TOTAL			\$ 6,491.50	
	LESS 20%			\$ 1,298.30	
	DISCOUNTED TOTAL			\$ 5,193.20	
	Boot Lid Comfort Logo & Tel No. Sticker <i>su</i>			\$ 30.00	Nett
	Rear Bumper Reverse Sensor <i>X su</i>			\$ 135.70	Nett
	Rear Bumper Advertisement Logo <i>X su</i>			\$ 50.00	Nett
	Rear Bumper Rubber Mat <i>- su</i>			\$ 50.00	Nett
	Rear Windscreen Sealant <i>- su</i>			\$ 46.00	Nett
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 				
	<p>Acknowledged by Repairer</p> <p>Signature: <i>Kahie (Ull)</i></p> <p>Date: <i>31/5/18</i></p>			\$ 311.70	
	Labour Charge				
	Panel Beating			\$ 1,200.00	<i>800</i>
	Spray Painting Charge			\$ 1,000.00	<i>600</i>
	Wiring Charge			\$ 50.00	<i>20</i>
	Tuff Kote			\$ 50.00	<i>20</i>
	Remove/Refix Cushion & Upholstery Rear <i>After Repair p Lot</i>			\$ 150.00	<i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>100</i>
	Remove/Refix Reverse Sensor			\$ 120.00	<i>X 20</i>
	TOTAL LABOUR			\$ 2,690.00	
	ESTIMATE TOTAL			\$ 8,194.90	