

REPAIR ESTIMATE*

DATE 30/5/2018 11:12

Like

MODEL : HYUNDAI SONATA

L/sum
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover X			\$ 185.80
	Rear Bumper Protector (LH/RH) X		\$ 38.00	\$ 76.00
	Tail Lamp (RH) X old Damage			\$ 344.00
	SUB TOTAL			\$ 1,826.90
	LESS 20%			\$ 365.38
	DISCOUNTED TOTAL			\$ 1,461.52
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				\$ 385.70
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,617.22
	Kalun (U/C/L)			
	M 31/5/18 1410hrs.			
	2 Days			
	L/S			
	After Repair photo			
	LKK Auto Consultants hence notify the Reparer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Reparer			
	Signature:			
	Date:			