

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8559S

DATE 30/5/2018 11:34

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (RH) X Repair			\$ 1,351.10
	Front Door (RH) — <i>Repl</i>			\$ 1,403.05
	Rocker Panel Outer Garnish (RH) X Repair			\$ 483.60
	Rear Wheel Hup-Cap (RH) — <i>hubcap</i>			\$ 150.70