

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6708L

DATE 30/5/2018 15:49

MAKE :

MODEL : HYUNDAI i40

LKK/Kalvin
LikeL/Sun
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (LH) X repair			\$ 619.00
	Front Fender Shield (LH) X			\$ 169.80
	Front Fender Retainer X			\$ 9.20
	Front Bumper X repair			
	SUB TOTAL			\$ 798.00
	LESS 20%			\$ 159.60
	DISCOUNTED TOTAL			\$ 638.40
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 250.00 200
	Tuff Kote			\$ 50.00 X
	TOTAL LABOUR			\$ 860.00
	ESTIMATE TOTAL			\$ 1,498.40
Kalvin (CRK) 31/5/18 1015hrs 2072 P/P After Repair photo				LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal negotiation is allowed • Supplementary claims must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will