



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

INDIA INT'L INSURANCE PTE LTD 64 CECIL STREET #04-06 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Siow Hung Jui ADDRESS: 37A Simon Place Singapore 545983 TEL:		WIP: 34428 EXCESS: DATE: 31.05.2018	
VEH NO:	SJK99P	DATE IN:		CONTACT PERSON:	RICK 63602445
CHASSIS NO:	WPOZZZ99ZHS110594	MILEAGE:		TYPE OF CLAIM:	TP AGAINST SHA1044S
MODEL:	911 Carrera S	DATE REG.:	01.08.2016	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	P991-505-022-35-	DE ✓	\$ 2,285.80
2	SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	na ✓	\$ 451.40
3	SENSOR PARKASSIST GASKET	2	P5Q0-919-133- -989	na ✓	\$ 4.60
4	REAR BUMPER LOWER RETAINING STRIP LH	1	P991-505-837-03-	na ✓	\$ 33.70
5	REAR BUMPER LOWER SPOILER SCREW	2	P999-919-246-01-	na ✓	\$ 31.00
6	REAR BUMPER LOWER SPOILER	1	P991-505-811-04-OK1	DE ✓	\$ 545.90
7	BLIND RIVET	6	P999-190-191-30-	na ✓	\$ 31.20
8	TAIL PIPE GARNISH COVER	1	P991-505-651-04-OK1	DE ✓	\$ 198.50
9	BUMPER REINFORCEMENT	1	P991-505-141-08-	?	\$ 927.20
10	REINFORCEMENT SCREW	6	P900-378-351-01-	?	\$ 25.20
11	LOGO PORSCHE GALVANO SILVER	1	P991-559-235-00-	na ✓	\$ 189.50
12	LOGO CARRERA GALVANO SILVER	1	P991-559-237-01-	na ✓	\$ 122.90
13	LOGO S GALVANO SILVER 991	1	P991-559-243-01-	na ✓	\$ 94.40
14	LOGO "911" SMALL	1	P991-559-231-02-	na ✓	\$ 129.00
15	REAR BUMPER REFLECTOR LH	1	P991-631-455-01-	?	\$ 63.20
16	MAIN EXHAUST MUFFLER	1	P9P1-251-053-A -	PT ✓	\$ 4,720.00
17	TAIL PIPE	1	P9P1-251-187-B -	PT ✓	\$ 1,348.00
18	MAIN EXHAUST MUFFLER CLAMP BIG	2	P9P1-253-145- -	na ✓	\$ 140.80
19	MAIN EXHAUST MUFFLER CLAMP SMALL	2	P997-111-230-80-	na ✓	\$ 167.60
20	MAIN EXHAUST MUFFLER CENTER CLAMP	2	P9P1-251-571- -	na ✓	\$ 203.00

TOTAL PARTS \$ 11,712.90

LESS 10% \$ 1,171.29

TOTAL PARTS COST \$ 10,541.61

Labour Description

1	TO REPLACE REAR BUMPER & OTHER PARTS AFFECTED BY THE ACCIDENT.	1560 1300	\$ 3,120.00
2	TO RESPRAY REAR BUMPER .	1300	\$ 1,500.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ 1,560.00
4	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT	\$ CM 70.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 200 250.00

6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 480 600.00
7	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$ 300 300.00
8	SUNDRIES.	NETT	\$ 50 50.00
		TOTAL LABOUR	\$ - \$ 7,450.00
		TOTAL PARTS	\$ - \$ 10,541.61
		TOTAL	\$ - \$ 17,991.61
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ - \$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Paul
Hq 9001068
5 days
01/06/18 @ 1120
Resy by paul