## **ACCIDENT REPAIR COST**



ACCIDENT TIME REPORTED	1140HRS	BUS REGISTRATION NUMBER	SMB3565C
		<u></u>	
ACCIDENT DATE	27-May-18	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	TEO THYE SENG	BUS ROUTE NUMBER	
MPLOYEE NUMBER		BUS ADVERTS (Y/N)	N
•		·	

## SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

	Part No.	Part or Item Description	Quantity	Total Cost
	30106499	Exterior panel	1	\$419.17
	77016575	BEARING BUSH	1	\$17.75
			7% GST	\$30.58
			FINAL TOTAL COST	\$467.50
4				

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)		\$2,200.00
	7% GST	\$154.00
	FINAL TOTAL COST	\$2,354.00

PAGE 1

## **ACCIDENT REPAIR COST**



SECTION 5: REPAIRS TO BUS ADVERTISMENT VINYLS/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST
---------------------------------

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-

## SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	2/6/2018	
			Date Out From Repairs	5/6/2018
BUS TYPE (SD / DD)	DD		Number of Days Under Repair	3
LOSS OF USE COST				\$1,200.00

SUMMARY		
SECTION NO.	COST	
1	\$467.50	
2	\$2,354.00	
3	-	
4	-	
5	\$1,200.00	
ACCIDENT REPAIR COST (1+2+3+4+5)	\$4,021.50	

PAGE 2