

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 04 Jun 2018

Preliminary Advice

Vehicle No	: SLC6115E	Accident Date	: 27/05/2018
Make	: LEXUS CT200H	Policy No.	: 1000685245
Assignment Date	: 31/05/2018	Excess	: S\$1,500.00
Date of Inspection	: 01/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,289.65
Revised Amount	:S\$	9,185.57
Check Items (Estimated)	:S\$	3,158.08
Total	:S\$	12,343.65
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	51,603.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,397.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.