

ASS. REC. BY:

REF: CS/MSG18009944/Tlsd3

Special Instruction:

Surveyor

Tranfikh

ASSIGNMENT (Office)

Menner

From (Person)

Joslin Lim

of

MSG

Date/Time

31/5/18 4:55pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLC 611SE

Insured:

at Workshop info:

Borneo Motor (penden)

Tel:

66 31 11 88

of

No. 2 Pandan Creston

Policy No:

1000685245

Claim No:

Sum Insured:

Excess: \$1,500.00

Make of Veh:

D.O.A. 27/5/2018

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:01am @ 11/6/18

Person Contacted:

Wally Tan

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 611SE - NAI17NC18CO 9650/K4


D.O.A: 27/5/18

04/06/18 @ 14:09 p.m. revised IA to Joslin Lim via menner

04/06/18 @ 14:16 p.m. ~~request~~ mandate request Authorize repair to Joslin Lim via menner.

04/06/18 @ 17:34 p.m. mandate approved by Eng Huey Ni via menner.

REF: MSIG



From: _____ Date: 1/6/18

Estimated Cost: _____

☒ IP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SIC 6115 E

at Workshop m/s Borneo Motor

of No 2 ponden Crescent

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: \$1,500.00

(Client's Record) 11 am @ ourer waiting

Make of Veh: Wally fun

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$125K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 22222222

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Lexus CT200 cc 1798

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 80883 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHKD5BH102 265 266

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 55 R16

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or [Signature]

Front	Rear
R/Bal: 6 mm	R/Bal: 0 mm
L/Bal: 6 mm	L/Bal: 6 mm
D.O.A.	D.O.I. 11/02/18 1120

Survey held at Borneo Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$9209.24, Boleys

(\$4,080.41 Red - 5.1%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave. 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009944/T1sd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 01-06-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLC 6115E
Policy No. 1000685245	Coverage (\$)	0.00
Claim No.	Excess (\$)	1,500.00
Assign From MERIMEN (JOSLIN LIM)	Assign Date	01/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 27/05/2018	Inspection Date 01/06/2018
Survey held at BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SLC6115E
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS CT200H CVT EXECUTIVE
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2ZR6631399
Chassis No.:	JTHKD5BH102265266
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$39,156.00
Original Registration Date:	20 May 2016
First Registration Date:	20 May 2016
Transfer Count:	0
Actual ARF Paid:	\$16,819.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 May 2026
PARF Rebate Amount:	\$12,614.00
Intended COE Rebate Details	
COE Expiry Date:	19 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$38,989.00
Total Rebate Amount:	\$51,603.00

The information contained herein is correct as at 04 Jun 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 30 July 2018 9:10 AM
To: 'Wally Tan TCBC'; Taufikh (LKKAuto); Admin-D (LKKAuto)
Cc: 'Alvin Lee Yee Peng PTCBC'
Subject: RE: Final bill for SLC6115E

Dear Wally,

Confirmed final fig \$9,209.24 @ 6 days of repairs before excess \$1,500/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Wally Tan TCBC [mailto:wally.tan@borneomotors.com.sg]

Sent: Friday, 20 July 2018 9:54 AM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>

Subject: RE: Final bill for SLC6115E

Hi Taufikh,

Please find attached final bill of SLC6115E for your kind perusal.

Regards

Wally

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited.

Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited.

Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

View Received Message

This mail is associated with :

*SLC6115E (218180)
OD
May 27 2018 10:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Borneo Motors (S) Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 04/06/2018 17:34 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9185.57) - SLC6115E - Claim Handler: Joslin Lim

Approved:9185.57:check items of \$3158.08 to be verified and confirmed

DOCUMENTS SUMMARY
There are no documents.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 5 June 2018 9:26 AM
To: 'Wally Tan TCBC'
Cc: sur@lkkauto.com
Subject: SLC 6115E OD (MSIG)

Dear Wally,

As instructed by our client, please proceed to repair the insured vehicle **SLC 6115E (Excess \$ 1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 27 Jul 2018

Preliminary Advice

Vehicle No	: SLC6115E	Accident Date	: 27/05/2018
Make	: LEXUS CT200H	Policy No.	: 1000685245
Assignment Date	: 31/05/2018	Excess	: S\$1,500.00
Date of Inspection	: 01/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,289.65
Revised Amount	:S\$	9,209.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,209.24

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	51,603.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,397.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 04 Jun 2018

Preliminary Advice

Vehicle No	: SLC6115E	Accident Date	: 27/05/2018
Make	: LEXUS CT200H	Policy No.	: 1000685245
Assignment Date	: 31/05/2018	Excess	: S\$1,500.00
Date of Inspection	: 01/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,289.65
Revised Amount	:S\$	9,185.57
Check Items (Estimated)	:S\$	3,158.08
Total	:S\$	12,343.65

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	51,603.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,397.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2018 17:29
Date Of Accident	27/05/2018 10:30
Exact Location Of Accident	CAUSEWAY TWDS JOHOR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC6115E
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	ERWINCHEONG@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96280021
Vehicle Particulars	
Manufacturer	LEXUS
Model	CT200H-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	G 300023866 MCY
Cover Note Number	
Driver	
Name of Driver	LOW ENG TEE
Work Permit No	G6646318X
Date Of Birth	07/01/1991
Occupation	INDOOR
Date Of Driving Pass	03/09/2014
Driving Experience	3 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-86115133
Fax Number	
Contact Number	
Email Address	XI_YU@LIVE.COM.MY

Address	451 EAST COAST RD #01-04
Postcode	429024
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLE
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TAN YEN YEN GENDER: : FEMALE
Passenger 2	NAME: : SHAWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA6611L
Vehicle Make/Model/Colour	TOYOTA/SIENTA/GREEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

PASSENGER 2

Name:

SHAWN

Gender: Male ☒Female ☐

PASSENGER 3

Name:

Gender: Male ☐Female ☐

PASSENGER 4

Name:

Gender: Male ☐Female ☐

PASSENGER 5

Name:

Gender: Male ☐Female ☐

PASSENGER 6

Name:

Gender: Male ☐Female ☐

PASSENGER 7

Name:

Gender: Male ☐Female ☐

PASSENGER 8

Name:

Gender: Male ☐Female ☐

PASSENGER 9

Name:

Gender: Male ☐Female ☐

PASSENGER 10

Name:

Gender: Male ☐Female ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


HITACHI MOTOR ASIA PACIFIC (PTE) LTD.

CHWEI KWANG SIMON (MR)
Policyholder's Signature / Date &
S. Time
APAC Vehicle Solutions
APAC Business Division

28/5/18 0930H
Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving towards the left most lane when I felt and heard an impact on my right side of car. SKA66112 had knocked into me while changing lane. I changed the car and asked to exchange for particulars but the driver refused to give me his particulars. I have photo and video footage of the damage. A sound clip was also recorded of the exchange between the 2 parties. SKA 66112 was changing lane without signalling and I was travelling straight in my lane.

Declaration

We declare the foregoing particulars are true in every respect.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


 General Manager
 Total Finance Solutions
 Asia Pacific Business Division


 Driver's Signature (If driver is not the policyholder) / Date & Time
 28/5/18 0930M

Witnessed by Reporting Centre Personnel

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 Co.Reg No. 200412212G GST Reg. No. 20-0412212G
 A Member of **MS&AD** INSURANCE GROUP

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

MOTORMAX PLUS
Comprehensive

Certificate No. G 300023866 MCY

Excess : SGD1,500

Windscreen Excess : SGD100

1. **Index Mark and Registration Number of Vehicle**
 SLC6115E

2. **Name of Policyholder**
 Hitachi Capital Asia Pacific Pte. Ltd.

3. **Effective Date of the Commencement of Insurance for the purposes of the Act**
 20/05/2018

4. **Date of Expiry of Insurance**
 19/05/2019

5. **Persons or Classes of Persons entitled to drive***
 Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. **Limitations as to Use ***
 Use for the carriage of passengers or goods in connection with the Policyholder's business. Use for social domestic and pleasure purposes and business purposes of any person to whom the vehicle is hired
 The Policy does not cover
 (1) Use for racing pace-making reliability trial or speed-testing.
 (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
 (3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risk and Compensation) Act (Chapter 189) and Chapter 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offense under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Michael W Gourlay
 Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **G6646318X**

Name: **LOW ENG YEE**

Birth Date: **07 Jan 1991**

Issue Date: **03 Sep 2014**

Valid Till: **02 Sep 2019**

002341612B



S PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer: **BODYPERFECT PTE. LTD.**

Name: **LOW ENG YEE**

S Pass No.: **4 03287172**

Sector: **SERVICE**

K0208264



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg
03 Sep 2014



NP 428A

VISIT PASS
Immigration Regulations

26-02-2019

Name: **LOW ENG YEE**

ICN: **G6646318X**

Date of Birth: **07-01-1991**

Sex: **F**

Nationality: **MALAYSIAN**

Download SGWorkPass App to check status



YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept <i>salary on 1/6/18 @ 11am</i>	S1000004 / ICCU1	M/S Hitachi Capital Asia Pacific 111 Somerset Road #14-05 Tripleone Somerset Singapore 238164 Attn: Nuraida Mobile: 92325202
	Document No 0	
	Document Date 30/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	AHXBBW	S5	ZWA10R	20/05/2016	SLC6115E	0	15464 4UL/SLC6115E/27051

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHKD5BH102265266	2ZR6631399	60	Wally Tan G H	30/05/2018	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: G 300023866 MCY ACC DATE: 27.05.18 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 - 80.00
2	B	BP-LAB CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				✓ 204.00
3	B	BP-LAB REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				✓ 204.00
4	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL. R/H HEADLAMP PANEL AND FIT NEW PARTS.				1632 2448.00
5	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1650 1750.00
6	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT. (NETT)				✓ 816.00
7	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)				✓ 612.00
8	S	BP-SUBLET TRANSFER R/F TYRE TO NEW WHEEL RIM AND BALANCING. (NETT)				✓ 102.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Amount Due

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE 30/05/2018
TIME 16:16

Date:

VEHICLE NO SLC6115E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1398**ESTIMATE**

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept.	S1000004 / ICCUA1	M/S Hitachi Capital Asia Pacific 111 Somerset Road #14-05 Tripleone Somerset Singapore 238164 Attn: Nuraida Mobile: 92325202
	Document No 0	
	Document Date 30/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	AHXBBW	S5	20/05/2016	SLC6115E	0	15464	4UL/SLC6115E/27051
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHK5BH102265266	22R6631399	60	Wally Tan G H	30/05/2018	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	1	L81145-76140 UNIT, HEADLAMP	1.00	3390.60	15.00	? 2882.01 X
10	2	L53801-76010 FENDER, FR RH	1.00	1058.00	15.00	bt 899.30 912
11	3	L53823-76011 PROTECTOR, FR SIDE	1.00	31.90	15.00	new 27.11
12	4	L55783-30110 PAD, COWL TOP	1.00	36.20 35.70	15.00	new 30.34 30.7
13	5	L53153-76010 GUIDE, FR SIDE AIR	1.00	73.30	15.00	new 62.30
14	6	L53805-76011 SHIELD SUB-ASSY,	1.00	225.10	15.00	? 191.33 X
15	7	L52115-76011 SUPPORT FR BUMPER RH	1.00	56.30 55.60	15.00	new 47.26 47.8
16	8	L52611-76040 ABSORBER, FR BUMPER	1.00	99.70	15.00	? 84.74 X
17	9	L52543-76010 SEAL, FR BUMPER	1.00	33.10 32.70	15.00	new 27.79 28.2
18	0	L52119-76931 COVER, FR - front bumper	1.00	75.89 6.30	15.00	all 761.85 769.9
19	1	L53879-30040 RETAINER, FR FENDER	4.00	12.10 12.00	15.00	new 40.80 41.2
20	2	L47749-50090 CLIP	4.00	1.50 1.40	15.00	new 4.76 5.05
21	3	T90467-07201 CLIP	2.00	2.90	15.00	new 4.92
22	4	L89348-78020 RETAINER, ULTRASONIC	2.00	16.30 16.00	15.00	new 27.20 27.7
23	5	L42611-76130 WHEEL, DISC	1.00	2331.70	15.00	new 1981.94

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 7,073.65	13,289.65
		Labour 6,114.00	GST 7.00%
		Materials 102.00	930.28
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	
			Amount Due 14,219.93

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 30/05/2018

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

TIME 16:16

VEHICLE NO SLC6115E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 95X Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/S Hitachi Capital Asia Pacific 111 Somerset Road #14-05 Tripleone Somerset Singapore 238164 Attn: Nuraida Mobile: 92325202
	Document No 0	
	Document Date 20/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	AHXBBW	S5	20/05/2016	SLC6115E	82900	15464	4UL/SLC6115E/270511
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHKDD5BH102265266	2ZR6631399	60	Wally Tan G H	30/05/2018	0.00	20/07/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	S	BP-SUBLET TRANSFER R/F TYRE TO NEW C25 WHEEL RIM AND BALANCING. (NETT) PO#3493				102.00
9	V	EXC Excess element of insurance repair to be paidby the insured party				-1500.00
10	1	L53823-76011 PROTECTOR, FR SIDE	1.00	31.90	15.00	27.11
11	2	L53153-76010 GUIDE, FR SIDE AIR	1.00	73.30	15.00	62.30
12	3	L42611-76130 WHEEL, DISC	1.00	2331.70	15.00	1981.94
13	4	L53801-76010 FENDER, FR RH	1.00	1073.40	15.00	912.39
14	5	L55783-30110 PAD, COWL TOP	1.00	36.20	15.00	30.77
15	6	L52115-76011 SUPPORT FR BUMPER RH	1.00	56.30	15.00	47.85
16	7	L52543-76010 SEAL, FR BUMPER	1.00	33.10	15.00	28.13
17	8	L53879-30040 RETAINER, FR FENDER	4.00	12.10	15.00	41.12
18	9	L47749-50090 CLIP, PIN HOLD	4.00	1.50	15.00	5.08
19	0	T90467-07201 CLIP	2.00	2.90	15.00	4.92
20	1	L89348-78020 RETAINER, ULTRASONIC	2.00	16.30	15.00	27.70
21	2	L52119-76931 COVER, FR	1.00	905.80	15.00	769.93
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle 	Parts 3,939.24	7,709.24
		Labour 5,168.00	GST 7.00%
		Materials 102.00	539.65
		Lubrication/Fluid 0.00	Less
		Others 0.00	0.00
		Amount Due	8,248.89

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 20/07/2018
TIME 09:31

VEHICLE NO SLC6115E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Attn: Taufik
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/S Hitachi Capital Asia Pacific 111 Somerset Road #14-05 Tripleone Somerset Singapore 238164 Attn: Nuraida Mobile: 92325202
	Document No 0	
	Document Date 20/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	AHXBBW	S5	20/05/2016	SLC6115E	82900	15464	4UL/SLC6115E/27051
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHK55BH102265266	2ZR6631399	60	Wally Tan G H	30/05/2018	0.00	20/07/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:G 300023866 MCY ACC DATE:27.05.18 TOW/DRIVE IN: EXCESS:\$1500/- DATE-IN:25.06.18 DATE SURVEY:01.06.18 NO OF REPAIR DAYS:6 DAYS BY:TAUFIKH (LKK) AUTHORISED ON:05.06.18				50.00
2	B	BP-LAB CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)	*			204.00
3	B	BP-LAB REMOVE/REFIX FRONT PARKING SENSORS. (NETT)	*			204.00
4	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL. R/H HEADLAMP PANEL AND FIT NEW PARTS.	*			1632.00
5	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			1650.00
6	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT. (NETT)	18			816.00
7	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)	18			612.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLC6115E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018		31 May 2018 16:55 Edit Adj Rpt	\$59,209.24 Edit Estimates	\$59,209.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N, Email: ida@hcspl.com.sg							
Vehicle Reg. No.:		SLC6115E	Date of Loss:	27/05/2018 10:00 - :59 [24 Months and 7 Days From LTA Reg Date (Man Yr)]					
Claim Type:		OD / 218180	Policy/Cover Note No.:	1000685245 (Comprehensive) Coverage: 20/05/2018 - 19/05/2019					
			Excess:	S\$1,500.00					
Repairer:		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/06/2018]							
Driver/Custodian:		LOW ENG TEE (27 / Female), NRIC: G6646318X, Tel: +6586115133							
Adj Asg. Remarks:		Survey appt 01/06/18, 11am. Owner waiting. REVERT CASE. Please contact us ASAP if you are not able to attend this assignment.							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
<ul style="list-style-type: none"> MSIG_SG (30/07/2018): Alert - Adj Mandate Approved (\$59209.24) - SLC6115E - Claim Handler: Joslin Lim MSIG_SG (04/06/2018): Alert - Adj Mandate Approved (\$59185.57) - SLC6115E - Claim Handler: Joslin Lim 									
ALL ASSOCIATED TASKS									
			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC6115E (218180)
OD
May 27 2018 10:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Borneo Motors (S) Pte Ltd





[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser












Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/06/18 14:09	Adjuster Immediate Advice	1	Load HTM	<input type="checkbox"/>
2	27/07/18 14:47	Adjuster Immediate Advice	1	Load HTM	<input type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/06/18 14:14	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
2	04/06/18 14:14	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	04/06/18 14:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	27/07/18 14:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	27/07/18 14:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	27/07/18 14:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	27/07/18 14:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	31/05/18 11:10	LKK Auto Consultants Pte Ltd (HQ) Borneo email + Estimate + Accident statement + CI + DL + S Pass + Visit Pass	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/06/18 14:15	ESTIMATE	 Load PDF	
2	27/07/18 14:42	ESTIMATE MARKED	 Load PDF	
3	30/07/18 11:14	ESTIMATE MARKED 1	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	28/05/18 17:33	Borneo Motors (S) Pte Ltd (Leng Kee) Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	28/05/18 17:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 17:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 17:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 17:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 17:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 17:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	28/05/18 17:33	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 17:33	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 17:33	CI	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 17:33	IC	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18009944/T1SD3Q2

Date: 01/08/2018

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD

Policy No: 1000685245

Date of Loss: 27/05/2018

Nature of Claim: OD Claim No: 218180

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC6115E**

Make & Model: LEXUS CT200H, 1.8 (A)

Engine No: 2ZR6631399

Reg. Date: 20/05/2016 (Man. Year: 2015)

Chassis No: JTHKD5BH102265266

Colour: Black

Odometer: 80883 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$125,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,177.32	3,989.24	3,188.08	44.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,136.00	5,220.00	916.00	14.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,313.32	9,209.24	4,104.08	30.83
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	11,813.32	7,709.24	4,104.08	34.74
+ GST 7.00/7.00% (S\$)	826.93	539.65	287.28	34.74
Nett Amount (S\$)	12,640.25	8,248.89	4,391.36	34.74

INSPECTION

Date of Assignment: 31/05/2018

Date Inspected: 01/06/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
Parts: 143	LEXUS CT200H 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC6115E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
2	1		*UNIT ,HEADLAMP	Not Necessary	2,882.01 FS	*- FS
3	1		*FENDER ,FR RH	Bent	912.39 FS	*912.39 FS
4	1		*RPROTECTOR ,FR SIDE	Necessary	27.11 FS	*27.11 FS
5	1		*PAD ,COWL TOP	Necessary	30.77 FS	*30.77 FS
6	1		*GUIDE ,FR SIDE AIR	Necessary	62.30 FS	*62.30 FS
7	1		*SHIELD SUB-ASSY	Not Necessary	191.33 FS	*- FS
8	1		*SUPPORT FR BUMPER RH	Necessary	47.85 FS	*47.85 FS
9	1		*ABSORBER ,FR BUMPER	Not Necessary	84.74 FS	*- FS
10	1		*SEAL ,FR BUMPER	Necessary	28.13 FS	*28.13 FS
11	1		*COVER ,FR -FRONT BUMPER	Deformed	769.93 FS	*769.93 FS
12	4		*RETAINER ,FR FENDER	Necessary	41.12 FS	*41.12 FS
13	4		*CLIP	Necessary	5.08 FS	*5.08 FS
14	2		*CLIP	Necessary	4.92 FS	*4.92 FS
15	2		*RETAINER ,ULTRASONIC	Necessary	27.70 FS	*27.70 FS
16	1		*WHEEL ,DISC	Cut	1,981.94 FS	*1,981.94 FS
Total Parts (S\$)					7,177.32	3,989.24

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING SYSTEM AND FOCUS HEADLAMP	New	204.00	204.00
2	REMOVE/REFIX FRONT PARKING SENSORS	New	204.00	204.00
3	REMOVE ALL NECESSARY PARTS ,TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL.R/H HEADLAMP PANEL AND FIT NEW PARTS	New	2,448.00	1,632.00
4	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	1,750.00	1,650.00
5	TO CARRY OUT WHEEL ALIGNMENT	New	816.00	816.00
6	TO RESET ECU AND REPROGRAMME	New	612.00	612.00
7	TRANSFER R/F TYRE TO NEW WHEEL RIM AND BALANCING	New	102.00	102.00
Gross Labour Cost (S\$)			6,136.00	5,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >