

CLASS. REC. BY:

REF: CS/ICS18009963/Kvd3/02 Special Instruction:

Surveyor: menmen

ASSIGNMENT (Office)

From (Person): Janice goh of ECICS Date/Time: 20/5/18 @ 4:28pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8KR 4178 U Insured: SKD 7909 G

at Workshop m/s: BH Auto Tel: 6559 8944

of BK 1 - Scepter C 8in Miao Ind. Est #01-111

Policy No: _____ Claim No: DMPC1800215H / DL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/5/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up' H.O.D. Endorsement: _____

Date/Time: 12:05pm @ 1/6/18 Person Contacted: Janice Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>8KR 4178 U - X</u>
	<u>SKD 7909 G - X</u>
<u>20/5/18</u>	<u>\$1580.68 confirmed by email (Ref 4059.00, 7270) (NO LS)</u>

REF: ICS

ASSIGNMENT

From: _____ Date: 04062018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 4178U

at Workshop m/s: BH Auto

of: Blk 1 Sin Ming #01-115

Insured: _____

Policy No.: _____

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) 1 Dam - 1 lam

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: 20/7/18 ksc Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKR 4178U Yr Regn: 02, 15

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Accem c.c 1368

Colour: M Silver A/C: Insured / Std / NI / NA

Sp. Reading: 37950 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCT 51BTFU 216328

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /


TOYO / YOKO or Falken

Front	Rear
R/Bal. 8 mm	R/Bal. 8 mm
L/Bal. 8 mm	L/Bal. 8 mm
D.O.A. 26/5/18	D.O.I. 4/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



Date / Time	Action / Instruction
5/6	File pass to Catherine
RECEIVED 20 JUL 2018	
	<i>[Signature]</i> 20/7/2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) 20/7 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 1580.68)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: _____

Transportation: 250

\$ + RS, SI: 10

Photos: _____

Others: _____

TOTAL: 260

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 July 2018 12:04 PM
To: 'ECICS Claims'
Cc: SUR; Desmond Lee Ker Wen (ECICS, Claims)
Subject: RE: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

Dear Janice,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ECICS Claims [mailto:claims@ecics.com.sg]
Sent: Friday, 20 July 2018 11:54 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; ECICS Claims <claims@ecics.com.sg>
Cc: SUR <sur@lkkauto.com>; Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Subject: RE: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

Hi Veron

Our claim no is DMPC1800215H/DL and case handler is Desmond Lee.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, 20 July, 2018 11:05 AM
To: ECICS Claims
Cc: Phoebe Jay Xie (ECICS, Claims); SUR
Subject: RE: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

Dear Janice,

Please provides us claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 1 June 2018 11:35 AM

To: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Phoebe Jay Xie (ECICS, Claims)' <PhoebeJay_Xie@ecics.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ECICS Claims [<mailto:claims@ecics.com.sg>]

Sent: Wednesday, 30 May 2018 4:28 PM

To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; assignments@lkkauto.com

Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; ECICS Claims <claims@ecics.com.sg>

Subject: RE: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

Without Prejudice

Dear Janice

Thank you for your email.
We will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division

DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]
Sent: Wednesday, 30 May, 2018 11:15 AM
To: Phoebe Jay Xie (ECICS, Claims); ECICS Claims; Janice Goh Siew Geok (ECICS, Claims)
Cc: BHAS - Janice Koh; BHAS - Anthony Lau; BHAS - Moo Wen Zheng; BHAS - Bernard Kee
Subject: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,
Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate
#01-111/113/115/117 Singaopre:575636
(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404
Email: jacelyn.loh@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

follow us on  facebook follow us on  twitter visit our website  **ecics.com.sg**

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 30 May 2018 4:28 PM
To: BHAS - Jacelyn Loh; assignments@lkkauto.com
Cc: BHAS - Janice Koh; BHAS - Anthony Lau; BHAS - Moo Wen Zheng; BHAS - Bernard Kee; Phoebe Jay Xie (ECICS, Claims); ECICS Claims
Subject: RE: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)
Attachments: SAS2414088.pdf; SKM_C224e18053011150_0001.jpg

Without Prejudice

Dear Janice

Thank you for your email.
We will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: BHAS - Jacelyn Loh [mailto:jacelyn.loh@bhauto.com.sg]
Sent: Wednesday, 30 May, 2018 11:15 AM
To: Phoebe Jay Xie (ECICS, Claims); ECICS Claims; Janice Goh Siew Geok (ECICS, Claims)
Cc: BHAS - Janice Koh; BHAS - Anthony Lau; BHAS - Moo Wen Zheng; BHAS - Bernard Kee
Subject: pre repair inspection(OUR VEHICLE - SKR4178U / YOUR VEHICLE - SKD7909G)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,

Jacelyn Loh

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: Jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

follow us on  follow us on  visit our website  **ecics.com.sg**

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE

SECTOR C #01-115

SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 2009175125K

Your Vehicle: SKD7909G

Our Vehicle: SKR4178U

**WITHOUT PREJUDICE
BY FAX: 6827 7809 ONLY**

Date: 30/05/2018

ECICS LIMITED

7 TEMASEK BOULEVARD

#10-01 SUNTEC TOWER ONE

SINGAPORE 038987.

Dear Sir,

**ACCIDENT INVOLVING SKR4178U & SKD7909G ON 26/05/2018 ALONG
SENGKANG EAST ROAD TWDS COMPASSPOINT.**

We refer to the above matter.

Kindly let us have your list of ten surveyors for our consideration within the stipulated timeline under the NIMA protocol.

Please be informed that the said vehicle can be inspected at:

BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636.

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you.

Yours Faithfully



BH Auto Services Pte Ltd/JACELYN

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 1390H

Vehicle Details

Vehicle No.: SKR4178U
 Vehicle to be Exported: No
 Intended De-registration Date: 30 May 2018
 Vehicle Make: HYUNDAI
 Vehicle Model: ACCENT (RB) 5DR 1.4 CVT ABS D/AB
 2WD

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: G4LCEU338253

Chassis No.: KMHCT51BTFU216324

Maximum Power Output: 73.6 kW (98 bhp)

Open Market Value: \$11,063.00

Original Registration Date: 06 Feb 2015

First Registration Date: 06 Feb 2015

Transfer Count: 0

Actual ARF Paid: \$6,063.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 05 Feb 2025

PARF Rebate Amount: \$4,547.00

Intended COE Rebate Details

COE Expiry Date: 05 Feb 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$65,889.00

COE Rebate Amount: \$44,041.00

Total Rebate Amount: \$48,588.00

The information contained herein is correct as at 30 May 2018

OK

SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2007 BMW 325i Convertible. COE Expiry Date 16/5/2027.



\$15k Of Parts Changed With Receipts As Good As New Smooth Powerful Transmission.
 Direct Owner: StarAd

Lake View Credit Pte Ltd [View Our Cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

ACCENT

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	ACCENT	Any	Any	2015	Any	Any	Any	Available



Hyundai Accent 1.4A **\$60,800** **\$7,680 /yr** **31-Jul-2015** **1,368 cc** **49,000 km** **Sedan** **Available**

Price Reduce! Down Payment \$6,080, Beautiful Silver, 5 Years Agent Warranty, Full Agent Serviced, Very Good Consumption At 15.6Km/Litre. 100% Accident Free, Very Low Depreciation, High COE Value, As G...

Posted: 13-May-2018 Tags: 2015 Hyundai Accent, Hyundai Accent, Hyundai, Accent, Used Hyundai

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used ACCENT, ACCENT Singapore, used ACCENT Singapore, used ACCENT, used vehicles Singapore or even buy used ACCENT Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ECICS LIMITED

7 Temasek Boulevard

#10-01 Suntec Tower One,

Singapore 038987

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6337 4779 Fax :

DEAR SIR / MADAM :

Not Notion
Resurvey B4paim
1.B1

ACCIDENT REPAIR ON: SKR4178U

MODEL : HYUNDAI ACCENT (RB)

POLICY NO : P1589678

CHASSIS NO : KMHCT51BTFU216324

YEAR OF MANUFACTURE : 2015

DATE / TIME OF ACCIDENT: 26/05/2018 Time: 1450Hrs at Along sengkang east rd twds compasspoint.

THIRD PARTY VEHICLE NO: SKD7909G

Date: 31/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			SS		SS
1	Rear bumper	1	406.40	Torn	<i>Bu</i> 406.40 ✓
2	Rear bumper side retainer LH	1	24.30	Necessary	<i>su</i> 24.30 X
3	Rear bumper side retainer RH	1	24.30	Necessary	<i>ori</i> 24.30 —
4	Rear bumper clips	12	3.00	Necessary	<i>su</i> 36.00 —
5	Rear bumper reinforcement	1	365.40	Dented	365.40 ?
6	Rear bumper reflector LH	1	53.40	To Check	<i>su</i> 53.40 X
7	Rear bumper reflector RH	1	53.40	To Check	<i>su</i> 53.40 X
8	Rear bumper centre bracket	4	12.00	Broken	48.00 ?
9	Rear license plate lamp LH	1	35.30	To Check	35.30 ?
10	Rear license plate lamp RH	1	35.30	To Check	35.30 ?
11	Rear end panel	1	499.30	Dented	499.30 ?
12	Rear end panel top garnish	1	115.10	Kinked	<i>su</i> 115.10 X
13	Rear tail lamp assy LH	1	326.50	To Check	<i>su</i> 326.50 X
14	Rear tail lamp assy RH	1	326.50	To Check	<i>su</i> 326.50 X
15	Spare tyre panel	1	433.90	Dented	<i>su</i> 433.90 X
16	Spare tyre cover board	1	198.00	Kinked	<i>su</i> 198.00 X
Sub-Total:					2,981.10
Less: 20% discount -					596.22
Total Parts after 20% discount:					2,384.88

Special Nett Items

1	Anti-rust coating	2	80.00		160.00 ?
2	Rear bumper sensor set	1	250.00		250.00 ?
3	Rear end panel sealant	1	100.00		100.00 ?
4	Spare tyre panel sealant	1	100.00		<i>su</i> 100.00 X
5	Rear license plate				610.00

B1 45su

Total Parts: 2,994.88

Labour Charges For Rear Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.

To confirm
1,250.00 ?

2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,000.00	400
3	Provide skill labour to disconnect and check electrical wiring	60.00	20
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	150.00	?
5	Provide skill labour to remove and replace bumper sensor	60.00	50
6	Provide skill labour to dismantle and fitting spare tyre to facilitate repair	80.00	x
Total Labour:		5639.88	
		Total Parts & Labour:	2,600.00
		GST 7%	5,594.88
		Grand Total:	391.64
			5,986.52

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SKR4178U

Page : 2 of 2

2 - days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
 Company : LICK
 Date : 4/6/18
 Time : 11am
 Contact No : 9691 0663
 Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

KV

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ECICS LIMITED

7 Temasek Boulevard
#10-01 Suntec Tower One,
Singapore 038987
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6337 4779 Fax :
DEAR SIR / MADAM :

*Not Whorik
Resurvey B4pain
1.B1
81580-68*

ACCIDENT REPAIR ON: SKR4178U
MODEL : HYUNDAI ACCENT (RB)
POLICY NO : P1589678
CHASSIS NO : KMHCT51BTFU216324
YEAR OF MANUFACTURE : 2015
DATE / TIME OF ACCIDENT: 26/05/2018 Time: 1450Hrs at Along sengkang east rd twds compasspoint.
THIRD PARTY VEHICLE NO: SKD7909G

Date: 31/05/2018
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Rear bumper	1	406.40	Torn	<i>Bu</i> 406.40 ✓
2 Rear bumper side retainer LH	1	24.30	Necessary	<i>in</i> 24.30 X
3 Rear bumper side retainer RH	1	24.30	Necessary	<i>diy</i> 24.30 ✓
4 Rear bumper clips	12	3.00	Necessary	<i>in</i> 36.00 ✓
5 Rear bumper reinforcement	1	365.40	Dented	<i>CM</i> 365.40 ✓
6 Rear bumper reflector LH	1	53.40	To Check	<i>in</i> 53.40 X
7 Rear bumper reflector RH	1	53.40	To Check	<i>in</i> 53.40 X
8 Rear bumper centre bracket	4	12.00	Broken	<i>R</i> 48.00 X
9 Rear license plate lamp LH	1	35.30	To Check	<i>in</i> 35.30 X
10 Rear license plate lamp RH	1	35.30	To Check	<i>in</i> 35.30 X
11 Rear end panel	1	499.30	Dented	<i>R</i> 499.30 X
12 Rear end panel top garnish	1	115.10	Kinked	<i>in</i> 115.10 X
13 Rear tail lamp assy LH	1	326.50	To Check	<i>in</i> 326.50 X
14 Rear tail lamp assy RH	1	326.50	To Check	<i>in</i> 326.50 X
15 Spare tyre panel	1	433.90	Dented	<i>R</i> 433.90 X
16 Spare tyre cover board	1	198.00	Kinked	<i>in</i> 198.00 X
				Sub-Total: 2,981.10
				Less: 20% discount - 596.22
				Total Parts after 20% discount: 2,384.88

*\$ 832.10 - 20%
= \$ 665.68*

Special Nett Items

1 Anti-rust coating	<i>2</i>	80.00		<i>in</i> 160.00 X
2 Rear bumper sensor set	1	250.00		<i>in</i> 250.00 X
3 Rear end panel sealant	1	100.00		<i>in</i> 100.00 X
4 Spare tyre panel sealant	1	100.00		<i>in</i> 100.00 X
5 Rear license plate				<i>in</i> 610.00 X
				610.00

By \$550 \$45

Total Parts: 2,994.88

Labour Charges For Rear Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.

2000
1,250.00 *Good*

- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs
- 5 Provide skill labour to remove and replace bumper sensor
- 6 Provide skill labour to dismantle and fitting spare tyre to facilitate repair

	1,000.00	400
	60.00	201
AN	150.00	X
	60.00	501
M	80.00	X
<hr/>		
	2,600.00	
	5,594.88	
	391.64	
<hr/>		
	5,986.52	

Total Labour:

\$ 870

Total Parts & Labour:

GST 7%

Grand Total:

Estimate Repair Duration

10 days

2-4 days
3 days

ACCIDENT VEHICLE OF : SKR4178U

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Part : \$ 665.68 5639.88

S/M : \$ 45.00

Labour : \$ 870.00

Total : \$ 1580.68

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
 Company : CKK
 Date : 4/8/18
 Time : 11am
 Contact No : 9691 0663
 Email : _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18009963/KVD3N2
Date: 20/07/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:			
Claimant Vehicle No :	SKR4178U	Insured Vehicle No :	SKD7909G		
Date of Loss:	26/05/2018	Nature of Claim:	TP	Claim No:	DMPC1800215H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR4178U	Engine No:	G4LCEU338253
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCT51BTFU216324
Reg. Date:	06/02/2015 (Man. Year: 2015)	Odometer:	37960 km
Colour:	Metallic Silver		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,879.88	710.68	2,169.20	75.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	870.00	1,890.00	68.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,639.88	1,580.68	4,059.20	71.97
+ GST 7.00/7.00% (S\$)	394.79	110.65	284.14	71.97
Nett Amount (S\$)	6,034.67	1,691.33	4,343.34	71.97

INSPECTION

Date of Assignment:	30/05/2018	
Date Inspected:	04/06/2018	Inspected At: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2018)
Parts: 143	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR4178U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	406.40 FL	*406.40 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	24.30 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Distorted	24.30 FL	*24.30 FL
4	12		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	365.40 FL	*365.40 FL
6	1		*REAR BUMPER REFLECTOR LH	Serviceable	53.40 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RH	Serviceable	53.40 FL	*- FL
8	4		*REAR BUMPER CENTRE BRACKET	Repair	48.00 FL	*- FL
9	1		*REAR LICENSE PLATE LAMP LH	Serviceable	35.30 FL	*- FL
10	1		*REAR LICENSE PLATE LAMP RH	Serviceable	35.30 FL	*- FL
11	1		*REAR END PANEL	Repair	499.30 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Serviceable	115.10 FL	*- FL
13	1		*REAR TAIL LAMP ASSY LH	Serviceable	326.50 FL	*- FL
14	1		*REAR TAIL LAMP ASSY RH	Serviceable	326.50 FL	*- FL
15	1		*SPARE TYRE PANEL	Repair	433.90 FL	*- FL
16	1		*SPARE TYRE COVER BOARD	Serviceable	198.00 FL	*- FL
17	1		*SET REAR BUMPER SENSOR	Serviceable	250.00 FS	*- FS
18	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
19	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*REAR LICENSE PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,476.10	877.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	596.22	166.42
Total Parts (\$\$)	2,879.88	710.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	160.00	-
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,250.00	400.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	1,000.00	400.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
5	REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	-
6	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSOR	New	60.00	50.00
7	PROVIDE SKILL LABOUR TO DISMANTLE AND FITTING SPARE TYRE TO FACILITATE REPAIR	New	80.00	-
Gross Labour Cost (\$\$)			2,760.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >