

ASS. REC. BY:

REF

es/ics18009974/Tlvd3

Special Instruction:

Surveyor:

Tau Bikh

ASSIGNMENT (Office)

From (Person):

Sanice Goh

of

ECICS

Date/Time:

31/5/18 @ 5.49pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 6679D

Insured:

SJG 9440Z

at Workshop m/s:

Vermugun Ace

Tel:

63683031

of

1 Bukit Barok Crescent # 05-23

Policy No:

Claim No:

DMPC1800195H/DL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/05/2018

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

12.32pm @ 1/6/18

Person Contacted:

pila

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF 6679D-X
	SJG 9440Z-X
8/6/18	LS \$ 2900 confirmed by email (Reel 5643.65, 6679)

DATE

Tanpin

REF:

les

ASSIGNMENT

From:

Date:

1/6/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 6679D

Yr Regn:

2016 Sep.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Sienta

C.C

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

117167

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NSP1707025 895

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

1/6/18 01715

Survey held at

Vermey

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SS&1928

RECEIVED 08 JUN 2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

8/6 - typist

Report Format :

merimen

Lump Sum / I.B.I: (\$

29000

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

350

Transportation:

\$ + RS \$

Photos

Others

10

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS/ICS18009974/T1vd3	
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 01-06-2018	
		Code : ICS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJG 9440Z	Veh. Inspected	SLF 6679D
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1800195H/DL	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	01/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/05/2018	Inspection Date	01/06/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Thursday, 31 May 2018 5:49 PM
To: pila@vermogen-group.com; assignments@lkkauto.com; Desmond Lee Ker Wen (ECICS, Operations / Claims)
Cc: 'Tejano Exequiel Dawal'; 'Baldoz Juan Paulo Bongon'; 'Edmond Lim'; 'Lina Rosli'; 'Minoko Chan'; ace@vermogen-group.com; 'Luis Tan'; 'Glorioso Eric Paul Patambang'; ECICS Claims
Subject: RE: Accident involving SLF6679D & SJG9440Z (Your Insured) on 12/05/2018 - PLEASE ARRANGE TP SURVEY ; Our ref DMPC1800195H/DL
Attachments: SLF6679D.PDF

Without Prejudice

Dear Pila

Thank you for your email.

We will appoint LKK for the PRI.

Please be advised that this case is handle by my colleague, Desmond Lee and our claim no DMPC1800195H/DL.

- Aside to LKK

Please assist to arrange TP PRI.

- Aside to Desmond

Please look into this case and revert to Pila on the liability.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: pila@vermogen-group.com [mailto:pila@vermogen-group.com]

Sent: Thursday, 31 May, 2018 5:03 PM

To: ECICS Claims

Cc: 'Tejano Exequiel Dawal'; 'Baldoz Juan Paulo Bongon'; 'Edmond Lim'; 'Lina Rosli'; 'Minoko Chan'; ace@vermogen-group.com; 'Luis Tan'; 'Glorioso Eric Paul Patambang'

Subject: Accident involving SLF6679D & SJG9440Z (Your Insured) on 12/05/2018 - PLEASE ARRANGE TP SURVEY

Dear officer in-charge,

Refer to above attachment kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** here at **6 Benoi Sector**.

VEHICLE IN WORKSHOP

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thanks & regards,

Pila

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929

follow us on  facebook follow us on  twitter visit our website  **ecics.com.sg**

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2018 15:11
Date Of Accident	12/05/2018 14:15
Exact Location Of Accident	QUEEN STREET CAR PARK NO. Q0006 GANTRY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF6679D
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995027
Cover Note Number	

Driver

Name of Driver	EE AH SIONG
NRIC No	S0603676G
Date Of Birth	23/03/1949
Occupation	OUTDOOR
Date Of Driving Pass	24/09/1966
Driving Experience	51 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180516/2104

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20180516/2104

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/05/2018 15:13		Vide Report No.:		Station Diary No.: 123	
Informant's Particulars					
Name of Informant: EE AH SIONG			Address: APT BLK 411A FERNVALE ROAD #23-76 SINGAPORE 791411		
ID Type / ID No.: NRIC NO / S0603676G			Contact No.: Home/Office: Mobile:		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 69	Date of Birth: 23/03/1949	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 12/05/2018 14:15	Type of Location: Car Park
Location: Along Road 1 QUEEN STREET				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJG9440Z	Car					0
SLF6679D	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan Pg. 3



SINGAPORE
POLICE FORCE



T/20180516/2104

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20180516/2104

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt MUHAMMAD HELMI BIN SUBAWI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/05/2018 15:13

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

Classification Of Case:

SN 085

Authentication Stamp
NP168



Signature:

Singapore Police Force



SLF6679D

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : ECICS
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 12-05-18

Vehicle Reg. No. : SLF6679D
Vehicle Reg. Date: 2-Sep-2016
Make / Model : SIENTA 1.5G CVT ABS D/A
Engine No. : 2NR8597373
Chassis No. : NSP1707025895

COST OF CLAIMS

Parts Cost / List Items : \$ 6,318.20
Plus/Less 25% \$ 1,579.55
Total Cost / List : \$ 4,738.65
Special Nett Items : \$ 985.00
Total Parts Amount : \$ 5,723.65
Total Labour Amount : \$ 2,820.00
Gross Total : \$ 8,543.65
GST % : 7% \$ 598.06
Nett Amount : \$ 9,141.71

Surveyor Name and Company :

Taufik 97445449
Date of survey : 1/6/18 @ 1715
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sure@lkkauto.com
Fax No :
HP No :

This claim is handled by : MINOKO

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF6679D**
 Vehicle Reg. Date: **02-09-16**
 Make / Model : **SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **2NR8597373**
 Chassis No. : **NSP1707025895**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	new	\$ 168.40		
2	1	Rear number plate lamp assy	X new	\$ 158.00		
3	1	Rear bumper	new	\$ 838.80		
4	1	Rear bumper cover center	new	\$ 182.40		
5	1	Rear bumper cover LH	X new	\$ 195.50		
6	1set	Rear bumper clips	new	\$ 50.00		
7	2	Rear bumper side retainer LH	? new	\$ 82.00	✓	
8	1	Rear bumper bracket LH	? new	\$ 82.00	✓	
9	1	Rear bumper sponge	? new	\$ 98.00	✓	
10	1	Rear bumper reflector LH	X new	\$ 108.00		
11	1	Rear bumper splash shield LH	X new	\$ 170.00		
12	1	Tail gate	new	\$ 1,360.00		
13	1	Tail gate lock	? new	\$ 246.60	✓	
14	1	Tail gate striker	X new	\$ 48.00		
15	2	Tail gate stay LH/RH	X new	\$ 320.00		
16	1	Tail gate logo	new	\$ 50.00		
17	1	Tail gate emblem RH	new	\$ 59.40		
18	1	Tail gate outer garnish	X new	\$ 84.50		
19	1	Tail gate weatherstrip	X new	\$ 145.00		
20	1	Tail gate lamp LH	X new	\$ 360.00		
21	1	Tail door trim	X new	\$ 280.00		
22	1	Rear end panel outer	new	\$ 498.20		
23	1	Rear end panel inner	X new	\$ 498.20		
24	1	Rear end panel garnish	X new	\$ 195.20		
25	1set	Tail door trim clips	X new	\$ 40.00		
26	1	Tail gate seal	new	new 40	\$ 80.00	
27	1	Rear end panel sealant	new	X	\$ 80.00	
28	1	Spare tyre panel sealant	new	X	\$ 80.00	
29	1	Reverse sensor	new	200?	\$ 300.00	
30	1	Rear number plate	new	X	\$ 45.00	
31	1	Reverse camera	new	X	\$ 400.00	
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLF6679D
Vehicle Reg. Date:	02-09-16
Make / Model :	SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR
Engine No. :	2NR8597373
Chassis No. :	NSP1707025895

PAGE 1

Estimates on Labour

[illegible]

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 8 June 2018 12:42 PM
To: Asher Sng (LKKAUTO); Baldoz Juan Paulo Bongon; Admin-D (LKKAUTO); Taufikh (LKKAUTO); SUR
Cc: Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Luis Tan; Paul Tan
Subject: RE: SLF6679D DOA: 12/05/2018 TO FINALISE (ECICS TP)

Dear Paulo,

WITHOUT PREJUDICE

Confirm Lump Sum @ \$2,900 before gst @ 4 working days.

Final invoice and all supporting documents sent over to ECICS

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAUTO)

Sent: Thursday, 7 June 2018 11:00 AM

To: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: RE: SLF6679D DOA: 12/05/2018 TO FINALISE (ECICS TP)

Hi Paulo,

We acknowledge your email below.

Please note that the case handler for this case is Veron.

Hi Veron / Taufikh,

FYNA. - CS/ICS18009974/T1vd3

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Thursday, 7 June 2018 10:56 AM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: SLF6679D DOA: 12/05/2018 TO FINALISE (ECICS TP)

Dear Officer in-charge,

Please check and confirm finalise COR @ \$2,900 bef gst (lump sum) 4 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064



SLF6679D

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : ECICS
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 12-05-18

Vehicle Reg. No. : SLF6679D
Vehicle Reg. Date: 2-Sep-2016
Make / Model : SIENTA 1.5G CVT ABS D/A
Engine No. : 2NR8597373
Chassis No. : NSP1707025895

COST OF CLAIMS

Parts Cost / List Items : \$ 6,318.20
Plus/Less 25% \$ 1,579.55
Total Cost / List : \$ 4,738.65
Special Nett Items : \$ 985.00
Total Parts Amount : \$ 5,723.65
Total Labour Amount : \$ 2,820.00
Gross Total : \$ 8,543.65
GST % : 7% \$ 598.06
Nett Amount : \$ 9,141.71

Surveyor Name and Company :

Taufik 97495749
Date of survey : 1/6/18 @ 1715
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@urbanform
Fax No : _____
HP No : _____

This claim is handled by : MINOKO

LS=2900

PE 3217.60
-25%
2413.20
SM = 40
L = 1210
3663.20
-20%
2930.56

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF6679D
 Vehicle Reg. Date: 02-09-16
 Make / Model : SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR
 Engine No. : 2NR8597373
 Chassis No. : NSP1707025895

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	new	\$ 168.40		
2	1	Rear number plate lamp assy	X	\$ 158.00		
3	1	Rear bumper	new	\$ 838.80		
4	1	Rear bumper cover center	new	\$ 182.40		
5	1	Rear bumper cover LH	X	\$ 195.50		
6	1set	Rear bumper clips	new	\$ 50.00		
7	1	Rear bumper side retainer LH	?	\$ 82.00	*	
8	1	Rear bumper bracket LH	?	\$ 82.00	*	
9	1	Rear bumper sponge	?	\$ 98.00	*	
10	1	Rear bumper reflector LH	X	\$ 108.00		
11	1	Rear bumper splash shield LH	X	\$ 170.00		
12	1	Tail gate	new	\$ 1,360.00		
13	1	Tail gate lock	?	\$ 246.60	*	
14	1	Tail gate striker	X	\$ 48.00		
15	2	Tail gate stay LH/RH	X	\$ 320.00		
16	1	Tail gate logo	new	\$ 50.00		
17	1	Tail gate emblem RH	new	\$ 59.40		
18	1	Tail gate outer garnish	X	\$ 84.50		
19	1	Tail gate weatherstrip	X	\$ 145.00		
20	1	Tail gate lamp LH	X	\$ 360.00		
21	1	Tail door trim	X	\$ 280.00		
22	1	Rear end panel outer	By	\$ 498.20		
23	1	Rear end panel inner	X	\$ 498.20		
24	1	Rear end panel garnish	X	\$ 195.20		
25	1set	Tail door trim clips	X	\$ 40.00		
26	1	Tail gate seal	new	new 40	\$ 80.00	
27	1	Rear end panel sealant	X	\$ 80.00		
28	1	Spare tyre panel sealant	X	\$ 80.00		
29	1	Reverse sensor	X	200 ?	\$ 300.00	
30	1	Rear number plate	X	\$ 45.00		
31	1	Reverse camera	X	\$ 400.00		
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

P = 3217.60

SH = 40

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]
$$L = 1210$$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2018 17:38 Edit Reg		31 May 2018 00:00 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: email@yahoo.com		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLF6679D	Date of Loss:	12/05/2018 14:00 - :59 [20 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SJG9440Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Vermogen Ace Pte Ltd (Bukit Batok) 1 Bukit Batok Crescent, #04-54, 658064 Bukit Batok - Tel:		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF6679D
[SJG9440Z]
TP
LCRF PTE LTD
May 12 2018 2:00PM
[-]
Vermogen Ace Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 11:05	General View	Load JPG	
2	07/06/18 11:05	General View	Load JPG	
3	07/06/18 11:05	General View	Load JPG	
4	07/06/18 11:05	General View	Load JPG	
5	07/06/18 11:05	General View	Load JPG	
6	07/06/18 11:05	General View	Load JPG	
7	07/06/18 11:05	General View	Load JPG	
8	07/06/18 11:05	General View	Load JPG	
9	07/06/18 11:05	General View	Load JPG	
10	07/06/18 11:05	General View	Load JPG	
11	07/06/18 11:05	General View	Load JPG	
12	07/06/18 11:05	General View	Load JPG	
13	07/06/18 11:05	General View	Load JPG	
14	07/06/18 11:05	General View	Load JPG	
15	07/06/18 11:05	General View	Load JPG	
16	07/06/18 11:05	General View	Load JPG	
17	07/06/18 11:06	General View	Load JPG	
18	07/06/18 11:06	General View	Load JPG	
19	07/06/18 11:06	General View	Load JPG	
20	07/06/18 11:06	General View	Load JPG	
21	07/06/18 11:06	General View	Load JPG	
22	07/06/18 11:06	General View	Load JPG	
23	07/06/18 11:06	General View	Load JPG	
24	07/06/18 11:06	General View	Load JPG	
25	07/06/18 11:06	General View	Load JPG	
26	07/06/18 11:06	Reinspection Photo	Load JPG	
27	07/06/18 11:06	Reinspection Photo	Load JPG	
28	07/06/18 11:06	Reinspection Photo	Load JPG	
29	07/06/18 11:06	Reinspection Photo	Load JPG	
30	07/06/18 11:06	Reinspection Photo	Load JPG	
31	07/06/18 11:06	Reinspection Photo	Load JPG	
32	07/06/18 11:06	Reinspection Photo	Load JPG	
33	07/06/18 11:06	Reinspection Photo	Load JPG	
34	07/06/18 11:06	Reinspection Photo	Load JPG	
35	07/06/18 11:06	Reinspection Photo	Load JPG	

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
37	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
38	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
39	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
40	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
41	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
42	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
43	07/06/18 11:06	Reinspection Photo	 Load JPG	☒
44	07/06/18 11:06	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18009974/T1VD3S2
 Date: 11/06/2018

REFERENCE

Handling Insurer: ECICS Limited Policy No:
 Claimant Vehicle No: SLF6679D Insured Vehicle No: SJG9440Z
 Date of Loss: 12/05/2018 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF6679D Engine No: 2NR8597373
 Make & Model: TOYOTA SIENTA, 1.5 (A) Chassis No: NSP1707025895
 Reg. Date: 02/09/2016 (Man. Year: 2016) Odometer: 117167 km
 Colour: Blue
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R13 Rear Tyre Size: 185/60R13
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,303.20	2,453.20	4,850.00	66.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,210.00	1,610.00	57.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,123.20	3,663.20	6,460.00	63.81
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	10,123.20	2,900.00	7,223.20	71.35
+ GST 7.00/7.00% (S\$)	708.62	203.00	505.62	71.35
Nett Amount (S\$)	10,831.82	3,103.00	7,728.82	71.35

INSPECTION

Date of Assignment: 31/05/2018
 Date Inspected: 01/06/2018 Inspected At: Vermogen Ace Pte Ltd (Bukit Batok)
 1 Bukit Batok Crescent, #04-54
 Singapore 658064
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=713712&extid=273953&CFID=35252898&CFTOKEN=3

6/11/2018

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2018)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF6679D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	168.40 F	*168.40 FL
2	1		*REAR NUMBER PLATE LAMP ASSY	Not Necessary	158.00 F	*- FL
3	1		*REAR BUMPER	Deformed	838.80 F	*838.80 FL
4	1		*REAR BUMPER COVER CENTER	Cut	182.40 F	*182.40 FL
5	1		*REAR BUMPER COVER LH	Not Necessary	195.50 F	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	2		*REAR BUMPER SIDE RETAINER LH	Deformed	82.00 F	*82.00 FL
8	1		*REAR BUMPER BRACKET LH	Deformed	82.00 F	*82.00 FL
9	1		*REAR BUMPER SPONGE	Deformed	98.00 F	*98.00 FL
10	1		*REAR BUMPER REFLECTOR LH	Not Necessary	108.00 F	*- FL
11	1		*REAR BUMPER SPLASH SHIELD LH	Not Necessary	170.00 F	*- FL
12	1		*TAIL GATE	Bent	1,360.00 F	*1,360.00 FL
13	1		*TAIL GATE LOCK	Bent	246.60 F	*246.60 FL
14	1		*TAIL GATE STRIKER	Not Necessary	48.00 F	*- FL
15	2		*TAIL GATE STAY LH/RH	Not Necessary	320.00 F	*- FL
16	1		*TAIL GATE LOGO	Necessary	50.00 F	*50.00 FL
17	1		*TAIL GATE EMBLEM RH	Necessary	59.40 F	*59.40 FL
18	1		*TAIL GATE OUTER GARNISH	Not Necessary	84.50 F	*- FL
19	1		*TAIL GATE WEATHERSTRIP	Not Necessary	145.00 F	*- FL
20	1		*TAIL GATE LAMP LH	Not Necessary	360.00 F	*- FL
21	1		*TAIL DOOR TRIM	Not Necessary	280.00 F	*- FL
22	1		*REAR END PANEL OUTER	Not Necessary	498.20 F	*- FL
23	1		*REAR END PANEL INNER	Not Necessary	498.20 F	*- FL
24	1		*REAR END PANEL GARNISH	Not Necessary	195.20 F	*- FL
25	1		*SET TAIL DOOR TRIM CLIPS	Not Necessary	40.00 F	*- FL
26	1		*TAIL GATE SEAL	Necessary	80.00 FS	*40.00 FS
27	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
30	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
31	1		*REVERSE CAMERA	Not Necessary	400.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	7,303.20	3,257.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	804.40
Total Parts (\$\$)	7,303.20	2,453.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA.	New	1,200.00	500.00
2	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.	New	100.00	30.00
3	TO REMOVE AND REPLACE REVERSE SENSOR.	New	100.00	30.00
4	TO REMOVE AND REFIT INNER TRIM, INNER SEAT, TRIM BOARD, TO ASSIST REPAIR.	New	120.00	60.00
5	TO RUSTPROOF ACCIDENT REPAIR AREA.	New	150.00	30.00
6	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.	New	150.00	60.00
7	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA.	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,820.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >