

Signature: *Pass*

REF: NS/TNC18009992/R1Vbn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SJT 444J
 Policy No: 5070965400 2005H - 210918
 Claims No: MT/0996644-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 6318D Yr Regn: 2016 / Insy
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Car / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA PRIUS C.C. 1718
 Colour: MARON A/C: Insured / Std / NI / NA
 Sp. Reading: 175585 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN35U205768469
 Gen. Cond: Good / B / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / B Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or ACHILLES
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 30/05/18 D.O.I. 31/05/18
 Survey held at SMART
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
SHD 6318D - NS/TNC1703805/R1Vbn2
SJT 444J - X

DUR: 11/247

05/18/2138

NTAC

21/6/18 LS \$ 1300 confirmed by email (Ref 4225.78, 769)

SJT 444J

RECEIVED 28 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

☐ S + RS \$

☐ Photos

☐ Others

TOTAL

1) _____
 Date/Time, File Return to?

Report Format :

Lump Sum / I.B.I. (\$) TP

1300 1/2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

160
35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18009992/R1vb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-06-2018



189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 494J	Veh. Inspected	SHD 6318D
Policy No.	5090965400	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/05/2018	Inspection Date	31/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0999759-002	COMFORT TRANSPORTATION	SH 8667G	GBF 8998M	22/06/2018	\$ 8,936.54	\$ 1,500.00
2	MT/0996644-002	SMRT TAXIS PTE LTD	SHD 6318D	SJT 494J	30/05/2018	\$ 5,525.78	\$ 1,609.91
3	MT/1000328-002	CITYCAB	SHC 7948J	SKH 7443L	24/06/2018	\$ 5,794.76	\$ 2,700.00
4	MT/0999772-002	COMFORT TRANSPORTATION	SHA 2661D	SIF 8419A	22/06/2018	\$ 2,161.78	\$ 1,014.11

Claim received from LKK Auto

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="30/05/2018 14:50"/>						
Vehicle No. (For Motor)	<input type="text" value="SJT494"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5090965400	CHONG WEI CONG	58816302H	GPC	drive CLASSIC	SJT494J	SJT494J	20/05/2017	21/09/2018
<input type="button" value="Continue"/>									

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 27 June 2018 6:06 PM
To: Veron Chen (LKKAUTO)
Subject: RE: SHD6318D
Attachments: img-627175405-0001.pdf

Hi

Amount confirmed as per your recommendation, revised estimate was attached for your reference. Thanks.

Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 27 June 2018 4:22 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHD6318D

Dear Poh Suan,

WITHOUT PREJUDICE

Offer Lump Sum \$1300 @ 3 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Wednesday, 27 June 2018 1:23 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SHD6318D

Hi Rasul,

Due to Wega unable to provide the before paint photos, I will submit this case as lump sum repair.

Thanks & Regards
Poh Suan

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Wednesday, 27 June 2018 10:43 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team; Veron Chen (LKKAUTO)
Subject: RE: SHD6318D

Hi Poh Suan,

Kindly assist

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 19 June, 2018 2:33 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHD6318D

Dear Poh Suan,

Please forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 19 June 2018 1:28 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHD6318D

Hi Rasul,

Attached herewith the repair estimate of SHD 6318D having Case No: TAX/05/18/2138.

There is no change to the approved amount of \$1,609.91 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Tuesday, 19 June 2018 1:29 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2018 09:59
Date Of Accident	30/05/2018 22:35
Exact Location Of Accident	ALEXANDRA ROAD TOWARDS TELOK BLANGAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6318D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	CHONG ZHI HOU (ZHANG ZHHAO)
NRIC No	S8470401F
Date Of Birth	09/09/1984
Occupation	OUTDOOR
Date Of Driving Pass	29/05/2004
Driving Experience	14 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG ALEXANDRA ROAD AT THE RIGHT MOST LANE WHEN THE VEHICLE SJT494J FROM MY LEFT LANE ABRUPTLY CUT INTO MY LANE AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE TOO LARGE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJT494J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHONG WEI CHONG

NRIC/Passport Number

S8816302H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Chin

Driver's Signature
(If driver is not the policyholder)
Date & Time:

du 31/5/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES

DECLARATION.

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHD6318D

Vehicle to be Exported: No

Intended De-registration Date: 04 Jun 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2015

Engine No.: 22R6608727

Chassis No.: JTDKN36U905768469

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$29,508.00

Original Registration Date: 27 Jul 2016

First Registration Date: 27 Jul 2016

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Jul 2024

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 26 Jul 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$39,616.00

COE Rebate Amount: \$30,417.00

Total Rebate Amount: \$34,167.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jun 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6318D
 Ref. No : TAX/05/18/2138
 Reg. Date : 27/07/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHONG ZHI HOU (ZHANG ZIHAO)
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 30/05/2018 10:35:00 PM
 Accident Reported Date / Time : 31/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 30/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096351
 Special Instruction to ARC, if any :
 TOWED \$40 / SGT494J - NTUC IDAC *Resurvey by paint*
 Prepared Date : 31/05/2018 10:18:37 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905768469


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 2,368.93	2,368.93
Other Charges	: 684.44	0.00
TOTAL	: 4,834.37	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00 3 days - p/p
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 31/05/2018 11:58:28 AM	01/01/1900 12:00:00 AM


31/05/18 R1415
6/6/18

Prepared / Adjusted Date :

Remarks :

Prepared Date : 31/05/2018 11:58:13 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 5/31/2018 1:01:34 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	845.00	0.00 300
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 X 7.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 m- 148.44
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	684.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>Repair</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>X</i>	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>PA</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>nu</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>X</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>X</i>	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>Repair</i>	No
TOTAL MATERIALS								2,368.94	2,368.93	
TOTAL MATERIALS(Discounted)								2,368.93	2,368.93	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



2-6-18/15:52

APV: 4-6-18/10:52

4-6-18/14:52

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

31-5-18/14:52

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6318D
 Ref. No : TAX/05/18/2138
 Reg. Date : 27/07/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHONG ZHI HOU (ZHANG ZHIAO)
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 30/05/2018 10:35:00 PM
 Accident Reported Date / Time : 31/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Rasul
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 30/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096351
 Special Instruction to ARC, if any :
 TOWED \$40 / SJT494J - NTUC IDAC
 Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com
 Prepared Date : 31/05/2018 10:18:37 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒
1st witness

Date 31-5-18

2nd witness

Date

E 0 1/2 F
 KM 175585

Vehicle to Wega Date In: 31/5 Towing: _____
 Time In: 1700 Driver: PCH
 Wega Job No: 05/0842
 Vehicle sent to SMRT Date In: 2/6/18 Towing: _____
 Time In: 1045 Driver: Chien
 Received by (SMRT): _____

QC 2/6/18 11.10 PAS

Section B - To be Completed by Service Advisor, Accident Repair Centre



Chassis No : JTDKN36U905768469

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	300.00
Total Spray Painting Charges	: 936.00	450.00
Total Material Charges	: 581.47	581.47
Other Charges	: 628.44	-31.47
TOTAL	: 2,990.91 <i>5525.78</i>	1,300.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 31/05/2018 11:58:28 AM	31/05/2018 02:52:50 PM
		

Prepared / Adjusted Date :

Remarks :

Prepared Date : 31/05/2018 11:58:13 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : *QN-1806-0378* Invoice No : *IV180600568*
Quotation Date : *18/6* Invoice Date : *27/6*
Invoice Amount : 0.00 Prepared Date : 5/31/2018 1:01:34 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	845.00	300.00
Total Labour	845.00	300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY RIM	180.00	50.00
Total Spray Painting & Panel Beating	936.00	450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148.44 NEC
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-309.91
Total Other Costs	628.44	-31.47

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	R ¹	482.00	100.00	0.00	Replace	Repair	No R
52116-47040		6505516	BUMPER SUPPORT F/LH SVC	X ⁰	76.40	25.00	0.00	Replace	Not given	No X
53802-47050		6505558	FENDER FRT/LH BT	✓ ¹	723.40	25.00	542.55	Replace	Replace	No ✓
75374-47051			NAME PLATE (HYBRID) NEC	✓ ¹	51.90	25.00	38.92	Replace	Replace	No ✓
53876-47030		6505554	FENDER LINER FRT/LH SVC	X ⁰	171.70	25.00	0.00	Replace	Not given	No X
		6503707	TYRE SVC	X ⁰	126.74	0.00	0.00	Replace	Not given	No X
42611-47140 (Frt)		6505658	WHEEL DISC FRONT	R ¹	1,484.20	100.00	0.00	Replace	Repair	No R
TOTAL MATERIALS							581.48	581.47		
TOTAL MATERIALS(Discounted)							581.47	581.47		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

581.47
 + 300.00
 + 728.44

 1609.91
 - 202

 1287.93
 US \$1300/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18009992/R1vbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-07-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 494J	Veh. Inspected	SHD 6318D
Policy No.	5090965400	Coverage (\$)	0.00
Claim No.	MT/0996644-002	Excess (\$)	0.00
Assign From		Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U905768469	Colour	MAROON
Odometer	175585	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	ACHILLES	5 mm
L/H Front Tyre	195/65 R15	ACHILLES	5 mm
R/H Rear Tyre	195/65 R15	ACHILLES	5 mm
L/H Rear Tyre	195/65 R15	ACHILLES	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/05/2018	Inspection Date	31/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6318D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER FRT/LH (DISC 25%)	BENT	723.40	542.55
1	NAME PLATE (HYBRID)(DISC 25%)	NECESSARY	51.90	38.92
1	ADVERTISEMENT STICKER (SN)	NECESSARY	148.44	148.44
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	FENDER LINER FRT/LH	SERVICEABLE	171.70	-
1	TYRE	SERVICEABLE	126.74	-
1	BUMPER FRT	TO REPAIR	482.00	-
1	WHEEL DISC,FRONT	TO REPAIR	1,484.20	-
			3,264.78	729.91
LABOUR				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			1,165.00	390.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			1,036.00	490.00
TO WASH AND VACUUM.			60.00	-
			2,261.00	880.00
GRAND TOTAL			5,525.78	1,609.91
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,300.00

Report Ref No. NS/INC18009992/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.