

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒好噴漆
代理保險：車禍
賠償及買賣汽車

TPAXA.

Xiao Tony.

MS LYNETTE CHONG HUI FONG

DATE: 31/05/2018

DOA: 24/05/2018

ESTIMATE REPAIR FOR VEHICLE NO. SKZ 2030 H (HYUNDAI ACCENT)

	Description	List Price
1 pc	Rear bumper <i>del</i>	\$ 460.00 ✓
1 pc	Rear bumper reinforcement <i>del</i>	\$ 388.50 ✓
1 pc	Bumper bracket <i>net m</i>	\$ 98.80 ✓
2 pcs	Bumper side retainer @S\$38.00 <i>net m</i>	\$ 76.00 ✓
	924.5	\$ 1,023.30
	Less : 20%	\$ (204.66)
	739.60	\$ 818.64
	Special Nett Items	
1 set	Reverse sensor <i>net m</i>	\$ 280.00 ✗
	To remove & fix reverse sensor	\$ 80.00 40
	To spray anti-rust	\$ 80.00 ✗
	Labour charges for knocking & replacing parts.	\$ 500.00 300
	Spraypainting	\$ 550.00 400
	740	TOTAL : \$ 2,308.64

Adrian hiny
P/P 04/06/18.

03 Days

total: 1479.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: