



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 30.05.2018

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01/02

AXA Tower

Singapore 068811

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjun 97495749

WP 1/6/18 @ 1730

6 days

Resurvey after repair
sur @ 1/6/18 @ 1730

RE: ESTIMATE COST OF REPAIR TO SHD2164G TOYOTA AXIO HYBRID

To Supply

1) 1pc	rear bumper	\$ de 700.00
2) 1set	rear bumper clip	\$ net 30.00
3) 1pc	rear bumper left side retainer	\$ net 60.00
5) 1pc	rear bumper left reflector	\$? 94.00
6) 1pc	left tail lamp lower bracket	\$ net 70.00
7) 1pc	left tail lamp	\$ car 450.00
8) 1pc	left tail lamp housing	\$ Ry 285.60
9) 1pc	rear boot lid	\$ bt 680.00
10) 1pc	rear boot lid lock	\$? 90.00
11) 1pc	rear boot lid catch	\$ x 50.00
12) 1pc	rear boot lid "corolla" emblem	\$ net 59.60
13) 1pc	rear boot lid "Hybrid Synergy Drive" emblem	\$ net 61.70
14) 1pc	rear boot lid "Axio" emblem	\$ net 48.60
15) 1pc	rear boot lid weatherstrip	\$ net 120.00
16) 2pcs	rear boot lid hinges	\$ Ry 315.20
17) 1pc	rear boot lid trim board	\$ x 180.00
18) 1pc	spare wheel cushion	\$ x 120.00
19) 1pc	rear floor panel	\$ Ry 1,187.00
20) 1pc	rear end panel	\$ bt 380.00
21) 1pc	rear end panel top garnish	\$ de 180.00
22) 1set	rear end panel top garnish clip	\$ net 20.00
23) 1pc	left rear fender assy	\$ Ry 885.80

@ \$157.60

24) 1pc left rear fender mudflap

\$ ~~de~~ 72.60

Sub total Parts \$ 6,140.10

Less: 25% discount \$ (1,535.02)

\$ 4,605.08

To supply S.Nett Parts

1) 1set floor panel sealant

\$ ~~X~~ 200.00

2) 1pc "Prime Taxi" sticker

\$ ~~un~~ 55.00

3) 2pcs "Dial-A-Cab" sticker

@ \$45.00

\$ ~~un~~ 90.00

Sub total S.Nett Parts \$ 345.00

L/charges

1) Towing charges (use king trolley)

\$ ~~✓~~ 80.00

2) To transfer rear boot lid trim board, mechanism parts

\$ ~~60~~ 80.00

3) To tuff kote rear portion

\$ ~~30~~ 150.00

4) To remove fuel tank to facilitate the repair

\$ ~~X~~ 100.00

5) To remove rear bumper, cut / welding rear end panel, floor panel, left rear fender, replace rear boot lid, rear bumper, left tail lamp. Align rear boot lid, rear bumper, left rear fender & etc

\$ ~~700~~ 1,400.00

6) To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel, floor panel & left rear fender. To polish

\$ ~~800~~ 1,400.00

Sub total L/charges \$ 3,210.00

Estimated total \$ 8,160.08