

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63637168 / 63837466 Fax: 62815767

Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No : SGY6828A
Make & Model : Honda civic ima 1.5lcv

Case Owner	:	<u>PATRICK</u>
Year of Manufacture	:	2014

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

3/2/18

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SGY6828A Case Owner : PATRICK

Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014

Chassis No : JHMFB4620CS200273 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRT NUMBER PLATE W/CASING	1				\$45.00	
2	FRT BUMPER	1	\$180.00	/	/		
3	FRT BUMPER SIDE RETAINER RH	1	\$8.00	/			
4	FRT BUMPER SIDE RETAINER LH	1	\$8.00	/			
5	FRT BUMPER LOWER CENTER GRILLE	1	\$40.00	/	/		
6	FRT RADIATOR GRILLE	1	\$130.00	/	/		
7	FRT RADIATOR GRILLE LOGO	1	\$17.00	/			
8	FRT BUMPER REINFORCEMENT	1	\$190.00	/	/		
9	FRT BUMPER SPONGE	2	NA				
10	FRT BUMPER CLIP	8	\$16.00	/	/		
11	FRT SUPPORT PANEL	1	\$270.00				
12	BRACE PANEL	1	w11				
13	RH HEADLAMP PANEL	4	w11				
14	LH HEADLAMP PANEL	1	w11				
15	FRT SUPPORT PANEL TOP COVER	1	\$14.00				
16	FRT SUPPORT PANEL TOP COVER CLIP	8	\$16.00	/			
17	RH HEADLAMP	1	\$500.00	/			
18	LH HEADLAMP	1	\$500.00	/	/		
19	AIRCON CONDENSOR	1	\$380.00	/	/		
20	RADIATOR	1	\$500.00				
21	COOLANT	1	\$22.00				
22	BONNET	1	\$300.00	/	/		
23	BONNET LOCK	1	\$50.00				
24	BONNET INSULATOR	1	\$60.00				
25	BONNET INSULATOR CLIP	12	\$24.00				
26	REAR BUMPER	1	\$350.00	/	/		
27	REAR BUMPER STAY RH	1	\$29.00	/	/		
28	REAR BUMPER STAY LH	1	\$29.00	/	/		
29	REAR BUMPER REINFORCEMENT	1	\$130.00	/	/		
30	REAR BUMPER CLIP	8	\$16.00	/	/		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2839

SN 45

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SGY6828A Case Owner : PATRICK

Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014

Chassis No : JHMFB4620CS200273 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	REAR BUMPER SIDE RETAINER RH	1	\$12.00	/	/		
32	REAR BUMPER SIDE RETAINER LH	1	\$12.00	/	/		
33	REVERSE SENSOR	1	\$120.00	/			
34	REAR END PANEL	1	\$230.00	/	/		
35	REAR END PANEL TOP COVER	1	\$30.00	/	/		
36	TAILLAMP PANEL LH	1	\$65.00				
37	TAILLAMP PANEL RH	1	\$65.00				
38	TAILLAMP LH	1	\$350.00				
39	TAILLAMP H RH	1	\$350.00	/	/		
40	REAR BOOTLID WEATHER STRIP	1	\$40.00	/			
41	BOOTLID	1	\$430.00	/	/		
42	BOOTLID REFLECTOR RH	1	\$150.00				
43	BOOTLID REFLECTOR LH	1	\$150.00	/			
44	BOOTLID LOCK	1	\$45.00	/			
45	REAR NUMBER PLATE W/CASING	1				\$45.00	/
46	REAR CIVIC EMBLEM	1	\$20.00	/			
47	BOOTLID LOGO	1	\$19.00	/			
48	REAR HYBRID BADGE	1	\$32.00	/			
49	BOOTLID INSULATOR	1	\$100.00	/			
50	REAR LH FENDER	1	\$540.00	/			
51	REAR WINDSCREEN GLASS MOULDING	1	\$60.00	/			
52	REAR W/S SEALANT	2				\$40.00	/
53	REAR W/S INNER SEAL	1				\$30.00	/
54		0					
55		0					
56		0					
57		0					
58		0					
59		0					
60		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2050

SN 115

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SGY6828A Case Owner : PATRICK

Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014

Chassis No : JHMF4620CS200273 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : IP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Reverse sensor cover	1	25.00	Agree	5/7		
2	Rear end panel top garnish center cover	1	30.00	Agree	5/7		
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

65