

15/5/2010

INS. CASE OWNER:

Stacy

CC 4/ASM 180

10005

Ti Kasor

LKK:

IDAC:

49065

Surveyor:

TAMIKH

DOI:

12/06/18

Date / Time:

1/6/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHX 3035 X

Name of Insured:

Blagden Seth Jago

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

27/05/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

U MANU

Driver Tel No.:

96757258

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHX 3035 X

SHX 6828 A

SHX 5124 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kham
SPARKS
76

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/6/18

SHX 6828 A - X; SHX 3035 X - X
- Please check consistency.

12/06/18

- Plus required. Old involved in a 3
veh. c.o. & was the last car.
- Small liability check
- Total loss (unconventional to repair)

19/06/18

- Type total loss report for workshop
- TP changed workshop. SPARKS BRADU

20/06/18

- Small marked evidence to TP.
- TO PINKIE DOOR.

9/7/19

* Proposed Settlement sent to w/s
Anding agree acceptance.

18/7/19

* offer accepted *, send DV

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

14/06/18

Sent By:

03

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

7800

(12 days)

Reduction:

42

%

Email

Call

FINAL SETTLEMENT

Date/Time:

18/7/19

Confirm with

16/11/19

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

SS

8,346.00

Loss of Rental (LOR):

SS

-

(12 days)

1360

Loss of Use (LOU):

SS

1020

(\$ 60 x 17 days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

9366.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

9,366.00

Name 1:

Comfort Belgro Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1350 - \$350

COPY SENT
22/7/19

Tangshan

REF:

AXIA

10005/711603

W.

ASSIGNMENT

SGY 6828A

214 Jan.

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 461K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12. days Res: Yes or No

Lum Sum: 20. % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____ Yr Regn: _____
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic 1.4T C.C. 1497

Colour: 4442 A/C Insured / Std / NI / NA

Sp Reading Silver T/Radio: Insured / Std / NI / NA

Eng/No: JHMF4620CS200273

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 12/6/18

Survey held at: Kah Mohr Khondor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction

Repair Unit \$1K, not economical to repair
CHASIS WORKSHOP - CIGGS SPECIAL CAR CARE

US \$ 78W Cred \$ 5578 by 424.

12 + 2 Sum + 1 PH + 1 PRS = 16 days

MV: \$ 61,000.00 (Gest)
LTH: \$ 19,400.00 (Gest)
Nett: \$ 11,500.00 (Gest)

Date/Time: File Pass to?

☐

: Prefi. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. \$ + P.S. \$

2. Photos

3. Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Inter./Sv (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010005/ha3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 03-06-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGX 3035X	Veh. Inspected	SGY 6828A	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00IRY	Excess (\$)	0.00	
Assign From		Assign Date	03/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/05/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SGY6828AMake & Model : Honda civic ima 1.5lcvYear of Manufacture : 2014Chassis No. : JHMF84620CS200273Ins Company : SOMPO VS AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : DOA27/05/18

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : PATRICK

Signature : _____

Contact No

Parts (a) Cost / List Price Items \$6,599.00Plus/Less 15% \$989.85Total of Cost / List \$7,588.85(b) Nett Price Items \$-

Less _____

Total of Nett Item _____

(c) Special Nett Items \$160.00Total Parts Cost (Appendix A) \$7,748.85Labour (Appendix B) \$5,630.00Total Repair Cost \$13,378.85

63837466 – Patrick

patrickia@sparkcarcare.com

63838115 – WILLIAM

63837656 - Ngo

ngotw@cdge.com.sg

63837730 – Brenda Ng

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Tan JiaCompany : CDG

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair 12 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature]Date: 28/6/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SGY6828A Case Owner : PATRICK

Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014

Chassis No : JHMFBA620CS200273 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : IP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRT NUMBER PLATE W/CASING <i>de/</i>	1				\$45.00	
2	FRT BUMPER <i>de/</i>	1	\$180.00				
3	FRT BUMPER SIDE RETAINER RH <i>nei</i>	1	\$8.00				
4	FRT BUMPER SIDE RETAINER LH <i>nei</i>	1	\$8.00				
5	FRT BUMPER LOWER CENTER GRILLE <i>de/</i>	1	\$40.00				
6	FRT RADIATOR GRILLE <i>ant</i>	1	\$130.00				
7	FRT RADIATOR GRILLE LOGO <i>nei</i>	1	\$17.00				
8	FRT BUMPER REINFORCEMENT <i>bt/?</i>	1	\$190.00				
9	FRT BUMPER SPONGE <i>un 2</i>	2	NA				
10	FRT BUMPER CLIP <i>nei</i>	8	\$16.00				
11	FRT SUPPORT PANEL <i>Rx</i>	1	\$270.00	X			
12	BRACE PANEL <i>nei</i>	1	w11	X			
13	RH HEADLAMP PANEL <i>Rx</i>	4	w11	X			
14	LH HEADLAMP PANEL <i>Rx</i>	1	w11	X			
15	FRT SUPPORT PANEL TOP COVER <i>Xm</i>	1	\$14.00	X			
16	FRT SUPPORT PANEL TOP COVER CLIP <i>nei</i>	8	\$16.00				
17	RH HEADLAMP <i>ant/?</i>	1	\$500.00				
18	LH HEADLAMP <i>ant/?</i>	1	\$500.00				
19	AIRCON CONDENSOR <i>bt/?</i>	1	\$380.00				
20	RADIATOR <i>un 2</i>	1	\$500.00	X			
21	COOLANT <i>un 2</i>	1	\$22.00	X			
22	BONNET <i>bt</i>	1	\$300.00				
23	BONNET LOCK <i>nei</i>	1	\$50.00				
24	BONNET INSULATOR <i>nei</i>	1	\$60.00	X			
25	BONNET INSULATOR CLIP <i>Rx</i>	12	\$24.00	X			
26	REAR BUMPER <i>de/</i>	1	\$350.00				
27	REAR BUMPER STAY RH <i>nei</i>	1	\$29.00				
28	REAR BUMPER STAY LH <i>nei</i>	1	\$29.00				
29	REAR BUMPER REINFORCEMENT <i>bt/?</i>	1	\$130.00				
30	REAR BUMPER CLIP <i>nei</i>	8	\$16.00				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SGY6828A Case Owner : PATRICK
Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014
Chassis No : JHMFB4620CS200273 Engine No : 0
Sales Order : 0 Supplier : 0
Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	REAR BUMPER SIDE RETAINER RH <i>neu</i>	1	\$12.00				
32	REAR BUMPER SIDE RETAINER LH <i>neu</i>	1	\$12.00				
33	REVERSE SENSOR <i>neu</i>	1	\$120.00				
34	REAR END PANEL <i>bt</i>	1	\$230.00				
35	REAR END PANEL TOP COVER <i>del</i>	1	\$30.00				
36	TAILLAMP PANEL LH <i>RP</i>	1	\$65.00				
37	TAILLAMP PANEL RH <i>RP</i>	1	\$65.00				
38	TAILLAMP LH <i>SVC</i>	1	\$350.00				
39	TAILLAMP RH <i>CR</i>	1	\$350.00				
40	REAR BOOTLID WEATHER STRIP <i>neu</i>	1	\$40.00				
41	BOOTLID <i>bt</i>	1	\$430.00				
42	BOOTLID REFLECTOR RH <i>neu</i>	1	\$150.00				
43	BOOTLID REFLECTOR LH <i>CR</i>	1	\$150.00				
44	BOOTLID LOCK <i>bt</i>	1	\$45.00				
45	REAR NUMBER PLATE W/CASING <i>del</i>	1				\$45.00	
46	REAR CIVIC EMBLEM <i>neu</i>	1	\$20.00				
47	BOOTLID LOGO <i>neu</i>	1	\$19.00				
48	REAR HYBRID BADGE <i>neu</i>	1	\$32.00				
49	BOOTLID INSULATOR <i>neu</i>	1	\$100.00				
50	REAR LH FENDER <i>bt</i>	1	\$540.00				
51	REAR WINDSCREEN GLASS MOULDING <i>neu</i>	1	\$60.00				
52	REAR W/S SEALANT <i>neu</i>	2				\$40.00	
53	REAR W/S INNER SEAL <i>neu</i>	1				\$30.00	
54		0					
55		0					
56		0					
57		0					
58		0					
59		0					
60		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

*Parts 4884
supp 65*

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. :	<u>SGY6828A</u>	Case Owner :	<u>PATRICK</u>
Make & Model :	<u>Honda civic ima 1.5lcvt</u>	Year of Manufacture :	<u>2014</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SGY6828A Case Owner : PATRICK

Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014

Chassis No : JHMFB4620CS200273 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Reverse sensor cover	1	35.00	Agro	5/7	de	
2	Rear end panel top garnish center cover	1	30.00	Agro	5/7	de	
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
 ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SGY6828A Case Owner : PATRICK
 Make & Model : Honda civic ima 1.5lcv Year Manufacture : 2014
 Chassis No : JHMFB4620CS200273 Engine No : 0
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRT NUMBER PLATE W/CASING	1				\$45.00	
2	FRT BUMPER	1	\$180.00	/	/		
3	FRT BUMPER SIDE RETAINER RH	1	\$8.00	/			
4	FRT BUMPER SIDE RETAINER LH	1	\$8.00	/			
5	FRT BUMPER LOWER CENTER GRILLE	1	\$40.00	/	/		
6	FRT RADIATOR GRILLE	1	\$130.00	/	/		
7	FRT RADIATOR GRILLE LOGO	1	\$17.00	/			
8	FRT BUMPER REINFORCEMENT	1	\$190.00	/	/		
9	FRT BUMPER SPONGE	2	NA				
10	FRT BUMPER CLIP	8	\$16.00	/	/		
11	FRT SUPPORT PANEL	1	\$270.00				
12	BRACE PANEL	1	w11				
13	RH HEADLAMP PANEL	4	w11				
14	LH HEADLAMP PANEL	1	w11				
15	FRT SUPPORT PANEL TOP COVER	1	\$14.00				
16	FRT SUPPORT PANEL TOP COVER CLIP	8	\$16.00	/			
17	RH HEADLAMP	1	\$500.00	/			
18	LH HEADLAMP	1	\$500.00	/	/		
19	AIRCON CONDENSOR	1	\$380.00	/	/		
20	RADIATOR	1	\$500.00				
21	COOLANT	1	\$22.00				
22	BONNET	1	\$300.00	/	/		
23	BONNET LOCK	1	\$50.00				
24	BONNET INSULATOR	1	\$60.00				
25	BONNET INSULATOR CLIP	12	\$24.00				
26	REAR BUMPER	1	\$350.00	/	/		
27	REAR BUMPER STAY RH	1	\$29.00	/	/		
28	REAR BUMPER STAY LH	1	\$29.00	/	/		
29	REAR BUMPER REINFORCEMENT	1	\$130.00	/	/		
30	REAR BUMPER CLIP	8	\$16.00	/	/		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
 ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SGY6828A

Make & Model : Honda civic ima 1.5lcv

Chassis No : JHMFB4620CS200273

Sales Order : 0

Order By : 0

Case Owner : PATRICK

Year Manufacture : 2014

Engine No : 0

Supplier : 0

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	REAR BUMPER SIDE RETAINER RH	1	\$12.00	/	/		
32	REAR BUMPER SIDE RETAINER LH	1	\$12.00	/	/		
33	REVERSE SENSOR	1	\$120.00	/	/		
34	REAR END PANEL	1	\$230.00	/	/		
35	REAR END PANEL TOP COVER	1	\$30.00	/	/		
36	TAILLAMP PANEL LH	1	\$65.00	/	/		
37	TAILLAMP PANEL RH	1	\$65.00	/	/		
38	TAILLAMP LH	1	\$350.00	/	/		
39	TAILLAMP H RH	1	\$350.00	/	/		
40	REAR BOOTLID WEATHER STRIP	1	\$40.00	/	/		
41	BOOTLID	1	\$430.00	/	/		
42	BOOTLID REFLECTOR RH	1	\$150.00	/	/		
43	BOOTLID REFLECTOR LH	1	\$150.00	/	/		
44	BOOTLID LOCK	1	\$45.00	/	/		
45	REAR NUMBER PLATE W/CASING	1				\$45.00	/
46	REAR CIVIC EMBLEM	1	\$20.00	/	/		
47	BOOTLID LOGO	1	\$19.00	/	/		
48	REAR HYBRID BADGE	1	\$32.00	/	/		
49	BOOTLID INSULATOR	1	\$100.00	/	/		
50	REAR LH FENDER	1	\$540.00	/	/		
51	REAR WINDSCREEN GLASS MOULDING	1	\$60.00	/	/		
52	REAR W/S SEALANT	2				\$40.00	/
53	REAR W/S INNER SEAL	1				\$30.00	/
54		0					
55		0					
56		0					
57		0					
58		0					
59		0					
60		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2050

SN 115

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63637166 / 63637466 Fax: 62815767

Vehicle No	: <u>SGY6828A</u>	Case Owner	: <u>PATRICK</u>
Make & Model	: <u>Honda civic ima 1.5lcv</u>	Year of Manufacture	: <u>2014</u>

395

2/8/18

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGY6828A

Chassis No : JHMF84620CS200273

Model : CIVIC 2012 IMA AT

Owner's Name : TANG YOKE FATT

Ins Policy No. :

Date of Accident :

Document No. : SQT18002231 Page 1

Date : 31. May 2018

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : LEA21009138

Date | Time : 31. May 2018 4:45:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:TANG YOKE FATT						
	OWNER INSURER:SOMPO						
	ACC DATE:27/05/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE S'PORE PTE LTD						
	TP VEH.SGX3035X						
32131-TR0-000	SUB CORDRR BUMPER CORNER SENS	1 ?	51.80	25	38.85	2.72	41.57
39680-TK8-A11ZB	SENSOR ASSYPARKING	2 ?	283.10	25	424.65	29.73	454.38
39681-TL0-G01ZW	RETAINERPARKING SENSOR	4 ?	47.50	25	142.50	9.98	152.48
39685-TR0-G01ZD	SENSOR ASSYPARKING	2 ?	283.10	25	424.65	29.73	454.38
33500-TR2-E01	TAILLIGHT ASSYR	1 ?	495.30	25	371.47	26.00	397.47
33550-TR2-E01	TAILLIGHT ASSYL	1 <i>inf</i> ✓	495.30	25	371.47	26.00	397.47
68500-TR2-Z10ZZ	LID COMPTRUNK	1 <i>ht</i> ✓	587.90	25	440.92	30.86	471.78
71700-TR2-A01ZK	SPOILER ASSYTRUNK	1 ?	331.00	25	248.25	17.38	265.63
74851-TA0-003	LOCK ASSYTRUNK	1 <i>ht</i> ✓	89.90	25	67.42	4.72	72.14
74865-TR0-G01	WEATHERSTRIPTRUNK LID	1 ?	91.80	25	68.85	4.82	73.67
75701-TS2-003	EMBLEM H	1 <i>ne</i> ✓	27.20	25	20.40	1.43	21.83
75722-TR0-A01	EMBLEMRR.CIVIC	1 <i>ne</i> ✓	28.30	25	21.22	1.49	22.71
75723-TR2-Q01	EMBLEMRR	1 <i>ne</i> ✓	33.10	25	24.82	1.74	26.56
04715-TR0-G10ZZ	FACERR.BUMPER	1 <i>de</i> ✓	700.70	25	525.52	36.79	562.31
71530-TR0-A00	BEAM COMPRR.BUMPER	1 ?	273.00	25	204.75	14.33	219.08
71535-TR0-A00ZZ	EXTENSION COMPR.RR.BUMPER	1 ?	38.80	25	29.10	2.04	31.14
71585-TR0-A00ZZ	EXTENSION COMPR.RR.BUMPER	1 ?	38.80	25	29.10	2.04	31.14
71593-TR0-A02	SPACERR.RR.BUMPER SIDE	1 <i>ne</i> ✓	18.30	25	13.72	0.96	14.68
71598-TR0-A02	SPACERL.RR.BUMPER SIDE	1 <i>ne</i> ✓	18.30	25	13.72	0.96	14.68
91506-S9A-003	CLIP BBUMPER	2 <i>all</i> ✓	2.40	25	3.60	0.25	3.85
04636-TR0-A00ZZ	PANEL SETR.RR.OUTSIDE	1 <i>ht</i> ✓	799.00	25	599.25	41.95	641.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGY6828A

Chassis No : JHMF84620CS200273

Model : CIVIC 2012 IMA AT

Owner's Name : TANG YOKE FATT

Ins Policy No. :

Date of Accident :

Document No. : SQT18002231

Date : 31. May 2018

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : LEA21009138

Date | Time : 31. May 2018 4:45:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04646-TR0-G00ZZ	PANEL SETL.RR.OUTSIDE	1 bt	799.00	25	599.25	41.95	641.20
66100-TR0-U30ZZ	PANEL COMPR.	1 bt	329.20	25	246.90	17.28	264.18
04655-TR2-Q30ZZ	PANEL SETRR.FLOOR	1 bt	1011.10	25	758.32	53.08	811.40
84640-TR0-A01ZA	LINING ASSYRR.	1 de	77.70	25	58.27	4.08	62.35
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2 bt	45.00		90.00	6.30	96.30
33100-T9A-T61	HEADLIGHT ASSY. R.	1 ?	549.30	25	411.97	28.84	440.81
33150-TR2-T01	HEADLIGHT ASSY.L	1 ?	741.90	25	556.42	38.95	595.37
33900-TR0-003	LIGHT ASSYR.FR.FOG	1 ?	305.90	25	229.42	16.06	245.48
33950-TR0-003	LIGHT ASSYL.FR.FOG	1 ?	305.90	25	229.42	16.06	245.48
60100-TR0-A00ZZ	HOOD COMPENGINE	1 bt	634.80	25	476.10	33.33	509.43
74120-TR0-A01	LOCK ASSYHOOD	1 bt	106.00	25	79.50	5.57	85.07
71103-TR0-A00	DUCTFR.BUMPER UPPER	1 ?	18.30	25	13.72	0.96	14.68
71121-TR2-A01	BASEFR.GRILLE	1 cut	182.60	25	136.95	9.59	146.54
71122-TR2-A01	MOLDINGFR.GRILLE UPPER	1 wt	137.00	25	102.75	7.19	109.94
71123-TR2-A01	STAYR.FR.GRILLE	1 ?	18.30	25	13.72	0.96	14.68
71124-TR2-A01	LENSR.FR.GRILLE	1 ?	125.60	25	94.20	6.59	100.79
71125-TR2-A01ZC	MOLDINGFR.GRILLE LOWER	1 ?	148.40	25	111.30	7.79	119.09
71129-TR2-A01	LENSL.FR.GRILLE	1 ?	125.60	25	94.20	6.59	100.79
75700-TR0-000	EMBLEM H	1 uni	23.50	25	17.62	1.23	18.85
91505-S9A-003	CLIP ABUMPER	10 uni	3.90	25	29.25	2.05	31.30
71101-TR0-U00ZZ	FACEFR.BUMPER	1 de	658.30	25	493.72	34.56	528.28
71105-TR0-G00	GRILLEFR.BUMPER CENTER LOWER	1 de	182.60	25	136.95	9.59	146.54
71130-TR0-G00ZZ	BEAM COMPFR.BUMPER	1 ?	296.70	25	222.52	15.58	238.10
71140-TR0-A00	BEAM COMPR.FR.BUMPER UPPER	1 ?	35.40	25	26.55	1.86	28.41
71190-TR0-A00	BEAM COMPL.FR.BUMPER UPPER	1 ?	35.40	25	26.55	1.86	28.41
71193-TR0-A02	SPACERR.FR.BUMPER	1 uni	10.70	25	8.02	0.56	8.58
71198-TR0-A02	SPACERL.FR.BUMPER	1 uni	10.70	25	8.02	0.56	8.58
60211-TR0-A00ZZ	PANELR.FR.FENDER	1 ?	477.00	25	357.75	25.04	382.79
60261-TR0-A00ZZ	PANELL.FR.FENDER	1 ?	477.00	25	357.75	25.04	382.79
60400-TR0-G00ZZ	BULKHEAD COMPFR.	1 bt	445.10	25	333.82	23.37	357.19

Printed on 31/5/2018 5:27:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SGY6828A
Chassis No : JHMF84620CS200273
Model : CIVIC 2012 IMA AT
Owner's Name : TANG YOKE FATT
Ins Policy No. :
Date of Accident :

Document No. : SQT18002231 Page 3
Date : 31. May 2018
Customer No. : WZA006
Svc Advisor : NG SIN HAI
Engine No : LEA21009138
Date | Time : 31. May 2018 4:45:26 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
80110-TS4-T01	CONDENSER COMP	1	489.60	25	367.20	25.70	392.90
19010-RW0-A51	RADIATOR COMP	1	1324.00	25	993.00	69.51	1062.51
08CLA-P9911LK8	COOLANTANTI-FREEZE	6	23.20	25	104.40	7.31	111.71
Sum Item					11869.76	830.91	12,700.67
BOSUN	SUNDRIES	1	20.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	✓ 180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR LHR FENDER	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR END PANEL	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	✓ 80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	✓ 180.00		180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	✓ 560.00		560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	✓ 560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	280 560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL.	1	4480 5000.00		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2700 4000.00		4000.00	280.00	4280.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	✓ 380.00		380.00	26.60	406.60
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	✓ 180.00		180.00	12.60	192.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	✓ 380.00		380.00	26.60	406.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	✓ 330.00		330.00	23.10	353.10
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	1	X 1000.00		1000.00	70.00	1070.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2700 3000.00		3000.00	210.00	3210.00
BKBH11B	CUT OFF & RENEW BULKHEAD FR L HOUSING COMP.	1	2240 4000.00		4000.00	280.00	4280.00
Sum Labor					20810.00	1,456.70	22,266.70

Printed on 31/5/2018 5:27:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SGY6828A
Chassis No : JHMFB4620CS200273
Model : CIVIC 2012 IMA AT
Owner's Name : TANG YOKE FATT
Ins Policy No. :
Date of Accident :

Document No. : SQT18002231 Page 4
Date : 31. May 2018
Customer No. : WZA006
Svc Advisor : NG SIN HAI
Engine No : LEA21009138
Date | Time : 31. May 2018 4:45:26 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
Survey By	Tan Jiah 97495749						
Date & Time	12/6/18 @ 1445						
Excess							
Status	WP						
Signature	tuftu						
					Total Amount	32,679.76	2,287.61
					Total (Inclusive of GST)		34,967.37

20 days
Resurvey before paint
sur e 1445:00:00

R 5587.58
? 6192.30
L 15370

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 31/5/2018 5:27:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/6/2018

Survey Details:

Date of loss	27-May-18
Date of appointment	01.06.2018
Date of survey	12-Jun-18
Location of survey	Kah Motor Co Sdn Bhd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SGY 6828A
Make and Model	HONDA CIVIC IMA 1.5L CVT - 1497cc
Date of registration	2-Jan-14
Excess	
Market Value	\$ 61,000.00
Parf Rebate	\$ 49,440.00
Nett Loss	\$ 11,560.00

Repair details:

Initial Estimate	\$ 32,679.76
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,587.58
Check items (estimate)	\$ 6,192.30
Labour	\$ 15,570.00
Total	\$ 27,349.88
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>20 days</u>
---------------------------	----------------



Service Request Details

Claim

S8M00IRY

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Reference

None

Loss Date

May 27, 2018

Request Date

June 1, 2018

Due Date

June 8, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SGY6828A

Make

TPVD HONDA

01062018 @ 11:43am
Sin Hui veh nudi.

Service Address

...

Primary Contact/Insured

BLAGDEN SETH JAGO

58 FARRER ROAD, #05-06 SPANISH VILLAGE, 268845, Singapore

sethjago@yahoo.co.uk

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



<TP - Mandate IA> - S8M00IRY [ACCIDENT INVOLVING
SGX 3035X(OI) / SGY 6828A(TP) / OTHERS ON
27/05/2018]

Type

🔗 Question

Message

Liability: 100%. 3 vehicles chain collision whereby OID was the last car. Inform OI about third party claim.

Agreed to settle at best and aware NCD issue. We seek your mandate at \$9,366.00(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 02 July 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/07/2019

Survey Details:

Date of loss	27.05.2018
Date of appointment	01.06.2018
Date of survey	12.06.2018
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGY6828A
Make and Model	Honda Civic (1497cc)
Date of registration	02.01.2014
Excess	
Market Value/ Book Value	\$ 61,000.00 (est)
Parf/COE Rebate	\$ 49,420.00 (est)
Nett Value/ ERV	\$ 11,580.00 (est)

Repair details:

Initial Estimate	\$ 13,378.85
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,782.35
Check items (estimate)	NIL
Labour	\$ 3,900.00
Supplementary	\$ 74.75
Total	\$ 9,757.10
Lump Sum(if applicable)	\$ 7,800.00

Number of days for repair	<u>12</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

12 recommended repair days + 2 Sunday + 1PH + 1PRS = 16days

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 8,346.00	
Loss of use	\$ 1,020.00	(17days x \$60.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	NIL	
Others	NIL	
Proposed Total	\$ 9,366.00	



**Re:<TP - Mandate IA> - S8M00IRY [ACCIDENT INVOLVING
SGX 3035X(OI) / SGY 6828A(TP) /OTHERS ON
27/05/2018]**

Type

🔗 Question

Message

Please proceed as per your propose mandate

Reply

PTE/SGY6828A/20180527/DS-CL
02/01/2019

M/s AXA Insurance Singapore Pte Ltd
C/o LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1, #02-25
Singapore 408933
Attn: Motor Claims Department

WITHOUT PREJUDICE

Dear Sirs

ACCIDENT ON 27/05/2018 INVOLVING SGY6828A & SGX3035X
ALONG QUEENWAY TURNING OUT OF HOLLAND ROAD

We are the authorised repair workshop for the owner of vehicle, SGY6828A, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SGX3035X, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repairs	8,346.00
2. Car Rental	-
3. 17.0 days Loss of Use @ \$80	1,360.00
4. Surveyor Fee	-
5. LTA Fee	-
6. TP/GIA Fee	-
7. Medical	-
8. Others	-

(E&OE) 9,706.00

We enclose the following documents to support the claims: -

- | | |
|--|---|
| ☒ Repair/Excess Bill | ☒ Insurance Certificate |
| ☒ Surveyor Report | ☒ Power of Attorney |
| ☐ Coloured Photographs | ☐ Car Rental Bill |
| ☒ GIA/Police Report(s) | ☐ Medical Bill |
| ☒ GIA/TP Search | ☐ Witness Statement |
| ☐ Others: _____ | |

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully

Cecilia Lee

CDGE Claims Department

59 Loyang Drive S(508969)

DID: 6214 8354 FAX: 6214 1843

Email: cecilialee@sparkcarcare.com



ComfortDelGro Engineering

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road Singapore 579701
Mainline +65 6383 6280
Facsimile +65 6280 9755

Company Registration No: 19550548W

Car Care Centres

Braddell
205 Braddell Road
Singapore 579701
Tel 6383 9110

Loyang
59 Loyang Drive
Singapore 508969
Tel 6214 8300

Pandan
45 Pandan Road
Singapore 609286
Tel 6338 8778

Sin Ming
383 Sin Ming Drive
Singapore 575717
Tel 5553 0400

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791
Tel 6369 7369

Ubi
320 Ubi Road 3
Singapore 408649
Tel 6848 5721

www.SPARKcarcare.com

A member of

COMFORTDELGRO





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010005/T1pa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG			Date : 24-07-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGX 3035X	Veh. Inspected	SGY 6828A	
Policy No.	GA019368	Coverage (\$)	0.00	
Claim No.	S8M00IRY	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	01/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC IMA	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JHMFB4620CS200273	Colour	SILVER	
Odometer	044442	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	DUNLOP	6 mm	
L/H Front Tyre	195/65R15	DUNLOP	6 mm	
R/H Rear Tyre	195/65R15	DUNLOP	6 mm	
L/H Rear Tyre	195/65R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/05/2018	Inspection Date	12/06/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 6828A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER (WCP) (CONSISTENT)	DEFORMED	180.00	180.00
1	FRT BUMPER SIDE RETAINER RH (WCP) (CONSISTENT)	NECESSARY	8.00	8.00
1	FRT BUMPER SIDE RETAINER LH (WCP) (CONSISTENT)	NECESSARY	8.00	8.00
1	FRT BUMPER LOWER CENTER GRILLE (WCP) (CONSISTENT)	DEFORMED	40.00	40.00
1	FRT RADIATOR GRILLE (WCP) (CONSISTENT)	CUT	130.00	130.00
1	FRT RADIATOR GRILLE LOGO (WCP) (CONSISTENT)	NECESSARY	17.00	17.00
1	FRT BUMPER REINFORCEMENT (WCP) (CONSISTENT)	BENT	190.00	190.00
2	FRT BUMPER SPONGE (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
8	FRT BUMPER CLIP (WCP) (CONSISTENT)	NECESSARY	16.00	16.00
1	FRT SUPPORT PANEL (WCP) (CONSISTENT) }	TO REPAIR SEE LABOUR	270.00	-
1	BRACE PANEL (WCP) (CONSISTENT) }	SERVICEABLE	-	-
4	RH HEADLAMP PANEL (WCP) (CONSISTENT) }	TO REPAIR SEE LABOUR	-	-
1	LH HEADLAMP PANEL (WCP) (CONSISTENT) }	TO REPAIR SEE LABOUR	-	-
1	FRT SUPPORT PANEL TOP COVER (WCP) (CONSISTENT)	NOT NECESSARY	14.00	-
8	FRT SUPPORT PANEL TOP COVER CLIP (WCP) (CONSISTENT)	NECESSARY	16.00	16.00
1	RH HEADLAMP (WCP) (CONSISTENT)	CUT	500.00	500.00
1	LH HEADLAMP (WCP) (CONSISTENT)	CUT	500.00	500.00
1	AIRCON CONDENSER (WCP) (CONSISTENT)	BENT	380.00	380.00
1	RADIATOR (WCP) (CONSISTENT)	NOT NECESSARY	500.00	-
1	COOLANT (WCP) (CONSISTENT)	NOT NECESSARY	22.00	-
1	BONNET (WCP) (CONSISTENT)	BENT	300.00	300.00
1	BONNET LOCK (WCP) (CONSISTENT)	NOT NECESSARY	50.00	-
1	BONNET INSULATOR (WCP) (CONSISTENT)	NOT NECESSARY	60.00	-
12	BONNET INSULATOR CLIP (WCP) (CONSISTENT)	NOT NECESSARY	24.00	-
1	REAR BUMPER (WCP) (CONSISTENT)	DEFORMED	350.00	350.00
1	REAR BUMPER STAY RH (WCP) (CONSISTENT)	NECESSARY	29.00	29.00
1	REAR BUMPER STAY LH (WCP) (CONSISTENT)	NECESSARY	29.00	29.00

Report Ref No. CC4/ASM18010005/T1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REINFORCEMENT (WCP) (CONSISTENT)	BENT	130.00	130.00
8	REAR BUMPER CLIP (WCP) (CONSISTENT)	NECESSARY	16.00	16.00
1	REAR BUMPER SIDE RETAINER RH (WCP) (CONSISTENT)	NECESSARY	12.00	12.00
1	REAR BUMPER SIDE RETAINER LH (WCP) (CONSISTENT)	NECESSARY	12.00	12.00
1	REVERSE SENSOR (WCP) (CONSISTENT)	NOT WORKING	120.00	120.00
1	REAR END PANEL (WCP) (CONSISTENT)	BENT	230.00	230.00
1	REAR END PANEL TOP COVER (WCP) (CONSISTENT)	DEFORMED	30.00	30.00
1	TAILLAMP PANEL LH (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	TAILLAMP PANEL RH (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	TAILLAMP LH (WCP) (CONSISTENT)	SERVICEABLE	350.00	-
1	TAILLAMP RH (WCP) (CONSISTENT)	CRACKED	350.00	350.00
1	REAR BOOTLID WEATHER STRIP (WCP) (CONSISTENT)	NOT NECESSARY	40.00	-
1	BOOTLID (WCP) (CONSISTENT)	BENT	430.00	430.00
1	BOOTLID REFLECTOR RH (WCP) (CONSISTENT)	NOT NECESSARY	150.00	-
1	BOOTLID REFLECTOR LH (WCP) (CONSISTENT)	CRACKED	150.00	150.00
1	BOOTLID LOCK (WCP) (CONSISTENT)	BENT	45.00	45.00
1	REAR CIVIC EMBLEM (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	BOOTLID LOGO (WCP) (CONSISTENT)	NECESSARY	19.00	19.00
1	REAR HYBRID BADGE (WCP) (CONSISTENT)	NECESSARY	32.00	32.00
1	BOOTLID INSULATOR (WCP) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR LH FENDER (WCP) (CONSISTENT)	BENT	540.00	540.00
1	REAR WINDSCREEN GLASS MOULDING (WCP) (CONSISTENT)	NECESSARY	60.00	60.00
1	REVERSE SENSOR COVER (WCP) (CONSISTENT) (ADDITIONAL)	DEFORMED	35.00	35.00
1	REAR END PANEL TOP GARNISH CENTER COVER (WCP) (CONSISTENT) (ADDITIONAL)	DEFORMED	30.00	30.00
	COST PLUS 15%		999.60	743.10
			7,663.60	5,697.10
	SPECIAL NETT ITEMS			
1	FRT NUMBER PLATE W/CASING (SN) (CONSISTENT)	DEFORMED	45.00	45.00
1	REAR NUMBER PLATE W/CASING (SN) (CONSISTENT)	DEFORMED	45.00	45.00

Report Ref No. CC4/ASM18010005/T1pa3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR W/S SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR W/S INNER SEAL (SN) (CONSISTENT)	NECESSARY	30.00	30.00
			160.00	160.00
	LABOUR			
	CUT WELD END PANEL, LH REAR FENDER, PANEL BEAT ON AFFECTED AREAS, REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL LH AND TAILLAMP PANEL RH.		1,600.00	1,300.00
	TO PUTTY, RESPRAY ON BOOTLID, REAR FENDERS, REAR BUMPER, END PANEL, FLOOR PANEL AND AFFECTED AREAS.		1,200.00	1,000.00
	TO REMOVE REAR INTERIOR UPHOLSETRY TO ASSIST REPAIR AND REFIT.		150.00	60.00
	TO REMOVE REAR WINDSCREEN GLASS TO ASSIST REPAIR AND REFIT.		120.00	120.00
	TO CUT WELD FRONT PANEL, REPLACE DAMAGE PARTS, REPAIR FRONT AFFECTED AREAS AND REALIGN. INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL, RH HEADLAMP PANEL AND LH HEADLAMP PANEL.		1,000.00	500.00
	TO PUTTY, RESPRAY BONNET, BUMPER, FRT PANEL, FENDERS AND AFFECTED AREAS.		1,000.00	600.00
	TO REMOVE AIRCON, RADIATOR TO ASSIST REPAIR AND REFIT.		180.00	120.00
	TO CHECK FRONT AND REAR LIGHTING AND WIRING FOCUS HEADLIGHT AND REPLACE SENSOR.		80.00	50.00
	TO RESET ECU SYSTEM.		300.00	150.00
			5,630.00	3,900.00
GRAND TOTAL			13,453.60	9,757.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,800.00

Report Ref No. CC4/ASM18010005/T1pa3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.