

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGY6828A

Chassis No : JHMFB4620CS200273

Model : CIVIC 2012 IMA AT

Owner's Name : TANG YOKE FATT

Ins Policy No. :

Date of Accident :

Document No. : SQT18002231 Page 1

Date : 31. May 2018

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : LEA21009138

Date | Time : 31. May 2018 4:45:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TANG YOKE FATT OWNER INSURER:SOMPO ACC DATE:27/05/2018 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE S'PORE PTE LTD TP VEH:SGX3035X						
32131-TR0-000	SUB CORDRR BUMPER CORNER SENS	1 ?	51.80	25	38.85	2.72	41.57
39680-TK8-A11ZB	SENSOR ASSYPARKING	2 ?	283.10	25	424.65	29.73	454.38
39681-TL0-G01ZW	RETAINERPARKING SENSOR	4 ?	47.50	25	142.50	9.98	152.48
39685-TR0-G01ZD	SENSOR ASSYPARKING	2 ?	283.10	25	424.65	29.73	454.38
33500-TR2-E01	TAILLIGHT ASSYR	1 ?	495.30	25	371.47	26.00	397.47
33550-TR2-E01	TAILLIGHT ASSYL	1 <i>ent</i> ✓	495.30	25	371.47	26.00	397.47
68500-TR2-Z10ZZ	LID COMPTRUNK	1 <i>bt</i> ✓	587.90	25	440.92	30.86	471.78
71700-TR2-A01ZK	SPOILER ASSYTRUNK	1 ?	331.00	25	248.25	17.38	265.63
74851-TA0-003	LOCK ASSYTRUNK	1 <i>bt</i> ✓	89.90	25	67.42	4.72	72.14
74865-TR0-G01	WEATHERSTRIPTRUNK LID	1 ?	91.80	25	68.85	4.82	73.67
75701-TS2-003	EMBLEM H	1 <i>ne</i> ✓	27.20	25	20.40	1.43	21.83
75722-TR0-A01	EMBLEMRR.CIVIC	1 <i>ne</i> ✓	28.30	25	21.22	1.49	22.71
75723-TR2-Q01	EMBLEMRR	1 <i>ne</i> ✓	33.10	25	24.82	1.74	26.56
04715-TR0-G10ZZ	FACERR.BUMPER	1 <i>dev</i> ✓	700.70	25	525.52	36.79	562.31
71530-TR0-A00	BEAM COMPRR.BUMPER	1 ?	273.00	25	204.75	14.33	219.08
71535-TR0-A00ZZ	EXTENSION COMPR.RR.BUMPER	1 ?	38.80	25	29.10	2.04	31.14
71585-TR0-A00ZZ	EXTENSION COMPR.RR.BUMPER	1 ?	38.80	25	29.10	2.04	31.14
71593-TR0-A02	SPACERR.RR.BUMPER SIDE	1 <i>ne</i> ✓	18.30	25	13.72	0.96	14.68
71598-TR0-A02	SPACERL.RR.BUMPER SIDE	1 <i>ne</i> ✓	18.30	25	13.72	0.96	14.68
91506-S9A-003	CLIP BBUMPER	2 <i>all</i> ✓	2.40	25	3.60	0.25	3.85
04636-TR0-A00ZZ	PANEL SETR.RR.OUTSIDE	1 <i>bt</i> ✓	799.00	25	599.25	41.95	641.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGY6828A
Chassis No : JHMF84620CS200273
Model : CIVIC 2012 IMA AT
Owner's Name : TANG YOKE FATT
Ins Policy No :
Date of Accident :

Document No. : SQT18002231 Page 2
Date : 31. May 2018
Customer No. : WZA006
Svc Advisor : NG SIN HAI
Engine No : LEA21009138
Date | Time : 31. May 2018 4:45:26 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04646-TR0-G00ZZ	PANEL SETL.RR.OUTSIDE	1 <i>bt</i>	799.00	25	599.25	41.95	641.20
66100-TR0-U30ZZ	PANEL COMPRR.	1 <i>bt</i>	329.20	25	246.90	17.28	264.18
04655-TR2-Q30ZZ	PANEL SETRR.FLOOR	1 <i>bt</i>	1011.10	25	758.32	53.08	811.40
84640-TR0-A01ZA	LINING ASSYRR.	1 <i>de</i>	77.70	25	58.27	4.08	62.35
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2 <i>bt</i>	45.00		90.00	6.30	96.30
33100-T9A-T61	HEADLIGHT ASSY, R.	1 ?	549.30	25	411.97	28.84	440.81
33150-TR2-T01	HEADLIGHT ASSY,L	1 ?	741.90	25	556.42	38.95	595.37
33900-TR0-003	LIGHT ASSYR.FR.FOG	1 ?	305.90	25	229.42	16.06	245.48
33950-TR0-003	LIGHT ASSYL.FR.FOG	1 ?	305.90	25	229.42	16.06	245.48
60100-TR0-A00ZZ	HOOD COMPENGINE	1 <i>bt</i>	634.80	25	476.10	33.33	509.43
74120-TR0-A01	LOCK ASSYHOOD	1 <i>bt</i>	106.00	25	79.50	5.57	85.07
71103-TR0-A00	DUCTFR.BUMPER UPPER	1 ?	18.30	25	13.72	0.96	14.68
71121-TR2-A01	BASEFR.GRILLE	1 <i>cut</i>	182.60	25	136.95	9.59	146.54
71122-TR2-A01	MOLDINGFR.GRILLE UPPER	1 <i>cut</i>	137.00	25	102.75	7.19	109.94
71123-TR2-A01	STAYR.FR.GRILLE	1 ?	18.30	25	13.72	0.96	14.68
71124-TR2-A01	LENSR.FR.GRILLE	1 ?	125.60	25	94.20	6.59	100.79
71125-TR2-A01ZC	MOLDINGFR.GRILLE LOWER	1 ?	148.40	25	111.30	7.79	119.09
71129-TR2-A01	LENSL.FR.GRILLE	1 ?	125.60	25	94.20	6.59	100.79
75700-TR0-000	EMBLEM H	1 <i>all</i>	23.50	25	17.62	1.23	18.85
91505-S9A-003	CLIP ABUMPER	10 <i>all</i>	3.90	25	29.25	2.05	31.30
71101-TR0-U00ZZ	FACEFR.BUMPER	1 <i>de</i>	658.30	25	493.72	34.56	528.28
71105-TR0-G00	GRILLEFR.BUMPER CENTER LOWER	1 <i>de</i>	182.60	25	136.95	9.59	146.54
71130-TR0-G00ZZ	BEAM COMPFR.BUMPER	1 ?	296.70	25	222.52	15.58	238.10
71140-TR0-A00	BEAM COMPFR.FR.BUMPER UPPER	1 ?	35.40	25	26.55	1.86	28.41
71190-TR0-A00	BEAM COMPL.FR.BUMPER UPPER	1 ?	35.40	25	26.55	1.86	28.41
71193-TR0-A02	SPACERR.FR.BUMPER	1 <i>all</i>	10.70	25	8.02	0.56	8.58
71198-TR0-A02	SPACERL.FR.BUMPER	1 <i>all</i>	10.70	25	8.02	0.56	8.58
60211-TR0-A00ZZ	PANELR.FR.FENDER	1 ?	477.00	25	357.75	25.04	382.79
60261-TR0-A00ZZ	PANELL.FR.FENDER	1 ?	477.00	25	357.75	25.04	382.79
60400-TR0-G00ZZ	BULKHEAD COMPFR.	1 <i>bt</i>	445.10	25	333.82	23.37	357.19

Printed on 31/5/2018 5:27:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGY6828A

Chassis No : JHMFB4620CS200273

Model : CIVIC 2012 IMA AT

Owner's Name : TANG YOKE FATT

Ins Policy No. :

Date of Accident :

Document No. : SQT18002231 Page 3

Date : 31. May 2018

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : LEA21009138

Date | Time : 31. May 2018 4:45:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
80110-TS4-T01	CONDENSER COMP	1	489.60	25	367.20	25.70	392.90
19010-RW0-A51	RADIATOR COMP	1	1324.00	25	993.00	69.51	1062.51
08CLA-P9911LK8	COOLANTANTI-FREEZE	6	23.20	25	104.40	7.31	111.71
Sum Item					11869.76	830.91	12,700.67
BOSUN	SUNDRIES	1	20 100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	✓ 180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR LHR FENDER	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR END PANEL	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	✓ 80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	✓ 80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	✓ 180.00		180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	✓ 560.00		560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	✓ 560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	280 560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL.	1	4480 5000.00		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2700 4000.00		4000.00	280.00	4280.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	✓ 380.00		380.00	26.60	406.60
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	✓ 180.00		180.00	12.60	192.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	✓ 380.00		380.00	26.60	406.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	✓ 330.00		330.00	23.10	353.10
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	1	X 1000.00		1000.00	70.00	1070.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2700 3000.00		3000.00	210.00	3210.00
BKBH11B	CUT OFF & RENEW BULKHEAD FR L HOUSING COMP.	1	2240 4000.00		4000.00	280.00	4280.00
Sum Labor					20810.00	1,456.70	22,266.70

Printed on 31/5/2018 5:27:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

