

Surveyor:

Ampuan

DOI:

31/5/18

Date / Time:

31/5/18

Registered in Merimen:

3/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLQ5744Y

Name of Insured:

LEFF Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

29/05/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Abdul Rahim Bin Md. Yassin

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

280089037254

Policy No.:

5999994803

Make / Model:

Honda V2

Place of Accident:

MCP 646686

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKP80405



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kang Car



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/6/18

SKP80405 - X; SLQ5744Y - X

7/6/18

email workshop liability voucher.
receive TP video
Email letter to O2.

RECEIVED 27 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 1605.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

360.00 (360 x 6 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 10.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 1575.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 1975.00

Name 1:

Kang Car Repairs Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Adrian King

REF:

ASSIGNMENTFrom: _____ Date: _____
Estimated Cost: _____OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP80405 Yr Regn: 2014, OctType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis cc 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 68865 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROS3REH104517633Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO (YOKO) or

Front Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 31/05/18Survey held at KanyDes. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPA16</u>
<u>26/9/18</u>	<u>Confirm US \$1500.00 with 3 working day</u>

(Red - \$1704.13
53%)Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format :

Lump Sum / I.B.I: (\$ - _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18010010/Awa3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 03-06-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 5744Y	Veh. Inspected	SKP 8040S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/05/2018	Inspection Date	31/05/2018	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800155
Date: 30 May 2018
Veh Reg No: SKP8040S
Make/Model: TOYOTA COROLLA
ALTIS
Chasis No: MR053REH104517633
Reg. Date: 14/10/2014
Your Ref No: SLQ5744Y

Claim Type: Third Party
Accident Date: 29/05/2018
TP Veh Reg No: SLQ5744Y

Estimate Repair Cost to Vehicle No :SKP8040S

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT DOOR LH <i>Dented</i>	1,079.60	
2	1 PC FRT DOOR GLASS REGULATOR ASSEMBLY LH <i>2nd glass reg</i>	530.80	
3	1 PC FRT DOOR RUBBER LH <i>new</i>	157.60	
4	1 PC FRT LH DOOR INNER LOCK <i>new</i>	521.80	
5	1 PC FRT DOOR OUTER MOULDING LH <i>new</i>	155.70	
	1 PC Front Door Black Tape <i>100 60(SN)</i>	2,445.50	
	Less 25%	611.38	1,834.13
	Labour		
6	1 TO CHECK WIRING	50.00	30
7	1 TO REMOVE AND REFIX FRT DOOR GLASS LH <i>880</i>	120.00	100
8	1 (FRONT) TO SPRAY PAINTING	600.00	400
9	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00	350
		1,370.00	1,370.00
	Total		SS 3,204.13
	Add GST @ 7%		224.29
	Total Amount Payable		SS 3,428.42

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED TWENTY EIGHT AND CENTS FORTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged parts during resurvey
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim
1/2 31/05/18
03 days



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0520188040AIG
Your Ref : SLQ5744Y

Date : 24 AUG 2018

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933
Attention : Motor Claim Department

Dear Sirs,

Accident involving SKP8040S and SLQ5744Y on 29.05.2018 along Blk 686 Choa Chu Kang Crescent MSCP Deck 1A.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SLQ5744Y.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Ms Lim Sheau Chyi, the owner of motor-vehicle no: SKP8040S, we submit her claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 1,605.00
Loss of rental (6 days x \$80.00)	\$ 480.00
LTA search by Law Firm	\$ 10.00
	<u>\$ 2,095.00</u>
	=====

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1800449
- 2) GIA report of SKP8040S
- 3) LTA search fee & invoice from A C Syed & Partners

We hope to receive your early reply soon.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD

.....

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Thursday, 7 June, 2018 2:40 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLQ 5744Y AND SKP 8040S ON 29/05/2018

Our Ref: CC6/LCR18010010/Awa3

07 June 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLQ 5744Y AND SKP 8040S ON 29/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within 7 days i.e. by **18/06/2018**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORITY

Your Ref: SLQ5744Y

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Dear Sirs,

Accident involving SKP8040S and SLQ5744Y
on 29.05.2018 at Blk 686 Choa Chu Kang Crescent MSCP Deck 1A.

I/We am/are the owner/s of vehicle number SKP8040S.


I/We had instructed KANG CAR REPAIRERS PTE LTD to make a claim on my/our behalf against your company in respect of the abovementioned matter.

I/We hereby authorize you to issue the settlement cheque in favour of my/our workshop, KANG CAR REPAIRERS PTE LTD in full and final settlement of my/our claim for my/our repair cost and loss of use/rental charges, in respect of the above accident.

Yours faithfully,


.....
Lim Sheau Chyi

KANG CAR REPAIRERS PTE. LTD.


.....
Witnessed by: Kong Chin Watt

This Discharge Voucher applies strictly for Claimant's claim for personal injury/ property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER (AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Kang Car Repairers Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKP Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 1,605.00 (repair costs), S\$ 360.00 (loss of use/~~rental~~) S\$ 10.00 (search fees) for vehicle no. SKP8040S that was damaged pursuant to the accident which occurred on 29.05.18 (date) along Blk 686 Choa Chu Kang Crescent MSCP Deck 1A (location) involving vehicle no/s SLQ5744Y

This is pursuant to the inspection conducted on 31/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Lim Sheau Chyi ("third party claimant") of vehicle no. SKP8040S to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKP8040S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

27 SEP 2018

Dated this _____ day of _____ (month) 20____ (year)

KANG CAR REPAIRERS PTE. LTD.

LWP
Signed by AIG appointed surveyor

[Signature]
Chopped & Signed by "the workshop"



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883

TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg

Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Your Ref No: SLQ5744Y
Claim Type: Third Party
Accident Date: 29/05/2018
TP Veh Reg No: SLQ5744Y

Final No: KCR-INV1800449
Claim No: EST1800155
Date: 17 Aug 2018
Policy No: 5091968478
Veh Reg No: SKP8040S
Make/Model: TOYOTA COROLLA
ALTIS
Chassis No: MR053REH104517633
Engine No: 1ZR452555
Reg. Date: 14/10/2014

Tax Invoice to Vehicle No :SKP8040S

			PAGE:1
Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
As recommended by surveyor to proceed repair at total cost/lumpsum cost			S\$ 1,500.00
Add GST @ 7%			105.00
Total Amount payable			<u>S\$ 1,605.00</u>

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SIX HUNDRED AND FIVE ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

Enquire Vehicle & Owner Information (Vehicle No. SLQ5744Y As At 29 May 2018 / 14:50:00)**Law Firm Search Details ***

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: ACS,KC.LTA.05.18

Current Owner Details

Owner ID Type: Company
Owner ID: 201624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11 - 01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details


Vehicle No.: SLQ5744Y
Make Description/Model: HONDA / VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : KANG CAR REPAIRERS PTE LTD	BILL NO: B048 /2018												
YOUR REF:													
OUR REF : ACS.KC.LTA.MAY.2018	DATE : 7/5/18												
<p>TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.</p> <p><u>LTA SEARCHES FOR THE MONTH MAY 2018</u></p> <table><tr><td>1. GBD 5711D as at 2.5.18</td><td>\$ 10.00</td></tr><tr><td>2. SLE 3283L as at 18.5.18</td><td>\$ 10.00</td></tr><tr><td>3. SLP 6590Y as at 2.5.18</td><td>\$ 10.00</td></tr><tr><td>4. SLQ 5744Y as at 29.5.18 <i>SKP 80405</i></td><td>\$ 10.00</td></tr><tr><td>5. EW 8833E as at 19.5.18</td><td>\$ 10.00</td></tr><tr><td>6. YN 2829T as at 31.5.18</td><td>\$ 10.00</td></tr></table> <p style="text-align: right;">Total: <u>\$ 60.00</u></p> <p>[SINGAPORE DOLLARS: SIXTY ONLY.]</p> <p> M/s A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE</p> <p>We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.</p>		1. GBD 5711D as at 2.5.18	\$ 10.00	2. SLE 3283L as at 18.5.18	\$ 10.00	3. SLP 6590Y as at 2.5.18	\$ 10.00	4. SLQ 5744Y as at 29.5.18 <i>SKP 80405</i>	\$ 10.00	5. EW 8833E as at 19.5.18	\$ 10.00	6. YN 2829T as at 31.5.18	\$ 10.00
1. GBD 5711D as at 2.5.18	\$ 10.00												
2. SLE 3283L as at 18.5.18	\$ 10.00												
3. SLP 6590Y as at 2.5.18	\$ 10.00												
4. SLQ 5744Y as at 29.5.18 <i>SKP 80405</i>	\$ 10.00												
5. EW 8833E as at 19.5.18	\$ 10.00												
6. YN 2829T as at 31.5.18	\$ 10.00												

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2018 Edit Reg		31 May 2018 00:00 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K				
Main Claimant:	LIM SHEAU CHYI, ID: S8279522G				
Vehicle Reg. No.:	SKP8040S	Date of Loss:	29/05/2018 14:00 - :59 [43 Months and 15 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 2800890372SG	Policy/Cover Note No.:	0999994807 (Comprehensive)		
Vehicle Reg. No. (Insured):	SLQ5744Y	Policy No. (Claimant):	5091968478		
		Excess:			
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com				
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/06/2018]				

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
• AIG_SG (04/06/2018): Request To Upload TP GIA Report			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SKP8040S (2800890372SG)
[SLQ5744Y]
TP
LIM SHEAU CHYI
May 29 2018 2:00PM
[LCRF Pte Ltd]
Kang Car Repairers Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1 Edit			
Photos/Images										3 per page 3 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
2	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
3	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
4	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
5	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
6	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
7	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
8	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
9	25/09/18 13:46	General View						1 Load JPG		<input checked="" type="checkbox"/>	
10	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
11	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
12	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
13	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
14	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
15	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
16	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
17	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
18	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
19	25/09/18 13:46	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
Documentation										1 per page 1 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	05/06/18 09:16	TP GIA REPORT						1 Load PDF		<input checked="" type="checkbox"/>	
2	07/06/18 14:41	Email letter to OI ACCIDENT INVOLVING SLQ 5744Y AND SKP 8040S ON 29.05.2018						1 Load PDF		<input checked="" type="checkbox"/>	
3	03/10/18 10:35	WORKSHOP INVOICE						1 Load PDF		<input checked="" type="checkbox"/>	
4	03/10/18 10:35	AUTHORISATION TO ACT FORM						1 Load PDF		<input checked="" type="checkbox"/>	
5	03/10/18 10:35	Release Voucher						1 Load PDF		<input checked="" type="checkbox"/>	
6	03/10/18 10:35	LTA SEARCH						1 Load PDF		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	04/06/18 16:21	OI GIA REPORT						1 Load PDF		<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLQ5744Y (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SKP8040S (TP veh)		1.6 CVT (A)
Date of Accident:	29/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	3,535.41	
Final Repair Cost	:	\$	1,605.00	
Loss of Use	:	\$	360.00	6.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	10.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	1,975.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 1,975.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

03 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18010010/AWA3Q2

Date: 03/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994807

Claimant Vehicle No: SKP8040S

Insured Vehicle No: SLQ5744Y

Date of Loss: 29/05/2018

Nature of Claim: TP

Claim No: 2800890372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP8040S

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A)

Engine No: 1ZR452555

Reg. Date: 14/10/2014 (Man. Year: 2014)

Chassis No: MR053REH104517633

Colour: Silver

Odometer: 68865 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,934.12	987.90	946.22	48.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	880.00	490.00	35.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,304.12	1,867.90	1,436.22	43.47
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	3,304.12	1,500.00	1,804.12	54.60
+ GST 7.00/7.00% (S\$)	231.29	105.00	126.29	54.60
Nett Amount (S\$)	3,535.41	1,605.00	1,930.41	54.60
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		10.00		
Nett Liability (S\$)		1,975.00		

INSPECTION

Date of Assignment: 31/05/2018

Date Inspected: 31/05/2018 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH	Dented	1,079.60 FL	*1,079.60 FL
2	1		*FRT DOOR GLASS REGULATOR ASSEMBLY LH	Not Necessary	530.80 FL	*- FL
3	1		*FRT DOOR RUBBER LH	Necessary	157.60 FL	*157.60 FL
4	1		*FRT LH DOOR INNER LOCK	Not Necessary	521.80 FL	*- FL
5	1		*FRT DOOR OUTER MOULDING LH	Not Necessary	155.70 FL	*- FL
6	1		*FRONT DOOR BLACK TAPE	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,545.50	1,297.20
- List Item Discount on L Items 25.00/25.00% (S\$)	611.38	309.30
Total Parts (S\$)	1,934.12	987.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIX FRT DOOR GLASS LH	New	120.00	100.00
3	(FRONT) TO SPRAY PAINTING	New	600.00	400.00
4	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS	New	600.00	350.00
Gross Labour Cost (S\$)			1,370.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >