

FYS CASE OWNER:

CC 4/Asm

180

0026

V wa34

LKK:

IDAC:

49693

4/6/2018

Surveyor:

Sathya

DOI:

5/6/18

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEM35745

Name of Insured:

APRIL KUNDA SIO KUNDAHVEL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

2/6/2018

Is driver the owner?

(YES/NO)

Nature of Accident:

Claim No.:

S8M0UJF7

Policy No.:

6A085894P1

Make / Model:

7. APHARO

Place of Accident:

PARC ROSEWOOD CONDO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Automotive
Repair
Center
(APC)

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18/6/18

SPK 1188D - X

SEM35745, 616/ADA1705158/11/11/17

* To fix: is it before attorney. to confirm liability.

28-06-18

IF VEHICLE WAS ON MAIN DRIVING WAY, WHEREAS 9/1 CAME OUT FROM BASEMENT CAR PARK, MUST GIVE WAY BEFORE ENTERING INTO MAIN DRIVEWAY, 9/1 IS AT FAULT.

30/7/18

TP confirm revert to OP.

RECEIVED 03 AUG 2018

RECEIVED 03 AUG 2018

PRELIMINARY ADVICE Date/Time:

8/6

Sent By:

Hw

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 3/8/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

w/p

3) Survey fee:

1850.00

REF: ASM (AXA)

ASSIGNMENT

From: Date: 05062018

Estimated Cost:

OD / TS / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 1188D

at Workshop m/s Automotive Repairs

of 38 Woodlands Ind Park EL #05-18

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Morning

X N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKE 1188D Yr Regn: Sept / 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi ASX C.C 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 192234 T/Radio: Insured / Std / NI / NA

Eng/No: 4B11GM7918

C/No: JMYXTGAJ2WB3000906

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65 R16

R: 215/65 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 2/6/18 D.O.I: 5/6/18

Survey held at Automotive Repair Centre

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/7/18 confirm U/S \$2850.00 with 14 working days.

(Red) - \$300.00
60%!

Date/Time: File Pass to?

☐ : Preli. Report

f)

☐ : Final Report

Date/Time: File Return to?

Q)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + R\$ \$

) Phone

) Others

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010026/Vwa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 04-06-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKM 3574S	Veh. Inspected	SKE 1188D	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00JF7	Excess (\$)	0.00	
Assign From		Assign Date	04/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/06/2018	Inspection Date	05/06/2018	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

$$\begin{array}{r}
 20 \quad 9 \quad 2021 \\
 \cdot \quad \cdot \quad 8 \quad 6 \quad 2018 \\
 \hline
 12 \text{ days} \quad 3 \text{ month} \quad 3 \text{ year}
 \end{array}$$

$$\begin{array}{r}
 \downarrow \\
 0.4 \text{ month} + 3 \text{ months} + 36 \text{ month} \\
 \hline
 39.4 \text{ months}
 \end{array}$$

$$\begin{aligned}
 \$ \text{ Depreciation} &= 11470 / \text{year} \\
 &= 955.8 / \text{month}
 \end{aligned}$$

$$\begin{array}{r}
 \rightarrow 37658.52 \\
 + 11462.00 \\
 \hline
 49120.52 \\
 - 35585.00 \\
 \hline
 13535.52 \\
 \hline
 \hline
 \end{array}$$

$$\therefore \text{Repair Range} = \$ \underline{\underline{11,000 - 12,000}}$$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6689B
Vehicle Details	
Vehicle No.:	SKE1188D
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ASX 2.0 6-CVT (M) ABS D/AIRBAG SR 2WD
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	4B11GM7918
Chassis No.:	JMYXTGA2WBZ000966
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$22,924.00
Original Registration Date:	21 Sep 2011
First Registration Date:	21 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$22,924.00 11462
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2021
PARF Rebate Amount:	\$14,900.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$63,002.00
COE Rebate Amount:	\$20,685.00
Total Rebate Amount:	\$35,585.00

The information contained herein is correct as at 08 Jun 2018

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKE1188D		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
* Vehicle Attachment 1 :	With Sun Roof		
Vehicle Scheme :	Normal		
* Vehicle Make :	MITSUBISHI		
Vehicle Model :	ASX 2.0 6-CVT (M) ABS D/AIRBAG SR 2WD		
Chassis No. :	JMYXTGA2WBZ000966		
Propellant :	Petrol		
Engine No. :	4B11GM7918		
Engine Capacity :	1998 cc		
Maximum Power Output :	110.0 kW (147 bhp)		
Maximum Laden Weight :	1970 kg		
Unladen Weight :	1438 kg		
Year Of Manufacture :	2010		
Original Registration Date :	21 Sep 2011		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$63,002.00		
COE Expiry Date :	20 Sep 2021		
Road Tax Expiry Date :	20 Sep 2018		
PARF Eligibility Expiry Date :	20 Sep 2021		
Inspection Due Date :	20 Sep 2018		
Intended Transfer Date :	08 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

- COE Bidding – 1st Round of June 2018
- Sausage McGriddles is coming back to McDonald's 7L...
- Boleh Land Election 2018

Mitsubishi ASX Price Range Depreciation 2011 Vehicle Type

Advanced Search

Home » Used Cars » United Auto Trading Pte Ltd » Mitsubishi ASX 2.0A Panoramic Roof

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing

CL LEASING

YOUR PREFERRED CAR LEASING OPTION IN SINGAPORE



6768 7117 8728 5008 8720 8000

VIEWQWEST

PC SHOW EXCLUSIVE

2Gbps
Fibre Broadband
Bundle

\$49.95
per month

*Standard rate based on annual payment



FREE NETGEAR® Smart Cloud WiFi
worth \$199

Terms & Conditions apply

Mitsubishi ASX 2.0A Panoramic Roof

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$48,800	
Depreciation	\$11,470 /yr View models with similar depreciation	?
Reg Date	08-Sep-2011 (3yrs 2mths 30days COE left)	
Manufactured	2010	?
Mileage	124,000 km (18.4k /yr)	
Transmission	Auto	
Engine Cap	1,998 cc	
Road Tax	\$1,210 /yr	?
Power	110.0 kW (147 bhp) View specs of the Mitsubishi ASX (2010-2014)	
Curb Weight	1,438 kg	?
Features	2.0L DOHC 16V MIVEC Engine At 150BHP, 6-Speed Steptronic CVT, Smart Entry, Push Start, Hill Start Assist, Cruise Control, ABS, SRS Airbags, 19" Rims	
Accessories	-	
Description	Sporty White, Yearly Mileage 17,700 Only, Maintained By Agent. 100% Accident Free. Buy With Confidence!	
COE	\$65,490	?
OMV	\$23,014	?
ARF	\$23,014	?
Dereg Value	\$36,257 as of today (change)	?
No. of Owners	2	?
Type of Veh	SUV	
Category	PARF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 05-Jun-2018 | Last Updated on: 07-Jun-2018

Tags: Mitsubishi ASX, 2011 Mitsubishi ASX, Mitsubishi, ASX, Used Mitsubishi

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$14,640 (change)	Maximum 70% Loan ?
1st Instalment	\$961	?
Total Upfront Payment	\$15,626 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Mitsubishi ASX

» View All



Seller Information

Company	United Auto Trading Pte Ltd » dealer's pricelist » 44 vehs sold 13 vehs available
Address	210 Turf Club Road Lot B38 Search cars nearby this location
Location	Car Mall @ The Grandstand
Office No	63141150
Contact Person(s)	Jonathan Tan 96423832 Kenny Ho 98785736

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1806-049
DATE : 4-Jun-2018
POLICY NO. : FWD PNPV2017-00001982-01
VEHICLE REG. NO. : SKE1188D
VEHICLE MAKE : MITSUBISHI ASX 2.0 6-CVT (M)

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST	
SPARE PARTS					
1	Front Door LH ✓ DMG	1	\$ 1,080.00	\$ 1,080.00	915
2	Front Door Outer Handle LH ✓ DMG	1	\$ 70.00	\$ 70.00	✓
3	Front Door Outer Handle Small Cover with Remote LH ✓ DT	1	\$ 20.00	\$ 20.00	✓
4	Front Door Outer Handle Remote Switch LH 2 X NN	1	\$ 80.00	\$ 80.00	
5	Front Door Handle Inner Gasket LH ✓ Deform	1	\$ 30.00	\$ 30.00	✓
6	Front Door Handle Inner Cover Gasket LH 2 X } NN	1	\$ 30.00	\$ 30.00	
7	Front Door Handle Inner Base Garnish LH 2 X }	1	\$ 120.00	\$ 120.00	
8	Front Door Window Glass LH ✓ BR	1	\$ 350.00	\$ 350.00	✓
9	Front Door Window Regulator LH 2 X }	1	\$ 140.00	\$ 140.00	
10	Front Door Window Regulator Motor LH 2 X }	1	\$ 400.00	\$ 400.00	
11	Front Door Window Glass Moulding LH 2 X }	1	\$ 50.00	\$ 50.00	
12	Front Door Lower Hinge LH 2 X }	1	\$ 50.00	\$ 50.00	
13	Front Door Lower Hinge LH 2 X }	1	\$ 50.00	\$ 50.00	
14	Front Door Lock LH 2 X }	1	\$ 280.00	\$ 280.00	
15	Front Door Out Weather Seal LH ✓ BT	1	\$ 150.00	\$ 150.00	134
16	Front Door Inner Seal LH 2 X }	1	\$ 220.00	\$ 220.00	
17	Front Door Inner Moulding LH 2 X }	1	\$ 120.00	\$ 120.00	
18	Front Door Inner Lower Seal LH 2 X }	1	\$ 120.00	\$ 120.00	
19	Front Rear Door Moulding (Black Sticker) LH ✓ NEL	1	\$ 40.00	\$ 40.00	✓
20	Front Door Inner Trim LH 2 X }	1	\$ 790.00	\$ 790.00	
21	Front Door Retractor/Check LH 2 X }	1	\$ 40.00	\$ 40.00	
22	Side Skirt LH ✓ DT	1	\$ 490.00	\$ 490.00	435
Total Spare Parts				\$ 4,720.00	
SPECIAL NETT					
23	Glass Solar Film LH for Front Door Window ✓ Nel	1	\$ 150.00	\$ 150.00	
Total Special Nett				\$ 150.00	
LABOUR					
24	S-painting B-Pillar LH, Skirt LH, Front Fender LH and 2 Doors LH 4 panels		\$ 1,200.00	\$ 1,200.00	800
25	Repair, Replace and Refill Affected Accident Area	1	\$ 800.00	\$ 800.00	600
26	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00	50
27	Reset SRS and Door lock Sensor/Remote	1	\$ 150.00	\$ 150.00	150
28	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00	✓



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1806-049
DATE : 4-Jun-2018
POLICY NO. : FWD PNPV2017-00001982-01
VEHICLE REG. NO. : SKE1188D
VEHICLE MAKE : MITSUBISHI ASX 2.0 6-CVT (M)

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan				
	Total Labour		\$	2,280.00
	Amount Before Excess		\$	7,150.00
	Add GST @ 7%			500.50
	Total Amount Payable		\$	7,650.50

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

sebastiangeang@lkkauto.com

Sathya Sai
5/6/2018

- Lump Sum Repair
- Question mark item photo
- Photo after paint

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1994
- 10%
1794.6
+ 150
+ 1630
3574.6
- 20%
2859.68

L/S: \$ 2850 @ 4 days



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 8/6/2018

Survey Details:

Date of loss	2-Jun-18
Date of appointment	4-Jun-18
Date of survey	5-Jun-18
Location of survey	Automotive Repair Centre Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SKE 1188D
Make and Model	MITSUBISHI ASX 2.0 6-CV - 1998cc
Date of registration	21-Sep-11
Excess	
Market Value	\$ 49,000.00
Part Rebate	\$ 35,655.00
Nett Loss	\$ 13,345.00

Repair details:

Initial Estimate	\$ 7,150.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,380.00
Check items (estimate)	\$ 2,490.00
Labour	\$ 1,630.00
Total	\$ 6,500.00
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>4 days</u>
---------------------------	---------------

 **S8M00JF7**

Type

 Question

Message

Dear Stacy, we refer to the above matter, We check with TP repairer, they have revert to OD. In view of above, we will submit W/P report to your office. Thank you Vivian Lau (30.7.18)

[Reply](#)

Service Request Details

Claim

S8M00JF7

Reference

CC4/ASM18010026/Vwa3q2

Loss Date

2 June 2018

Request Date

4 June 2018

Due Date

4 June 2019

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SKE118BD

Make

TPVD MITSUBISHI

Model

ASX 2.0 6-CVT (M) ABS D/AIRBAG SR 2WD

Service Address

...

Primary Contact/Insured

KOLANTHAVEL ARJUN KUMAR S/O
30 WOODLANDS CRESCENT, #15-15, 738086,
Singapore

Claim Handler

NG Stacey
6548804351
stacey.ng@axa.com.sg

Actions

Next Step

Finish the work

Completion View

None

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes										
Document Type Document SubType Upload Documents <table><thead><tr><th>NAME</th><th>TYPE</th><th>SUB-TYPE</th><th>AUTHOR</th><th>DATE UPLOADED</th></tr></thead><tbody><tr><td> Immediate Advice.pdf </td><td>Reports & Statement</td><td>Others</td><td>LKX AUTO CONSULTANTS PTE LTD (TP)</td><td>12 June 2018</td></tr></tbody></table>							NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED	Immediate Advice.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	12 June 2018
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED												
Immediate Advice.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	12 June 2018												

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKX SURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	12 June 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	12 June 2018
 ACCIDENT PHOTO 4.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 3.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 5.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 8.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 7.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 6.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 1.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 ACCIDENT PHOTO 2.JPG	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	4 June 2018
 SKM35745 INSD CIA REPORT.PDF	Reports & Statement	CIA Report	DHAKAL Raghav	4 June 2018
 TP PRI RECEIVED FROM WORKSHOP WITH CIA AND ESTIMATE.png	Letters and Correspondence	Workshop	DHAKAL Raghav	4 June 2018

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC CUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE		
	1	1			FRONT DOOR LH			Damaged	915		10		823.5	Approve			
	2	1			FRONT DOOR OUTER HANDLE RH			Damaged	70		10		63	Approve			
	3	1			FRONT DOOR OUTER HANDLE SMALL COVER WITH REMOTE LH			Dented	20		10		18	Approve			
	4	1			FRONT DOOR OUTER HANDLE REMOTE SWITCH LH			Serviceable	0	0	0	0	0	Deny			
	5	1			FRONT DOOR HANDLE GASKET LH			Deformed	30		10		27	Approve			
	6	1			FRONT DOOR HANDLE COVER GASKET LH			Serviceable	0	0	0	0	0	Deny			
	7	1			FRONT DOOR HANDLE INNER BASE GARNISH LH			Serviceable	0	0	0	0	0	Deny			
	8	1			FRONT DOOR WINDOW GLASS LH			Broken	350		10		315	Approve			
	9	1			FRONT DOOR WINDOW REGULATOR LH			Serviceable	0	0	0	0	0	Deny			

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	 10	1			FRONT DOOR WINDOW REGULATOR MOTOR LH			Serviceable	0	0	0	0	0	Deny	
	 11	1			FRONT DOOR WINDOW GLASS MOULDING LH			Serviceable	0	0	0	0	0	Deny	
	 12	1			FRONT DOOR LOWER HINGE LH			Serviceable	0	0	0	0	0	Deny	
	 13	1			FRONT DOOR LOWER HINGE LH			Serviceable	0	0	0	0	0	Deny	
	 14	1			FRONT DOOR LOCK LH			Serviceable	0	0	0	0	0	Deny	
	 15	1			FRONT DOOR OUT WEATHER STRIP LH			Bent	134		10		120.6	Approve	
	 16	1			FRONT DOOR INNER SEAL LH			Serviceable	0	0	0	0	0	Deny	
	 17	1			FRONT DOOR INNER MOULDING LH			Serviceable	0	0	0	0	0	Deny	
	 18	1			FRONT DOOR INNER LOWER SEAL LH			Serviceable	0	0	0	0	0	Deny	
	 19	1			FRONT REAR DOOR MOULDING (BLACK STICKER) LH			Necessary	40		10		36	Approve	
	 20	1			FRONT DOOR INNER TRIM LH			Serviceable	0	0	0	0	0	Deny	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/LBTR%	DISC QUNTY	SALV AGE%	PART PRCE(NET)	ACTION (PARTS)	REMOVE
	21	1			FRONT DOOR RETRACTOR /CHECK LH			Serviceable	0	0	0	0	0	Deny	
	22	1			SIDE SKIRT LH			Dented	435		10		391.5	Approve	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		S-PAINTING B-PILLAR LH ,SKIRT LH,FRONT FENDER LH AND 2 DOORS LH	900	0	0	Approve		
	2		REPAIR ,REPLACE AND REFILL AFFECTED ACCIDENT AREA	600	0	0	Approve		
	3		TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR	50	0	0	Approve		
	4		RESET SRS AND DOOR LOCK SENSOR (REMOTE	150	0	0	Approve		
	5		CHECK AND RECTIFY ELECTRICAL WIRING	30	0	0	Approve		

Assessment Details

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR 4 DAYS	Approve			
	2	GLASS SOLAR FILM LH FRONT DOOR WINDOW	Approve	150	NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Claim Amount
Claim Amount		\$3,574.60							\$3,574.60
CATEGORY		ESTIMATE	REVISED AMOUNT						
Labour		\$1,630.00	\$1,630.00						
Miscellaneous		\$150.00	\$150.00						
Spare Parts		\$1,794.60	\$1,794.60						

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Claim Amount
Claim Amount		\$2,850.00							\$2,850.00
CATEGORY		ESTIMATE	REVISED AMOUNT						
Miscellaneous		\$2,850.00	\$2,850.00						