



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1806-049
DATE : 4-Jun-2018
POLICY NO. : FWD PNPV2017-00001982-01
VEHICLE REG. NO. : SKE1188D
VEHICLE MAKE : MITSUBISHI ASX 2.0 6-CVT (M)

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Door LH ✓ DMG	1	\$ 1,080.00	\$ 1,080.00
2	Front Door Outer Handle LH ✓ DMG	1	\$ 70.00	\$ 70.00
3	Front Door Outer Handle Small Cover with Remote LH ✓ DT	1	\$ 20.00	\$ 20.00
4	Front Door Outer Handle Remote Switch LH ?	1	\$ 80.00	\$ 80.00
5	Front Door Handle Inner Gasket LH ✓ Deform	1	\$ 30.00	\$ 30.00
6	Front Door Handle Inner Cover Gasket LH ?	1	\$ 30.00	\$ 30.00
7	Front Door Handle Inner Base Garnish LH ?	1	\$ 120.00	\$ 120.00
8	Front Door Window Glass LH ✓ BR	1	\$ 350.00	\$ 350.00
9	Front Door Window Regulator LH ?	1	\$ 140.00	\$ 140.00
10	Front Door Window Regulator Motor LH ?	1	\$ 400.00	\$ 400.00
11	Front Door Window Glass Moulding LH ?	1	\$ 50.00	\$ 50.00
12	Front Door Lower Hinge LH ?	1	\$ 50.00	\$ 50.00
13	Front Door Lower Hinge LH ?	1	\$ 50.00	\$ 50.00
14	Front Door Lock LH ?	1	\$ 280.00	\$ 280.00
15	Front Door Out Weather Seal LH ✓ BT	1	\$ 150.00	\$ 150.00
16	Front Door Inner Seal LH ?	1	\$ 220.00	\$ 220.00
17	Front Door Inner Moulding LH ?	1	\$ 120.00	\$ 120.00
18	Front Door Inner Lower Seal LH ?	1	\$ 120.00	\$ 120.00
19	Front Rear Door Moulding (Black Sticker) LH ✓ NEL	1	\$ 40.00	\$ 40.00
20	Front Door Inner Trim LH ?	1	\$ 790.00	\$ 790.00
21	Front Door Retractor/Check LH ?	1	\$ 40.00	\$ 40.00
22	Side Skirt LH ✓ DT	1	\$ 490.00	\$ 490.00
Total Spare Parts				\$ 4,720.00
	SPECIAL NETT			
23	Glass Solar Film LH for Front Door Window ✓	1	\$ 150.00	\$ 150.00
Total Special Nett				\$ 150.00
	LABOUR			
24	S-painting B-Pillar LH, Skirt LH, Front Fender LH and 2 Doors LH	1	\$ 1,200.00	\$ 1,200.00 800
25	Repair, Replace and Refill Affected Accident Area	1	\$ 800.00	\$ 800.00 600
26	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00 50
27	Reset SRS and Door lock Sensor/Remote	1	\$ 150.00	\$ 150.00 150
28	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00 ✓



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1806-049
DATE : 4-Jun-2018
POLICY NO. : FWD PNPV2017-00001982-01
VEHICLE REG. NO. : SKE1188D
VEHICLE MAKE : MITSUBISHI ASX 2.0 6-CVT (M)

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan			Total Labour	\$ 2,280.00
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.			Amount Before Excess	\$ 7,150.00
			Add GST @ 7%	500.50
			Total Amount Payable	\$ 7,650.50

Please arrange this vehicle to be surveyed soonest possible. Thank you.

sebasthanyang@lkkauto.com

Sathya Sai
5/6/2018

- Lump Sum Repair
- Question mark item photo
- Photo after paint

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: