

INS. CASE OWNER:

CC 3/CTI18010028, F24312

LKK:

IDAC:

Surveyor:

talin

DOI:

16/18

Date / Time:

11/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFE 6550

Name of Insured:

HONG KONG POO

Insured Tel No.:

HP:

900 50503

Excess Sec II :SS

D.O.A.:

21/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

GWM180074640015

Policy No.:

DMP65W1648601701

Make / Model:

BMW

Place of Accident:

TAK MYE LANE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability:

%

Final ? Yes / No

SMA 345E



INSRS:

WSP:

Tel:

Liability:

RMKS:

COBE

WS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/6/18
AzhurSMA 345E - 12/11/17 01:40/11/17 01:40/11/17 01:40
SFE 6550 - X

7.6.18 @ 12:40

CALLED TO CONFIRMED ACCIDENT. ON REAR END TP. MYOM
TP CLAIM. OI WOULD LIKE TO KNOW THE FINAL AMOUNT BEFORE
SETTLEMENT AS THE MAY WANT TO DO PRIVATE SETTLEMENT.

RECEIVED 18 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 07.06.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 7.6.18

Sent By: ISP

FINALIZATION

Date/Time: 8.6.18

Confirm with: LM KE

Confirm by: AMK

Repair Cost:

PIP SS151.72

(2 days)

Reduction:

56 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 11.7.18

Confirm with: WILLIAM

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

W/L59

SS1617.60

OI REAR ENDED TP.

Loss of Rental (LOR):

SS 468.00

(4 days)

x 117

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS 200.00

(\$ 50

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☒

(Tick only one)

GIA/LTA Search

SS 7.99

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

400

Total:

SS 2,293.09

Global Sum SS:

FINAL PAYMENT

Date/Time: 11.7.18

Confirm with: WILLIAM

Email ☒ Call ☐

Payee 1:

SS 2,293.09

Name 1:

COMFORTDEIGNO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18010028/K1eb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 04-06-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 655D	Veh. Inspected	SHA 345E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/05/2018	Inspection Date	01/06/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18010028/K1eb3

Date: 07.06.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA345E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.06.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,457.18
Revised Estimate Amount	: S\$	1,511.78
"Check" Items Amount	: S\$	845.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Tuesday, 5 June 2018 4:40 PM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Asher Sng (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SKE655D (OI : CTI - SNM18D02769C02/5) and SHA345E (TP : LKK REF -CC3/CTI18010028/K1eb3) on 31.05.2018
Attachments: MSYH18071198-SKE655D.pdf

Dear Shu Pei,

As requested, attached a copy of our insured's GIA report for your perusal.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6225 5879
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 4 June, 2018 6:05 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: Direct Settlement - Accident Involving SKE655D (OI : CTI - TBA) and SHA345E (TP : LKK REF - CC3/CTI18010028/K1eb3) on 31.05.2018

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHA 345E at M/s ComfortDelGro Engineering Pte Ltd.

Enclosed for your perusal is:
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Date/Time: 01.06.2018 15:07 Page : 1

am: ARC Repair TP(CFS0)1

JOB CARD Sales Order:

JC NO305168188

OMER
IS CITYCAB PTE LTD
OMER NO 7010070
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188
(R) (O)
(P)

REGN NO SHA 345E	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 01.06.2018 10:40
YR OF MANU 25.08.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU092658	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 31.05.2018
ATURE: 3P 31.05.2018

NO LABOR CODE DESCRIPTION

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHA 345E LKE

Vehicle No.: SHA 345E

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHH 345E

MAKE :

MODEL : HYUNDAI i40

DATE 1/6/2018 12:23

LKK/Kalvin

Pbyl

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (RH)			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Rear Bumper Reverse Sensor			\$ 135.70 Nett
	Rear Bumper Rubber Mat			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH)	\$	100.00	\$ 200.00 Nett
				\$ 385.70
	Labour Charge			
	Panel Beating-Repair Fender			\$ 850.00 ²⁰⁰
	Spray Painting Charge-Fender/Bumper			\$ 500.00 ²⁰⁰
	Wiring Charge			\$ 50.00 ^X
	R/Refix Reverse Sensor			\$ 120.00 ²⁰
	TOTAL LABOUR			\$ 1,520.00
	ESTIMATE TOTAL			\$ 3,457.18

Kalvin LKK
 1/6/18 1520hrs
 2 Pys
 P/P
 Before Part pld

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 345Z

MAKE :

MODEL : HYUNDAI i40

DATE 1/6/2018 12:23

LKK/kalvin
Like- PbyP
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Rebuilt</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>Rebuilt</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Rebuilt</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>Rebuilt</i>			\$ 49.00	
	Rear Bumper Clips <i>Rebuilt</i>			\$ 22.00	
	Rear Bumper Sponge <i>Rebuilt</i>			\$ 143.40	
	Rear Bumper Under Cover <i>Rebuilt</i>			\$ 225.00	
	Rear Bumper Reflector Lamp (RH) <i>Rebuilt</i>			\$ 32.00	
	SUB TOTAL			\$ 1,939.35	
	LESS 20%			\$ 387.87	
	DISCOUNTED TOTAL			\$ 1,551.48	
	 Rear Bumper Reverse Sensor <i>shorted</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat <i>Rebuilt</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>Rebuilt</i>		\$ 100.00	\$ 200.00	Nett
				\$ 385.70	
	 Labour Charge				
	Panel Beating-Repair Fender			\$ 850.00 <i>200</i>	
	Spray Painting Charge-Fender/Bumper			\$ 500.00 <i>200</i>	
	Wiring Charge			\$ 50.00 <i>20</i>	
	R/Refix Reverse Sensor			\$ 120.00 <i>20</i>	
	TOTAL LABOUR			\$ 1,520.00	
	ESTIMATE TOTAL			\$ 3,457.18	
<i>Kalvin LKK</i> <i>1/6/18 1520hrs</i> <i>2 Pys</i> <i>P/P</i> <i>Before Part phd</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305168188
REGN NO : SHA 345E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 01.06.2018 10:40
ACCIDENT DATE : 31.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	603.60	20.00	482.88
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	225.00	20.00	180.00
0004 04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1 L	32.00	20.00	25.60
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00-	135.70
0006 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	0.20	50.00

SUB-TOTAL : 891.78

JOB NATURE

0000 20-05	RENEW ADVERTISMENT STICKER-	200.00
0001 L	PANEL BEATING	200.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0003 L	REMOVE/REFIX REAR REVERSE SENSOR	20.00

SUB-TOTAL : 620.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 08.06.2018

Time: 13:41:36

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305168188
REGN NO : SHA 345E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 01.06.2018 10:40
ACCIDENT DATE : 31.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,511.78

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No 305168188
Date : 08/06/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. SHA345E CCPL

Fax :

31.05.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SKE655D
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$891.78
(b) Labour Charges	\$620.00
Total for Part-By-Part Repair Cost	\$1,511.78
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : KALVIN ANG
Date : 8/6/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18010028/K1eb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 19-07-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKE 655D	Veh. Inspected	SHA 345E
Policy No.	DMPCSN1648601701	Coverage (\$)	0.00
Claim No.	SNM18D02769C02/5	Excess (\$)	0.00
Assign From		Assign Date	01/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU092658	Colour	YELLOW
Odometer	273390	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/05/2018	Inspection Date	01/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 345E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	CUT	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (RH)	CRACKED	32.00	32.00
	LESS 20% DISCOUNT		-387.87	-176.52
			1,551.48	706.08
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			385.70	385.70
<u>LABOUR</u>				
	PANEL BEATING-REPAIR FENDER.		850.00	200.00
	SPRAY PAINTING CHARGE-FENDER/BUMPER.		500.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	R/REFIX REVERSE SENSOR.		120.00	20.00
			1,520.00	420.00
GRAND TOTAL			3,457.18	1,511.78
RECOMMENDED COST OF REPAIRS				1,511.78

Report Ref No. CC3/CT18010028/K1eb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.