

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 345E

MAKE :

MODEL : HYUNDAI i40

DATE 1/6/2018 12:23

LKK/kalvin

PbyP

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ✓			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	Rear Bumper Reflector Lamp (RH) ✓			\$ 32.00	
	SUB TOTAL			\$ 1,939.35	
	LESS 20%			\$ 387.87	
	DISCOUNTED TOTAL			\$ 1,551.48	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 385.70	
	Labour Charge				
	Panel Beating-Repair Fender			\$ 850.00	200
	Spray Painting Charge-Fender/Bumper			\$ 500.00	200
	Wiring Charge			\$ 50.00	x
	R/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 1,520.00	
	ESTIMATE TOTAL			\$ 3,457.18	

Kalvin LKK
 1/6/18 1520hrs
 2 Pys
 P/P
 Before Part p/h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: