

SERVICE ESTIMATE

86974 - C00001 SL: SERVICE SALES - PC
 Ms Van Burm Kristin Maria Willy
 107 Mariam Way

Singapore 508610

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Ms Van Burm Kristin

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 04/06/2018
 WIP No. . : 63936
 Veh.In/Out:
 *Tel.No. . : Mobile: 97487909
 Reg.No. . : SLD2506G
 Reg.date . : 09/06/2016
 Mileage .. : 0
 Chassis No: YV1MV28H0G2330016

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR SPOILER, REAR SENSOR, ETC	0	1600.00	0		1,600.00	\$ 800
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC	0	1000.00	0		1,000.00	\$ 700
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00	\$ ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	\$ ✓
	V039814190/BUMPER CO	1.0 EA	1186.50			1,186.50	\$ de ✓
	TOW COVER REAR V40 1	1.0 EA	73.90			73.90	\$ mis ✓
	BUMPER BRACKET LHR V	1.0 EA	88.70			88.70	\$ see ✓
	BUMPER BRACKET RHR V	1.0 EA	88.70			88.70	\$ see ✓
	BUMPER SPOILER REAR	1.0 EA	486.40			486.40	\$ cut ✓
	BUMPER RAIL (BEAM) R	1.0 EA	1336.30			1,336.30	\$?
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00	\$ see ✓

L-2010
 R-216/4
 ? - 1336.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanjer 97495749
 12/6/18 @ 130pm
 Resurvey before paint
 03 days
 sur @ thant.u.u.

SERVICE ESTIMATE

86974 - C00001 SL: SERVICE SALES - PC
 Ms Van Burm Kristin Maria Willy
 107 Mariam Way

Singapore 508610

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Ms Van Burm Kristin

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 04/06/2018
 WIP No. . : 63936
 Veh.In/Out:
 *Tel.No. . : Mobile: 97487909
 Reg.No. . : SLD2506G
 Reg.date. : 09/06/2016
 Mileage . : 0
 Chassis No: YV1MV28H0G2330016

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER CLIP	10.0 EA	4.80			48.00	S <i>all</i> /
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S <i>all</i> /
	ADHESIVE TUBE CHEMIC	1.0 EA	75.80			75.80	S <i>all</i> /

			Gross Total.	6,607.70
Labour Total	3,110.00		Net.....	6,607.70
Parts Total	3,497.70		GST @ 7.0%	462.54
Package Total	0.00		Total.....	7,070.25
			Paid.....	0.00
			Please Pay..	7,070.25

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated