

175309

INS. CASE OWNER:

CC 4, A16 180 (0038)

LKK

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

4/6/18

Date / Time:

4-6-18

Registered in Merimen:

4-6-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

STJ 5915D

Name of Insured:

Leo Soon Hual

Insured Tel No.:

HP:

96498679

Excess Sec II :SS

D.O.A:

31/5/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

200170075.

7. A115

PIE 7 SL6 / CTE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Men's United



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/6
11H

STJ 5915D, X; STJ 5915D, X

OI car ended to TP.

MINAUBD

ORIGINAL TP LOB IN

28-11-18

FILE TP TRANSFER FROM THIN2 TO JUT.

25/06/19

TP Accubed OFFER.
ALL DOCS IN ORDER
TO CLOS.

6/19 search date is diff in VPA.

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI

After call ltr to OI. 12/12/18 - UK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill

Car Rental Invoice:

Towing Invoice

ITA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

PRELIMINARY ADVICE Date/Time:

Sent By:

ASS. REC. BY:

REF:

1461

Kearney

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKH 5624 Yr Regn: 10, 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy AIA c.c. 1598

Colour: M. Gold AC: Insured / Std / NI / NA

Sp. Reading: 80449 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053RE10414P573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 3/15/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 4/6/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/6 File pass to Catherine

L/G \$ 7,700.00

RBD: \$ 4,279.15 (55%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJT 5915D
Accident Date : 31-May-2018

No. : 05788

Date : 01-Jun-2018

Our Ref : 218092 (AIG) / CHAN

PAGE : 1

LIM BENG BEE
BLK 218 BISHAN ST 23
#01-299
Singapore 570218

Not Authorized
6/1 Jun @ 770d
Recovery After Pain
9 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SKH562Y

1 pc Boot lid		<i>B₂</i> 754.30	—
1 pc Boot lid rubber		<i>DIT/IN</i> 175.30	<i>John 87.65</i>
1 pc Boot lid inner lock		<i>R</i> 96.50	—
2 pcs Boot lid hinge		<i>B₂</i> 120.40	✓
1 pc Boot lid inner trim	@ S\$ 60.20	<i>CM</i> 259.10	✓
12 pcs Boot lid inner trim clip	@ S\$ 3.80	<i>R</i> 45.60	✓
2 pcs Boot lid reflector	@ S\$167.20	<i>CM</i> 334.40	✓
1 pc Boot lid outer chrome		<i>CM</i> 382.90	—
1 pc Boot lid "1.6" emblem		<i>R</i> 32.40	—
1 pc Boot lid "VVT-i" emblem		<i>R</i> 38.70	—
1 pc Boot lid "COROLLA" emblem		<i>R</i> 42.30	—
1 pc Boot lid "ALTIS" emblem		<i>R</i> 44.20	—
1 pc Boot lid logo		<i>R</i> 52.10	—
2 pcs Taillamp	@ S\$281.90	<i>CM</i> 563.80	—
2 pcs Taillamp corner panel	@ S\$ 76.80	<i>R</i> 153.60	✓
2 pcs Taillamp lower bracket	@ S\$ 72.70	<i>DIT</i> 145.40	—
1 pc Rear end panel		<i>B₂</i> 552.20	—
1 pc End panel top garnish		<i>mg DIT</i> 185.20	—
2 pcs End panel top garnish clip	@ S\$ 3.90	<i>R</i> 7.80	—
1 pc Spare tyre board		<i>CM</i> 348.10	—
1 pc Rear bumper fascia		<i>B₂</i> 482.10	—
1 pc Rear bumper reinforcement		<i>CM</i> 157.50	—
2 pcs Rear bumper bracket	@ S\$ 82.80	<i>R</i> 165.60	✓
2 pcs Rear bumper side retainer (L)	@ S\$ 66.80	<i>DIT</i> 133.60	✓
2 pcs Rear bumper side retainer (S)	@ S\$ 29.40	<i>DIT</i> 58.80	—
2 pcs Rear bumper reflector	@ S\$ 37.20	74.40	✓ <i>1/2 only</i>
1 pc Rear o/s fender		<i>R</i> 828.90	X
1 pc Rear w/s glass moulding		<i>R</i> 75.60	X

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJT 5915D

Page : 2

- 1 pc Front bumper fascia
- 2 pcs Front bumper side retainer
- 1 pc Front bumper reinforcement
- 1 pc Front bumper lower grille
- 2 pcs Headlamp
- 1 pc Radiator grille
- 1 pc Radiator grille logo
- 1 pc Radiator support panel
- 1 pc Brace panel

o/s d.i

@ S\$ 50.80

ngcm @ S\$525.30

Rn 459.70

At 101.60

D.1 339.70

139.80

ngcm 1,050.60

ngcm 287.30

sn 64.30

R 715.30

R 103.10

Less 25% :

9,572.20

2,393.05

7521.70

1880.43

5641.27

7,179.15

50.00 sn

50.00 sn

300.00 sn

60.00 sn

30.00 sn

20.00

150.00

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

1,800.00

1200

601

120.00

100.00

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJT 5915D

Page : 3

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1200

2,000.00

Total : S\$11,979.15
=====

Singapore Dollars Eleven Thousand Nine Hundred
and Seventy Nine and Cents Fifteen Only

L/Sum

7700

@ 10 days

↑
Kennerly PUS
Co. 7/12/15

R 5641.27

SN 377.65

L 2860.00

8578.52

-10% 857.89

7721.03

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport
/Company Cert No.: S0172724I

Owner ID Type: Singapore NRIC

Owner Name: LIM BENG BEE

Registered Address: APT BLK 218 BISHAN STREET 23 #01-299 SINGAPORE 570218

Mailing Address: -

Birth Date: 30 Oct 1954

Vehicle Particulars

Vehicle No.: SKH562Y

Previous Vehicle No.: -

Effective Date of Ownership: 30 Oct 2012

Original Regn Date: 30 Oct 2012

Registration Date: 30 Oct 2012

Year of Manufacture: 2012

Vehicle Type: Passenger Motor Car

Vehicle Scheme: -

Vehicle Attachment 1: No Attachment

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Beige

Secondary Colour: -

Passenger Capacity: 4

Chassis No.: MR053REE104149573

Engine No.: 1ZRX231423

Engine Capacity /Power Rating: 1598 cc / -

Maximum Power Output: 90.0 kW (120 bhp)

Propellant: Petrol

Max Unladen Weight:	1195 kg
Maximum Laden Weight:	1630 kg
Open Market Value:	\$14,944.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2022
Minimum PARF Benefit:	\$7,472.00
No. of Transfers:	0
IU Label No.:	1124807314
COE No.:	2012100101000269K
COE Expiry Date:	29 Oct 2022
COE Category:	A - Car (1600cc & below)
COE Registration Category:	A - Car (1600cc & below)
Quota Premium (QP) / Prevailing Quota Premium:	\$68,000.00 / -
Actual QP Paid:	\$68,000.00
QP (Regn Cat):	\$68,000.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$68,000.00
Additional Registration Fee Rate:	100.00 %
Actual ARF Paid:	\$14,944.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category A.



Best Value For Money! Fuel Efficiency And Money Saver For Your Family! Enjoy A Smooth Drive With Toyota Reliability And Durability! Previous Owner Was A Lady Teacher Who Has Taken Care Of This Car Meticulously...

Car House Pte Ltd

Posted: 23 May 2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Allion 1.5A (New 5-yr COE)

-

N.A

16-Jul-2008

1,496 cc

-

Sedan

SOLD

Option With 10 Years COE \$54800. Army Owner Unbelievable Selling At Lowest Depreciation With 100% Guaranteed Just Inspected Toyota Allion In The Market. Fully Maintained And Well Taken Care By Owner S...

Posted: 23 May 2018 Tags: 2008 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



Toyota Corolla Altis 1.6A

\$50,800

\$10,420 /yr

25-Jul-2012

1,598 cc

96,223 km

Sedan

Available

Rare! Genuine Low Mileage Done Of 95223km! Like New Condition, Test Drive/See To Certify. 1 Expat Owner, Rarely Use. New Car Number. New Michelin Tyres. 100% Accident Free. Price Negotiable. Call Now!

Like View Credit Pte Ltd

Posted: 23 May 2018 Tags: 2012 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Let's help you 2888 K7

Many auspicious and rare car plates for sale at a good price! Get lucky today with our Bidded car plate numbers for sale!

Find out more!



Toyota Corolla Altis 1.6A

\$33,666

\$6,820 /yr

08-May-2008

1,598 cc

113,868 km

Sedan

Available

Elegance (COE till 05/2023)

One Of The Best Toyota Altis 1.6A Elegance For 5 Years COE Renewal In Stock Now. Very Well Maintained By Previous Owner. Transmission And Engine Still In Excellent State. Guarantee No Repair Needed. L...

Creative Auto

Posted: 23 May 2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$93,800

\$8,810 /yr

17-Oct-2017

1,598 cc

-

Sedan

Available

Elegance

Posted: 23 May 2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Vios 1.5A E (New 5-yr COE)

\$31,533

\$6,300 /yr

24-May-2008

1,497 cc

-

Sedan

Available

Posted: 23 May 2018 Tags: 2008 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Corolla Altis 1.6A

\$51,800

\$10,080 /yr

25-Oct-2012

1,598 cc

83,000 km

Sedan

Available

1 Owner! Low Mileage! Most Reliable Sedan! Call Now For Viewing.

Posted: 23 May 2018 Tags: 2012 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

-

N.A

26-Feb-2010

1,598 cc

-

Sedan

SOLD

(Buy With Confidence!) 1st Owner Unit. Low Mileage Done. Vehicle Fully Maintained By Agent (Borneo Motor) With Full Servicing History. Purchase And Enjoy 6 Months Engine And Gearbox Protection Plan With...

Sincere Motoring Pte Ltd

Posted: 23 May 2018 Tags: 2010 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE)

\$34,800

\$6,950 /yr

27-Mar-2008

1,598 cc

-

Sedan

Available

1 Owner Only! Fully Refurbished, New Paintwork, Fully Agent Maintained Since Day One, Well Maintained, Excellent Condition! Minimum Down Payment With Bank Or In House Loan Available. Call For More Enq...

Posted: 23 May 2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Axio 1.5A X

\$65,800

\$8,060 /yr

06-Apr-2016

1,496 cc

14,508 km

Sedan

Available

Lowest Price In Market! \$0 Down Payment Drive Away! Low Mileage Done, Fast Sales Hurry Before It's Too Late. Tip Top Condition Inside Out. Trade In Welcome. All Type Loan Available. Buy With A Peace Of Mind...

Benelli Auto Enterprise Pte Ltd

Posted: 23 May 2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$79,999

\$8,990 /yr

21-Mar-2016

1,598 cc

19,959 km

Sedan

Available

Elegance

Lowest Price In Market! \$0 Down Payment Drive Away! Low Mileage Done, Fast Sales Hurry Before It's Too Late. Tip Top Condition Inside Out. Trade In Welcome. All Type Loan Available. Buy With A Peace Of Mind...

Benelli Auto Enterprise Pte Ltd

Posted: 23 May 2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

For viewing Toyota Corolla Altis 1.6A 25-Oct-2012

To compare cars, select from the search results.

To compare cars, select from the search results.

To compare cars, select from the search results.

Add to Shortlist

Compare Now

Clear All

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2724I

Vehicle Details

Vehicle No.: SKH562Y
Vehicle to be Exported: Yes
Intended De-registration Date: 01 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Beige
Manufacturing Year: 2012
Engine No.: 1ZRX231423
Chassis No.: MR053REE104149573
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$14,944.00
Original Registration Date: 30 Oct 2012
First Registration Date: 30 Oct 2012
Transfer Count: 0
Actual ARF Paid: \$14,944.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Oct 2022
PARF Rebate Amount: \$10,460.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$68,000.00
COE Rebate Amount: \$29,978.00
Total Rebate Amount: \$40,438.00

The information contained herein is correct as at 01 Jun 2018

OK

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05788

Vehicle Insured : SJT 5915D
Accident Date : 31-May-2018

Date : 01-Jun-2018

Our Ref : 218092 (AIG) / CHAN

PAGE : 1

LIM BENG BEE
BLK 218 BISHAN ST 23
#01-299
Singapore 570218

*Not Authorized
6/1/2018
Resony After Pain*

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SKH562Y

1 pc	Boot lid			<i>Bz</i>	754.30	<i>1</i>
1 pc	Boot lid rubber			<i>DIS/IN</i>	175.30	<i>50/10</i>
1 pc	Boot lid inner lock			<i>IN</i>	96.50	<i>1</i>
2 pcs	Boot lid hinge	@ S\$ 60.20		<i>Bz</i>	120.40	<i>✓</i>
1 pc	Boot lid inner trim			<i>CM</i>	259.10	<i>✓</i>
12 pcs	Boot lid inner trim clip	@ S\$ 3.80		<i>IN</i>	45.60	<i>✓</i>
2 pcs	Boot lid reflector	@ S\$167.20		<i>DIS/CM</i>	334.40	<i>✓</i>
1 pc	Boot lid outer chrome			<i>CM</i>	382.90	<i>1</i>
1 pc	Boot lid "1.6" emblem			<i>IN</i>	32.40	<i>1</i>
1 pc	Boot lid "VVT-i" emblem			<i>IN</i>	38.70	<i>1</i>
1 pc	Boot lid "COROLLA" emblem			<i>IN</i>	42.30	<i>1</i>
1 pc	Boot lid "ALTIS" emblem			<i>IN</i>	44.20	<i>1</i>
1 pc	Boot lid logo			<i>IN</i>	52.10	<i>1</i>
2 pcs	Taillamp	@ S\$281.90		<i>CM</i>	563.80	<i>1</i>
2 pcs	Taillamp corner panel	@ S\$ 76.80		<i>Bz</i>	153.60	<i>1</i>
2 pcs	Taillamp lower bracket	@ S\$ 72.70		<i>DIS</i>	145.40	<i>1</i>
1 pc	Rear end panel			<i>Bz</i>	552.20	<i>1</i>
1 pc	End panel top garnish			<i>IN DIS</i>	185.20	<i>1</i>
2 pcs	End panel top garnish clip	@ S\$ 3.90		<i>IN</i>	7.80	<i>1</i>
1 pc	Spare tyre board			<i>CM</i>	348.10	<i>1</i>
1 pc	Rear bumper fascia			<i>Bz</i>	482.10	<i>1</i>
1 pc	Rear bumper reinforcement			<i>CM</i>	157.50	<i>1</i>
2 pcs	Rear bumper bracket	@ S\$ 82.80			165.60	<i>✓</i>
2 pcs	Rear bumper side retainer (L)	@ S\$ 66.80		<i>DIS</i>	133.60	<i>✓</i>
2 pcs	Rear bumper side retainer (S)	@ S\$ 29.40		<i>DIS</i>	58.80	<i>✓</i>
2 pcs	Rear bumper reflector	@ S\$ 37.20			74.40	<i>4</i>
1 pc	Rear o/s fender			<i>R</i>	828.90	<i>X</i>
1 pc	Rear w/s glass moulding			<i>IN</i>	75.60	<i>X</i>

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJT 5915D

Page : 2

1 pc Front bumper fascia	<i>o/s d.i</i>	<i>Pr</i> 459.70	✓
2 pcs Front bumper side retainer	@ S\$ 50.80	101.60	<i>4</i>
1 pc Front bumper reinforcement		339.70	<i>?</i>
1 pc Front bumper lower grille		<i>d.i</i> 139.80	✓
2 pcs Headlamp	@ S\$525.30	1,050.60	<i>?</i>
1 pc Radiator grille		287.30	<i>?</i>
1 pc Radiator grille logo		64.30	<i>?</i>
1 pc Radiator support panel		715.30	<i>?</i>
1 pc Brace panel		<i>A</i> 103.10	<i>X</i>
		9,572.20	
	Less 25% :	2,393.05	

1 pc Front no.plate with box	<i>Pr</i> 7,179.15	<i>65m</i>
1 pc Rear no.plate with box	<i>Pr</i> 50.00	<i>sn 45</i>
1 pc Rear bumper reverse sensor(set	<i>shot 200sn</i> 300.00	<i>sn</i>
1 pc Rear w/s glass sealant	<i>nn</i> 60.00	<i>sn X</i>
1 pc Radiator coolant		30.00 <i>sn ?</i>

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To remove & refix rear windscreen glass and conduct water leak test.

nn 150.00 *X*

To remove roof lining, front and rear seats, trim board and carpet

120.00 *801*

To remove air con condenser, pipes and drier, vacuum and to recharge gas

120.00 *?*

To apply undersealing

100.00 *601*

To putty and spray replaced parts

1,800.00 *1200*

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJT 5915D

Page : 3

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1200
2,000.00

Total : S\$11,979.15

=====

Singapore Dollars Eleven Thousand Nine Hundred
and Seventy Nine and Cents Fifteen Only

Joy Irene (LKKAUTO)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Friday, 16 November 2018 2:24 PM
To: Joy Irene (LKKAUTO)
Subject: RE: Accident Involving GBG2481X & SKQ9644M On 19/10/2017 | 2556584855SG-003

Hi Joy,

Appreciate if you could justify the damages on parts mentioned below:

5 *TAILGATE REFLECTORS
13 *REAR SPARE TYRE COMPARTMENT TOP BOARD
15-17 (16) BEND

27-28

NECESSARY ASK SURVAYOR TO COMMENT.
Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: 16 November 2018 11:47 AM
To: Ler, Bernard-JQ
Subject: RE: Accident Involving GBG2481X & SKQ9644M On 19/10/2017 | 2556584855SG-003

Hi Bernard,

Re-inspection photos uploaded in Meirmen.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

PLEASE CHECK
IF SURVAYOR HAS TAKEN PHO
ON PARTS MENTIONED?

CRACKED
DEFORMED
BEND

27 HEAD LAMP LH
28 REAR BUZZER SENSOR

From: Ler, Bernard-JQ [mailto:Bernard-JQ.Ler@aig.com]
Sent: Friday, 16 November 2018 11:09 AM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: Accident Involving GBG2481X & SKQ9644M On 19/10/2017 | 2556584855SG-003

Dear Joy,

We refer to the subject above and your mandate request.

Kindly provide justification/damaged photographs for the below items:

5 *TAILGATE REFLECTORS
13 *REAR SPARE TYRE COMPARTMENT TOP BOARD
15-17
27-28

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Olivia Lau (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 25 April, 2019 11:34 AM
To: Olivia Lau (LKKAuto)
Subject: FW: Our Ref: 23899259365G-003 || Mandate request (TP veh: SKH 562Y) WSP ALAN'S UNITED

Categories: Orange Category

From: Tan, Bennie-WZ [mailto:Bennie-WZ.Tan@aig.com]
Sent: Monday, 14 January 2019 11:31 AM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref: 23899259365G-003 || Mandate request (TP veh: SKH 562Y) WSP ALAN'S UNITED

Hi Joy

Please refer below on our In House comment:

23	2	*REAR BUMPER BRACKET	Best	165.60 FL	*165.60 FL X 165.60 FL
----	---	----------------------	------	-----------	------------------------

Thank you.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenlon Way #08-16 Singapore 079120
Tel +65 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]
Sent: Friday, January 11, 2019 2:18 PM
To: Tan, Bennie-WZ
Cc: Kenneth Kong (LKKAuto); Admin A
Subject: RE: Our Ref: 23899259365G-003 || Mandate request (TP veh: SKH 562Y) WSP ALAN'S UNITED

Hi Bennie,

We uploaded re-survey photos in Merimen.

For item no 5. Rear Bumper Bracket, our surveyor is asking to expound the comment "not fitted"

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
818 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5408933

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Joy Irene (LKKAuto)
Sent: Wednesday, 9 January 2019 8:54 AM
To: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Cc: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref: 23899259365G-003 || Mandate request (TP veh: SKH 562Y) WSP ALAN'S UNITED

Hi Bennie,

Forwarding your comments to our Mr. Kenneth for review.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
818 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5408933

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Tan, Bennie-WZ [mailto:Bennie-WZ.Tan@aig.com]
Sent: Tuesday, 8 January 2019 11:55 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: Our Ref: 23899259365G-003 || Mandate request (TP veh: SKH 562Y)

Hi Joy

Referring to the above matter.

Below is our In-House comments on the following parts:

Print Received Message

This mail is associated with :

***SKH562Y (2389925936SG)**
[SJT5915D]
TP
LIM BENG BEE
May 31 2018 9:00PM
[LEE SOON HUAT]
Alan's United Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 01/05/2019 00:21 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$\$9000.00) - SKH562Y - Claim Handler: Tan, Bennie-WZ

Approved:9000.00:Pls do your utmost to negotiate settlement at best from: \$8600-9000 (All-in).

Print Received Message

This mail is associated with :

***SKH562Y (2389925936SG)**
[SJT5915D]
TP
LIM BENG BEE
May 31 2018 9:00PM
[LEE SOON HUAT]
Alan's United Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/06/2019 10:50 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9400.00) - SKH562Y - Claim Handler: Tan, Bennie-WZ

Approved:9400.00:Pls do your utmost to negotiate settlement at best from: \$9000-9400 (All-in). Our offer is fair and reasonable. Rental commence on 01/06/18 Survey notice received: 04/06/18 Survey conducted: 04/06/18

Kuas

CKK

LIM BENG BEE

c/o Blk 7 Sin Ming Industrial Estate

#01-76

Singapore 575642

Date: 27-7-2018

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIMS DEPT.

78 STENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SKH 562Y AND SJT 5915 D
ALONG PIE (THRU JURONG / NEAR CTE EXIT) ON 31-05-2018

I / We, the owner of Vehicle No. SKH 562Y which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | |
|---|------------------|
| 1. Costs of repair | - \$8339.00 |
| 2. Loss of Use /Rental fees 15 Days (2 Sunday 1 Holiday) | - \$1500.00 |
| 3. Police / GIA report / LTA fees | - \$2.00 |
| 4. Surveyor report fees | - |
| 5. Others | - |
| Total: | <u>\$9741.00</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

13 DECEMBER 2018

LEE SOON HUAT
BLOCK 532 SERANGOON NORTH AVENUE 4
#06-255
SINGAPORE 550532

Dear Sir/Madam,

OUR REF : CC4/AIG18010038/Kha3
YOUR REF : SJT 5915D
ACCIDENT INVOLVING SJT 5915D AND SKH 562Y ALONG PIE TOWARDS SLE ON
31.05.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKH 562Y against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKH 562Y. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT INVOLVING SKH 562 Y AND SJT 5915 D
ALONG P1E (INDS JURONG/NEAR C7E Exit)
ON 31-05-2018

BY THE LETTER OF AUTHORITY, I/We, LIM BENG BEE
NRIC NO. S0172724 I The owner of Vehicle No. SKH 562 Y

Hereby irrevocably appoint Messrs **Alan's United Auto Pte. Ltd.** at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of **Alan's United Auto Pte. Ltd.**
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I/We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by Messrs **Alan's United Auto Pte. Ltd.** of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 01 (day) 06 (month) 2018 (year)



Acknowledged by Owner
(company stamp if applicable)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **ALAN'S UNITED AUTO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$9,400.00** (Global Sum – all in) for vehicle no. **SKH 562Y** that was damaged pursuant to the accident which occurred on **31/05/2018** (date) along **PIE TOWARDS SLE** (location) involving vehicle no/s **SJT 5915D**. This is pursuant to the inspection conducted on **04/06/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **LIM BENG BEE** ("the third party claimant") of vehicle no. **SKH 562Y** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKH 562Y** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25th (day) of Jun (month) **2019** (year)


Kec

Signed by appointed surveyor

Signed by "the workshop" (with chop)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

TAX INVOICE

No. : 225198

Date : 26.07.2018

PAGE : 1

Vehicle Insured : SJT 5915D
Accident Date : 31-May-2018

Our Ref : 218092 (AIG) / CHAN

LIM BENG BEE
BLK 218 BISHAN ST 23
#01-299
Singapore 570218

FINAL REPAIR COST FOR TOYOTA ALTIS SKH562Y

To supply spare parts

To rewire damaged parts and refocus
headlamp beam.

To remove & refix rear windscreen
glass and conduct water leak test.

To remove roof lining, front and
rear seats, trim board and carpet

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

To apply undersealing

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

	7,700.00
Add 7% GST :	539.00
Total :	S\$ 8,239.00

Singapore Dollars Eight Thousand Two Hundred
and Thirty Nine Only

CHIN HUI CAR RENTAL

REGN. NO.: 53090791K

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76, SINGAPORE 575642. TEL: 6453 4680

CUSTOMER

LIM BENG BEE
C/O ALAN'S UNITED AUTO PTE LTD
BLK 7 SIN MING IND. ESTATE
SECTOR C, #01-76
SINGAPORE 575642.

INVOICE NO : **180143**

DATE : 16.06.2018

TERM : CASH

RENTAL FEES FOR :-

s/n	rental veh no.	vha no.	yr reference	no. of day/s	unit pr \$	amount
1	SJU 3479D	8118	SKH 562Y	15	100.00	\$ 1,500.00
		***	*****	***		

PLEASE LET US HAVE YOUR CHEQUE MADE IN FAVOR
OF CHIN HUI CAR RENTAL

TOTAL: **\$ 1,500.00**

YOUR EARLY REMITTANCE IS MUCH APPRECIATED.





CHIN HUI CAR RENTAL

CHIN HUI CAR RENTAL

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76,
SINGAPORE 575642. TEL: 6453 4680
REGN. NO.: 53090791K

VEHICLE RENTAL AGREEMENT

NO: 8118

HIRER'S PARTICULAR		Vehicle No: 87430990		Mileage Out: 134750													
Hirer: LIM BENZ PEE		Make & Model: -10/07/15		Auto / Manual													
NRIC / Passport No: 801727202		Date of Birth: 30/10/1974		OUT : Date: 01/06/18													
Address: BLK 216 BISHAN ST 23		Replace Veh No:		OUT : Time: 12.20pm													
Driving Licence No: 801727202		Pass Date: 15/03/1979		Mileage Out:													
Contact Number: 81232273		OUT : Date:		OUT : Time:													
DRIVERS PARTICULARS (if different from Hirer)		CHARGES															
Appointed Driver: SABEULAHIM (HEW) YAN		Daily 15 @ \$100/- per day 1500.00															
NRIC / Passport No: 887157485		Weekly @ \$ per week															
Date of Birth: 03/06/1987		Monthly @ \$ per month															
Address: BLK 216 BISHAN ST 23		Hours @ \$ per hour															
Driving Licence No: 887157485		Others @ \$															
Pass Date: 12/12/2008																	
Contact Number: 99622167		SUB-TOTAL \$ 1500.00															
 <p>New Insurance Policy Terms & Conditions as at 08-12-2010</p> <p>1. NOT PERMITTED TO DRIVE - Not Covered</p> <ul style="list-style-type: none"> Driver Age 22 years old and below Driver above Age 70 years old Driver less than 2 years Driving Experience <p>2. ADDITIONAL EXCESS - S\$3000.00</p> <ul style="list-style-type: none"> Driver Age 23 to 25 years old with 2 years driving experience Driver Age 65 to 70 years old with 2 years driving experience <p>ADDITIONAL EXCESS S\$3000.00</p>		PETROL LEVEL															
		<table border="1"> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> </table>				Out	E	1/4	1/2	3/4	F	In	E	1/4	1/2	3/4	F
		Out	E	1/4	1/2	3/4	F										
In	E	1/4	1/2	3/4	F												
TOTAL CHARGES \$ 1500.00																	
REMARKS		<p>IMPORTANT!</p> <p>FOR SINGAPORE USE ONLY</p> <p>Excess Liability: S\$2500.00</p> <p>Malaysia Excess (With Prior Consent): NOT A MONITOR</p> <p>Hirer's Signature: </p> <p>Addition Driver's Signature: </p>															
SKN 5627																	
IU: 1123469248																	

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CHIN HUI CAR RENTAL in connection with this agreement is true.

* IMPORTANT

- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AND ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAJ WHERE APPLICABLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CHIN HUI CAR RENTAL.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CHIN HUI CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	SIGNATURE OF HIRER / DRIVER
16/06/18	4.40pm	135786		

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-083528
Date of Request: 01/06/2018

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date 01/06/2018
Enquiry By CHOU HWEE TIAN
TP Vehicle No. SJT5915D
Accident Date 01/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJT5915D	AIG Asia Pacific Insurance Pte. Ltd.	21/10/2017-20/10/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-083528

Date of Request: 01/06/2018

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date 01/06/2018
Enquiry By CHOU HWEE TIAN
TP Vehicle No. SJT5915D
Incident Date 01/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018 Edit Reg		04 Jun 2018 00:00 Edit Adj Rpt	\$7,700.00 Edit Estimates	\$7,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE SOON HUAT, ID: S1458769A								
Main Claimant:	LIM BENG BEE, ID: S01727241								
Vehicle Reg. No.:	SKH562Y	Date of Loss:	31/05/2018 21:00 - :59 [67 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2389925936SG	Policy/Cover Note No.:	2100170075 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT5915D	Policy No. (Claimant):	D71372504QMY						
		Excess:							
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (18/06/2019): Alert - Adj Mandate Approved (\$9400.00) - SKH562Y - Claim Handler: Tan, Bennie-... AIG_SG_EXPRESS (01/05/2019): Alert - Adj Mandate Approved (\$9000.00) - SKH562Y - Claim Handler: Tan, Bennie-... AIG_SG_EXPRESS (08/01/2019): Alert - Adj Mandate Maintained - SKH562Y - Claim Handler: Tan, Bennie-WZ 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKH562Y (2389925936SG)
[SJT5915D]
TP
LIM BENG BEE
May 31 2018 9:00PM
[LEE SOON HUAT]
Alan's United Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown									Edit		
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print		
1	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
2	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
3	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
4	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
5	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
6	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
7	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
8	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
9	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
10	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
11	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
12	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
13	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
14	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
15	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
16	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
17	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
18	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
19	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
20	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
21	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
22	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
23	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
24	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
25	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
26	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
27	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
28	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
29	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
30	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
31	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
32	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
33	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		
34	22/11/18 14:26	General View									Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
					<input checked="" type="checkbox"/>
35	22/11/18 14:26	General View	 Load JPG		<input checked="" type="checkbox"/>
36	22/11/18 14:26	General View	 Load JPG		<input checked="" type="checkbox"/>
37	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
38	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
39	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
40	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
41	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
42	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
43	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
44	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
45	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
46	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
47	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
48	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
49	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
50	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
51	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
52	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
53	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
54	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
55	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
56	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
57	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
58	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
59	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
60	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
61	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
62	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
63	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
64	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
65	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
66	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
67	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
68	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
69	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
70	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
71	11/01/19 13:53	Reinspection Photo	 Load JPG		<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/06/18 15:04	ACKNOWLEDGEMENT EMAIL TO AIG DD 04.06.2018	 Load PDF		
2	04/06/18 18:42	EMAIL FROM AIG DD 04.06.2018	 Load PDF		
3	04/06/18 18:42	TP ESTIMATE + TP GIA REPORT	 Load TIF		
4	09/06/18 14:03	TP ESTIMATE-MARKED	 Load PDF		
5	21/11/18 14:54	RENTAL RECEIPT	 Load PDF		
6	21/11/18 14:54	GIA SEARCH	 Load PDF		
7	25/06/19 10:35	LETTER TO OI	 Load PDF		
8	04/07/19 08:59	WORKSHOP INVOICE	 Load PDF		
9	04/07/19 08:59	AUTHORISATION TO ACT FORM	 Load PDF		
10	04/07/19 08:59	Release Voucher	 Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	05/06/18 15:45	OI GIA REPORT	 Load PDF		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJT5915D (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SKH562Y (TP veh)		1.6 (A)
Date of Accident:	31/05/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$	12,817.69	
Final Repair Cost	:	\$	9,400.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		12 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$	9,400.00	

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Alan's United Auto Pte Ltd	: \$	9,400.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

04 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any).

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18010038/KHA3Q2

Date: 04/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100170075

Claimant Vehicle No : SKH562Y

Insured Vehicle No : SJT5915D

Date of Loss: 31/05/2018

Nature of Claim:

TP

Claim No: 2389925936SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH562Y**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZR231423

Reg. Date: 30/10/2012 (Man. Year: 2012)

Chassis No: MR053REE104149573

Colour: Metallic Gold

Odometer: 80449 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Yokohama 7 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side:

Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,669.15	6,018.92	1,650.23	21.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	2,560.00	1,750.00	40.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,979.15	8,578.92	3,400.23	28.38
Approved Total (Overridden) (S\$)		7,700.00		
(S\$)	11,979.15	7,700.00	4,279.15	35.72
+ GST 7.00/7.00% (S\$)	838.54	539.00	299.54	35.72
Nett Amount (S\$)	12,817.69	8,239.00	4,578.69	35.72
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,441.00		
Global Sum Settlement (S\$)		9,400.00		

INSPECTION

Date of Assignment: 04/06/2018

Date Inspected: 04/06/2018 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	754.30 FL	*754.30 FL
2	1		*BOOT LID RUBBER (50%)	Distorted / Dented	131.48 FS	*87.65 FS
3	1		*BOOT LID INNER LOCK	Dented	96.50 FL	*96.50 FL
4	2		*BOOT LID HINGE	Bent	120.40 FL	*120.40 FL
5	1		*BOOT LID INNER TRIM	Cracked	259.10 FL	*259.10 FL
6	12		*BOOT LID INNER TRIM CLIP	Necessary	45.60 FL	*45.60 FL
7	2		*BOOT LID REFLECTOR	Cracked	334.40 FL	*334.40 FL
8	1		*BOOT LID OUTER CHROME	Cracked	382.90 FL	*382.90 FL
9	1		*BOOT LID 1.6 EMBLEM	Necessary	32.40 FL	*32.40 FL
10	1		*BOOT LID VVT-I EMBLEM	Necessary	38.70 FL	*38.70 FL
11	1		*BOOT LID COROLLA EMBLEM	Necessary	42.30 FL	*42.30 FL
12	1		*BOOT LID ALTIS EMBLEM	Necessary	44.20 FL	*44.20 FL
13	1		*BOOT LID LOGO	Necessary	52.10 FL	*52.10 FL
14	2		*TAILLAMP	Cracked	563.80 FL	*563.80 FL
15	2		*TAILLAMP CORNER PANEL	Bent	153.60 FL	*153.60 FL
16	2		*TAILLAMP LOWER BRACKET	Distorted	145.40 FL	*145.40 FL
17	1		*REAR END PANEL	Bent	552.20 FL	*552.20 FL
18	1		*END PANEL TOP GARNISH	Mtg Distorted	185.20 FL	*185.20 FL
19	2		*END PANEL TOP GARNISH CLIP	Necessary	7.80 FL	*7.80 FL
20	1		*SPARE TYRE BOARD	Cracked	348.10 FL	*348.10 FL
21	1		*REAR BUMPER FASCIA	Bent	482.10 FL	*482.10 FL
22	1		*REAR BUMPER REINFORCMENT	Cracked	157.50 FL	*157.50 FL
23	2		*REAR BUMPER BRACKET	Bent	165.60 FL	*165.60 FL
24	2		*REAR BUMPER SIDE RETAINER (L)	Distorted	133.60 FL	*133.60 FL
25	2		*REAR BUMPER SIDE RETAINER (S)	Distorted	58.80 FL	*58.80 FL
26	1		*REAR BUMPER REFLECTOR	O/S Cracked	74.40 FL	*37.20 FL
27	1		*REAR O/S FENDER	Repair	828.90 FL	*- FL
28	1		*REAR W/S GLASS MOULDING	Not Necessary	75.60 FL	*- FL
29	1		*FRONT BUMPER FASCIA	Buckled	459.70 FL	*459.70 FL
30	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	101.60 FL	*50.80 FL
31	1		*FRONT BUMPER REINFORCEMENT	Bent	339.70 FL	*339.70 FL
32	1		*FRONT BUMPER LOWER GRILLE	Distorted	139.80 FL	*139.80 FL
33	2		*HEADLAMP	Mtg Cracked	1,050.60 FL	*1,050.60 FL
34	1		*RADIATOR GRILLE	Mtg Cracked	287.30 FL	*287.30 FL
35	1		*RADIATOR GRILLE LOGO	Serviceable	64.30 FL	*- FL
36	1		*RADIATOR SUPPORT PANEL	Repair	715.30 FL	*- FL
37	1		*BRACE PANEL	Repair	103.10 FL	*- FL
38	1		*FRONT NO PLATE WITH BOX	Bent	50.00 FS	*45.00 FS
39	1		*REAR NO PLATE WITH BOX	Bent	50.00 FS	*45.00 FS
40	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
41	1		*REAR W/S GLASS SEALANT	Not Necessary	60.00 FS	*- FS
42	1		*RADIATOR COOLANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,018.38	7,899.35
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,349.23	1,880.43
Total Parts (\$\$)	7,669.15	6,018.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	20.00	20.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	0.00
3	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	80.00
4	TO REMOVE AIR CON CONDENSER ,PIPES AND DRIER ,VACUUM AND TO RECHARGE GAS	New	120.00	0.00
5	TO APPLY UNDERSEALING	New	100.00	60.00
6	TO PUTTY AND SPRAY REPLACED PARTS	New	1,800.00	1,200.00
7	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			4,310.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >