

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date :

Reference: SKJ3727J
 OPEL ASTRA J
 Make: 1.4AT 5DR
 TURBO

To Whom It May Concern

TP AXA.
 Vivian

Dear Sir,

RE: VEHICLE :SKJ3727J
CHASSIS NO.: W0LPD6DC3C8103816
ENGINE NO.:A14NET19AP0455

Name of insured :FREDERICK VENETIUS CHRYSANTHA MENDIS
 Date of accident.: 23/05/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Tailgate <i>Byrie</i>	\$ 1,751.00
2	1	Astra Lettering <i>3 Max</i>	\$ 47.00
3	1	Turbo Lettering	\$ 47.00
4	1	Rear Tailgate Latch <i>3 Max</i>	\$ 289.00
5	1	Rear Tailgate Striker	\$ 35.00
6	1	LHR Taillamp <i>3 Max</i>	\$ 646.00
7	1	RHR Taillamp	\$ 646.00
8	1	Rear Bumper Upper <i>2 mtd</i>	\$ 1,600.00
9	1	Rear Bumper Lower Moulding <i>2 mtd</i>	\$ 450.00
10	1	Rear Bumper Towing Cover <i>2 mtd</i>	\$ 86.00
11	1	LHR Bumper Reflector <i>3 Max</i>	\$ 80.00
12	1	RHR Bumper Reflector	\$ 80.00
13	2	Rear Number Plate Lamp <i>2 Max</i>	\$ 60.00
14	1	Rear Bumper Absorber <i>3 Max</i>	\$ 190.00
15	1	Rear Bumper Reinfortment Bar <i>2 mtd</i>	\$ 550.00
16	1	Rear End Panel <i>Byrie</i>	\$ 953.00
17	1	Rear End Panel Trim <i>2 mtd</i>	\$ 190.00

<u>18</u>	1	Rear Bumper Centre Bracket, Guide	\$	65.00	✓
<u>19</u>	1	LHR Bumper Bracket, Guide	\$	75.00	✓
<u>20</u>	1	RHR Bumper Bracket, Guide	\$	75.00	✓
<u>21</u>	1	LHR Lower Bumper Bracket	\$	40.00	✓
<u>22</u>	1	RHR Lower Bumper Bracket	\$	40.00	✓
<u>23</u>	2	Rear Bumper Air Ventilator	\$	120.00	✓

3109
2798.10

Parts Total: \$ 8,115.00
Less 10%: \$ 811.50
Total: \$ 7,303.50

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>Rear portion</u>		
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 1,200.00 400
<u>2</u>	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,000.00 400
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00 ✓
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 80.00 50
<u>5</u>	To remove and refix reverse camera and conduct test	\$ 80.00 50
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00 x
<u>7</u>	To conduct water leakage test after repairs of vehicle	\$ 30.00 x
<u>8</u>	To remove and refix rear tail gate windscreen	\$ 120.00 x

930

Labour Total: \$ 2,620.00

Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>Rear portion</u>			
1	1	Rear number plate <i>cancel</i>	\$ 45.00 ✓
2	1	Rear bumper clip <i>Nec</i>	\$ 65.00 30
3	1	Rear fender liner clips <i>Nec</i>	\$ 19.50 x
4	1	Rear end panel trim clip <i>Nec</i>	\$ 65.00 x
5	1	Reverse sensor 1 set <i>Nec</i>	\$ 600.00 300
6	1	Rear reverse camera <i>Nec</i>	\$ 550.00 x
7	1	Rear end panel insulation seal <i>Nec</i>	\$ 120.00 x

375

Other Total: \$ 1,464.50

GRAND TOTAL: \$ 11,388.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor
Suhaimi
HP : 9189 2617 Email - aceautosolution@gmail.com

Adrian King,
P/P 1/5 06/05/18.
0.3 days.
total: 4103.10 (P/P)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company.

Acknowledged by Repairer

Signature:

Date: