



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Goh Kim San
Blk 602 Elias Road
#09-236
Singapore 510602

Not Asstained
1.B.1
Re survey 3 days

Dear sir

Estimate cost of repair to vehicle no. SLM 6128R

To supply

1. Rear bumper	<i>Bumper</i>	950.00	—
2. Rear bumper sensor x4	<i>sn</i>	692.00	X
3. Rear bumper retainer x2	<i>sn</i>	72.00	X
4. Rear bumper reinforcement		538.00	?
5. Rear bumper reflector x2	<i>sn</i>	102.00	X
6. Rear boot badge mazad 3	<i>sn</i>	75.00	—
7. Rear boot logo	<i>sn</i>	51.00	—

Labour charges

Rust proofing

Panel beating

Spray painting

<i>nn</i>	50.00	X
	600.00	<i>250</i>
	650.00	<i>400</i>

Total

Your faithfully

ALBERT POON

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: