

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R*Not Authorized
11/12/2018***AAD1805-292**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5156R

VF1ABL15AUC276551

RENAULT

LATITUDE

31.5.2018

CHINA TAIPING

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>As</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>mis</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>CM</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>D.Y</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i> 472.83 ✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>D.Y</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>As</i> 914.08 ✓
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>mgcm</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>SL</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>CM</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP RH	\$	<i>As</i> 1,184.43 X
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>As</i> 1,941.63 ✓

Trans-cab Auto Services Pte Ltd**AAD1805-292**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

27	1	BONNET INSULATOR	\$	Sn	405.73	}
28	1	BONNET STRUT LH	\$	Sn	88.61	
29	1	BONNET STRUT RH	\$	Sn	88.61	
30	1	BONNET HINGE LH	\$	R	348.31	
31	1	BONNET HINGE RH	\$	R	348.31	
32	1	BONNET LOCK	\$	R	305.48	
33	1	BONNET CABLE	\$	Sn	119.19	
34	1	BONNET CABLE COVER	\$	Sn	161.03	
35	1	BONNET SEAL OUTER	\$	Sn	92.36	
36	1	BONNET SEAL INNER	\$	Sn	157.28	
37	1	FENDER PANEL FRT LH	\$	R	783.83	
38	1	FENDER PANEL FRT RH	\$	R	783.83	
39	1	WHEELARCH FRT LH	\$	Sn	278.84	
40	1	WHEELARCH FRT RH	\$	Sn	278.84	
41	1	FENDER BRACKET LOWER LH	\$	R	15.79	
42	1	FENDER BRACKET LOWER RH	\$	R	15.79	
43	1	FENDER INSULATOR LH	\$	Sn	130.84	
44	1	FENDER INSULATOR RH	\$	Sn	130.84	
45	1	WIPER RESERVOIR	\$	Sn	348.25	
46	1	WIPER RESERVOIR NECK	\$	Sn	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	Sn	270.06	
48	1	AIR CLEANER LOWER	\$	Sn	271.26	
49	1	AIR CLEANER HOSE	\$	Sn	76.14	
55	1	ENGINE TOP COVER 2.0	\$	Sn	555.12	
56	1	ENGINE OIL SUMP	\$	Sn	484.67	
58	1	BASE BATTERY TRAY	\$	Sn	363.40	
59	1	AIR CLEANER BOX	\$	Sn	464.20	
60	1	TURBO DUCT	\$	Sn	1,027.80	
61	1	A/C HEATER VALVE	\$	Sn	484.50	
63	1	SUBFRAME OUTER FRT	\$	Sn	2,652.45	
64	1	SUBFRAME BRACKET OUTER LH	\$	R	92.36	
65	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36	
66	1	ENGINE UNDERTRAY	\$	Sn	564.98	
67	1	A/C CONDENSER	\$	Sn	2,020.37	
68	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67	
69	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67	
70	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81	
71	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60	

Trans-cab Auto Services Pte Ltd**AAD1805-292**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

72	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S\$ 208.39	}
73	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S\$ 658.72	
74	1	A/C PIPE COMPRESSOR	\$	S\$ 334.29	
75	1	A/C PIPE	\$	S\$ 658.72	
76	1	A/C COMRPRESSOR	\$	S\$ 2,684.61	
77	1	AIR COOLER	\$	S\$ 792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S\$ 1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	S\$ 375.14	
80	1	TRANSMISSION COOLER	\$	S\$ 1,219.30	
81	1	TRANSMISSION COOLER PAD	\$	S\$ 17.96	
82	1	RADIATOR	\$	S\$ 1,202.20	
83	2	RADIATOR STUD UPPER	\$	S\$ 14.41	
84	2	RADIATOR BUSH UPPER	\$	S\$ 50.12	
85	2	RADIATOR MTG LOWER	\$	S\$ 55.85	
86	1	RADAITOR FAN COWLING	\$	S\$ 820.54	
87	1	RADIATOR FAN MOTOR LH	\$	S\$ 967.36	
88	1	RADIATOR FAN MOTOR RH	\$	S\$ 1,479.46	
89	1	RADIATOR TANK	\$	S\$ 324.62	
90	1	RADIATOR HOSE UPPER	\$	S\$ 240.56	
91	1	RADIATOR HOSE LOWER	\$	S\$ 491.18	
92	1	RADIATOR TANK HOSE	\$	S\$ 61.18	
93	1	WINDSCREEN FRT	\$	S\$ 1,364.06	}
94	1	AUTO COMPUTER	\$	S\$ 5,032.17	
95	1	INJECTION COMPUTER	\$	S\$ 4,706.30	
96	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S\$ 5,154.52	
97	1	STEERING PUMP ELECTRIC	\$	S\$ 2,306.90	
98	1	STEERING PINION RACK	\$	S\$ 4,413.11	
99	1	ENGINE HARNESS	\$	S\$ 4,084.54	

TOTAL	\$	70,846.53
10%	\$	7,084.65
	\$	63,761.88

Special Nett

1	1SET RADIATOR GRILLE FRAME CLIP	\$	Net 52.00	✓
2	1SET BUMPER CLIP FRT	\$	Net 66.00	✓

Trans-cab Auto Services Pte Ltd**AAD1805-292**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	}	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50		
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50		
7	1	TOW COVER FRT	\$	nn	14.50		
8	1SET	RADAITOR GRILLE SCREW	\$	nn	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
21	1	Windscreen moulding	\$	nn	100.00	}	X
22	1SET	Front licence plate with holder	\$	nn	80.00		

TOTAL	\$	562.50
TOTAL PARTS	\$	64,324.38

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,400.00 *600*

Towing Fees.

\$ 120.00 *50*

To apply paint protection system (PPS) maintain and enhancement

\$ 380.00 *nn X*

Putty and spray painting of the affected portion.

\$ 5,000.00 *880*

To rust-proofing of the affected areas.

\$ 170.00 *30*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *nn X*

To check steering geometry and computer wheel alignment

\$ 220.00 *nn X*

Trans-cab Auto Services Pte Ltd

AAD1805-292

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20%
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100%
To replace, refix and top up coolant for radiator	\$	170.00 50%
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 50%
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) not for resurvey and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 15,400.00**Over All Total \$ 79,724.38****Repair Days (LUMP SUM)****20 DAYS**

4 days