

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref : SP9999A

M/S MSIG INSURANCE (SINGAPORE) PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final approval
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SP9999A (WDD2050422R104449)

TO SUPPLY:

List Items

1	1 PC	FRONT LH FENDER <i>Dented</i>	\$ 882.00	✓
2	1 PC	FRONT LH FENDER SHIELD <i>src</i>	\$ 240.00	x
3	1 PC	FRONT LH HEADLAMP <i>broken</i>	\$ 3,127.00	✓
4	1 PC	FRONT BUMPER <i>cut</i>	\$ 1,710.00	✓
5	1 SET	FRONT BUMPER CLIPS <i>4pc</i>	\$ 45.00	✓
6	1 PC	FRONT BUMPER LH SENSOR <i>Damn</i>	\$ 210.00	✓
7	1 PC	FRONT BUMPER SPONGE <i>src</i>	\$ 165.00	x
8	1 PC	FRONT BUMPER REINFORCEMENT <i>src</i>	\$ 410.00	x
9	1 PC	FRONT BUMPER LH SIDE RETAINER <i>src</i>	\$ 24.00	x
			\$ 6,813.00	
			LESS 10%	\$ (681.30)
			\$ 6,131.70	
10	1 PC	FRONT LH RIM <i>✓</i>	\$ 1,412.00	x
11		FRONT LH TYRE <i>Punctured 30%</i>	\$ 300.00	300.00 150/-
12		TOWING	\$ 120.00	?
13		SPRAY PAINTING	\$ 800.00	400/-
14		LABOUR CHARGES	\$ 660.00	500/-
15		ALIGNMENT	\$ 120.00	60/-
16		WIRING	\$ 35.00	30/-
17		PROGRAMMING	\$ 200.00	150/-
			TOTAL	\$ 9,778.70

04/06/2012 @ 1500h

N/A Antinut

Excess R700/-

4 days.

Part / Part.

Photo with damaged item(s).

97237799

Photo

2KK Auto