

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 05 Jun 2018

Preliminary Advice

Vehicle No	: SP9999A	Accident Date	: 28/05/2018
Make	: MERCEDES-BENZ C200 AMG LINE (R18 LED)	Policy No.	: A29068842QMY
Assignment Date	: 01/06/2018	Excess	: S\$700.00
Date of Inspection	: 04/06/2018	Est. Duration of Repair	: 4.00
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,778.70
Revised Amount	:S\$	6,666.60
Check Items (Estimated)	:S\$	120.00
Total	:S\$	6,786.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	80,109.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,891.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.