

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 05 Jun 2018

**Preliminary Advice**

Insured Vehicle No	: SCW2808S		
TP Vehicle No	: SHF735L	Accident Date	: 28/05/2018
Make	: RENAULT LATITUDE	Assignment Date	: 01/06/2018
Date of Inspection	: 04/06/2018	Est. Duration of Repair	: 18 days
Inspection At	: Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	75,425.97
Revised Amount	:S\$	32,638.02
Check Items (Estimated)	:S\$	1,177.88
Total	:S\$	33,815.90
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- (      ) The vehicle is economical/not economical for repair.  
( X ) The above survey was conducted on a 'without prejudice' basis.