

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 05 Jun 2018

Preliminary Advice

Insured Vehicle No	: FV5701R		
TP Vehicle No	: SHC4197D	Accident Date	: 01/06/2018
Make	: TOYOTA PRIUS TAXI	Assignment Date	: 04/06/2018
Date of Inspection	: 04/06/2018	Est. Duration of Repair	: 3/Days
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Front O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,834.87
Revised Amount	:S\$	5,914.64
Check Items (Estimated)	:S\$	2,119.96
Total	:S\$	8,034.60

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :We have not authorized repairs.