

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800158
Date: 31 May 2018
Veh Reg No: SJS9881X
Make/Model: KIA CERATO FORTE 1.6 AT
Chasis No: KNAFW411MA5122012
Reg. Date: 18/09/2009
Your Ref No: SLU384P

Claim Type: Third Party
Accident Date: 25/05/2018
TP Veh Reg No: SLU384P

VIC

Estimate Repair Cost to Vehicle No :SJS9881X

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT BUMPER <i>Rel'd</i>	668.00	✓
2	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	204.00	✓
3	1 PC FRT BUMPER SPONGE <i>encl'd</i>	94.00	✓
4	1 PC FRT BUMPER RETAINER RH <i>new</i>	26.00	✓
5	1 PC FRT BUMPER BRACKET RH <i>new</i>	12.00	✓
6	1 PC HEADLAMP RH <i>encl'd</i>	447.00	✓
7	1 PC FRT FOG LAMP RH <i>encl'd</i>	143.00	✓
8	1 PC FRT FOG LAMP COVER RH <i>new</i>	28.00	✓
9	1 PC FRT GRILLE <i>encl'd</i>	241.00	✓
10	1 PC FRT GRILLE EMBLEM <i>new</i>	39.00	✓
11	1 PC FRT SUPPORT PANEL <i>new encl'd</i>	680.00	✓
	<i>1pc " wiper tank -103.60 ✓</i>	2582.00	
	<i>Del'd</i>	Less 20%	516.40
			2.065.60
	Special Net		
12	1 SET FRT BUMPER CLIPS <i>new</i>	48.00	30
13	1 SET FRT GRILLE CLIPS <i>new</i>	48.00	10
		96.00	96.00
	Labour		
14	1 TO CHECK WIRING <i>1250</i>	50.00	30
15	1 TO SPRAY UNDERSEAL	80.00	+
16	1 (FRONT) TO SPRAY PAINTING	800.00	400
17	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	700
18	1 TO REFILL AIRCON GAS	120.00	✓
		2,050.00	2,050.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangear@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 25/05/2018
TP Veh Reg No: SLU384P

Estimate No: EST1800158
Date: 31 May 2018
Veh Reg No: SJS9881X
Make/Model: KIA CERATO FORTE 1.6
AT
Chasis No: KNAFW411MA5122012
Reg. Date: 18/09/2009
Your Ref No: SLU384P

Estimate Repair Cost to Vehicle No :SJS9881X

Quantity	Description	List Price	Amount
		SS	SS
	Total		S\$ 4,211.60
	Add GST @ 7%		294.81
	Total Amount Payable		S\$ 4,506.41

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FIVE HUNDRED AND SIX AND CENTS FORTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Adrian Ling
1/s 01/06/18.
05 Days.
total 3671.04
4/s 2912.
2.9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: