

(OPTIONAL)

INS. CASE OWNER:

SUNDARI

CC 4/1111801 0073, GMB

LKK:
IDAC:

Surveyor:

XGQ

DOI:

ASSIGNMENT
06/06/18

Date / Time:

4/6/18

Registered in Merimen:

4/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 75337

Claim No.:

MCT18060066

Name of Insured:

YPR

Policy No.:

M10M0015

Insured Tel No.:

HP:

Make / Model:

MURBARI

Excess Sec II :SS

D.O.A.:

7/6/18

Place of Accident:

M16 ST TO M14H ST

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Amh Bmh YEW

OI GIA REPORT YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) YES / NO

Insured Liability: %

Final ? Yes / No

sy 877B



INSRS:
WSP:
Tel:
Liability:
RMKS:

BH Auto



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
6/6/18	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
07/06/18	After call Itr to OI:	
	Documentation Check List: Handler Typist	
08/06/18	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	
7/8/18	Release Voucher:	
8/8/18	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
13/8/18	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27	If NO or B 28, Ass. Lia:
Repair Cost:	SS 5895.27			(COV) RENEW-ENDED TP)
Loss of Rental (LOR):	SS	(days)		
Loss of Use (LOU):	SS 600.00	5/50 x 4 days)		
Loss of Income (LOI):	SS	(S x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>				[Tick only one]
GIA/LTA Search:	SS 7.45			
Medical:	SS			1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS	(e.g. Tow/ Independent)		2) Report Format:
Legal Cost:	SS			3) Survey fee:
Total:	SS 6502.72	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS 6502.72	Name 1:	BH Auto Services Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT

The original document is forwarded to II

Xml.

REF: III

h

5557H

ASSIGNMENT

From: 06062018
 Date: 06062018
 Estimated Cost: 0
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: SLJ 8373B
 at Workshop no: BH Auto
 of: Blk 1 Sun Ming #01-115
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Claim's Record)
 Make of Veh:
 (Policy Condition) 3pm - 4pm
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Rpt: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted: Vehicle: IN / OUT



Vehicle No: SLJ 8373B Yr Reg: 19 Apr 2018
 Type: M Car (M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
 Make: Land Rover Range Rover 3.0
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 67824 T/Ratio: Insured / Std / NI / NA
 Eng/No:
 C/No: SACLSAA05DA804938
 Gen. Cond: Good (Fair / Poor / Burnt)
 Steering: In Order (Jammed / Leaked / Burnt or
 Brake: In Order (Jammed / Leaked / Burnt or
 Mod: Nil (S/Rim / STD / Rim or
 Tyre Size: F: 215/40R20
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
 Front: R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 06-06-18
 Survey held at: w/s 3:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
Invoiced \$ 8509.6 with Bernard.

(Ref: #1571-2f 73.1)

Date/Time: File Pass to? Prel. Report Final Report

Date/Time: File Return to?

Report Format

Lump Sum / I.B.F. / S

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Site Insp: \$

Interview: \$

Test: \$

Workshop: \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18010073/hb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-06-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3533U	Veh. Inspected	SLJ 8373B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/06/2018	Inspection Date	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLJ8373B
MODEL : RANGE ROVER SPORT 3.0
POLICY NO : VA1/GA331245
CHASSIS NO : SALLSAAG5DA804938
MANUFACTURING YEAR : 2013
DATE / TIME OF ACCIDENT: 02/06/2018 Time: 1330Hrs ALONG HILL STREET
THIRD PARTY VEHICLE NO : SHA3533J

Date: 05/06/2018
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Rear Bumper Corner Guide LH <i>- CMA</i>	1			
2	Rear Bumper Sensor Holder <i>- N/C</i>	4			
3	Rear Bumper Retainer LH <i>- RR</i>	1			
Sub-Total:					-
Less Discount 10%					-
Total Parts:					-

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : _____
Company : _____
Date : _____
Time : _____
Contact No : _____
Email : _____

Anthony

UKK

11/7/18

BH AUTO SERVICES

7/8/19
v/v/b

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117
Tel: 6559 8944 / Fax: 6269 2404

Wm

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLJ8373B
MODEL : RANGE ROVER SPORT 3.0
POLICY NO : VA1/GA331245
CHASSIS NO : SALLSAAG5DA804938
MANUFACTURING YEAR : 2013
DATE / TIME OF ACCIDENT : 02/06/2018 Time: 1330Hrs ALONG HILL STREET
THIRD PARTY VEHICLE NO : SHA3533J

Appended below are the estimated cost of repair and parts to be replaced for the :

Replacement Of Parts

S/N	Description	Quantity	Unit Price S\$
1	Tailgate <i>X repair</i>	1	5400.00
2	Tailgate Lettering "Range Rover" <i>- spec</i>	1	269.00
3	Tailgate Lettering "Sport" <i>- spec</i>	1	59.00
4	Tailgate Lettering "HES" <i>- spec</i>	1	141.00
5	Tailgate Centre Moulding <i>X NN</i>	1	538.00
6	Tailgate Lower Garnish <i>- cut</i>	1	588.00
7	Rear Windscreen Moulding <i>X spec</i>	1	408.00
8	Tailgate Weatherstrip <i>X spec</i>	1	134.00
9	Rear Bumper <i>- re</i>	1	1910.00
10	Rear Bumper Side Retainer LH <i>X NN</i>	1	24.00
11	Rear Bumper Side Bracket LH <i>- re</i>	1	75.00
12	Rear Bumper Side Retainer RH <i>X NN</i>	1	24.00
13	Rear Bumper Side Bracket RH <i>X NN</i>	1	75.00
14	Rear Bumper Centre Bracket <i>- CRB</i>	1	150.00
15	Rear Bumper Lower Centre Garnish <i>- SCR</i>	1	116.00
16	Rear Bumper Reflector LH <i>- CRB</i>	1	77.00
17	Rear Bumper Sensor <i>- DM</i>	4	215.00
18	Rear Bumper Trade Plate <i>- RZPC</i>	1	142.00
19	Rear Bumper Reinforcement <i>X REPAIR</i>	1	1367.00
20	End Panel <i>X repair</i>	1	1689.00
21	End Panel Top Garnish <i>X NN</i>	1	153.00
22	Tail Lamp LH <i>- CRB</i>	1	850.00
23	Tail Lamp Bracket <i>X NN</i>	1	515.00
24	Muffler Exhaust Tip <i>X leg cut</i>	1	751.40

4807
10% : 4326.3

A]

2

Special Nett Items

1	Anti-rust coating <i>X NN</i>	2	80.00
2	Rear Bumper Clips <i>- spec</i>	10	4.50
3	Rear Windscreen Sealant <i>X NN</i>	1	100.00

2.B.2

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	400 300	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	500	900.00
3	Provide skill labour to disconnect and check electrical wiring	-	30.00
4	Remove and refit rear windscreen	NN? X	180.00
5	Remove and refit rear end panel lining and garnish to facilitate repairs	X	100.00
6	Reset management system with diagnostic fault e.g. sensor sensitivity	X	300.00
7	Remove and replace bumper sensor	40	100.00
8	Remove/realign/replace exhaust pipe to facilitate repairs	NN? X	150.00
9	Mount vehicle onto chassis alignment bench and reset chassis alignment to recommended specifications	X	350.00

Total Labour:

970

3,610.00

Total Parts & Labour:

18,598.86

GST 7%

1,301.92

Grand Total:

19,900.78

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SLJ8373B

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Total: 5509.6

Survey attended by:

Name : Lim Qiang

Company : LKK

Date : 06/6/18

Time :

Contact No: 82880282

Email : lim.qliang@lkkauto.com

4 Days.

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLJ8373B
MODEL : RANGE ROVER SPORT 3.0
POLICY NO : VA1/GA331245
CHASSIS NO : SALLSAAG5DA804938
MANUFACTURING YEAR : 2013
DATE / TIME OF ACCIDENT : 02/06/2018 Time: 1330Hrs ALONG HILL STREET
THIRD PARTY VEHICLE NO : SHA3533J

Date: 05/06/2018
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle :-

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			SS		SS
1	Rear Bumper Corner Guide LH - CFA	1	37.4		
2	Rear Bumper Sensor Holder - MC	4	@ 18.7	74.8	
3	Rear Bumper Retainer LH - RR	1	74.8		
			30.7 18.7		
				Sub-Total:	-
				Less Discount 10%	-
				Total Parts:	-
			10%: 17.81		168.3

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Anthony

ESTIMATOR: ANTHONY

UKK

Survey attended by:

11/7/18

Name : _____

Company : _____

Date : _____

Time : _____

Contact No: _____

Email : _____

BH AUTO SERVICES PTE LTD

Blk I, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLJ8373B

MODEL : RANGE ROVER SPORT 3.0

POLICY NO : VA1/GA331245

CHASSIS NO : SALLSAAG5DA804938

MANUFACTURING YEAR : 2013

DATE / TIME OF ACCIDENT : 02/06/2018 Time: 1330Hrs ALONG HILL STREET

THIRD PARTY VEHICLE NO : SHA3533J

Date: 05/06/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Tailgate <i>X repair</i>	1	5400.00		5,400.00
2	Tailgate Lettering "Range Rover" <i>- spec</i>	1	269.00		269.00 ✓
3	Tailgate Lettering "Sport" <i>- spec</i>	1	59.00		59.00 ✓
4	Tailgate Lettering "HES" <i>- spec</i>	1	141.00		141.00 ✓
5	Tailgate Centre Moulding <i>X NA</i>	1	538.00		538.00
6	Tailgate Lower Garnish <i>- cut</i>	1	588.00		588.00 ✓
7	Rear Windscreen Moulding <i>X spec</i>	1	408.00		408.00
8	Tailgate Weatherstrip <i>X spec</i>	1	134.00		134.00
9	Rear Bumper <i>- re</i>	1	1910.00		1,910.00 ✓
10	Rear Bumper Side Retainer LH <i>- spec</i>	1	24.00		24.00 ✓
11	Rear Bumper Side Bracket LH <i>?</i>	1	75.00		75.00
12	Rear Bumper Side Retainer RH <i>X</i>	1	24.00		24.00
13	Rear Bumper Side Bracket RH <i>X</i>	1	75.00		75.00
14	Rear Bumper Centre Bracket <i>X</i>	1	150.00		150.00
15	Rear Bumper Lower Centre Garnish <i>- spec</i>	1	116.00		116.00 ✓
16	Rear Bumper Reflector LH <i>- CRA</i>	1	77.00		77.00 ✓
17	Rear Bumper Sensor <i>- DM</i>	4	215.00		860.00 ✓
18	Rear Bumper Trade Plate <i>- RZPC</i>	1	142.00		142.00 ✓
19	Rear Bumper Reinforcement <i>?</i>	1	1367.00		1,367.00
20	End Panel <i>X repair</i>	1	1689.00		1,689.00
21	End Panel Top Garnish <i>X</i>	1	153.00		153.00
22	Tail Lamp LH <i>- CRA</i>	1	850.00		850.00 ✓
23	Tail Lamp Bracket <i>?</i>	1	515.00		515.00
24	Muffler Exhaust Tip <i>X repair</i>	1	751.40		751.40
Sub-Total:					16,315.40 <i>5036</i>
Less Discount 10%:					1,631.54
Total Parts:					14,683.86 <i>4532.4</i>
<u>Special Nett Items</u>					
1	Anti-rust coating <i>X</i>	2	80.00		160.00
2	Rear Bumper Clips <i>- spec</i>	10	4.50		45.00 ✓
3	Rear Windscreen Sealant <i>X</i>	1	100.00		100.00
Total Parts:					305.00

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	300	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	500	900.00
3	Provide skill labour to disconnect and check electrical wiring	1	30.00
4	Remove and refit rear windscreen	X	180.00
5	Remove and refit rear end panel lining and garnish to facilitate repairs	X	100.00
6	Reset management system with diagnostic fault e.g. sensor sensitivity	X	300.00
7	Remove and replace bumper sensor	40	100.00
8	Remove/realign/replace exhaust pipe to facilitate repairs	X	150.00
9	Mount vehicle onto chassis alignment bench and reset chassis alignment to recommended specifications	X	350.00
Total Labour:			<u>3,610.00</u>
		Total Parts & Labour:	<u>18,598.86</u>
		GST 7%	<u>1,301.92</u>
		Grand Total:	<u><u>19,900.78</u></u>

Estimate Repair Duration 10 days

5447.4

ACCIDENT VEHICLE OF : SLJ8373B

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Guo Qiang
 Company : LKK
 Date : 06/6/18
 Time : _____
 Contact No: 82880282
 Email : Guo Qiang @ lkk auto . com

4 Days .

LKK Auto Centre	Warranty hence notify
the Repairer	the following:
• To resurvey	• After spray painting
• To display damaged part(s) during resurvey	
• Parts prices	• subject to confirmation
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5557H

Vehicle Details

Vehicle No.: SLJ8373B
Vehicle to be Exported: No
Intended De-registration Date: 04 Jun 2018
Vehicle Make: LAND ROVER
Vehicle Model: RANGE ROVER SPORT 3.0L AUTO HID 4WD
Primary Colour: White
Manufacturing Year: 2013
Engine No.: 0690791306DT
Chassis No.: SALLSAAG5DA804938
Maximum Power Output: 180.0 kW (241 bhp)
Open Market Value: \$77,442.00
Original Registration Date: 19 Apr 2013
First Registration Date: 19 Apr 2013
Transfer Count: 2
Actual ARF Paid: \$111,396.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Apr 2023
PARF Rebate Amount: \$77,977.00

Intended COE Rebate Details

COE Expiry Date: 18 Apr 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$67,010.00
COE Rebate Amount: \$32,648.00
Total Rebate Amount: \$110,625.00

The information contained herein is correct as at 04 Jun 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2012 Golf 7mc 2014 Unit 3 SL SUV



Low Mileage, New Dealer One
Year Plus, Location, Annual
Inchape Pre-Owned

Post an Ad Advertiser Login Ways of Selling

HIN LUNG AUTO
Ho Dee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

2 vehicles

Range Rover Sport 3.0A

Sort by Date Posted 20 results/page

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Range Rover Sport 3.0A	Any	Any	2012	Any	Any	Any	Available
	Land Rover Range Rover Sport Diesel 3.0A	\$149,800	\$24,120 /yr	13-Dec-2012	2,993 cc	78,000 km	SUV	Available
<p>Fuel Type: Diesel (Euro 5 Engine and Above) Agent's Wearies Unit. Fully Agent's Maintained Since Day One. Reasonable Mileage Done. Unique Land Rover Driving Experience, Effortless Pulling Power, Unmistakable Road Presence, It's The Ultimate SU... In-Carz Credit Pte Ltd Posted: 05-May-2018 Tags: 2012 Land Rover Range, Land Rover Range, Land Rover, Range, Used Land Rover</p>								
	Land Rover Range Rover Sport Diesel 3.0A	\$119,800	\$21,230 /yr	14-Feb-2012	2,993 cc	80,000 km	SUV	Available
<p>Fuel Type: Diesel (Euro 5 Engine and Above) Low Fuel Costs. Smooth And Responsive Ride, One Of The Most Sought After Pure Off-Road Suv, Handling In It's Class, View To Believe Excellent Condition, Call Us Now To View. Posted: 23-Apr-2018 Tags: 2012 Land Rover Range, Land Rover Range, Land Rover, Range, Used Land Rover</p>								

Save this search criteria, to get email alerts whenever a match is found.

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
-------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Range Rover Sport 3.0A, Range Rover Sport 3.0A Singapore, used Range Rover Sport 3.0A Singapore, used Range Rover Sport 3.0A, used vehicles Singapore or even buy used Range Rover Sport 3.0A Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 4 June, 2018 11:56 AM
To: BHAS - Jacelyn Loh; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: pre repair inspection (OUR VEHICLE - SLJ8373B / YOUR VEHICLE - SHA3533J)
Attachments: SAS2416516.pdf; SKM_C224e18060410190_0001.jpg

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLJ8373B and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

0406 2018 @ 1.24pm
Jacelyn veh nlin.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: BHAS - Jacelyn Loh [mailto:jacelyn.loh@bhauto.com.sg]
Sent: 04 June, 2018 11:30 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>
Subject: RE: pre repair inspection (OUR VEHICLE - SLJ8373B / YOUR VEHICLE - SHA3533J)

Dear sir / mdm,

We choose below surveyor: LKK Auto Consultants Pte Ltd

Ps- vehicle currently not in our workshop.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Monday, 4 June 2018 11:19 AM

To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>

Subject: RE: pre repair inspection (OUR VEHICLE - SLJ8373B / YOUR VEHICLE - SHA3533J)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]

Sent: 04 June, 2018 10:20 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Moo Wen Zheng

<wenzheng.moo@bhauto.com.sg>; BHAS - Janice Koh <janice.koh@bhauto.com.sg>

Subject: pre repair inspection (OUR VEHICLE - SLJ8373B / YOUR VEHICLE - SHA3533J)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance

Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SLJ8373B (MCT18060066)
[SHA3533J]**

TP
CHRISTOPHER ADAM BOBIN
Jun 2 2018 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
BH Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/08/2019 14:34 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6622.72) - SLJ8373B - Claim Handler: Sundari Nagarajan

Approved:6622.72:

DOCUMENTS SUMMARY

There are no documents.

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SHA3533J

Our Reference: SLJ8373B

Date: 10/07/2019

M/s India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

Attention: Claims Department

CLAIMANT: CHRISTOPHER ADAM BOBIN

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 02/06/2018 ALONG HILL STREET, INVOLVING VEHICLE NO SLJ8373B & SHA3533J

We act for CHRISTOPHER ADAM BOBIN who was the owner of motor vehicle no. SLJ8373B

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 02/06/2018 involving our client's vehicle registration number SLJ8373B and vehicle registration number SHA3533J, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 5895.27
2	Loss of Use (\$ 180 x 04 days) surveyor recommended 04 days	\$ 720.00
3	LTA Search Fee	\$ 7.45
	Total :	\$ 6622.72

We enclose a copy of each of the following documents for your consideration:-

- GIA/ Police report lodged by driver of ;
- Final Repair Bill
- Rental Invoice / Loss Of Use
- LTA Search Fee Invoice
- Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,



Yun Shi

(O): 6559 8944 (F): 6269 2404

Email: yunshi.chan@bhauto.com.sg



BY POST & EMAIL

MCT/18060066
Sund
11/2019 ✓

*Cheque payments should be crossed and made payable to IFS CAPITAL LIMITED, 10 Eunos Road 8, #09-04 Singapore Post Centre, Singapore 408600 Republic of Singapore who has acquired this account.

Remittance is to be made directly to the account of IFS CAPITAL LIMITED with Standard Chartered Bank as follows:

Account Number : 01-0-088528-4 (SGD) or

01-741-0422-7 (USD)

Address : 6 Battery Road, Singapore 049909

Kindly ensure full payment specification accompanies your payment. Unless any claims, queries or discrepancies are referred to IFS Capital Limited within fourteen days hereof all particulars herein shall be deemed to be correct.

AUTHORISATION

Name of owner of m/vehicle: CHRISTOPHER ADAM ROBIN

Address: 4 SPOTTISWOODE PARK ROAD SINGAPORE 099631

NRIC No: S2684574

RE ACCIDENT ON 02/06/18 ALONG HILL STREET

INVOLVING SLJ8373B Y's SHA 3533J

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no SLJ8373B at my/our request. I/We the abovenamed owner of motor vehicle no. SLJ8373B hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 02 (day) of 06 (month) 18 (year)

Signed: 
Owner of m/vehicle: SLJ8373B

HP: 97724209

Witnessed:

redefining

Date: 02/06/2018

To: Owner of Vehicle Number SLJ83736

The following has been advised to you via your workshop, BIT AUTO SERVICES P/L through their staff, Anthoni LAM

Please tick the applicable box if you had been advice on the content as seen below:

- You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- You had been advised by the workshop on the liability and merits of the case accordingly
- You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- The estimated waiting time for the spare parts to arrive is _____ The estimated arrival time does not include the repair period.
- You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy
- For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident
- For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim
- Others THIRD PARTY CLAIM.

Signed and acknowledge by

CLAB
Name and signature of policyholder/authorised driver

[Signature]
Name and signature of workshop personnel including company stamp

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18060066
 Claimant Ref: SLJ 8373B

We/I, BH Auto Services Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 5,895.278 (repair cost), S\$ 600.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SLJ 8373B that was damaged pursuant to the accident which occurred on 02/06/2018 (date) at HILL STREET (location) involving vehicle no. SHA 3533J (insured vehicle). This is pursuant to the inspection conducted on 06/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHRISTOPHER ADAM BOBIN ("the third party claimant") of vehicle no. SLJ 8373B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLJ 8373B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 6,507.72 to BH Auto Services Pte Ltd

Dated this 13 day of 08 2019

CLAIMANT:

Signature:


Name:

NRIC:

Address:

Nationality:

Occupation:


 Signed by "the workshop" (with chop)
CHAN YUN CHI
G7E74078G
BH Auto Services Pte Ltd
51 Ubi Ave 1 #01-25
Singapore 408933
Malaysia
Admin

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


 Signed by appointed Surveyor
LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE

SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: SLJ8373B

Date: 10/07/2019

M/s India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

BY POST & EMAIL

Vehicle No : SLJ8373B
Make/ Model : LAND ROVER
Year of Manufacture : 2013
Chassis No. : SALLSAAG5DA804938
Colour : WHITE
D.O.A : 02/06/2018

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. SLJ8373B
Type of repair: Part By Part :S\$ 5509.60

GST @ 7% : S\$ 385.67

GRAND TOTAL:S\$ 5895.27

Total : Singapore Dollars Five Thousand Eight Hundred Ninety-Five Dollars and
Twenty-Seven Cents Only.

Company's Stamp & Signature

[> Back to OneMotoring](#)

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 04 Jun 2018 / 09:51:14

Receipt Date/Time : 04 Jun 2018 / 09:51:14

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180604-000417

Previous Receipt No. :

**S/N Item Description/
 Business Transaction Reference
 No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHA3533J
 As at 02 Jun 2018/13:30:00
 Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SHA3533J
 Enquiry Fee
 20180604094931818440

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx0664	Credit Card: Visa/MasterCard	7.45
------------------	---------------------------------	------

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[Print Receipt](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jun 2018 Edit Reg		04 Jun 2018 00:00 Edit Adj Rpt	S\$5,509.60 Edit Estimates	S\$5,509.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	CHRISTOPHER ADAM BOBIN , ID: S2685557H								
Vehicle Reg. No.:	SLJ8373B	Date of Loss:	02/06/2018 13:00 - :59 [61 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060066	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA3533J	Policy No. (Claimant):	VA1/GA331245						
		Excess:							
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (08/08/2019): Alert - Adj Mandate Approved (S\$6622.72) - SLJ8373B - Claim Handler: Sundari Nag... • III_SG (07/06/2018): Alert - Adj Mandate Approved (S\$0.00) - SLJ8373B - Claim Handler: Sundari Nagara... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ8373B (MCT18060066)
[SHA3533J]

TP

CHRISTOPHER ADAM BOBIN

Jun 2 2018 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

BH Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
2	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
3	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
4	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
5	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
6	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
7	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
8	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
9	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
10	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
11	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
12	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
13	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
14	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
15	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
16	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
17	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
18	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
19	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
20	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
21	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
22	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
23	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
24	08/08/19 14:06	General View			Load JPG	<input checked="" type="checkbox"/>	
25	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
26	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
27	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
28	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
29	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
30	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
31	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
32	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
33	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
34	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
35	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
36	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
37	08/08/19 14:06	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	08/08/19 14:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/06/18 16:53	EMAIL FROM III DD 04062018	 Load PDF	
2	04/06/18 16:53	TP GIA REPORT	 Load PDF	
3	07/06/18 19:19	TP ESTIMATE- MARKED	 Load PDF	
4	08/08/19 13:21	WORKSHOP INVOICE	 Load PDF	
5	08/08/19 13:21	LTA SEARCH	 Load PDF	
6	08/08/19 13:21	LOD	 Load PDF	
7	22/08/19 10:01	AUTHORISATION TO ACT FORM	 Load PDF	
8	22/08/19 10:01	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 08:55	Singapore Accident Statement	 Load PDF	
2	01/08/19 16:56	Letter of Demand from Third Party TPD LOD FROM BH AUTO SERVICES (SLJ83738)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18010073/GWB3Q2

Date: 22/08/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant Vehicle No : SLJ8373B	Insured Vehicle No : SHA3533J
Date of Loss: 02/06/2018	Nature of Claim: TP
	Claim No: MCT18060066

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ8373B	Engine No: 0690791306DT
Make & Model: LAND ROVER RANGE ROVER SPORT, 3.0 (A)	Chassis No: SALLSAAG5DA804938
Reg. Date: 19/04/2013 (Man. Year: 2013)	Odometer: 67824 km
Colour: White	
Engine Capacity: 2993 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/40 R20	Rear Tyre Size:	215/40 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,997.16	4,539.60	10,457.56	69.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,770.00	970.00	2,800.00	74.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,767.16	5,509.60	13,257.56	70.64
+ GST 7.00/7.00% (S\$)	1,313.70	385.67	928.03	70.64
Nett Amount (S\$)	20,080.86	5,895.27	14,185.59	70.64
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,502.72		

INSPECTION

Date of Assignment:	04/06/2018	
Date Inspected:	06/06/2018 Inspected At:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Aug 2019)	
Parts:	N/A	LAND ROVER RANGE ROVER SPORT 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8373B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	5,400.00 FL	*- FL
2	1		*TAILGATE LETTERING RANGE ROVER	Necessary	269.00 FL	*269.00 FL
3	1		*TAILGATE LETTERING SPORT	Necessary	59.00 FL	*59.00 FL
4	1		*TAILGATE LETTERING HES	Necessary	141.00 FL	*141.00 FL
5	1		*TAILGATE CENTRE MOULDING	Not Necessary	538.00 FL	*- FL
6	1		*TAILGATE LOWER GARNISH	Cut	588.00 FL	*588.00 FL
7	1		*REAR WINDSCREEN MOULDING	Not Necessary	408.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Not Necessary	134.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	1,910.00 FL	*1,910.00 FL
10	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	24.00 FL	*- FL
11	1		*REAR BUMPER SIDE BRACKET LH	Deformed	75.00 FL	*75.00 FL
12	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	24.00 FL	*- FL
13	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	75.00 FL	*- FL
14	1		*REAR BUMPER CENTRE BRACKET	Cracked	150.00 FL	*150.00 FL
15	1		*REAR BUMPER LOWER CENTRE GARNISH	Scratched	116.00 FL	*116.00 FL
16	1		*REAR BUMPER REFLECTOR LH	Cracked	77.00 FL	*77.00 FL
17	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	860.00 FL	*430.00 FL
18	1		*REAR BUMPER TRADE PLATE	Deformed	142.00 FL	*142.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Repair	1,367.00 FL	*- FL
20	1		*END PANEL	Repair	1,689.00 FL	*- FL
21	1		*END PANEL TOP GARNISH	Not Necessary	153.00 FL	*- FL
22	1		*TAIL LAMP LH	Cracked	850.00 FL	*850.00 FL
23	1		*TAIL LAMP BRACKET	Not Necessary	515.00 FL	*- FL
24	1		*MUFFLER EXHAUST PIPE	Repair	751.40 FL	*- FL
25	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
27	1		*REAR BUMPER CORNER GUIDE LH	Cracked	37.40 FL	*37.40 FL
28	4		*REAR BUMPER SENSOR HOLDER	Necessary	74.80 FL	*74.80 FL
29	1		*REAR BUMPER RETAINER LH	Broken	74.80 FL	*74.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,647.40	5,039.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,650.24	499.40
Total Parts (\$\$)	14,997.16	4,539.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ANTI-RUST COATING	New	160.00	0.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,500.00	400.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	900.00	500.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	30.00	30.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	180.00	0.00
6	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIRS	New	100.00	0.00
7	RESET MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT E.G.SENSOR SENSITIVITY	New	300.00	0.00
8	REMOVE AND REPLACE BUMPER SENSOR	New	100.00	40.00
9	REMOVE/REALIGN /REPLACE EXHAUST PIPE TO FACILITATE REPAIRS	New	150.00	0.00
10	MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH AND RESET CHASSIS ALIGNMENT TO RECOMMANDED SPECIFICATIONS	New	350.00	0.00
Gross Labour Cost (S\$)			3,770.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >