SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	sont to the dronwing of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	31/05/2018 15:40
Date Of Accident	31/05/2018 08:45
Exact Location Of Accident	HAVELOCK TWDS CHURCH ST.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC8961M
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	140
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	CHUA SOY MAI @ CHUA PUI HENG

NRIC No S0345861Z
Date Of Birth 23/09/1943
Occupation OUTDOOR
Date Of Driving Pass 05/01/1961

Driving Experience 57 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90301302

Fax Number
Contact Number

EMail Address NOEMAIL

Address BLK 59 ANG MO KIO AVENUE 8

#30-12

Postcode 567752

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

1

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Details of Police Action

Number of Passengers (Including Driver)

Was the accident reported to the police? NO

If Yes,Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes,against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA4613E

Vehicle Make/Model/Colour HYUNDAI SONATA

Details Of Properties

Vehicle Category TAXI

Name of DriverTEO HAN BOCKNRIC/Passport Number\$1383925EContact Number90268839

Address Postcode

Insurance Company Name

Nature Of Damage RH FRONT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time: 31.05.2018 @ 15:30 Hrs

Reporting Centre Personnel's Signature

Name: Rubbini NRIC/FIN No.:

Sketch Plan Pg. 2

Along Havelock Rd Twds Church St. DESCRIBE CIRCUMSTANCES OF THE ACCIDENT On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came ou and thus collided onto my taxi (A)	IC 8961M.
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) PFT From portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model. Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	A 4613E
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) 100 from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model. Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) Profile from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) 100 from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model. Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) Profit from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model. Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) 100 from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model. Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	!
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came out and thus collided onto my taxi (A) PA Amportion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
On 31.05.2018 at about 08:45 Hrs, I was traveling along Havelock Rd towards with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came out and thus collided onto my taxi (A) PA Amportion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
with no passenger on board. Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came ou and thus collided onto my taxi (A) PTON portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support model. Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	do Church
Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came ou and thus collided onto my taxi (A) of filter portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	is Church
Just after I crossed the junction with New Market Rd, I switched on left signal on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came ou and thus collided onto my taxi (A) ICFT From portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) PT from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	_
on my intention. Then, I slowly filtered to left hand side after ensure the traffic is cle When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came of and thus collided onto my taxi (A) PT from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came or and thus collided onto my taxi (A) of front portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support movel (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	ii to alert
When I was about to enter the lane, suddenly veh (B) (SHA 4613E) came or and thus collided onto my taxi (A) of front portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support movel (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
and thus collided onto my taxi (A) ICFT Front portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support mover (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	ncai.
and thus collided onto my taxi (A) left from portion. As it took place so fast, I could evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support mover (B) (SHA 4613E). Mr. Teo Han Bock. NRIC: S 1383925E. Hp: 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	out from r
evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC : S 1383925E. Hp : 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
evasive action to prevent the collision. I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC : S 1383925E. Hp : 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	d not take
I had company video fixed in my taxi and photos taken at scene to support m Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC : S 1383925E. Hp : 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC : S 1383925E. Hp : 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
Veh (B) (SHA 4613E). Mr. Teo Han Bock. NRIC : S 1383925E. Hp : 9026 8839. Nobody was conveyed by the ambulance as no injury at that point of time.	
Nobody was conveyed by the ambulance as no injury at that point of time.	my claim
Nobody was conveyed by the ambulance as no injury at that point of time.	
DECLARATION	
DECLARATION	
i h	
i h	
ih.	
T TRANSPORTATION PTE LTD	

(If driver is not the policyholder)


Date & Time: 31.05.2018 @ 15:30 Hrs

Date & Time:


Page 4 of 11

Reporting Centre Personnel's Signature Name: Rubbini

NRIC/FIN No.:







Accident Photo



Accident Photo



Accident Photo



