

Signature

From

REF: **LPC**

95946

ASSIGNMENT

From:	Date:	09/07/2018	Veh No:	SLQ 2851R	Yr Regn:	2017 July				
Estimated Cost:			Type:	M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /						
OD:	TP WS / TP RES / OD RES / EVA / INV / MV		Truck / Trailer or							
To inspect Vehicle No:	SLQ 2851R		Make:	B.M.W X1 5DRIVE	C.C.	1998				
at Workshop m/s	Performance		Colour:	WHITE	A/C:	Insured / Std / NI / NA				
of	303 Alexandra Road		Sp. Reading	65921	T/Radio:	Insured / Std / NI / NA				
Insured:			Eng/No:							
Policy No.			C/No:	WBA HS 72060566477						
Claims No.			Gen. Cond:	Good / Fair / Poor / Burnt						
Sum Insured:	Excess:		Steering:	Inorder / Jammed / Leaked / Burnt or						
(Client's Record)			Brake:	Inorder / Jammed / Leaked / Burnt or						
Make of Veh:	Kevin		Modi:	Nil / 2Rim / STD A/Rim or						
(Policy Condition)			Tyre Size:	F: 225/50R18						
Remark: The veh had commenced its repair at the time of inspection.	<table border="1"> <tr> <td>N/S</td> <td>O/S</td> </tr> <tr> <td></td> <td></td> </tr> </table>		N/S	O/S			B / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or			
N/S	O/S									
Ball. or Market Value:			Front	Rear						
IDAC Accident Rpt:	Consistent? : Yes or No		R/Bal.	6 mm	R/Bal. 6 mm					
GIA / PR Seen:	Consistent? : Yes or No		L/Bal.	6 mm	L/Bal. 6 mm					
Est. Repairs:	4 days	Res.: Yes or No	D.O.A.	03/06/18	D.O.I. 09/07/18					
Lum Sum:	%	3 Val.: Yes or No	Survey held at	Performance						
CA / REV / REP. / 24 HRS lup			Des. of Damages:	Frt Res / O/S / N/S / U/C / Rooftop or						
Date:	Person Contacted:	Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.							

Date / Time Action / Instruction

\$ 2640.15

Date/Time: File Pass to?	☐ : Preli. Report	Days Of Repair:	Survey Fee:	
0)	☐ : Final Report	Resurvey No. of Trip:	Transportation	
Date/Time: File Return to?			☐ G + RS. \$	
1)		Add Fee:	☐ Photos	
		☐ Site Insp (\$)	☐ Others	
Report Format :		☐ Interview (\$)		
Lump Sum / L.B.I (\$)		☐ Tech. Insp (\$)		
		☐ Weekend (\$)		
			TOTAL	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18010083/ub3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 04-06-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 6688C	Veh. Inspected	SLQ 2851R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/06/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18010083/R1ub3

Date: 12.07.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLQ2851R


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.07.2018 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$	8,514.45
Revised Estimate Amount	: S\$	2,622.20
"Check" Items Amount	: S\$	3,149.95
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3-4 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 5 June 2018 11:02 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Thin Thin (LKKAUTO); Admin A
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLQ2851R AND SJT6688C (LONPAC) ON 03/06/2018 Our Ref: 18/18/18/VP05/020646 ***LKK REF:CC4/LPC18010083/ub3
Attachments: SJT6688C 030618.PDF

Hi Shu Pei

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 4 June, 2018 5:19 PM
To: ERIC WOO JUN KIAT; GERALD POH WEE BIN; ONG LI LI
Cc: MT_Claim_SG; Admin A; Thin Thin (LKKAUTO)
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLQ2851R AND SJT6688C (LONPAC) ON 03/06/2018 Our Ref: 18/18/18/VP05/020646 ***LKK REF:CC4/LPC18010083/ub3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 4 June 2018 2:58 PM
To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLQ2851R AND SJT6688C (LONPAC) ON 03/06/2018 Our Ref: 18/18/18/VP05/020646

Dear Eric,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Monday, 4 June, 2018 12:41 PM

To: assignments@lkkauto.com

Cc: PBSP <pml-pbsp@simedarby.com.sg>; ?? © <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>;

MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: REQ FOR DIRECT SETTLEMENT- SLQ2851R AND SJT6688C (LONPAC) ON 03/06/2018 Our Ref: 18/18/18/VP05/020646

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SLQ 2851R on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Monday, 4 June, 2018 11:05 AM

To: 甯瑋 ©; CS A Team; GERALD POH WEE BIN; ERIC WOO JUN KIAT; MT_Claim_SG

Subject: REQ FOR DIRECT SETTLEMENT- SLQ2851R AND SJT6688C (LONPAC) ON 03/06/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

04 JUN 2018

Estimate No. : b1 47166
Date Estimated : 04/06/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lim Pek Suat
12A Cairnhill Rise
#03-04

Singapore 229746

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper upp, bumper mid, bumper lower,
reinforcement & all attachments cause by accident.

850 ~~2,580.00~~

Painting on rear bumper assembly

934 ~~1,038.00~~

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

451? 531.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~177.00~~

Sundries.

? 150.00

Total Labour 1: 4,446.00

DESCRIPTION

REAR SILENCER
TAILPIPE TRIM CHROME
REAR LH BUMPER MOUNT
REAR RH BUMPER MOUNT
RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER BOTTOM TRIM PANEL (LINE
REAR BUMPER TOWING EYE COVER
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	1,465.05	1,465.05
1pc x	107.85	215.70
1	142.55	142.55
1	142.55	142.55
1	456.90	456.90
1	36.60	36.60
1	99.85	99.85
1	142.55	142.55
1	142.55	142.55
1	723.45	723.45
1	227.90	227.90
1	217.05	217.05
1	35.55	35.55
4	5.05	20.20

7
sur
?
?
?
?
sur
?
?
repair
sur
sur
sur
?
?

Total Parts : 4,068.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47166
Date Estimated : 04/06/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 09/07/18 @ 1205 Excess S\$ _____
Surveyor's Name Rasm Sign _____
Surveyor's Tel 90010018 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVYOR Yes / No Yes / No / No
Surveyor's E-mail _____
No. of Working Days Resurveyed 3-4 days

Labour 1	:	4,446.00
Parts	:	4,068.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	596.01
Grand Total	:	9,110.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

1282010

04 JUN 2018

Estimate No. : b1 47166
Date Estimated : 04/06/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lim Pek Suat
12A Cairnhill Rise
#03-04

Singapore 229746

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper upp, bumper mid, bumper lower, reinforcement & all attachments cause by accident.

850 ~~2,580.00~~

Painting on rear bumper assembly

934 ~~1,038.00~~

To replace rear exhaust silencer including alignment system and conduct checks for leak.

X 451? 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

Sundries.

40 ? 150.00

Total Labour 1: 4,446.00

DESCRIPTION

REAR SILENCER
TAILPIPE TRIM CHROME
REAR LH BUMPER MOUNT
REAR RH BUMPER MOUNT
RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER BOTTOM TRIM PANEL (LINE
REAR BUMPER TOWING EYE COVER
DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC

1 1,465.05
1 107.85
1 142.55
1 142.55
1 456.90
1 36.60
1 99.85
1 142.55
1 142.55
1 723.45
1 227.90
1 217.05
1 35.55
4 5.05

VALUE

X 850 1,465.05
sur 215.70
sur 142.55
sur 142.55
sur 456.90
sur 36.60
sur 99.85
sur 142.55
sur 142.55
repair 723.45
sur 227.90
sur 217.05
repair 35.55
X 20.20

Total Parts : 4,068.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190880 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190520 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47166
Date Estimated : 04/06/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 09/07/18 @ 1205 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90510018 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes Link

Surveyor's E-mail _____

No. of Working Days Resurveyed 3-4 days

Labour 1	:	4,446.00
Parts	:	4,068.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	596.01
Grand Total	:	9,110.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



SUPPLEMENTARY

Estimate No. : b1 47166
Date Estimated : 04/06/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Lim Pek Suat
12A Cairnhill Rise
#03-04

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 229746

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET *	1.35	10.00		13.50

Total Labour :	
Total Parts :	13.50
Total Labour & Parts :	13.50

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S2559594G**
Name: **LIM PEK SUAT**

Birth Date: **19 Nov 1964**
Issue Date: **13 Jan 2004**



 001085266G

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2559594G



Name
LIM PEK SUAT

林 碧 雪
Race
CHINESE
Date of birth
19-11-1964
Country of birth
MALAYSIA

Sex
F

S2559594G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 07 Jul 1990

NP 428A



482021

NRIC No: **S2559594G**



Date of issue
02-02-2012

**12A CAIRNHILL RISE #03-04
SINGAPORE 229746**

NRIC No: **S2559594G**

Date: **30/11/2014**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18010083/R1ub3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 08-11-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 6688C	Veh. Inspected	SLQ 2851R
Policy No.	Z18VP05017682	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020646	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	BMW X1 SDRIVE	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAHS720605G66477	Colour	WHITE
Odometer	5921	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/06/2018	Inspection Date	09/07/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2851R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	40.00
1	REAR SILENCER (SN)	SERVICEABLE	1,465.05	-
2	TAILPIPE TRIM CHROME (SN)	SCRATCHED (1 PC ONLY)	215.70	107.85
1	REAR LH BUMPER MOUNT (SN)	SERVICEABLE	142.55	-
1	REAR RH BUMPER MOUNT (SN)	SERVICEABLE	142.55	-
1	RR BUMPER CARRIER (SN)	SERVICEABLE	456.90	-
1	MOUNTING SMART OPENER (SN)	SERVICEABLE	36.60	-
1	REAR TRIM UNDERRIDE PROTECTION (X L)(SN)	SCRATCHED	99.85	99.85
1	RR BUMPER LH CORNER MOUNTING (SN)	SERVICEABLE	142.55	-
1	RR BUMPER RH CORNER MOUNTING (SN)	SERVICEABLE	142.55	-
1	REAR BUMPER PANEL PRIMED (SN)	TO REPAIR SEE LABOUR	723.45	-
1	REAR BUMPER MIDDLE TRIM PANEL (PDC)(SN)	SCRATCHED	227.90	227.90
1	REAR BUMPER BOTTOM TRIM PANEL (LINE) (SN)	SCRATCHED	217.05	217.05
1	REAR BUMPER TOWING EYE COVER (SN)	NOT NECESSARY	35.55	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	20.20	-
10	EXPANDING RIVET (SN)(ADDITIONAL)	NECESSARY	13.50	13.50
			4,231.95	706.15
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER UPP ,BUMPER MID ,BUMPER LOWER,REINFORCEMENT & ALL ATTACHMENTS CAUSE BY ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR BUMPER PANEL PRIMED.		2,550.00	850.00
	PAINTING ON REAR BUMPER ASSEMBLY .		1,038.00	934.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	NOT NECESSARY	531.00	-
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			4,296.00	1,934.00
GRAND TOTAL			8,527.95	2,640.15

Report Ref No. CC4/LPC18010083/R1ub3n2



RECOMMENDED COST OF REPAIRS			2,640.15
-----------------------------	--	--	----------

Report Ref No. CC4/LPC18010083/R1ub3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.