

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

04 JUN 2018

Estimate No. : b1 47166
Date Estimated : 04/06/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lim Pek Suat
12A Cairnhill Rise
#03-04

Singapore 229746

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper upp, bumper mid, bumper lower,
reinforcement & all attachments cause by accident.

850 ~~2,500.00~~

Painting on rear bumper assembly

934 ~~1,038.00~~

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

451? 531.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~177.00~~

Sundries.

? 150.00

Total Labour 1: **4,446.00**DESCRIPTION

REAR SILENCER
TAILPIPE TRIM CHROME
REAR LH BUMPER MOUNT
REAR RH BUMPER MOUNT
RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER BOTTOM TRIM PANEL (LINE
REAR BUMPER TOWING EYE COVER
DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC

1 1,465.05
1pc 107.85
1 142.55
1 142.55
1 456.90
1 36.60
1 99.85
1 142.55
1 142.55
1 723.45
1 227.90
1 217.05
1 35.55
4 5.05

VALUE

? 1,465.05
sub 215.70
? 142.55
? 142.55
? 456.90
? 36.60
sub 99.85
? 142.55
? 142.55
repair 723.45
sub 227.90
sub 217.05
sub 35.55
? 20.20

Total Parts : **4,068.45**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47166**
Date Estimated : **04/06/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2851R	5G66477	03/07/2017	X1 sDrive20i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 09/07/18 @ 1205 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90010018 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No

Surveyor's E-mail _____

No. of Working Days Recommended 3-4 days

Labour 1	:	4,446.00
Parts	:	4,068.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	596.01
Grand Total	:	9,110.46

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****