

ASS. REC. BY:

REF: CS/FCI/8010092/Kgd3 n2

Special Instruction:

Surveyor: Kannik.
WS

ASSIGNMENT (Office)

From (Person): Karon Tan

of PCI

Date/Time: 4/6/18 @ 4:15 pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 5172Y

Insured: SHB 4126P

at Workshop m/s: Cheng Hoe Motor

Tel: 67556142

of Bik 1019 Yishun Ind. park A # 01-374

Policy No:

Claim No: D18004405MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/06/2018

CA / REV / REP. / REV 24 HRS

cup

5/6/18

H.O.D. Endorsement:

Date/Time: 5:22pm @ 4/6/18

Person Contacted: efeda

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJL 5172Y - CS/LAW/11006420/Gfn DOA: 5/09/2010
	SHB 4126P - NA/III/17004448/hq DOA: 03/03/17
<u>05/6/18 @ 2:27pm</u>	<u>revised to Karon Tan by email.</u>
<u>4/7</u>	<u>11 Days @ 25500 Cap Simd Turn (Mod @ 1089.12; 30%)</u>

ASS. REC. BY:

REF: FC21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Cheng Hoe Trans Cab

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STL 5172Y Yr Regn: 11, 08

Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Honda Fit c.c. 1339

Colour: M.L. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 136371 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GEE . 1087516

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 2/6/18 D.O.I. 4/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or ols body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/6 File pass to Catherine

RECEIVED 04 JUL 2018

Date/Time, File Pass to?

1) 04/7/2018

Date/Time, File Return to?

2) _____

: Prel. Report

: Final Report

Days Of Repair: 5

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

Fixtots

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 7P 2550)

130
50
50+50
21
TOTAL
301



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004405MFSH

Date: 05 June 2018

Our Ref: CS/FCI18010092/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJL 5172Y.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2018 at the premises of M/s CHENG HOE MOTOR, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,639.12</u>
Revised Estimate Amount	: <u>S\$ 2,882.16</u>
“Check” Items Amount	: <u>S\$ 341.68</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the o/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-06-2018	Our Ref No. D18004405MFSH
Accident Date	02-06-2018	Claim Type. Third Party
Insured Vehicle	SHB4126P	Third Party Vehicle. SJL5172Y
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	EFEEDA	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 5 June 2018 2:27 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004405MFSH/1
Attachments: CSFCI18010092Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SJL 5172Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 4 June 2018 5:25 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004405MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 4 June 2018 4:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004405MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5183Z
Vehicle Details	
Vehicle No.:	SJL5172Y
Vehicle to be Exported:	No
Intended De-registration Date:	02 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G F A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13A4098043
Chassis No.:	GE61087516
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,979.00
Original Registration Date:	29 Nov 2008
First Registration Date:	29 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$9,607.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2018
PARF Rebate Amount:	\$4,803.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$2,924.00
COE Rebate Amount:	\$649.00
Total Rebate Amount:	\$5,452.00

The information contained herein is correct as at 02 Jun 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJL 5172Y
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 02/06/2018

TP Veh Reg No: SHB4126P

Not Notified
11 Sep @ 2550.
Benay After Paint
5 days

Estimate No: ES1890610/YISHUN

Date: 04 Jun 2018

Policy No: 5095951951

Veh Reg No: SJL5172Y

Make/Model: HONDA FIT 1.3G F A

Chassis No: GE61087516

Engine No: L13A4098043

Reg. Date: 29/11/2008

Estimate Repair Cost to Vehicle No :SJL5172Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT LH DOOR	781.50	1 PC	<i>B</i> 781.50	✓
2 REAR LH DOOR	746.20	1 PC	<i>B</i> 746.20	✓
3 REAR LH DOOR BOTTOM HINGE	39.60	1 PC	<i>717</i> 39.60	✓
4 REAR LH DOOR INNER LOCK	231.60	1 PC	<i>R</i> 231.60	X
5 LH SIDE SKIRT	387.50	1 PC	<i>cm</i> 387.50	✓
			2,186.40	
		Less 20%	437.28	1,749.12
Special Net				
6 REAR LH SPORT RIM	380.00	1 PC	<i>RD</i> 380.00	<i>280.00</i>
			380.00	380.00
Labour				
7 REMOVE & REFIX FRT & REAR LH DOORS,TRANSFER DOORS ATTACHMENTS,LH SIDE SKIRT,TO KNOCK & REPAIR LH DOOR PILLAR & REALIGN THE SAME	580.00	1 LA	580.00	<i>500</i>
8 PUTTY & RESPRAY ON LH DOOR PILLAR,LH SIDE SKIRT,FRT & REAR LH DOORS	750.00	1 LA	750.00	<i>700</i>
9 REMOVE & REFIX FRT & REAR LH DOOR GLASS	120.00	1 LA	120.00	✓
10 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,510.00	1,510.00
		Total	SS 3,639.12	
		Add GST @ 7%		254.74
		Total Amount Payable	SS 3,893.86	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

[Signature]

AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010092/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4126P	Veh. Inspected	SJL 5172Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18004405MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	04/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61087516	Colour	METALLIC LIGHT BLUE
Odometer	136371	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	DUNLOP	5 mm
L/H Front Tyre	195/55 R15	DUNLOP	5 mm
R/H Rear Tyre	195/55 R15	DUNLOP	5 mm
L/H Rear Tyre	195/55 R15	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/06/2018	Inspection Date	04/06/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5172Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH DOOR	BENT	781.50	781.50
1	REAR LH DOOR	BENT	746.20	746.20
1	REAR LH DOOR BOTTOM HINGE	DISTORTED	39.60	39.60
1	REAR LH DOOR INNER LOCK	TO REPAIR SEE LABOUR	231.60	-
1	LH SIDE SKIRT	CRACKED	387.50	387.50
	LESS 20% DISCOUNT		-437.28	-390.96
			1,749.12	1,563.84
SPECIAL NETT ITEMS				
1	REAR LH SPORT RIM (SN)	DENTED	380.00	280.00
			380.00	280.00
LABOUR				
	REMOVE & REFIX FRT & REAR LH DOORS. TRANSFER DOORS ATTACHMENTS, LH SIDE SKIRT, TO KNOCK & REPAIR LH DOOR PILLAR & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR LH DOOR INNER LOCK.		580.00	500.00
	PUTTY & RESPRAY ON LH DOOR PILLAR, LH SIDE SKIRT, FRT & REAR LH DOORS.		750.00	700.00
	REMOVE & REFIX FRT & REAR LH DOOR GLASS.		120.00	120.00
	RUSTPROOFING.		60.00	60.00
			1,510.00	1,380.00
GRAND TOTAL			3,639.12	3,223.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CS/FCI18010092/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.