

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC1901269
INV Date 14/02/2019
Reference CC6/EQ118010105/Aha3q2
Code EQI

**PROFESSIONAL SERVICE FEE**

Vehicle No. GBH 3794G
Insured Veh. GBH 3001L
Claim No. DM18HO02739-JG
Policy No. DMCPHQ18-002319
Accident Date 28/05/2018
Inspection Date 01/06/2018

Description	Total
Survey Inspection	160.00
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

INS. CASE OWNER

CC 6, EQ1 180, 60105, Aha3/1/

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess See II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)		
After call ltr to OI:		
Authorisation To Act:		
Release Voucher:		
Final Repair Bill:		
Car Rental Invoice:		
Towing Invoice:		
LTA / GIA:		
Medical Bill:		
PIR:		
Mandate/Reject Instruction:		
LOD		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE

Date/Time: 12/10/18

Sent By: 93

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 410 SS 900.00 (3 days) Reduction: 81 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: SS —

Loss of Rental (LOR): SS — (days)

Loss of Use (LOU): SS — (\$ x days)

Loss of Income (LOI): SS — (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: SS —

Medical: SS —

Disbursement: SS — (e.g. Tow/ Independent)

Legal Cost: SS —

Total: SS — Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: WP REPORT

3) Survey fee:

8100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: SS —

Name 1:

Payee 2: (Strike if N.A.) SS —

Name 2:

Payee 3: (Strike if N.A.) SS —

Name 3:

12/21/19

ASS. REC. BY: Abhinav Singh

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH37946

Yr Regn:

2018, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

cc 2982

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading:

1732

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH2010209395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

01/06/18

Survey held at

F1 Auto Clinic

Des. of Damages: Frt / Rear (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPEQ

L/S \$ 900.00

CRMD: \$ 3,864.20 / 31%

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQI18010105/Aha3

Date: 12/10/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

GBH 3794G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.06.2018 at the premises of M/s F-1 Autoclinic Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	4,764.20
Revised Estimate Amount	: S\$	900.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	900.00

Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1105K

Vehicle Details

Vehicle No:

GBH3794G

Vehicle to be Exported:

Yes

Intended De-registration Date:

31 May 2018

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE DX 3.0 MANUAL

Primary Colour:

White

Manufacturing Year:

2016

Engine No:

1KD2661350

Chassis No:

KDH2010209395

Maximum Power Output:

-

Open Market Value:

\$33,816.00

Original Registration Date:

08 May 2018

First Registration Date:

08 May 2018

Transfer Count:

0

Actual ARF Paid:

\$1,691.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

07 May 2028

COE Category:

C - Goods Vehicle & Bus

COE Period (Years):

10

QP Paid:

\$36,859.00

COE Rebate Amount:

\$29,487.00

Total Rebate Amount:

\$29,487.00

The information contained herein is correct as at 31 May 2018

OK

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

NET LINK LEASING PTE LTD
 25 KAKI BUKIT ROAD4
 # 05-26 SYNERGY @KB
 Singapore 417800

TPEA

VIC

01st JUNE 2018

Accident date: 28th MAY 2018

Estimated repair cost for vehicle no: GBH3794G TOYOTA HIACE 3.0 18

S/n	Qty	Items	U/price	Amount
1	1	LH rear side panel <i>Repair</i>		\$2,800.00 *
2	1	LH rear lower panel <i>Repair</i>		\$105.00 *
3	1	tail lamp LH lower panel <i>Repair</i>		\$88.00 *
4	1	tail lamp-LH <i>Repair</i>		\$229.10 ✓
5	1	rear bumper <i>Repair</i>		\$482.10 ✓
711.20 533.40				Subtotal :-
				\$3,704.20

Labour charges

To Check Wiring System

~~\$60.00~~ 300

Panel beating

630

~~\$500.00~~ 300

Spray painting

~~\$500.00~~ 300

Subtotal :- \$1,060.00

Total:- \$4,764.20

LKK Auto Consultant hereby notify

the following:

- To resurvey before and after spray painting
- To display damaged car during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary works must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 1163.40

1/5 : 900

030mp

Mei Kwan (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Friday, 14 December, 2018 5:22 PM
To: Joel Goh; Mei Kwan (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Admin A; Vic (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBH3001L (OI : EQI - DM18HO02739-JG) and GBH3794G (TP : LKK REF - CC6/EQI18010105/Aha3) on 28/05/2018
Attachments: GBH3001L.PDF; VIDEO-2018-10-04-22-15-44.mp4
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Joel,

We refer to your below email and the contents were noted.

Meanwhile, please find attached TP video footage for your reference.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vic@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Friday, 14 December, 2018 5:04 PM
To: Mei Kwan (LKKAUTO)
Cc: Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBH3001L (OI : EQI - DM18HO02739-JG) and GBH3794G (TP : LKK REF - CC6/EQI18010105/Aha3) on 28/05/2018

Dear Mei Kwan

Attached our insured's accident report for your attention.
Please do not proceed with direct settlement for this case at the moment.

We are investigating into a potential breach.

Best Regards,

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle GBH 3794G at M/s F-1 Autoclinic Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vic (LKKAUTO)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Monday, 11 February, 2019 11:03 PM
To: Vic (LKKAUTO)
Subject: Re: GBH3794G & GBH3001L DOA 28.05.2018 LKK REF CC6/EQI18010105/Aha3

Dear Vic ,

Noted . Closed case . Thanks

Regards,
Chris Chan Pick Yuen

From: Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Sent: Monday, January 28, 2019 8:08 PM
To: chan pick yuen
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: GBH3794G & GBH3001L DOA 28.05.2018 LKK REF CC6/EQI18010105/Aha3

Without Prejudice

Dear Chris,

We refer further to our below email.

We were informed by our principal that our Insured had settle privately with your client. Kindly refer to the attached signed documents.

As such, kindly confirm that your client will withdraw the claim against our Insured.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Thursday, 10 January, 2019 12:10 PM

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 12 February, 2019 9:32 AM
To: Joel Goh
Cc: Hsiao Tong (LKKAUTO); Admin A; Vic (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBH3001L (OI : EQI - DM18HO02739-JG) and GBH3794G (TP : LKK REF - CC6/EQI18010105/Aha3) on 28/05/2018
Attachments: Private Settlement Agreement.pdf; Re: GBH3794G & GBH3001L DOA 28.05.2018 LKK REF CC6/EQI18010105/Aha3

Dear Joel,

We refer to your below email.

Please be informed that TP repairer confirmed private settlement and closed case in their side.

As such, we will also close the matter in our end and will forward our WP report accordingly.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Monday, 28 January, 2019 7:20 PM
To: Vic (LKKAUTO); Mei Kwan (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBH3001L (OI : EQI - DM18HO02739-JG) and GBH3794G (TP : LKK REF - CC6/EQI18010105/Aha3) on 28/05/2018

Dear Vic

Please assist to check if third party is withdrawing their claim against our insured.

Attached private settlement agreement showing that insured had settled this matter with F-1 Autoclinic directly.

Best Regards,

Joel Goh

Executive | Claims

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC5/EQ18010105/Aha3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 14-02-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 3001L	Veh. Inspected	GBH 3794G
Policy No.	DMCPHQ18-002319	Coverage (\$)	0.00
Claim No.	DM18HO02739-JG	Excess (\$)	0.00
Assign From		Assign Date	01/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KDH2010209395	Colour	WHITE
Odometer	1732	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	DUNLOP	6 mm
L/H Front Tyre	195/60 R15	DUNLOP	6 mm
R/H Rear Tyre	195/60 R15	DUNLOP	6 mm
L/H Rear Tyre	195/60 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/05/2018	Inspection Date	01/06/2018
Survey held at	F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 3794G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH REAR SIDE PANEL	TO REPAIR SEE LABOUR	2,800.00	-
1	LH REAR LOWER PANEL	TO REPAIR SEE LABOUR	105.00	-
1	TAIL LAMP LH LOWER PANEL	TO REPAIR SEE LABOUR	88.00	-
1	TAIL LAMP -LH	CUT	229.10	229.10
1	REAR BUMPER	CUT	482.10	482.10
	LESS 25% DISCOUNT		-	-177.80
			3,704.20	533.40
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF LH REAR SIDE PANEL, LH REAR LOWER PANEL AND TAIL LAMP LH LOWER PANEL.		500.00	300.00
	SPRAY PAINTING.		500.00	300.00
			1,060.00	630.00
	GRAND TOTAL		4,764.20	1,163.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CC6/EQ118010105/Aha3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.