

2017

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
HP: 96583371 TEL: (65) 67022915 FAX: 67022916

INVOICE

NET LINK LEASING PTE LTD
25 KAKI BUKIT ROAD 4
#05-26 SYNERGY @KB
Singapore 417800

Date: 12th OCT 18

Accident date: 28th MAY 2018
Final Bill For Vehicle No: GBH3794G TOYOTA HIACE

Descriptions	AMOUNT
Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD Surveyor : Mr Adrian Ling	\$900.00
Total	\$900.00

S/DLRS: NINE HUNDRED ONLY