



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 04.06.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2632Y TOYOTA PRIUS HYBRID 1.5S (2010)

To supply

1) 1pc	Rear bumper	\$	580.00 <i>de</i>
2) 1set	Rear bumper clip	\$	30.00 <i>ner</i>
3) 1pc	Rear bumper left bracket	\$	132.10 <i>X</i>
4) 1pc	Rear bumper left side retainer	\$	122.25 <i>ner</i>

Sub total parts	\$	864.35
Less: 25% discount	\$	(216.09)
	\$	648.26

To supply S.Nett parts

1) 1pc	Rear bumper advertisement sticker	\$	100.00 <i>ner</i>
2) 1set	Reverse sensor	\$	160.00 <i>ner</i>

Sub total S.Nett Parts	\$	260.00
------------------------	----	--------

L/charges

1) To remove & replace reverse sensor.	\$	40.00 <i>30</i>
2) To remove rear bumper. Knock rear end panel. Replace rear bumper.	\$	350.00 <i>200</i>
3) To putty, respray painting rear bumper & rear end panel.	\$	400.00 <i>200</i>

Tanpin 97495749
WP 6/6/18E 1pm
2 days
Resurvey after repair
sure lkkauto.com

Sub total L/charges	\$	790.00
Estimated Grand Total	\$	1,698.26