

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J**AAD1806-031***Not Authored
1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5444J

VF1ABL15AUC280071

RENAULT

LATITUDE

2.6.2018

CHINA TAIPING

PART		LIST	
1	1 BUMPER COVER REAR	\$	B ₁ 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	B ₁ 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	C ₁ 113.47 ✓
4	1 BUMPER BRACKET SIDE RH REAR	\$	S ₁ 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	S ₁ 44.99 X
6	1 BUMPER REFLECTOR RH	\$	S ₁ 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	C ₁ 135.97 ✓
8	1 BUMPER RETAINER LH REAR	\$	D ₁ 44.99 ✓
9	1 BUMPER REFLECTOR LH	\$	C ₁ 43.61 ✓
10	1 BUMPER BEAM REAR	\$	B ₁ 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	B ₁ 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	B ₁ 225.95 ✓
13	1 BOOT REAR	\$	B ₁ 2,872.68 ✓
14	1 BOOT FINISHER	\$	S ₁ 470.06 X
15	1 BOOT WHEATERSTRIP	\$	D ₁ 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	C ₁ 493.35 ✓
17	1 BOOT REFLECTOR LAMP RH	\$	S ₁ 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	M ₁ 225.36 ✓
19	1 BOOT BADGE	\$	M ₁ 225.36 ✓
20	1 BOOT STRUT LH	\$	S ₁ 276.08
21	1 BOOT STRUT RH	\$	S ₁ 276.08
22	1 BOOT HINGE LH	\$	R ₁ 367.84
23	1 BOOT HINGE RH	\$	R ₁ 367.84
24	1 BOOT INNER TRIM	\$	S ₁ 586.45
25	1 BOOT SWITCH	\$	S ₁ 168.13
26	1 BOOT LOCK	\$	R ₁ 202.67
27	1 BOOT LOCK CATCH	\$	R ₁ 74.40
28	2 LICENCE PLATE LAMP	\$	S ₁ 50.52
29	2 BOOT RUBBER PLUG	\$	S ₁ 221.81

Trans-cab Auto Services Pte Ltd
AAD1806-031

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
32	1 FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
33	1 WHEELARCH REAR LH	\$	Sn	543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Return	671.45	✓
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
36	1 WHEELARCH REAR RH	\$	Sn	543.47	X
37	1 TAILLAMP RH	\$	Sn	552.55	X
38	1 TAILLAMP PANEL RH	\$	R	986.70	X
39	1 TAILLAMP LH	\$	MyCM	552.55	✓
40	1 TAILLAMP PANEL LH	\$	R	986.70	✓
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/R	2,189.88	✓
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
45	1 EXHAUST REAR	\$	R	7,489.05	X
46	1 EXHAUST CAP REAR	\$	R	230.49	X
47	1 FUEL FLAP L70Y	\$	Sn	343.57	X
48	1 BUMPER COVER FRT	\$	R	1,259.42	✓
49	1 BUMPER SPOILER FRT	\$	Sn	181.75	
50	1 BUMPER ABSORBER FRT	\$	CM	394.68	✓
51	1 BUMPER RETAINER FRT LH	\$	D.Y	151.41	✓
52	1 BUMPER SUPPORT FRT	\$	Sn	123.88	X
53	1 BUMPER RETAINER FRT RH	\$	D.Y	150.77	✓
54	1 BUMPER SUPPORT FRT	\$	Sn	123.88	X
55	1 BUMPER UNDERTRAY FRT	\$	Sn	472.83	X
56	1 BUMPER GRILLE LOWER FRT	\$	Sn	266.80	X
57	1 BUMPER FOG LAMP GRILLE LH	\$	Sn	207.21	X
58	1 BUMPER FOG LAMP GRILLE RH	\$	Sn	207.21	X
59	1 BUMPER BEAM FRT	\$	R	914.08	✓
60	1 TOW COVER FRT	\$	D.Y	28.61	✓
61	1 RADIATOR GRILLE	\$	My	1,707.78	✓
62	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	My	225.36	✓
63	1 RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
64	1 FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
65	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	✓
66	1 FRONT BRACE PANEL	\$	D.Y	177.22	✓
67	1 HORN	\$	Sn	314.17	X
68	1 HORN BRACKET	\$	R	40.45	X

Trans-cab Auto Services Pte Ltd**AAD1806-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

69	1 HEADLAMP LH	\$	<i>mg</i> 1,184.43	✓
70	1 HEADLAMP RH	\$	<i>h</i> 1,184.43	✓
71	1 HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
72	1 HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
73	1 BONNET	\$	<i>B</i> 1,941.63	✓
74	1 BONNET INSULATOR	\$	<i>Sn</i> 405.73	X
75	1 BONNET STRUT LH	\$	<i>Sn</i> 88.61	X
76	1 BONNET STRUT RH	\$	<i>Sn</i> 88.61	X
77	1 BONNET HINGE LH	\$	<i>R</i> 348.31	X
78	1 BONNET HINGE RH	\$	<i>R</i> 348.31	X
79	1 BONNET LOCK	\$	<i>D.7</i> 305.48	✓
80	1 BONNET CABLE	\$	<i>Sn</i> 119.19	X
81	1 BONNET CABLE COVER	\$	<i>Sn</i> 161.03	X
82	1 BONNET SEAL OUTER	\$	<i>Sn</i> 92.36	X
83	1 BONNET SEAL INNER	\$	<i>Sn</i> 157.28	X
84	1 FENDER PANEL FRT LH	\$	<i>B</i> 783.83	✓
85	1 WHEELARCH FRT LH	\$	<i>Sn</i> 278.84	} X
86	1 FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79	
87	1 FENDER INSULATOR LH	\$	<i>Sn</i> 130.84	
88	1 FENDER INSULATOR RH	\$	<i>Sn</i> 130.84	
89	1 AIR CLEANER LOWER	\$	<i>Sn</i> 271.26	
90	1 AIR CLEANER HOSE	\$	<i>Sn</i> 76.14	
91	1 BASE BATTERY TRAY	\$	<i>Sn</i> 363.40	
92	1 AIR CLEANER BOX	\$	<i>Sn</i> 464.20	
93	1 TURBO DUCT	\$	<i>Sn</i> 1,027.80	
94	1 A/C HEATER VALVE	\$	<i>Sn</i> 484.50	
95	1 SUBFRAME OUTER FRT	\$	<i>Sn</i> 2,652.45	} X
96	1 SUBFRAME BRACKET OUTER LH	\$	<i>Sn</i> 92.36	
97	1 ENGINE UNDERTRAY	\$	<i>Sn</i> 564.98	
98	1 A/C CONDENSER	\$	<i>Pr</i> 2,020.37	
99	1 A/C CONDENSER GARNISH LH UPPER	\$	<i>Sn</i> 39.67	
100	1 A/C CONDENSER GARNISH RH UPPER	\$	<i>Sn</i> 39.67	
101	1 A/C CONDENSER GARNISH LH	\$	<i>Sn</i> 58.81	
102	1 A/C CONDENSER GARNISH RH	\$	<i>Sn</i> 59.60	
103	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	<i>Sn</i> 208.39	
104	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	<i>Sn</i> 658.72	
105	1 A/C PIPE COMPRESSOR	\$	<i>Sn</i> 334.29	} X
106	1 A/C PIPE	\$	<i>Sn</i> 658.72	

Trans-cab Auto Services Pte Ltd**AAD1806-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

107	1 A/C COMPRESSOR	\$	2,684.61	✓
108	1 AIR COOLER	\$	792.60	X
109	1 AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	X
110	1 AIR INTERCOOLER HOSE (Short)	\$	375.14	X
111	1 TRANSMISSION COOLER	\$	1,219.30	X
112	1 TRANSMISSION COOLER PAD	\$	17.96	X
113	1 RADIATOR	\$	1,202.20	?
114	2 RADIATOR STUD UPPER	\$	14.41	X
115	2 RADIATOR BUSH UPPER	\$	50.12	X
116	2 RADIATOR MTG LOWER	\$	55.85	X
117	1 RADIATOR FAN COWLING	\$	820.54	?
118	1 RADIATOR FAN MOTOR LH	\$	967.36	?
119	1 RADIATOR FAN MOTOR RH	\$	1,479.46	?
120	1 RADIATOR TANK	\$	324.62	}
121	1 RADIATOR HOSE UPPER	\$	240.56	
122	1 RADIATOR HOSE LOWER	\$	491.18	
123	1 RADIATOR TANK HOSE	\$	61.18	
124	1 AUTO COMPUTER	\$	5,032.17	
125	1 INJECTION COMPUTER	\$	4,706.30	}
126	1 RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52	
127	1 STEERING PUMP ELECTRIC L70Y	\$	2,306.90	
128	1 STEERING PINION RACK L70Y	\$	4,413.11	

TOTAL	\$	99,633.49
10%	\$	9,963.35
	\$	89,670.15

Special Nett

1 1SET PARKING AID	\$	700.00	✓
2 1SET REAR BUMPER CLIP	\$	66.00	✓
3 1SET BUMPER BRACKET CTR CLIP	\$	33.00	✓
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	66.00	✓

Trans-cab Auto Services Pte Ltd**AAD1806-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

10	1 EXHAUST MOUNTING REAR	\$	Sn 17.82	
11	1SET BOOT FINISHER CLIP	\$	nn 24.20	
12	1 BOOT STICKER "Trans-cab"	\$	nn 30.00	
13	1 BOOT STICKER "6555-3333"	\$	nn 30.00	
14	1 BOOT INNER TRIM CLIP	\$	nn 45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn 35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn 35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	nn 28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	nn 28.00	
19	1 TAILLAMP CLIP RH	\$	nn 5.00	
20	1 TAILLAMP CLIP LH	\$	nn 5.00	
21	2 REAR WINDSCREEN SELANT	\$	nn 80.00	40sn
22	1 WINDSCREEN MOULDING	\$	nn 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	30sn
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn 385.00	X
25	1 SPARE TYRE	\$	Sn 330.00	X
26	1SET RADIATOR GRILLE FRAME CLIP	\$	nn 52.00	
27	1SET BUMPER CLIP FRT	\$	nn 66.00	X
28	1 BUMPER BRACKET CLIP FRT LH	\$	nn 12.00	
29	1 BUMPER SUPPORT CLIP FRT LH	\$	nn 10.50	
30	1 BUMPER BRACKET CLIP FRT RH	\$	nn 12.00	
31	1 BUMPER SUPPORT CLIP FRT RH	\$	nn 10.50	
32	1 TOW COVER FRT	\$	Sn 14.50	
33	1SET RADIATOR GRILLE SCREW	\$	nn 16.00	
34	1SET BUMPER GRILLE LOWER CLIP	\$	nn 69.00	
35	1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00	
36	2 FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00	
37	2 FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00	
38	1 Windscreen moulding	\$	nn 100.00	
39	1SET Front licence plate with holder	\$	Bt 80.00	45sn

TOTAL \$ 2,787.52**TOTAL PARTS \$ 92,457.67****LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 9,000.00

2400

Trans-cab Auto Services Pte Ltd**AAD1806-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	2200
To Rust-Proofing Of The Affected Areas.	\$	170.00	✓
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	600
To repair and realign rear exhaust pipe.	\$	170.00	} 600
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1000
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	600
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X
Towing Fees.	\$	120.00	

Trans-cab Auto Services Pte Ltd**AAD1806-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	X
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>4d</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} <i>25d</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00	X
To remove and refit air bag system and reset.	\$	<i>nn</i> 480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	<i>6d</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00	<i>10d</i>
To replace, refix and top up coolant for radiator	\$	170.00	<i>5d</i>

Trans-cab Auto Services Pte Ltd**AAD1806-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5444J

To vacuum, replace, refix and recharge Air

Intercooler

\$ 170.00 *501*

To Transfer Of Fender Fittings, Attachments And

Perform Water Seepage Test.

\$ *nn* 170.00 *X***TOTAL \$ 24,220.00****Over All Total \$ 116,677.67****(LUMP SUM)***28***Repair Days***~~30~~ DAYS***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: