

ASSIGNMENT

Surveyor:

ANK

DOI:

4-6-18

Date / Time:

4-6-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKB5487E

Name of Insured:

CHINA ARMY

Insured Tel No.:

HP:

30105/2018

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHEN CANA

Driver Tel No.:

90182869

(V/L: YES / NO)

Claim No.:

121114 / VPO5020644

Policy No.:

218 VPO5018246

Make / Model:

C. CRUIZE

Place of Accident:

MCE TUNNEL

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

PREMIER
Premier

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

13/11/18
JingSKB5487E } NA/LPC/5009803/64 ; WPA: 30105/2018
SKB5487E

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

☒☐

After call ltr to OI:

☒☐

Authorisation To Act:

☒☐

Release Voucher:

☒☐

Final Repair Bill:

☒☐

Car Rental Invoice:

☒☐

Towing Invoice

☒☐

LTA / GIA :

☒☐

Medical Bill:

☒☐

PIR:

☒☐

Mandate/Reject Instruction:

☒☐

LOD

☒☐

Payment Breakdown Form:

☐☐

Post-Repair Photos:

☐☐

Others:

☐☐

PRELIMINARY ADVICE

Date/Time:

6/6

Sent By:

Jing

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

30-11-18

Confirm with:

GARY

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 27

Repair Cost:

SS

2,033.86

Loss of Rental (LOR):

SS

217.86

(2 days)

108.93

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

80

(\$ 40 x 2 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.21

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

2,332.86

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,332.86

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC3/LPC18010148/K1ja3	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 05-06-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 5487E	Veh. Inspected	SHD 1086E	
Policy No.	Z18VP05018246	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020644	Excess (\$)	0.00	
Assign From		Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/05/2018	Inspection Date	05/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 11 June, 2018 2:24 PM
To: Mei Kwan (LKKAUTO); MT_Claim_SG
Cc: Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SKB5487E (OI : LPC - 18/18/18/VP05/020644) AND SHD1086E (TP : LKK REF - CC3/LPC18010148/K1ja3) on 30/05/2018
Attachments: SKB5487E 300518.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Attached is our Insured's GIA report for your handling.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Monday, 11 June, 2018 11:45 AM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT; Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A

Subject: Direct Settlement - Accident Involving SKB5487E (OI : LPC - TBA) AND SHD1086E (TP : LKK REF - CC3/LPC18010148/K1ja3) on 30/05/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 1086E at M/s Premier Automotive Services Pte Ltd – Changi.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Gary Shi

From: Gary Shi
Sent: Friday, 30 November, 2018 1:57 PM
To: 'Joy Irene (LKKAUTO)'
Cc: AccReport
Subject: RE: LOD / Accident involving SHD1086E & SKB5487E on 30.05.18 (Lonpac case)

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHD1086E, our client agreed to direct settle the above claims at \$2332.86

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$2332.86 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Wednesday, 28 November, 2018 2:34 PM
To: Gary Shi
Cc: AccReport
Subject: RE: LOD / Accident involving SHD1086E & SKB5487E on 30.05.18 (Lonpac case)

WITHOUT PREJUDICE

Dear Gary,

DV and ATA attached for your necessary action.

Kindly send or hand over the original copy to our surveyor.

Thank you.

PREMIER TAXIS	HIRER / RELIEF / SUPER RELIEF
VEHICLE NO.	SHD 1086 E
CONTACT NO.	9735 3386
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S00288511



Name

TAN POH ANN KENNETH

Race

CHINESE

Date of Birth

12-07-1953

Sex

M

Country of Birth

SINGAPORE

S00288511

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S00288511

Name

TAN POH ANN KENNETH

Birth Date: 12 Jul 1953

Issue Date: 31 Mar 2006



NRIC No. S00288511



Blood Group: Date of Issue

A+

16-07-1993

APT BLK 312A SUMANG LINK #08-177
SINGAPORE 821312

NRIC No: S00288511

Date: 20/11/2014

1113779

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

28 May 1971

NP 428A



Licence No: S00288511

Land Transport Authority

VOCATIONAL LICENCE

Licence No: S00288511

Name: TAN POH ANN KENNETH

Issue Date: 30/9/2015

Please visit www.lta.gov.sg to check the status of this vocational licence



Text size +

Enquire Transaction History**Transaction History Details**

Log Date/Time:	30 Oct 2015 / 08:53:12	Receipt No.:	AACCK001-AX239-151030-000021
Asset Type:	Vehicle	Transaction Amount:	\$69,044.00
Asset ID:	SHD1086E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151030085312963589		

Vehicle No.:	SHD1086E
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	30 Oct 2015
Original Registration Date:	30 Oct 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5639555
Engine No.:	D4FDEH313485
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$22,475.00
Minimum PARF Benefit:	\$14,079.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	30 Oct 2015 08:53:12
COE No.:	2015103001003657Z
COE Expiry Date:	29 Oct 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$45,439.00
Lifespan Expiry Date:	29 Oct 2023

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle : **SHD1086E**
Chassis Number : KNAGM414MF5639555
2. Name of Policyholder : **PREMIER TAXIS PTE. LTD.**
3. Effective Date of Insurance : **20 Oct 2017**
4. Expiry Date of Insurance : **19 Oct 2018**

5. Persons or Classes of Persons entitled to drive*

- (a) The Policyholder.
- (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

- (a) Use as a Taxi.
- (b) Use for social domestic and pleasure purposes.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	30 Oct 2015 / 08:53:12	Receipt No.:	AACCK001-AX239-151030-000021
Asset Type:	Vehicle	Transaction Amount:	\$69,044.00
Asset ID:	SHD1086E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151030085312963589		
Vehicle No.:	SHD1086E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	30 Oct 2015		
Original Registration Date:	30 Oct 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5639555		
Engine No.:	D4FDEH313485		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,475.00		
Minimum PARF Benefit:	\$14,079.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	30 Oct 2015 08:53:12		
COE No.:	2015103001003857Z		
COE Expiry Date:	29 Oct 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,439.00		
Lifespan Expiry Date:	29 Oct 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1086 E

1 pc	Boot lid ✕	\$	1,119.00
1 pc	Boot lid lock ✕	\$	99.00
1 pc	Bootlid striker ✕	\$	21.00
1 pc	Bootlid emblem ✕	\$	27.00
1 pc	Bootlid CRDi ✕	\$	29.00
1 pc	Bootlid rubber weatherstrip ✕	\$	96.00
1 pc	Bootlid lower garnish ✕	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 ✕ <i>ry</i>	\$	132.00
2 pcs	n/s & o/s tail lamp @ \$421.00 ✕	\$	842.00
1 pc	End panel ✕	\$	250.00
1 pc	End panel garnish ✕	\$	74.00
1 pc	Spare tyre clamp ✕	\$	6.00
1 pc	Rear bumper ✕	\$	696.00
1 pc	Rear bumper lower cover ✕	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$	58.00
1 pc	Rear bumper inner sponge ✕	\$	114.00
1 pc	Rear bumper reinforcement ✓	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✕	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✕	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✕	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 ✕	\$	92.00
		\$	4,938.00
		Less 10%	\$ 569.80
			<u>\$ 4,368.20</u>

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips ✕	\$	30.00
1 set	Bootlid lower garnish clips ✕	\$	60.00
1 set	Bootlid stickers ✕	\$	100.00
1 set	Reverse sensor ✓	\$	280.00
			<u>200</u>

4-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1086 E

Sundry	\$	50.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	1,200.00 400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$	800.00 360
To apply rustproofing on the repaired and replaced panels.	\$	150.00 X
	\$	<u>7,386.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 1 LKK

4/6/18 1600 hrs

2 Days

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

4-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1086 E

1 pc	Boot lid	X sue	\$	1,119.00
1 pc	Boot lid lock	X sue	\$	99.00
1 pc	Bootlid striker	X sue	\$	21.00
1 pc	Bootlid emblem	X "	\$	27.00
1 pc	Bootlid CRDi	X "	\$	29.00
1 pc	Bootlid rubber weatherstrip	X sue	\$	96.00
1 pc	Bootlid lower garnish	X sue	\$	290.00
2 pcs	Bootlid hinges @ \$66.00	X repair	\$	132.00
2 pcs	n/s & o/s tail lamp @ \$421.00	X sue	\$	842.00
1 pc	End panel	X sue	\$	250.00
1 pc	End panel garnish	X sue	\$	74.00
1 pc	Spare tyre clamp	X sue	\$	6.00
1 pc	Rear bumper	deformed	\$	696.00
1 pc	Rear bumper lower cover	cut	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X sue	\$	58.00
1 pc	Rear bumper inner sponge	X sue	\$	114.00
1 pc	Rear bumper reinforcement	✓ sue	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X sue	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X sue	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X sue	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	X sue	\$	92.00
			\$	4,938.00
			Less 10%	\$ 569.80
			\$	4,368.20

S/NETT

1 set	Rear bumper clips	✓ sue	\$	48.00
1 set	End panel inner garnish clips	X "	\$	30.00
1 set	Bootlid lower garnish clips	X "	\$	60.00
1 set	Bootlid stickers	X "	\$	100.00
1 set	Reverse sensor	✓ sited	\$	280.00
				200

4-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1086 E

Sundry	\$ 50.00 X 1.1
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X 1.1
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 1,200.00 400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$ 800.00 360
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 X 1.1
	<u>\$ 7,386.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

PIP 2386.00

U/S 1900

7486.20

Kalvin LKK

4/6/18 1600 hrs

2 Days

PIP

Before Part photo

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12/6/18

with 45 \$1900/ 2 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18010148/K1ja3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 13-12-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 5487E	Veh. Inspected	SHD 1086E	
Policy No.	Z18VP05018246	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020644	Excess (\$)	0.00	
Assign From		Assign Date	04/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5639555	Colour	SILVER	
Odometer	286872	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/05/2018	Inspection Date	04/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1086E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	SERVICEABLE	1,119.00	-
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NOT NECESSARY	27.00	-
1	BOOTLID CRDI	NOT NECESSARY	29.00	-
1	BOOTLID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOTLID LOWER GARNISH	SERVICEABLE	290.00	-
2	BOOTLID HINGES @\$66.00	TO REPAIR SEE LABOUR	132.00	-
2	N/S & O/S TAIL LAMP @\$421.00	SERVICEABLE	842.00	-
1	END PANEL	SERVICEABLE	250.00	-
1	END PANEL GARNISH	SERVICEABLE	74.00	-
1	SPARE TYRE CLAMP	SERVICEABLE	6.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
	LESS 10% DISCOUNT		-493.80	-150.90
			4,444.20	1,358.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-

Report Ref No. CC3/LPC18010148/K1ja3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			568.00	248.00
	LABOUR			
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE THE END PANEL. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF BOOTLID HINGES.		1,200.00	400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.		800.00	360.00
	TO APLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			2,450.00	780.00
GRAND TOTAL			7,462.20	2,386.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CC3/LPC18010148/K1ja3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.