

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3255.35

Loss of Rental (LOR):

S\$

564.30

(

4.5

days)

x 125.40

Loss of Use (LOU):

S\$

225.00

(\$

50

x

4.5 days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

4052.14

Global Sum S\$: 4050.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4050.00

Name 1:

Comfortdelgro Engineering Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

(DE 113)

Q meyer: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Est. ☒ Insured Cost: _____OD ☒ ITP / INS / TP RES / OD RES / EVA / INV / MV

To Insured Vehicle No: _____

at ☒ Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 282 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 2444 PYr Regn: 10 Aug, 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 80166

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD KB3F4 7035 63138Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wettkle

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. 7

mm

L/Bal. 7

mm

D.O.A. 1/6/18D.O.A. 4/6/18Survey held at CPGE (Loring)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/6/18

Continued PIP \$ 3042.38 / 2 days.

(TZ)

PIP

(40-81375-7)

31/1)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18010149/K1wa3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 05-06-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 258Z	Veh. Inspected	SHA 2444P
Policy No.	DMCVSN3059871700	Coverage (\$)	0.00
Claim No.	SNM18D02800C02	Excess (\$)	0.00
Assign From		Assign Date	05/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/06/2018	Inspection Date	04/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD. 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 11 June, 2018 5:20 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBE258Z (OI : CTI - SNM18D02800C02) and SHA2444P (TP : LKK REF - CC3/CTI18010149/K1wa3) on 01/06/2018
Attachments: leeSZ_SNM18D02800C01-GBE258Z-
LKKDirectSettlementAccidentLtr_CLCR95.007.pdf; MLHM18071731-GBE258Z.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 11 June, 2018 12:02 PM
To: Claims Dept of CTI
Cc: Elaine Cheong; Lucas Lee; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving GBE258Z (OI : CTI - TBA) and SHA2444P (TP : LKK REF - CC3/CTI18010149/K1wa3) on 01/06/2018

WITHOUT PREJUDICE

Our Reference: **SNM18D02800/C01/8**

Date : **11 JUNE 2018**

via Ordinary & Registered Mail

FIRST SIGHT INTERNATIONAL PRIVATE LIMITED
998 TOA PAYOH NORTH
#02-08
SINGAPORE 318993

Dear Sir / Madam

ACCIDENT INVOLVING GBE258Z AND SHA2444P ON 01 JUNE 2018
ALONG SLIP ROAD AT LOR 6 TOA PAYOH TOWARDS BRADDELL ROAD

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHA2444P**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIVIAN
Ref : CC3/CTI18010149/L1WA3
Contact No : 68418625
via Email : VIVIAN@LKKAUTO.COM

CC : Agent - (AN0450A) - INXPIRE N SOLUTIONS

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Bradden Road Singapore 679701
 Mainline + 65 6383 6250 Facsimile + 65 6280 9755
 Workshops
 60 Loyang Drive Singapore 508908 64 Serangoon Loop Singapore 758156
 383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728721
 45 Pandan Road Singapore 608288 8 Defu Avenue 1 Singapore 539537
 300 Upper Road Singapore 368939

Date/Time: 01.06.2018 17:44 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC No: 305168256

OMER	REGN NO: SHA2444P	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
OMER NO 7010045	MODEL PRIUS HYBRID(G4)01.06.2018 12:05	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE	DATE/TIME IN	
TESS Singapore SINGAPORE 575717	YR OF MANU 10.08.2017	TARGET DATE
65508755 (R) (P)	CHASSIS CODE JTDKB3FU703563138	COMPLETION DATE/TIME:
DUNT CARD NO.		

JOB DESCRIPTION

Incident Date: 01.06.2018
 NATURE: 3P 01.06.18

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHA2444P

LIMITS

Vehicle No.: SHA2444P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE

VEHICLE NO : SHA 2444P

MAKE :

MODEL : TOYOTA PRIUS

China Taiping - (P/P)

2/6/2018

(Sat)

LKK - Kalvin

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID LOGO(PRIUS) — <i>nc</i>			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) — <i>nc</i>			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) — <i>nc</i>			\$ 52.90
REAR BUMPER — <i>Detail</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>2/Bul</i>			\$ 318.80
REAR BUMPER UNDER COVER — <i>cl</i>			\$ 552.60
REAR BUMPER SPONGE <i>X 12</i>			\$ 143.40
REAR BUMPER TOWING COVER — <i>cl</i>			\$ 82.70
REAR BUMPER CLIPS — <i>nc</i>			\$ 22.00
3 RD BREAK LIGHT — <i>nc</i>			\$ 198.40
SPOILER SUB-ASSY, REAR <i>X Repair</i>			\$ 953.70
<i>Boat lid lower harsh - nc</i>			\$ 889.70
SUB TOTAL			\$ 2,896.30
LESS 25%			\$ 724.08
DISCOUNTED TOTAL			\$ 2,172.23
REAR TRUNK LID APPS STICKER — <i>nc</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER — <i>nc</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR — <i>still</i>			\$ 135.70
REAR BUMPER RUBBER MAT — <i>nc</i>			\$ 50.00
			\$ 285.70
LABOUR CHARGE			
Panel Beating			\$ 300
Spray Painting Charge			\$ 450.00
Wiring Charge			\$ 400 450.00
Remove/Refix Reverse Sensor			\$ 20 50.00
			\$ 20 120.00
TOTAL LABOUR			\$ 1,070.00
ESTIMATE TOTAL			\$ 3,527.93

Kalvin LKK

4/6/18 1045h

2 P/P

P/P

Return Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

VEHICLE	:	SHA2444P	TYPE OF CLAIM	:	TP
MODEL	:	TOYOTA PRIUS	SURVEY BY	:	LKK-KALVIN
JOB NO	:	305168256	DATE	:	04/06/18

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 05.06.2018

Time: 17:51:10

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305168256
 REGN NO : SHA2444P
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 10.08.2017
 DATE/TIME IN : 01.06.2018 12:05
 ACCIDENT DATE : 01.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	28-01-0302-0006-A	BOOTLID 65521111	1	30.00	0.00	30.00
0002	28-01-0302-2013-A	BOOTLID APPS STICKERS	1	40.00	0.00	40.00
0003	28-01-0302-2015-A	BOOTLID COMFORTDELGRO	1	30.00	0.00	30.00
0004	04-01-0302-2269-G	BOOTLID TOYOTA STAR	1	52.90	25.00	39.67
0005	04-01-0302-2270-G	BOOTLID HYBRID	1	52.40	25.00	39.30
0006	04-01-0302-2271-G	BOOTLID PRIUS	1	60.80	25.00	45.60
0007	04-01-0302-2282-G	REAR BUMPER	1	458.60	25.00	343.95
0008	04-01-0302-2287-G	REAR BUMPER UNDER COVER	1	552.60	25.00	414.45
0009	04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50
0010	09-01-0302-2005-A	REVERSE SENSOR	1	135.70	25.00	135.70
0011	04-01-0302-2286-G	REAR BUMPER TOW COVER	1	82.70	25.00	62.02
0012	09-01-0302-2135-G	THIRD BRAKE LIGHT	1	198.40	25.00	148.80
0013	04-01-0302-2288-G	REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305168256
REGN NO : SHA2444P
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 10.08.2017
DATE/TIME IN : 01.06.2018 12:05
ACCIDENT DATE : 01.06.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 04-01-0302-2346-G BOOTLID LOWER GARNISH	1	889.70	25.00	667.27	

SUB-TOTAL : 2,252.36

JOB NATURE

0000 L	PANEL BEATING	300.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 L	R/I REVERSE SENSOR	20.00
0004 20-05	REAR BUMPER MAT	50.00
SUB-TOTAL :		790.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 05.06.2018

Time: 17:51:10

REPAIR ESTIMATE

Page: 3


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305168256
REGN NO : SHA2444P
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 10.08.2017
DATE/TIME IN : 01.06.2018 12:05
ACCIDENT DATE : 01.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,042.36


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305168256

Date : 06/06/18

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHA2444P

Date of Accident : 01-Jun-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBE 258Z
2. The finalized amount shall be:


(a) Spare Parts after List discount	\$2,252.38
(b) Labour Charges	\$790.00
Total for Part-By-Part Repair Cost	\$3,042.38
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : KALVIN

Tel : 62148398

Date : 6/6/18

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18010149/K1wa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 258Z	Veh. Inspected	SHA 2444P
Policy No.	DMCVSN3059871700	Coverage (\$)	0.00
Claim No.	SNM18D02800C02/8	Excess (\$)	0.00
Assign From		Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703563138	Colour	BLUE
Odometer	80166	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/06/2018	Inspection Date	04/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2444P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	CUT	552.60	552.60
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
1	REAR BUMPER TOWING COVER	CUT	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	3 RD BREAK LIGHT	CRACKED	198.40	198.40
1	SPOILER SUB-ASSY ,REAR	TO REPAIR SEE LABOUR	953.70	-
1	BOOTLID LOWER GARNISH	CRACKED	889.70	889.70
	LESS 25% DISCOUNT		-946.50	-672.22
			2,839.50	2,016.68
SPECIAL NETT ITEMS				
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			285.70	285.70
LABOUR				
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF SPOILER SUB-ASSY ,REAR .		450.00	300.00
	SPRAY PAINTING CHARGE.		450.00	400.00
	WIRING CHARGE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	20.00
			1,070.00	740.00
GRAND TOTAL			4,195.20	3,042.38
RECOMMENDED COST OF REPAIRS				3,042.38

Report Ref No. CC3/CTI18010149/K1wa3n2



Report Ref No. CC3/CTI18010149/K1wa3n2

A stylized, handwritten signature in black ink, consisting of a large, flowing 'W' followed by a smaller 'K'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan' in a cursive style.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.